

COPY OF SERVICE MESSAGE BY ELECTRIC TELEGRAPH.

Patnamund. To Madras
 Lt. Rickerts To Col. Bridgman

WORDS 19M

Did not see my name
 Gazette of 22nd. Am I to
 see at Trichinopoly. Please
 explain back.

30" 14-25
 Among several others for leave
 in being long been required
 in the Dept of the Secretary
 and for the Secretary of the

at From
 at to

Station forward to
 J. C. [Signature]
 in Charge

Telegraph Office,
 June 1896

Division of the Delta.	Name of the Canal	Sectional Area in 1858	Average supply of water per acre from the S. the 1st of October 1858-8	Supply of water per acre from the Channels and <u>outlets</u> of supply	Remarks.
Eastern Delta	Sanulabatta High Level	25	20. 130	45.000	
	Coimada	42	98. 278	118.000	
	Cheringa	"	70. 000	98.000	
	Ganani	"	30. 000	42.000	
	Total		218. 408	303.000	
Central Delta	Larnadunka	30	22. 000	45.000	
	Anulapoor & Nalle	44	54. 500	64.000	
	Immarum.	14 1/4	48. 548	54.000	
	Total		125. 048	163.000	
	Elure High Level Canal	"	60. 000	70.000	
Western Delta	Akud	82	123. 400	200.000	
	Murospoor.	108	143. 800	200.000	
	Piddanum	30	34. 500	50.000	
	Total.	"	361. 700	520.000	
	Grand Total	"	904. 156	988.000	

1858-59
1859-60
1860-61
1861-62
1862-63
1863-64
1864-65
1865-66
1866-67
1867-68
1868-69
1869-70
1870-71
1871-72
1872-73
1873-74
1874-75
1875-76
1876-77
1877-78
1878-79
1879-80
1880-81
1881-82
1882-83
1883-84
1884-85
1885-86
1886-87
1887-88
1888-89
1889-90
1890-91
1891-92
1892-93
1893-94
1894-95
1895-96
1896-97
1897-98
1898-99
1899-00
1900-01
1901-02
1902-03
1903-04
1904-05
1905-06
1906-07
1907-08
1908-09
1909-10
1910-11
1911-12
1912-13
1913-14
1914-15
1915-16
1916-17
1917-18
1918-19
1919-20
1920-21
1921-22
1922-23
1923-24
1924-25
1925-26
1926-27
1927-28
1928-29
1929-30
1930-31
1931-32
1932-33
1933-34
1934-35
1935-36
1936-37
1937-38
1938-39
1939-40
1940-41
1941-42
1942-43
1943-44
1944-45
1945-46
1946-47
1947-48
1948-49
1949-50
1950-51
1951-52
1952-53
1953-54
1954-55
1955-56
1956-57
1957-58
1958-59
1959-60
1960-61
1961-62
1962-63
1963-64
1964-65
1965-66
1966-67
1967-68
1968-69
1969-70
1970-71
1971-72
1972-73
1973-74
1974-75
1975-76
1976-77
1977-78
1978-79
1979-80
1980-81
1981-82
1982-83
1983-84
1984-85
1985-86
1986-87
1987-88
1988-89
1989-90
1990-91
1991-92
1992-93
1993-94
1994-95
1995-96
1996-97
1997-98
1998-99
1999-00
2000-01
2001-02
2002-03
2003-04
2004-05
2005-06
2006-07
2007-08
2008-09
2009-10
2010-11
2011-12
2012-13
2013-14
2014-15
2015-16
2016-17
2017-18
2018-19
2019-20
2020-21
2021-22
2022-23
2023-24
2024-25
2025-26
2026-27
2027-28
2028-29
2029-30
2030-31
2031-32
2032-33
2033-34
2034-35
2035-36
2036-37
2037-38
2038-39
2039-40
2040-41
2041-42
2042-43
2043-44
2044-45
2045-46
2046-47
2047-48
2048-49
2049-50
2050-51
2051-52
2052-53
2053-54
2054-55
2055-56
2056-57
2057-58
2058-59
2059-60
2060-61
2061-62
2062-63
2063-64
2064-65
2065-66
2066-67
2067-68
2068-69
2069-70
2070-71
2071-72
2072-73
2073-74
2074-75
2075-76
2076-77
2077-78
2078-79
2079-80
2080-81
2081-82
2082-83
2083-84
2084-85
2085-86
2086-87
2087-88
2088-89
2089-90
2090-91
2091-92
2092-93
2093-94
2094-95
2095-96
2096-97
2097-98
2098-99
2099-00
2100-01
2101-02
2102-03
2103-04
2104-05
2105-06
2106-07
2107-08
2108-09
2109-10
2110-11
2111-12
2112-13
2113-14
2114-15
2115-16
2116-17
2117-18
2118-19
2119-20
2120-21
2121-22
2122-23
2123-24
2124-25
2125-26
2126-27
2127-28
2128-29
2129-30
2130-31
2131-32
2132-33
2133-34
2134-35
2135-36
2136-37
2137-38
2138-39
2139-40
2140-41
2141-42
2142-43
2143-44
2144-45
2145-46
2146-47
2147-48
2148-49
2149-50
2150-51
2151-52
2152-53
2153-54
2154-55
2155-56
2156-57
2157-58
2158-59
2159-60
2160-61
2161-62
2162-63
2163-64
2164-65
2165-66
2166-67
2167-68
2168-69
2169-70
2170-71
2171-72
2172-73
2173-74
2174-75
2175-76
2176-77
2177-78
2178-79
2179-80
2180-81
2181-82
2182-83
2183-84
2184-85
2185-86
2186-87
2187-88
2188-89
2189-90
2190-91
2191-92
2192-93
2193-94
2194-95
2195-96
2196-97
2197-98
2198-99
2199-00
2200-01
2201-02
2202-03
2203-04
2204-05
2205-06
2206-07
2207-08
2208-09
2209-10
2210-11
2211-12
2212-13
2213-14
2214-15
2215-16
2216-17
2217-18
2218-19
2219-20
2220-21
2221-22
2222-23
2223-24
2224-25
2225-26
2226-27
2227-28
2228-29
2229-30
2230-31
2231-32
2232-33
2233-34
2234-35
2235-36
2236-37
2237-38
2238-39
2239-40
2240-41
2241-42
2242-43
2243-44
2244-45
2245-46
2246-47
2247-48
2248-49
2249-50
2250-51
2251-52
2252-53
2253-54
2254-55
2255-56
2256-57
2257-58
2258-59
2259-60
2260-61
2261-62
2262-63
2263-64
2264-65
2265-66
2266-67
2267-68
2268-69
2269-70
2270-71
2271-72
2272-73
2273-74
2274-75
2275-76
2276-77
2277-78
2278-79
2279-80
2280-81
2281-82
2282-83
2283-84
2284-85
2285-86
2286-87
2287-88
2288-89
2289-90
2290-91
2291-92
2292-93
2293-94
2294-95
2295-96
2296-97
2297-98
2298-99
2299-00
2300-01
2301-02
2302-03
2303-04
2304-05
2305-06
2306-07
2307-08
2308-09
2309-10
2310-11
2311-12
2312-13
2313-14
2314-15
2315-16
2316-17
2317-18
2318-19
2319-20
2320-21
2321-22
2322-23
2323-24
2324-25
2325-26
2326-27
2327-28
2328-29
2329-30
2330-31
2331-32
2332-33
2333-34
2334-35
2335-36
2336-37
2337-38
2338-39
2339-40
2340-41
2341-42
2342-43
2343-44
2344-45
2345-46
2346-47
2347-48
2348-49
2349-50
2350-51
2351-52
2352-53
2353-54
2354-55
2355-56
2356-57
2357-58
2358-59
2359-60
2360-61
2361-62
2362-63
2363-64
2364-65
2365-66
2366-67
2367-68
2368-69
2369-70
2370-71
2371-72
2372-73
2373-74
2374-75
2375-76
2376-77
2377-78
2378-79
2379-80
2380-81
2381-82
2382-83
2383-84
2384-85
2385-86
2386-87
2387-88
2388-89
2389-90
2390-91
2391-92
2392-93
2393-94
2394-95
2395-96
2396-97
2397-98
2398-99
2399-00
2400-01
2401-02
2402-03
2403-04
2404-05
2405-06
2406-07
2407-08
2408-09
2409-10
2410-11
2411-12
2412-13
2413-14
2414-15
2415-16
2416-17
2417-18
2418-19
2419-20
2420-21
2421-22
2422-23
2423-24
2424-25
2425-26
2426-27
2427-28
2428-29
2429-30
2430-31
2431-32
2432-33
2433-34
2434-35
2435-36
2436-37
2437-38
2438-39
2439-40
2440-41
2441-42
2442-43
2443-44
2444-45
2445-46
2446-47
2447-48
2448-49
2449-50
2450-51
2451-52
2452-53
2453-54
2454-55
2455-56
2456-57
2457-58
2458-59
2459-60
2460-61
2461-62
2462-63
2463-64
2464-65
2465-66
2466-67
2467-68
2468-69
2469-70
2470-71
2471-72
2472-73
2473-74
2474-75
2475-76
2476-77
2477-78
2478-79
2479-80
2480-81
2481-82
2482-83
2483-84
2484-85
2485-86
2486-87
2487-88
2488-89
2489-90
2490-91
2491-92
2492-93
2493-94
2494-95
2495-96
2496-97
2497-98
2498-99
2499-00
2500-01
2501-02
2502-03
2503-04
2504-05
2505-06
2506-07
2507-08
2508-09
2509-10
2510-11
2511-12
2512-13
2513-14
2514-15
2515-16
2516-17
2517-18
2518-19
2519-20
2520-21
2521-22
2522-23
2523-24
2524-25
2525-26
2526-27
2527-28
2528-29
2529-30
2530-31
2531-32
2532-33
2533-34
2534-35
2535-36
2536-37
2537-38
2538-39
2539-40
2540-41
2541-42
2542-43
2543-44
2544-45
2545-46
2546-47
2547-48
2548-49
2549-50
2550-51
2551-52
2552-53
2553-54
2554-55
2555-56
2556-57
2557-58
2558-59
2559-60
2560-61
2561-62
2562-63
2563-64
2564-65
2565-66
2566-67
2567-68
2568-69
2569-70
2570-71
2571-72
2572-73
2573-74
2574-75
2575-76
2576-77
2577-78
2578-79
2579-80
2580-81
2581-82
2582-83
2583-84
2584-85
2585-86
2586-87
2587-88
2588-89
2589-90
2590-91
2591-92
2592-93
2593-94
2594-95
2595-96
2596-97
2597-98
2598-99
2599-00
2600-01
2601-02
2602-03
2603-04
2604-05
2605-06
2606-07
2607-08
2608-09
2609-10
2610-11
2611-12
2612-13
2613-14
2614-15

Statement of remunerative Works in the Jodanuz District in the Year 1861-1862.

Name of Work.	Capital.			Revenue.		
	Outlay on Construction			Income		
Description	Amount up to the End of the Past Year	Amount in the Current Year	Amount up to the End of the Past Year	Amount in the Current Year	Amount up to the End of the Past Year	Amount in the Current Year
	Description	Description	Description	Description	Description	Description
Jodanuz Canal and its Subsidiary Works.	Original Work and Reconstruct ⁿ	3.428.390 65.269 3.493.659	Interest on the Capital at 4 per Cent	1.069.397 137.136 1.206.533	Gross Proceeds from all Sources	10.457.457 1.797.912 12.255.369
	Deduct Deterioration of year and year at 1 per Cent	221.018 34.284 255.302	Insurance and Repairs	1.992.786 277.335 2.270.121		
	Balance of Capital	3.207.372 30.985 3.238.357	Total Balance of Charges	3.062.183 414.471 3.476.654	Total Balance of Income	10.457.457 1.797.912 12.255.369
Total Collections as per Statement of the Collector 23 rd of May 1862 deducting Income Tax				Rupees		
				3.820.912		
Average Revenue and Collection for 5 Years before the Construction of the Canal				2.023.000		

Balance of Capital = 3.238.357
 Balance of Income for Current Year = 1.383.441
 Per Centage Return = 42 ²/₃.

Increase 1.797.912.

[Signature]

21/09/2016

Statement Showing Expenditure incurred on some of the works in the
Irrigation District up to the end of the year 1861-62.

Names of Deltas	Names of the Channels &c.	Amount of the Expenditure	State of each Channel
Eastern Delta.	Sanibel Creek Canal	64.705-	Repairs.
	Branches	4.219	
	Masonry	12.725-	81.649
	Canada Canal	55.717	
	Branches	57.824	
Central Delta.	Masonry	43.493	157.034
	Main Channel	35-320	
	Repairs	118.256	153.546
	Palmer Channel	157.976	
	Masonry	5-224	173.200
Western Delta.	Sanibel Channel	54.711	
	Branches	19.439	
	Masonry	262.112	336.482
	Sanibel Channel	78.974	
	Branches	42.685-	
Western Delta.	Masonry	45-647	167.306
	Elbow Canal	204.146	
	Main Channel	1.479	
	Outlet Drains	97.382	303.047
	Masonry		
		Total	
		Total - Grand Total	

21 Feb -
The irrigation works etc.
in the
Godavari District -

The Goddard River.

The River Godavary has its
Sources amongst the
Hills in the Western Coast
of India and in its
Course down to the Sea
drains an enormous
Tract of Country

The length of the course
may be roughly taken
at between 650 and
700 miles. The Jordan
is liberally supplied
with by the North-East
and North-West Rivers
It emerges from among
the hills near a village
called Palarum, about
28 or 30 miles above the
It is used as a ...
the
an
... ..
... ..


Central, and Western
 Deltas These Deltas
 Collectively contain an
 area of about 2000 square
 miles of the most magnificent
 alluvial soil. In the
 irrigation of which the
 Godavari is most convenient
 situated as it actually
 flows along the top of
 a ridge, from a short
 distance below the point
 at which it debouches
 from amongst the hills.
 The ground sloping
 on either side in a
 perpendicular direction
 to its course.

General System of Irrigation

The General System of the
 Godavari Irrigation is as follows
 An ancient or dam at
 Dandakshwaram is to
 stop water and retain it
 at the required height for
 distribution over the surface
 of the Country.

Drainage Channels for the
 escape of surplus water
 River Embankments to
 prevent drainage from
 fishery
 Irrigation Channels

Sketch
 of the Head of the Godavari Delta, showing the arrangement
 of Railways and Canals for carrying on the work in
 1848-49



to lead the water over
the surface of the country
drainable channels for
the transport of goods,
produce and passengers.

Position of Anicut



The Anicut is situated at
Dmlaismeram, about $4\frac{1}{2}$
miles below Rajahmundry
by land, and at a distance
of the river (which varies
in the amount of water)
from 4 to 7 miles.

Between Dmlaismeram
and Vijashmeram the
river is divided into
four channels by embankments
or islands. See outline
attached. And across
each of these channels
there is a separate dam
or Anicut. The names
of these branches are
the Dmlaismeram, the
Raller, the Doddoo,
and the Vijashmeram.
These embankments are of
great advantage in
the construction of the
Anicut as they form
points from whence to
commence the work, and
also by subdividing the

The stream, admitted of the
being diverted from
each branch in succession
during the time of its
construction

Commencement of Cement
Historical Sketch

The cement-operations
were commenced in
1847. Between Jan'y
and Feb'y 1847 the
preparations for the
actual building were
completed. Boats of
rough stone, grass and
bamboos, and brushwood
were built up above the
actual site of the cement
stretching from Cunka
to Cunka, by this means
a dry space was secured
for the building operations
and also, the water being
retained, there was an
insufficient depth for
transport of materials.
Quarries, ramways, lime
kilns &c. &c. were
commenced, embankments
across the of the Cunka
were drawn up, Railways
were made &c. &c. and used

number of boats of about
25-30 tons each,
were launched.

Irish people was often
experienced in keeping
the Corlies on the boats
and at times the
supervision was clumsy
and inefficient.

1848.

In 1848 the Dmlaishuran
and Muddoor branches
of 1400 and 520 yards
in length respectively
were built up to a height
of 9' above the deep
bed of the river.

The Dmlaishuran
lock, head sluices,
and under sluices
were nearly completed
and the Paller branch
built up to a height
of 5 feet.

On the Paller branch
the wing walls and the
under sluices, the lock
and the head sluices
were commenced,
On the Vijashuran branch
the head and under
sluices and the locks
were also begun

During some unfortunate
failure in the steamway
waggon wheels, the rough
some portions of the
current were considerably
delayed, the water also
being very low, the
transport of stone was
a slow and tedious
affair. Two channels
were cut in the sand
on the Douglas River
side in the transport
of stone, but as they
were never deep enough
the boats were unable
to go up or down them
when properly laden.
On the 14th of June in
this year a freshet
came down, and
having risen above the
boats carried away
about 80 yards of
the middle of the
the embankment in front
of the sluices and the
railway embankment
on the Douglas River
side was carried away
about 1/2 of furlongs and
the boats again delayed
the work most seriously.

1849

In May 1849 the front
retaining wall on the
Douglas River branch was
carried away to the
extent of 44 yards, and
a quantity of loose stone
stone was also swept
down through the
reach.

In September 1849 a freshet
of unusual height
accompanied by a heavy
gale of wind caused
several breaches in
the river embankments
the steam dig and
several stone boats were
lost at this time
and the Douglas River
branch slightly breached.
In this year the drainage
works were nearly all
completed in the upper
of the head sluices and
locks at Puller.
Flows were at one time
entertained that the
Puller branch would
never be completed, as
it was then the only
outlet for the escape of
the water.

In 1850 the current was
April

an average height of 10 1/2
 feet - along its entire length
 In some the Rafter and
 Tyashuram Branches
 suffered some damage
 from freshets, some piers
 in the Rafter under
 sluices fell and 2 partially
 sunk. Col Cotton however
 remedied this in 1837
 by increasing the width
 of the front and rear
 aprons and placing
 a double row of walls
 under the front retaining
 wall the fall of these
 piers was attributed to
 the inefficiency of the
 masonry aprons.

Defects. Experienced

The Channel on the Tyash-
 uram side being too
 flat deeper than the
 others, the current
 had of course the drift
 too fast higher this made
 the surface very heavy
 consequently there was
 a tendency to disturb
 the apron and scour
 out the bed of the river

below. The position
 of the Dowlaismeram
 Lock is not particularly
 good as it lies in
 the direct line of the
 current of the river
 which makes entering it
 a matter of some difficulty
 and danger when the
 river is high, also the
 lock is divided from
 the river by a single
 and not particularly
 strong wall, and as
 the water outside is
 sometimes very much
 higher than it is
 inside, there is some
 danger of a collapse
 in the whole affair
 The Dowlaismeram
 Head and under
 sluices are sometimes
 prevented from closing
 during the freshets
 by accumulations of drift
 wood &c - against the
 shutters, To remedy this
 evil Col Horsley designed
 a very ingenious and
 simple contrivance of
 slips of iron jointed
 in much the same
 principle as that on

Which portable Jackhammers
or Churn Drills are
constructed. These
Machines have not had
as yet a fair trial.
In the Waller Reach
the deep rough stone
foundations allowed the
water to flow through
in considerable quantities.
Not long afterwards
made right of a puddling
of clay on the outside.
The current being built
of rather soft stone, there
is a good deal of
wear and tear during
the freshets; consequently
large portions have to
be renewed from time
to time.

In December 1887 a breach
of 200 yards was formed
in the Middleton Branch
there. The current had
scored a deep hole in
front of the works, the
pressure of the head of
water on the current
pressed the sand from
under the foundation
walls into the cleared hole.

Consequently the water quietly
subsided -
To repair this breach a
dam was thrown about
eight or nine hundred
yards above the ancient
where the river was
ten feet deep, large
baskets or gabions filled
with stones were laid
from the sides of the river
across the current. These
the lines of gabion-bowmen
could not be made to
join and hold in the
middle, they were
irregularly washed away
and the place deeply
scored. A month's
hard and disheartening
labour and this scheme
was finally abandoned.
The river however fortunately
fell. A place only
seven feet deep, a little
higher up stream was
thrown. Twenty boats
in line, simultaneously
laid down baskets as
before. In a week or
two a dam was formed and
the breach was thus
repaired.

Necessity for raising
Ammut

The ammut is now being
raised ten feet - along its
entire length. This
increased head of water
is required in the district
for the navigation and
irrigation. The water
was formerly retained
ten feet higher than the
crest of the ammut
by means of pillos or plants
let in between the ground
iron posts, which were
placed ten feet apart
along the front wall
throughout the entire
length of the ammut.
These plants were
taken out during the
fushets and again
replaced when the
water had subsided.
Now sometimes the
smaller fushets never
occur, and occasionally
they followed up the
subsidence of the larger
ones so quickly I admit
of them being replaced.
Consequently this temporary
method of raising the

Cost.

The ammut could not
be depended on.

The original estimate
was five lacs of Rupees.
The actual outlay
about 980,000 Rupees.
The average yearly cost
of maintenance about
30,000 Rupees.
The average prices for
repairs are as follows.
Replacing cut-stone facing
9 Rs. per cubic ft.
Plastering when required
2 1/2 Rs. per square
String lining the apron
1 Rs. per foot
Replacing sluice and
Culverts when necessary
2 1/2 Rs. per cubic ft.
Temporary drains at
1 Rs. per running ft.

Materials

The bricks used were
of the usual dimensions
but rather an inferior
make. They were used
in building the walls
Arches &c.

Each well was about
Rs. 5.

Stone was found in a
hill close to the Upper
Camp, about 2000.

Gards from the ancient
It was a soft coarse
sandstone which

found in well with
the Chumam which
has of a first-rate
hydraulic quality.


The stone was employed
on Ramways with a
good slope the loaded
waggons coming down

by their own weight
and the empty ones
being drawn up again
by horses or oxen in

the day time and
by coolies at night.
Locomotives were shown
used on the


Ramways but they did
not arrive from Calcutta
in time. We saw
three Ramways cost

about 6000 or 7000 Rs
per mile. The line
went in square



Plan.

Simulstath Canal.



Section

hard tiles built of brick
in Chumam. Outside and
inside and brick in
sand outside about
350 or 400 pounds of
Chumam are turned
out of each of these tiles
in four days. Their cost
was about 500 Rs each.
One was at Bolhar Lunkar
one at Rajabmundry
two at Dombais Ameram
and one at Vijayapuram.
The plan and section of
these tiles are shown
in the margin.


The Simulstath Canal
which branches off from
the Coomada Canal at
Cuddum, a village about
four miles from the
Dombais Ameram Anicut
is almost exclusively
a navigation channel.
It receives most of the
drainage of the country
about it, runs on nearly
a dead level and
irrigates but a small
portion of the land.

Between Simulstath and
Coomada there is a
branch or race of the

When the Canal crosses the
 drainage channels, the
 drainage water is disposed
 of in either of two ways
 as the case may be
 First - by passing it through
 a Culvert under the
 bed of the Canal,
 Or, when the drainage and
 Canal channels are
 nearly on the same level
 it is allowed to pass
 through a side opening
 directly into the Canal
 and flow out again over
 a Calingula on the
 opposite side. All the
 locks are provided
 with Calingulas, to get
 rid of any superfluous
 water in the Canals
 and to prevent the
 accumulation of dirt in
 front of the locks.

Each Calingula is fitted
 with another similar
 to them on the crest of
 the summit, by means
 of which the flow of
 water is regulated.
 There is also a deep
 pit called a Tambogina

Calingula and Lock. Coropz.



in Each Calingula
by means of which the
water can be let out
of the Canal to the
level of the channel bed.
The Spillway in the
margin shows the
injuries in which the
locks and Calingulas
are generally relatively
placed.

There are three locks
between Ontario
and Cocanada, each
100 feet long, 15 feet
wide, and 9 feet high.
Some of these locks are
in a good state of
repair and they are
all too short and
too narrow.

The contrast between
the above three locks
and the three between
Samuel Lake and
Cocanada is strongly
marked in favor of
the latter. The double
lock at Samuel Lake is
in a very perfect state
and is in fact a
very fine work. It
has formerly eight and
only 100 feet long.

It - The pressure of water
above was considered
unsafe and it was
accordingly lengthened
Another Chamber with
a 9 foot lift was
added and this was
150 feet long and 20
feet wide. The upper
Chamber filling by means
of a culvert and well
in addition to the usual
gate sluices. Before
reaching this lock the
Canal crosses the line
of the 3 means of an
aqueduct, which although
not a peculiarly picturesque
is a particularly good
work. It consists of
5 arches of 15 feet span
curved, arc of a circle, rise
3 feet. Foundations 6
feet deep. Squares of
hammer dressed stone
filled in with rubble
then which concrete 2 1/2
feet thick & present
leakages. The other
two locks between Coandea
and Jamulstake are
single, 150 feet
wide and 20 feet high.

Jmmarum Aqueduct.

fine masonry and in
good repair
In the central delta
in the Jmmarum Channel
as the locks have small
lifts of about 4 feet at
the most. The Chambers
sides are simply rubble
stone, dry laid at an
inclination. The gates
are of coarse brick
in the masonry in
the usual way.

The Jmmarum aqueduct
leads a branch of the
Jmmarum Canal across
the lower branch of the
Western or Tigris
Jordann. In the
irrigation of the tract
of country below, consisting
of about 352,000 acres
The length of the aqueduct
between the abutments is
2,248 feet, 49 arches
each 40 feet water way
at spring g. curve. The
piers are 48 in number
and have a waterway
batter of 6" down from
the spring. The abutments
on both banks are
segments of circles
with 35 feet radius.


including in return walls
15 feet long, thus locking
the work into the bank
firmly on either side of
the river. The entire
work rests on wells $5\frac{1}{2}$
feet diameter and 8 feet
deep in sand.
Height of piers from floor
spring of arches $11\frac{1}{2}$ feet.
Span of arches 4 feet.
Thickness throughout
 $2\frac{1}{2}$ feet. Height of parapet
above line of level of arch
crown 6 feet. On the
left stream side is an
opening or foot-path. There
is a fall of 2 feet between
the abutments, and as
there is no flooring to
the water way, in many
places the water flows
over the masonry smooth.
During the freshets the
water in the river
rises above the crown
of the arches, and great
and heavy masses of ice
and well packed stones
are provided, which are
further strengthened with
parallel lines of brickwork.
The whole work is built of
brick laid in mortar.

On some occasions at low
water the coolies being
obliged to handle them
with pads of straw &c -
they are of large dimensions
 $18" \times 6" \times 3"$, and to ensure
them being properly
vented - a hole of $\frac{1}{2}$ inch
diameter is bored each
brick through its entire
length. The coolies
do not have been procured
for this work, hence the
from Simla is
about 30 miles distant.
The aqueduct has been
reached three times,
but each time it was
successfully repaired.
Abutment piers are built
so that in case an arch
is damaged in any way
and falling the damage
will be limited to three
between two of the abutment
piers. The extraordinary
freshet of 1861 flooded
at a height of 4 feet
above the structure which
did no damage. The
aqueduct was estimated
at 73000 but in
consequence of the delay
being so hurriedly
built about 10

The work was finished up
 to the level of the arch
 crosses in the months
 and the whole affair
 completed in three months
 During the construction a
 freshet came and flooded
 over the building but no
 damage of a serious nature
 was caused by it.

The Elora Aqueduct

On the high level Canal
 in the Western District
 about 700 or 800 yards
 from the town of Elora
 there is a fine cut-
 stone lock, with a 9
 feet lift. The position
 of the Canal and aqu-
 educt will be seen
 in the accompanying
 diagram. The Lammillaire
 River runs which the
 Aqueduct is constructed
 divides at A. Embracing
 the town between its two
 branches. The water
 will essentially be directed
 from the Eastern Branch
 into the Western where
 it will be made to
 flow. The Canal marked
 by dotted lines.



Lammillaire
 These Lammillaire River are an area
 of about 5 square miles in the
 wet season and are quite
 dry during the hot season

Calingula and under
the Aqueduct.

The foundations in the
aqueduct are four feet
deep under the piers,
abutments and wing
walls, and two feet
beneath the water way.
They are of rough stone
in Chumana and the
ground excavated for
them was alluvial soil
and sand, alternated.
There are 12 arches for
the passage of water.
The span 15 feet and
rise 3 feet. They are
 $1\frac{1}{2}$ feet thick throughout.

The piers are four feet
high from the ground
level to the spring of
the arches, and four
feet thick. Every
fourth pier is an
abutment pier, & that
in case of one arch
giving way, no more
than three would fall
of necessity. The rising
path is built on the
down stream side, which
is supported by 6 arches
one of which spans over
2 of those supporting the
water way.

The arches are 2 feet thick
with a rise of 7 feet and
a span of 34 feet.

The depth of water bay
7 feet. width of ditto 32
feet 6 inches and
a layer of concrete 6
inches thick. over the
arch crown and rings
the water way is a arch.
The facing of the work is
old red sandstone which
was procured from
some old ruined temples
and parts of the old
bank lands. On many
of these stones there are
carvings of elephants
&c in relief.

In the rubble masonry
kind of packing stone
is used. The Simurgh
Calingula is on the
up stream side about
50 feet from the aqueduct
and the fall is 12 feet.
By placing the Calingula
these accumulations of
sand & silt &c are
near the Simurgh
aqueduct are prevented.
and a considerable
part also sand

This Calingula is
flat long.
The water which lodges
in the excavation for the
gate was got rid of
by means of Archimedian
Screws and the
usual device was
of balancing with cooked
bat shaped baskets.
A considerable saving
of labour and time
was effected by using
the screws. The
lime was procured
from 8 miles distant
and is of a good
hydraulic property.

The rate was about
10 Cut Stone mks.

10 Rupees —

For Brick work

3 1/2 Rupees

For Rubble work

4 Annas

Each per cubic yard
—————

The extent of Country
below the ancient which
may be irrigated by
the Godavery is about
1,000,000 acres.
There are about 7,00,000

or rather are irrigated
 at the present time.
 The remaining 300 000
 have not yet been
 irrigated yet. But
 there is sufficient command
 of water for the purpose
 The amount of water
 which is calculated
 for each acre is
 1 Cubic fad. —

The slopes, midlms and
 depths of the delta
 canals are marked
 in a tabular form
 which is appended.
 Also the quantities of
 water the canals
 are capable of supplying

The assessments in the Assessment and Cultivation
 divisions of the
 are average of about
 Rs 5 2 2. per acre
 They have not been
 made in all the
 talukas yet.

Kurnool	} Rs as per	5 8 3
and Sungur		
Tundi	} 4 14 3	5 5 5
and Tundi		
Tundi	4 11 5	

The assessment
 Cultivation Census
 given with any de-
 of accuracy but
 it may be estimated
 about 3 Puses per
 acre.
 A tabular statement
 appended will show
 the percentage, etc.
 1/2 --- on Capital
 Appended —

P. H. Thompson
 Mr. In charge the Engineer

P W 1863 Dept

No. 2263.

From Lieut. R. B. Thompson
Royal Engineering

Dated

Received 1st July/63.

Chief



Report on the
Irrigation Works &c
in the Godaverry District.

No. 7
Logged

22 July/63
Chapman