

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Public Works DEPARTMENT

G.O. No.	2123	Press
B.P. No.		Mis.
418-419-		
Dated	25-8-	1873

Not to be folded or roughly handled

1 d

4

*Proceedings of the Madras Government, Public Works Department,
25th August 1873.*

No. 418. Read the following letter from Captain H. M. VIBART, R.E., District Engineer, Bangalore, to Colonel G. W. WALKER, R.E., Chief Engineer, Public Works Department, dated Bangalore, 25th July 1873, No. 124:—

WITH reference to G. O., No. 155, dated 23rd July 1873, I have the honour to inform you that the G. O., No. 153, of 19th November 1872, has been complied with—*vide* my letter to the Superintending Engineer, 5th Division, No. 862, dated 28th November 1872.

2. A copy of the reply is herein annexed for your information.

From Captain H. M. VIBART, R.E., Executive Engineer, Bangalore, to the Superintending Engineer, 5th Division, dated Bangalore, 28th November 1872, No. 862.

WITH reference to your No. 161, dated 25th November 1872, I have the honour to inform you that in the annual Return of buildings at Bangalore it is stated that the date of erection of the Recreation-room is "unknown," and as the records on this point extend as far back as 1823, I presume that the Recreation-room is at least 50 years old. It is of course impossible and useless to state who were the Officers and Subordinates in charge of the work.

2. The Recreation-room has a coupled roof (junglewood) supported on masonry and wooden pillars and bressummers. On north and south sides there are enclosed verandahs with terraced roofs; adjoining this on the west side is the old skittle alley which has a coupled roof, also supported on pillars and bressummers. The side walls are very low with arched openings.

3. A plan is enclosed showing the arrangements of the building. The east wall is considerably cracked, but the necessity of unroofing the building is caused by the timber of the roof being in a decayed state from dry rot and whiteants.

No. 419. ORDER THEREON, 25th August 1873, No. 2,123.

ESTABLISHMENT, No. 29.

UNDER the circumstances explained in the letter to the late Superintending Engineer of the 5th Division the order may be omitted from future lists.

(True Extract.)

Colonel, R.E.,
Secretary to Government.

To the District Engineer, Bangalore.

Exd. T. O'Connor.
Spare Copies.

No. 124

DISTRICT ENGINEER'S OFFICE

Bangalore 25 July 1873.

From

The District Engineer,

Bangalore

To

The Chief Engineer

Public Works Department

Madras

SIR

With reference to G.O. No. 155
dated 23rd July 1873, I have the honour
to inform you that the G.O. No. 153, of
19th November 1872, has been complied
with, vide my letter to the Superintendent
of Submitted Engineers, 5th Division, No. 862, dated
28th Nov/72.

A copy of the reply is herein
annexed for your information.

I have the honour to be

Sir,
Your most Obedt. Servant.

Henry Stewart
Capt. R.E.
District Engineer, Bangalore

h^e 862.

Executive Engineer's Office.
Bangalore 28th Nov 1872.

From

The Executive Engineer
Bangalore

To

The Superintending Engineer
5th Division

Sir,

With reference to your h^e 161 dated 25th Nov 1872, I have the honour to inform you that in the Annual return of buildings at Bangalore, it is stated that the ^{date of} erection of the Recreation room is "unknown", and as the record on this point extend as far back as 1823, I presume that the Recreation room is at least 50 years old. It is of course impossible, and useless, to state who were the Officers and Subordinates in charge of the work.

The Recreation room has a cupped roof (lumpwood) supported on masonry and wooden pillars & brass summers. On north and south sides there are

enclosed

enclosed verandah with terraced ~~passage~~; adjoining this on the west side is the old ~~at the~~ ^{the} ~~alloy~~ ^{which} has a cupped roof, also supported on pillars and brass summers. The side walls are very low with arched openings.

A plan is enclosed showing the arrangements of the building. The East wall is considerably cracked, but the necessity of unroofing the building is caused by the sickness of the roof being in a decayed state from dry rot and white ants.

I have &c.

Signed H. L. Vibart Captain R.E.
Executive Engineer, Bangalore

True Copy

H. L. Vibart
Captain R.E.
District Engineer, Bangalore

Sept 24/94
 Dept. of MS733
 PUBLIC WORKS.

To The District Engineer
 San Francisco
 10 May 1895

Dated
 Recd.

a. o. 25th Aug 1893, 2123

Nos. 4187/119

Unanvowed Notice
 Permission granted
 for the omission of 80
 Nos. 153 date of 19th Nov
 1872 from future lists

P. M. 1894³ Defiant.

James No. 4194.

The Small Commission

To the Chief Engineer

P. M. 1894³ Defiant.

Date of 25th Aug 1893

Recd. 26th Nov

James No. 4194.

has been confirmed

with order

No. 2123

Under the circumstances explained in
 the letter to the late Superintendent Engineer of the
 5th & 6th Divisions the order may be omitted from future
 letters

JMM

To the District Engineer (San Francisco)
 10. and 20/9/73

10/11/13-11/13/13
 10/11/13-11/13/13