

*Proceedings of the Madras Government, Public Works Department,
8th April 1875.*

Read the following:—

No. 300.

No. 155:

Note by the Chief Engineer for Irrigation.

THE following estimate has been submitted by the District Engineer, South Arcot:—

Repairing the Vyllore small tank	...	...	...	...	Rupees 740.
Ayacut area	...	...	...	...	Acres 50.
„ assessment	...	...	...	...	Rupees 396.
Average revenue	...	...	...	...	„ 345.

The discharge of surplus is at present, and is intended to be for the future, over hard ground at the south-east end of the bund. It is stated that the tank has never breached, and that provision of a regular waste weir is unnecessary. The area of the drainage basin, and the length of ground over which discharge can take place with water at the maximum intended height of $1\frac{1}{2}$ feet above F. T. L., should have been reported.

2.. The rate, 6 Pies a square yard, for removing prickly-pear is unusually high.

CAMP, KISTNAPATAM,

(Signed) JOHN MULLINS, Lieut.-Colonel, R.E.,

17th March 1875.

Chief Engineer for Irrigation.

No. 156.

ORDER THEREON, 8th April 1875, No. 927.

IRRIGATION, No. 17.

THE following estimate is sanctioned:—

Repairing the Vyllore small tank, in the South Arcot District, Rupees 740.

(True Extract.)

Colonel, R.E.,

Secretary to Government.

To the District Engineer, South Arcot.

„ Chief Engineer for Irrigation.

„ Controller of Public Works Accounts.

Exl. S. T. Austin.

Spare Copies

No. 300.

Note by the Chief Engineer for Irrigation

The following estimate has been submitted by the District Engineer South Arcot.

Repairing the Vyfore small tank Rupees 740.

Ayacut area — acres 50.

— Assessment Rupees 396.

Average revenue — 345.

The discharge of surplus is at present, and is intended to be for the future, over hard ground at the South East end of the bund. It is stated that the tank has never breached and that provision of a regular waste weir is unnecessary. The area of the drainage basin, and the length of ground over which discharge can take place with water at the maximum intended height of $1\frac{1}{2}$ feet above F.T.L., should have been reported.

The rate 6 pias a square yard for removing prickly pear is unusually high.

at
Napalain
Feb 1875

W. L. Williams
To the Secretary to Government
P. W. D.
Chief Eng. for Irrigation

1923-3-75

302

12/53

C. N. 1875
No 300 No. 1927.

From the Chief Engineer to the Secretary & Government

Dated 17/3/75
Received 18/3/75

Submits for sanction
estimate of Rs. 7400/- for
repairs to the Vyllore small
tank South Arcot District

C. N. No. 927-84/75

The following estimate is sanctioned...

Repairing the Vyllore small tank, in the South Arcot District, Rupees 740.

17/3/75

[Signature]

1/1

John P. H. Depts

Proceedings of the Madras Government
Read the following.

From the Chief Engineer for Irrigation (A. E. No 300 of 17 March 75)

927

The following estimate is sanctioned...

Repairing the Vyllore small tank, in the South Arcot District, Rupees 740.

[Signature]

To The District Engineer South Arcot
- Chief Engineer for Irrigation ✓ with 2. Encls -
- Controller of P.W. Accounts. ✓

Dated - 9-4-75

[Signature]

1927
Govt. of Madras.

PUBLIC WORKS.

To

Int Engineer
South Arcot.

Dated

Recd.

Encl.

G. O. *8 April* 1875, No. *927*

No. *155-156*.

Tylore small Tank,

South Arcot Dist. Estimate

for repair of the tank,
sanctioned.