

No 177 of the ...
Sanctioned.

From

THE SUPERINTENDING ENGINEER,
5TH CIRCLE,

To

The ...
The ...

Dated

17/11/1883.

Recd

ENCLOSURES.

To ...

No 3520

Building ...
...
...
...

...
...
...
...

...
...

its shells under the surface was
the material of the building
will stand by which about 100
p. 150.

When the house is built
the
contract is signed.

the house is not built
(1)

the house is not built
(1)

No. 3520.

SUPERINTENDING ENGINEER'S OFFICE,

5TH CIRCLE, MADRAS,

Chepauk, 12 January 1883.

From

THE SUPERINTENDING ENGINEER,

5TH CIRCLE,

To

THE

Chief Engineer
P. W. D.

SIR,

Enclosures.

I have the honor to report
that on the land acquired
for the Buckingham Canal
Division, by G. O. No. 3024 of
dated 5th December 1881, there
is a building which is much
dilapidated, and unfit for
any use. The Building is
not required for Canal pur-
poses, and I recommend
that sanction be given for
its