

16-8-07✓

10/10/25

From

THE SUPERINTENDING ENGINEER,

5TH CIRCUIT,

No 3107 Way 2nd Nov 83

*The defence of the
suit is sanctioned.*

To

*THE Chief Engineer
P. W. D.*

Dated *23rd*

October 1883

Recd *24*

*Cy.
25/10*

*2C.
15.17.2W 30-7-83-
1577W. 7-7-83.*

ENCLOSURES /

No 3107 Way 2-11-83

No 2650

*Suit against the Exe.
Engineer Chingleput Dist.
Requesting that sanction
may be given to the defence
at the Govt. expense of a-
by Contractor Moonusawmy
Moos.*

*See
24
S.E. Fifth Circle
Examiner P.W.D. ✓*

*ALL 35/10. 11/10
15/10. 27/10. 29/10.*

*With order
Sub. Recd. Dept.*

said to be due on account of
work done at the Tanuara
paukum Amcut.

A Translation of the Plaint
with a draft of the proposed
defence is enclosed.

I have the honor to be
Yours Most Obedt Servt
Chas Sanderast Coll R. G.
Superintending Engineer
5th Circle.

No 2650

SUPERINTENDING ENGINEER'S OFFICE,

5TH CIRCLE, MADRAS,

Chepauk, 23^d October 1883.

From

THE SUPERINTENDING ENGINEER,

5TH CIRCLE,

To

THE

Chief Engineer
P. & D.

SIR,

Enclosures

I have the honor to re-
-quest that sanction may
be given to the defence of
the Government expense of a
suit filed by Contractor of
Moonisawmy Mood^y in the
Court of the District Moon-
-siff of Trivellore against
the Executive Engineer
Chingleput Division for
the recovery of Rs 921-6-5

Said

0. 2/ 257 13

Translation of Hamt Proposed Draft Defense

On the 15th of July 1881, Mr. J. W. Taylor (in what manner cannot be ascertained) to them in charge of the Sub. Allocated, Allocated in Division, gave the July 1881 by the Sub. Div. Plumber, on Contract, - about 6 Officer Sub. Conductor the execution of work. Taylor According to the work was for last certificate, signed upon. Estimated by Mr. Taylor the whole was 1355 for the work done by the Con. San Francisco Hamt - Contractor, amounted to 1 furnished him with 4258 1/2 of concrete Specification. Valued at \$638-11-2

2 While the work was being pushed out towards completion (25 July 1881) from whom it is now not known) that less than was used than the stipulated quantity, and on the 15th some portion of the concrete was powdered as bad. There was fresh on the 19th 1881 which caused damage to the concrete. The Chief Engineer for Irrigation Subsequently condemned the work

Superintendent of Genl. & Civil
23^d October 1883