

- (1) பக்கங்களின் எண்ணிக்கை 8-
 (2) புதுக்கித் திருப்பிய நாள் 6.9.90
 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம் 1000

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

(77)

P-W-D துறை

அரசாணை எண்.	1000	அச்சகம்
மு. கோப்புத் தாள் எண்.		பலவகை
நாள் :	9-4-1891	198

மடிக்கவேண்டிய கையாளவோ கூடாது

4 Sheets

ஆவணக் கா-1-18,006-15-6-87.

1000
1

9TH APRIL 1891, No. 1000 W., PUBLIC WORKS.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads,
Civil Works.

Read—the following paper :—

G.O., dated 2nd April 1891, No. 2119, Revenue.

Read—the following Proceedings of the Board of Revenue (Land Revenue), dated 7th March 1891, Mis. No. 1529 :—

Read—the following letter from the Collector of Kistna, dated 5th February 1891, Extra No. 8 :—

I have the honor to request the sanction of the Board and Government for the erection of a new taluk cutcherry at Bápatla.

2. Various endeavours have been made to patch up the old building, but without success. Last year the Executive Engineer was requested to estimate for the improvement of the treasury, a room 12' 6" × 10', which, contrary to the rules for safety, has a window in the outer wall, and also to issue the usual certificate as to the safety of the place. The Executive Engineer (copy of letter, No. 278, dated 3rd July 1890, enclosed) declined to give any certificate and said that the walls were so soft that he could bore into them with a pencil, that the iron bars were too thin, and that, in short, it was impossible to alter the treasury so as to make it safe. He remarked that a new cutcherry was "very badly required" and that the treasury could be used in the interim on an old certificate given by a predecessor of his—the date not given.

3. I then requested the Superintending Engineer to let me have a report on the general condition of the building as I was aware the roof was in an unsound condition. Mr. Hannan has forwarded the Executive Engineer's report No. 398, dated 13th November 1890 (copy with enclosure forwarded). It will be seen that the building generally is too dilapidated to be repaired. The rafters and the reapers are of palmyras, or of split bamboo, all more or less rotten; the roof leaks; the tiles threaten to fall; and some of the walls are cracked from top to bottom.

4. The only sound buildings are the prison wards and out-houses, the materials of which could be used again.

5. The site of the present building is quite insufficient and a new one must be selected. There will be no difficulty about this, but I will inspect the spot again before a final decision is made.

Resolution—dated 7th March 1891, Mis. No. 1529.

Submitted to Government with the recommendation that sanction be accorded for the construction of a new taluk cutcherry at Bápatla according to the standard design now under revision.

2. The Collector should report how he proposes to dispose of the present building and site when vacated.

Order—dated 2nd April 1891, No. 2119, Revenue.

The construction of a new taluk cutcherry at Bápatla is sanctioned.

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of {1891} Madras.
PUBLIC WORKS.

Dated April, 9th

Recd.

Encl.

G.O., 9th April 1891, No. 1000 W.

APRIL.

Taluk Cutcherry at Bapatla,
Kistna District

The Superintending Engineer, II Circle,
directed to submit an estimate for building
a new —,

REVENUE DEPARTMENT.

1000
3

G.O. dated 2nd April 1891, 2119

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read The following Proceeding

of the Board of Revenue (Land Revenue)
dated 7th March 1891 A: 1529 in the
following letter from the Collector of Kistna
dated 5th February 1891 A: Extra 428/22-41

I have the honor to request the
sanction of the Board, and Government
for the erection of a new Taluk Cutcherry at
Bapatla.

2. Various endeavours have been
made to patch up the old building but with-
out success. Last year the Executive Engineer
was requested to estimate for the improvement
of the Treasury, a room 12'6" x 10' which contrary
to the rules for safety has a window in the outer
wall; and also to issue the usual certificate as
to the safety of the place. The Executive
Engineer (copy of letter 278 dated 3rd July 1890
enclosed) declined to give any certificate
and said that the walls were so soft that
he could bore into them with a pencil, that
the iron bars were too thin and that in
short it was impossible to alter the Treasury
so as to make it safe. He remarked that a
new Cutcherry was "very badly required" and
that the Treasury could be used in the interior
on.

on an old certificate given by a predecessor of his, — the date not given.

3. I then requested the Superintending Engineer to let me have a report on the general condition of the building as I was aware the roof was in an unsound condition. Mr. Hannan has forwarded the Executive Engineer's report No. 398 dated 13th November 1890 (copy with enclosure forwarded). It will be seen that the building generally is too dilapidated to be repaired. The rafters and the reapers are of palm-pas or of split bamboo all more or less rotten, the roof leaks, the tiles threaten to fall, and some of the walls are cracked from top to bottom.

4. The only sound buildings are the prison wards and out houses, the materials of which could be used again.

5. The site of the present building is quite insufficient and a new one must be selected. There will be no difficulty about this, but I will inspect the spot again before a final decision is made.

Resolution

Submitted to Government with the recommendation that sanction be accorded for the construction of a new Taluk Catchery at Bapatla according to the standard design now under revision.

1000 20
4

2. The Collector should report how he proposes to dispose of the present building and site when vacated.

Order thereon 2nd April 1891 No. 2119

The construction of a new Taluk Catchery at Bapatla is sanctioned.

2. Orders will issue in the Public Works Department for the preparation of the necessary plans and estimates.
/ True extract /

Secretary to Government

La

The Comr. of L.R.

with the Collr's letter & enclosures

P.W. Dept.

with copy of the Collr's letter
& 188 in full.

1891

P.W. CN^o 3958

Rec^d at 0046 W. 91

9-4-91

A 30

B.R.
Civil Works

No 1000 W 4/9 April 1891

Communicated to
the Supty. Engineer II
circle who will ~~submit~~
on receipt of the revised type
design ~~submit~~ ^{submit} an estimate of
building a new Daling
Cutcherry at Bapadla.

1003
9-4-91

SLD

1003
9/11

S.E. II circle ✓ 9/14
Rev. Sept ✓ 17/14
Rev. Sept

(4)

1003 W
u. 7.11.91