

Gobt. of 1894 Madras.
REVENUE.

To
The Public Works
Department.

Dated
Recd. 17-12-94 Encl.

Mis. G.O., 12 Dec 1894 No. 4894.

SUBJECT.

According sanction to the
Construction of a new Taluk
Cutcherry at Karur, Coim-
batore Dist and requesting
the P. W. Dept^{ts} to issue
orders for the preparation
of the necessary plans &
estimates.

With order.

Le 3253 to dy 18 Dec 94
Communicated to the
Suptg. Engineer to Circle
for the preparation of the
required estimates.

17/12/94

17/12/94

S. E. to Circle
N.S.

DESPATCHED
18 DEC. 94

INDEXED

J.C.C.
24/12

T.A.
C.B.

4. The new Katcheri is estimated to cost about Rupees (29,000) Twenty-nine thousands. I have, therefore, the honor to request that sanction of Government may be obtained for the early construction of a new Taluk Katcheri.

Resolution.

Submitted to Government with the request that sanction be accorded for the construction of a Taluk cutcherry at Karur according to the revised standard design.

Order thereon, 12th Dec^r 1894, N^o 4894 His.

The Construction of a new Taluk cutcherry at Karur is sanctioned.

2. Orders will issue in the Public Works Department for the preparation of the necessary plans and estimates.

(True Extract)

W. H. Wilson
Secretary to Government.

To

The Board of Revenue (L.R.) with 4 encls.
P.W. Dept. W.H.
14.12.94
returned

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following Proceedings

of the Board of Revenue, Land Revenue, dated 24th November 1894, N^o 6475 Mis. on the following letter from the Collector of Coimbatore, dated 16th November 1894, Ref. on N^o 1976 Mis.

I have the honor to report that the Taluk Katcheri at Karur is an old building totally unfit for the purpose for which it is now used. It is reported that it was built in 1860 for a choultry and is now in very bad repairs. It is reported to be in very bad order and not to give accommodation for the establishment, and is deficient both as to light and ventilation. It is stated that 30 per cent of the rafters and 75 per cent of the reefers are rotten.

2. The outer roof of the Treasury has partially collapsed and it is stated that it leaks terribly. To execute further repairs will be very expensive and the Executive Engineer considers that the sooner a new building is erected the better.

3. A new standard building is most necessary. A ground plan of the existing building and a tracing of the proposed site for a new Katcheri are also submitted herewith.

3. The