

ORDINARY, PRINTED.

Public DEPARTMENT.
G.O., DATED 29-11-92
No. 827

INDEXED.

First copy sent to Press. 29-11-92

Returned for signature. 2-12-92

Despatched in print. 3/12

[Despatch Abstract.]

Archaeology:

Paying orders on the
inspection report of the
Super-Archaeological Sur-
vey Madras on certain
buildings in the And-
rapur & Bellary districts
suggested for preservation.

BACK PAPER, No.

4/3/93 11/83

OF 11

READ AGAIN ORDER OF GOVERNMENT, DATED
18 No.

FURTHER PAPER, No.

597 = reply to

OF 11

1st sentence of para 2 of 10

ENCLOSURES.

CURRENT No.

2960 (Oval) - a

STATEMENT WITH DICTO.

ORDER, &c., OF GOVERNMENT—A.

PAPERS KEPT OUT OF FILE FOR DESPATCH IN ORIGINAL
(not paged.)

NUMBER OF COPIES
REQUIRED.

Order complete. 100.
Letter only.
Order complete with Letter.

N.B.—

A = Print in full.
B = Not to be printed.
P = Print abstract only.
Q = Print heading only.
R = Print, but not for monthly volume.

Govt. of. {1892} Madras.
PUBLIC.

Issued

Recd.

Encl.

G.O., 29th November 1892, No. 827.

NOVEMBER.

Archæology.

Passing orders on the inspection report of the
Superintendent, Archæological Survey, Madras, on
certain buildings in the Cuddapah and Bellary
districts suggested for conservation.

Ananta Raja in the year 1303. It was afterwards taken by the Muhammadans, and under the Nizam's dynasty became the residence of the Patan Nâvab. A very considerable temple of great sanctity then existed on the spot, and the Muhammadans incorporated it in their re-building of portions of the fort. The ingenious way in which the extensive and finely-carved pillared mandapams of the temple were retained and added to and made to serve the purpose of spacious entrance halls inside the fort gateways forms one of the most interesting features of the place. Curiously, none of the numerous sculptural representations on the columns were defaced, and the idols were not destroyed, but handed over to the Hindus, who erected temples over them in the town. The fort is an interesting one in fair preservation, and occupies a fine position on the banks of the Pennâr river. It is constructed of stone and brickwork, and is rectangular in form, with bastions on the faces and angles. The walls are overgrown with plants and partly cracked in places. The enclosure is partly cultivated, and is much overgrown with rank vegetation. Some Muhammadan buildings, including a mosque, and tomb with some good stucco panels, stand inside. In the interior, near the south-east angle, is a large slab nearly six feet square, inscribed in Telugu.

6. The portions which should be preserved are the Hindu mandapams at the west and east entrances. They are fine examples of the floriated Vijayanagar style, and contain numerous examples of good carved work. They are much overgrown with vegetation, which requires removal.

7. The cave temple at Basarakôdu, in the Adôni taluk of the Bellary district (Lists, p. 320).—A short distance south-east of the village, at the base of a rocky hill, is a natural cave of irregular shape. It is formed by one huge mass of rock lying on the top of another, with an opening between. Loose boulders form the sides of the cave. The height is sufficient for a man to stand upright, and the breadth and depth are not more than fifteen feet. Lying on some small boulders on the uneven rocky floor are five small oval stones, which are designated lingas. Among them are some broken earthen puja utensils.

The place is simply a natural cavern, without rock cutting or built walls of any sort; the only marks that show the place to be a species of temple are the vertical red and white streaks of colour on the side boulders.

Puja is performed once a year on the first of the month of Chittrai, when an image of Anjaneya is brought here from a small temple in the village. If there should have been drought before, the proceedings are invariably followed by rain.

A few bushes grow in front, which the people wish removed to form a pathway to the cave. The villagers subscribe the expenses of the puja, and as they wish the bushes cleared away, they might easily pay a cooly for a day to do so. The place is undeserving of any expenditure from conservation funds.

ORDER—dated 29th November 1892, No. 827, Public.

The Government is of opinion that the Sômpalle temple should not be added to the existing list nor should any expenditure be incurred on its conservation. It is understood that the temple is still in use.

2. An estimate for removing the vegetation referred to in paragraph 6 should be furnished. The matter mentioned in paragraph 4 is one for the local authorities. No orders on paragraph 7 are called for.

(True Extract.)

To the Superintendent, Archæological Survey,
 „ Public Works Department.
 „ Collector of Cuddapah.
 „ Collector of Bellary.

Exd. A. Raitt.

Chief Secretary,

GOVERNMENT OF MADRAS.

PUBLIC DEPARTMENT.

READ—the following paper :—

From A. REA, Esq., M.R.A.S., Superintendent, Archaeological Survey, Madras, to the Chief Secretary to Government, dated Bangalore, 27th October 1892, No. 393.

I have the honour to submit a report on my inspection of the undernoted buildings suggested for conservation by district officers.

2. The old sculptured Vishnu temple at Sômpalle, in the Madanapalle taluk of the Cuddapah district (Lists, p. 133).—The temple is built in the floriated Vijayanagar style. It is a comparatively small building enclosed in a single court. The shrine and court walls are constructed of plain stone masonry, with ornamental brick niches on the wall heads. Though the building, as a whole, is not unusual, there are some portions of it which are unique and well worthy of conservation. These are a beautifully-carved four-pillared Kalyana mandapam, a similarly-carved ratha in front, and an unusually lofty and well-carved monolithic dipdân or lamp pillar which stands outside the front. The temple is much in need of repairs, but only those which are necessary to the preservation of the three portions mentioned need be carried out from conservation funds. These are comprised in the undernoted sections (a), (b), (c) and (h). The temple is said to have an annual income of only Rs. 45, so nothing can be done in the way of repairs from this source.

3. The following are the repairs which the building stands in need of :—

- (a) A column in the Kalyana mandapam is out of plumb and the bracket over the capital is coming off.
- (b) The back and side walls of the Kalyana mandapam have been constructed of outer and inner ashlar faces with packing between. Only the inner facing remains, and as the stones are large, comparatively thin and stand on edge, the whole mass of masonry is on the point of falling out.
- (c) The top of the inner wall of the madapalle or cooking-room has fallen.
- (d) The inner architrave of the entrance gopuram is dangerous, and masses of bricks fall down after rain.
- (e) The front epistylum of the Mukkha mandapam is broken. One end has dropped down, and is resting on the top of the finely-carved stone ratha.
- (f) The inner south wall head of the front wall is out of repair.
- (g) Plants are growing on the roofs of the main and amman shrines.
- (h) The roof of the finely-carved blackstone Kalyana mandapam is leaking.
- (i) The painted stone ceiling of the main front or Mukka mandapam is being spoiled by leaks.
- (j) The walls of the Pedda Nayadi mandapam are constructed in the same manner as the Kalyana mandapam (section b). The outer faces of the side walls are gone, and the inner faces are falling out.
- (k) The finely-carved dipdân requires no repairs.
- (l) The brick and plaster work is ruined, and the temple authorities wish it repaired; but this and other repairs not essential to the stability of the building should not be carried out from the conservation grant.

4. On a mound by the roadside in front of the above temple is a small stone shrine of Hanumân. It comprises a cell and pillared porch. The pillars of the porch lean over towards the road, and are likely to fall. The condition of the porch led to the stoppage of puja; and as it constitutes a danger to the passers on the road, it should either be propped up or pulled down.

5. The ancient fort at the taluk head-quarters of Siddhavatam (Sidhout) in the Cuddapah district (Lists, p. 130).—It is said to have been founded by a relative of

Public Dept.

Order 29 Nov 92 No 827

The Govt. is of opinion that the Sompalle temple should not be added to the existing list nor should any expenditure be incurred on its conservation. It is understood that the temple is still in use.

2. An estimate for removing the vegetation referred to in para 6 should be furnished. The matter mentioned in para 4 is one for the local authorities. No orders on para 7 are called for.

/ from orders /

27 Nov

Supdt: Arch Survey. 6

30.11.

24/11

P. W. Dept.

The Commr. of Buddapalle
of Bellary.

disps
31/12/92

Arche. Survey.

Govt. of Madras.

Pub 827-25-

C.21/11
R.24/11

The printed current
attached.

Para: 2 & 3. Orders are
requested whether the
P. W. D. may be asked for
an estimate for repairing
those portions which Mr
Rea considers "unique
and well worthy of con-
servation". He should
however be reminded that
it is not intended to conserve
several specimens of the
same particular style.

Para: 4. This seems to
be a matter for the local
authorities.

Para 6. No estimate is
furnished of the cost of
removing the vegetation.
May one be called for?

Para 7. No orders seem
necessary.

It is submitted that
because a few rupees
are sanctioned for minor
repairs it does not neces-
sarily follow that the
particular building should
be added to the list of
those selected for conservation.

25.B. 18/11.

4. On a mound by the roadside in front of the above temple is a small stone shrine of Hanumān. It comprises a cell and pillared porch. The pillars of the porch lean over towards the road, and are likely to fall. The condition of the porch led to the stoppage of puja; and as it constitutes a danger to the passers on the road, it should either be propped up or pulled down.

5. The ancient fort at the taluk head-quarters of Siddhavatam (Sidhout) in the Cuddapah district (Lists, p. 130).—It is said to have been founded by a relative of Ananta Raja in the year 1303. It was afterwards taken by the Muhammadans, and under the Nizam's dynasty became the residence of the Patan Nāvab. A very considerable temple of great sanctity then existed on the spot, and the Muhammadans incorporated it in their re-building of portions of the fort. The ingenious way in which the extensive and finely-carved pillared mandapams of the temple were retained and added to and made to serve the purpose of spacious entrance halls inside the fort gateways forms one of the most interesting features of the place. Curiously, none of the numerous sculptural representations on the columns were defaced, and the idols were not destroyed, but handed over to the Hindus, who erected temples over them in the town. The fort is an interesting one in fair preservation, and occupies a fine position on the banks of the Pennār river. It is constructed of stone and brickwork, and is rectangular in form, with bastions on the faces and angles. The walls are overgrown with plants and partly cracked in places. The enclosure is partly cultivated, and is much overgrown with rank vegetation. Some Muhammadan buildings, including a mosque, and tomb with some good stucco panels, stand inside. In the interior, near the south-east angle, is a large slab nearly six feet square, inscribed in Telugu.

6. The portions which should be preserved are the Hindu mandapams at the west and east entrances. They are fine examples of the floriated Vijayanagar style, and contain numerous examples of good carved work. They are much overgrown with vegetation, which requires removal.

7. The cave temple at Basarakōdu, in the Adōni taluk of the Bellary district (Lists, p. 320).—A short distance south-east of the village, at the base of a rocky hill, is a natural cave of irregular shape. It is formed by one huge mass of rock lying on the top of another, with an opening between. Loose boulders form the sides of the cave. The height is sufficient for a man to stand upright, and the breadth and depth are not more than fifteen feet. Lying on some small boulders on the uneven rocky floor are five small oval stones, which are designated lingas. Among them are some broken earthen puja utensils.

The place is simply a natural cavern, without rock cutting or built walls of any sort; the only marks that show the place to be a species of temple are the vertical red and white streaks of colour on the side boulders.

Puja is performed once a year on the first of the month of Chittrai, when an image of Anjaneya is brought here from a small temple in the village. If there should have been drought before, the proceedings are invariably followed by rain.

A few bushes grow in front, which the people wish removed to form a pathway to the cave. The villagers subscribe the expenses of the puja, and as they wish the bushes cleared away, they might easily pay a cooly for a day to do so. The place is undeserving of any expenditure from conservation funds.

GOVERNMENT OF MADRAS.

PUBLIC DEPARTMENT.

READ—the following paper :—

From A. REA, Esq., M.R.A.S., Superintendent, Archaeological Survey, Madras, to the Chief Secretary to Government, dated Bangalore, 27th October 1892, No. 393.

I have the honour to submit a report on my inspection of the undernoted buildings suggested for conservation by district officers.

2. The old sculptured Vishnu temple at Sômpalle, in the Madanapalle taluk of the Cuddapah district (Lists, p. 133).—The temple is built in the floriated Vijayanagar style. It is a comparatively small building enclosed in a single court. The shrine and court walls are constructed of plain stone masonry, with ornamental brick niches on the wall heads. Though the building, as a whole, is not unusual, there are some portions of it which are unique and well worthy of conservation. These are a beautifully-carved four-pillared Kalyana mandapam, a similarly-carved ratha in front, and an unusually lofty and well-carved monolithic dipdân or lamp pillar which stands outside the front. The temple is much in need of repairs, but only those which are necessary to the preservation of the three portions mentioned need be carried out from conservation funds. These are comprised in the undernoted sections (a), (b), (c) and (h). The temple is said to have an annual income of only Rs. 45, so nothing can be done in the way of repairs from this source.

3. The following are the repairs which the building stands in need of :—

(a) A column in the Kalyana mandapam is out of plumb and the bracket over the capital is coming off.

(b) The back and side walls of the Kalyana mandapam have been constructed of outer and inner ashlar faces with packing between. Only the inner facing remains, and as the stones are large, comparatively thin and stand on edge, the whole mass of masonry is on the point of falling out.

(c) The top of the inner wall of the madapalle or cooking-room has fallen.

(d) The inner architrave of the entrance gopuram is dangerous, and masses of bricks fall down after rain.

(e) The front epistylum of the Mukkha mandapam is broken. One end has dropped down, and is resting on the top of the finely-carved stone ratha.

(f) The inner south wall head of the front wall is out of repair.

(g) Plants are growing on the roofs of the main and amman shrines.

(h) The roof of the finely-carved blackstone Kalyana mandapam is leaking.

(i) The painted stone ceiling of the main front or Mukka mandapam is being spoiled by leaks.

(j) The walls of the Pedda Nayadi mandapam are constructed in the same manner as the Kalyana mandapam (section b). The outer faces of the side walls are gone, and the inner faces are falling out.

(k) The finely-carved dipdân requires no repairs.

(l) The brick and plaster work is ruined, and the temple authorities wish it repaired; but this and other repairs not essential to the stability of the building should not be carried out from the conservation grant.

Native (1892) Sept
CURRENT NO. 2960

From

The Superintendent
Archaeological Survey
Madras

To

The Chief Secretary
to the Government of
Fort Saint George

Dated 27th
Despatched 28th } October 1892.
Received 31st

No 393

Enclosure. Nil.

Ref No 827-23-11-92

Subject

Submits report on
inspection of buildings in
the Cuddapah and Bellary
districts suggested for con-
servation by district officers.

7
on the first of the month of Chittirai⁴ when
an image of Anjaneya is brought here
from a small temple in the village. If
there should have been drought before,
the proceedings are invariably followed
by rain.

A few bushes grow in front, which
the people wish removed, to form a path-
way to the cave. The villagers subscribe
the expenses of the pūja, and as they wish
the bushes cleared away, they might
easily pay a cooly for a day to do so.
The place is undeserving of any ex-
penditure from conservation funds.

I have the honour to be,

Sir,

Your most obedient servant,


Superintendent

6.
at the west and east entrances. They are
fine examples of the floriated Vijayanagar
style, and contain numerous examples of
good carved work. They are much over-
grown with vegetation, which requires
removal.

7- The cave temple at Basarakōdu
in the Adoni taluk of the Bellary dis-
trict (List p. 320.). A short distance
south-east of the village, at the base
of a rocky hill is a natural cave of
irregular shape. It is formed by one
huge mass of rock lying on the top of
another, with an opening between. Loose
boulders form the sides of the
cave. The height is sufficient for a man
to stand upright, and the breadth
and depth are not more than fif-
teen feet. Lying on some small boul-
ders on the uneven rocky floor, are
five small oval stones, which are des-
ignated lingas. Among them are some
broken earthen pūja utensils.

The place is simply a natural
cavern, without rock cutting or built
walls of any sort; the only marks that
shew the place to be a species of temple, are
the vertical red and white streaks of
colour on the side boulders.

Pūja is performed once a year on
the

The ingenious way in which the extensive and finely carved pillared mandapams of the temple ~~were~~ ^{were} retained, and added to, and made to serve the purpose of spacious entrance halls inside the fort gateway, forms one of the most interesting features of the place. Curiously, none of the numerous sculptural representations on the columns were defaced, and the idols were not destroyed, but handed over to the Hindus, who erected temples over them in the town. The fort is an interesting one in fair preservation, and occupies a fine position on the banks of the Pennâr river. It is constructed of stone and brickwork, and is rectangular in form, with bastions on the faces and angles. The walls are overgrown with plants, and partly cracked in places. The enclosure is partly cultivated, and is much overgrown with rank vegetation. Some Muhammadan buildings, including a mosque, and tomb with some good stucco panels, stand inside. In the interior, near the south-east angle, is a large slab nearly six feet square, inscribed in Telugu.

6- The portions which should be preserved are the Hindu Mandapams at

4- On a mound by the roadside in front of the above temple is a small stone shrine of Hanumân. It comprises a cell and pillared porch. The pillars of the porch lean over towards the road, and are likely to fall. The condition of the porch led to the stoppage of pûja; and as it constitutes a danger to the passers on the road, it should either be propped up, or pulled down.

in

5- The ancient fort at the taluk headquarters of Siddhavatam (Sidhout) in the Cuddapah district. (List p. 130). It is said to have been founded by a relative of Ananta Râja in the year 1303. It was afterwards taken by the Muhammadans, and under the Nizam's dynasty became the residence of the Patan Navâb. A very considerable temple of great sanctity then existed on the spot, and the Muhammadans incorporated it in their rebuilding of portions of the fort. Curiously, none of the numerous sculptural representations on the columns were defaced, and the idols were not destroyed, but handed over to the Hindus, who erected temples over them in the town. The fort is an interesting

- (d) The inner architrave of the entrance gopu-
ram is dangerous, and masses of bricks
fall down after rain. 2 P
- (e) The front Epistylum of the Mukkha
mandapam is broken. One end has
dropped down, and is resting on
the top of the finely carved stone ratha.
- (f) The inner south wallhead of the front
wall is out of repair.
- (g) Plants are growing on the roofs of
the main and Amman shrines.
- (h) The roof of the finely carved blackstone
Kalyana mandapam is leaking.
- (i) The painted stone ceiling of the main
front or mukkha mandapam is
being spoiled by leaks.
- (j) The walls of the Pedda Nayadi man-
dapam are constructed in the same
manner as the Kalyana mandapam.
(Sec. b.) The outer faces of the side
walls are gone, and the inner faces
are falling out.
- (k) The finely carved dipdan requires
no repairs.
- (l) The brick and plaster work is ruin-
ed, and the temple authorities
wish it repaired; but this, and
other repairs not essential to
the stability of the building
should not be carried out from
the conservation grant.

and well worthy of conservation. These are
a beautifully carved four pillared kal-
yana mandapam, a similarly carved
ratha in front, and an unusually lofty
and well carved monolithic dipdan or
lamp pillar which stands outside the front.
The temple is much in need of repair, but
only those which are necessary to the pre-
servation of the three portions mentioned
need be carried out from conservation funds.
These are comprised in the undernoted sec-
tions a. b. e. and h. The temple is said
to have an annual income of only Rs 45,
so nothing can be done in the way of repairs
from this source.

3- The following are the repairs
which the building stands in need of—

- (a) A column in the Kalyana mandapam
is out of plumb and the bracket over the
capital is coming off.
- (b) The back and side walls of the Kalyana
mandapam have been constructed of
outer and inner ashlar faces with
packing between. Only the inner facing
remains, and as the stones are large, com-
paratively thin and stand on edge, the
whole mass of masonry is on the point
of falling out.
- (c) The top of the inner wall of the Madapalle
or cooking room has fallen.

Archaeological Survey, Madras.
Bangalore, 23rd October 1892.

CERTIFICATE NO. 2960

No 393.

1 p

Pat. No. 29608

From

A. Rea, Esquire, M. R. A. S.,

Superintendent,

Archaeological Survey, Madras.

To

The Chief Secretary
to the Government of
Fort Saint George.

Sir,

I have the honour to submit a report on
my inspection of the undernoted buildings,
suggested for conservation by district
officers.

2- The old sculptured Vishnu temple
at Sompalle in the Madanapalle taluk
of the Buddapah District (Listo p. 133.) The
temple is built in the floriated Vijayana-
gar style. It is a comparatively small
building enclosed in a single court. The
shrine and court walls are constructed
of plain stone masonry, with ornamental
brick niches on the wall heads. Though the
building as a whole, is not unusual, there
are some portions of it which are unique

and