

Public Works (1896) Department.

G.O., No. 1069 J.

DATED 8 December

[Despatch Abstract.]

Breaches: Report from S.E. to Cuth, of —
in the Sankaranian Koil and
Zinnevelly, Lakhs Consequent on the
Recent heavy rains, recorded.

==

90
14

T. 19/12

[1896-97-98]

INDEXED

18/12

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Irrigation.

Read—the following papers :—

From M.R.Ry. N. COMARASAWMY ACHARI, Supervisor, Tinnevely, to the Executive Engineer, Tinnevely Division, dated 21st November 1896, No. 690.

I beg to report that on account of recent heavy rains, some small breaches have occurred in the undermentioned tanks and channels in my section :—

Tinnevely Taluk.

- (1) Ninarkulam branch channel, near Tinnevely town, $40' \times 14' \times 5'$.
- (2) Tinnevely channel, west of Kupipakurichi supply sluice, 17 feet long 9 feet high.
- (3) Pillayarkulam tank.
- (4) Ponnakudiyan channel, east of Sirusengulam, $45' \times 5'$.

Sankaranayinarkóyil Taluk.

- (1) Marathoni Periyakulam supply channel, 84 feet long.
- (2) Do. tank, 75 feet long.
- (3) Do. tank, north of surplus weir, 30 feet long.
- (4) Achankulam tank, east of surplus weir, 18 feet long.
- (5) Do. supply channel, 12 feet long.
- (6) Periyur Periyakulam tank, $32' \times 12' \times 10'$.
- (7) Perumbuthur Periyakulam channel, $80' \times 15' \times 4\frac{1}{2}'$.
- (8) Do. $72' \times 15' \times 4'$.

I have arranged to put the ring bunds in front of the above breaches. Estimates with other informations will be submitted later on, as soon as water subsides.

No. 5050.

Copy forwarded to the Superintending Engineer, VI Circle, for information. It is a matter for regret that these breaches should have occurred at a time when the division is already starved for funds.

29th November 1896.

(Signed) A. JOYCE,
Executive Engineer.

No 1332 T.N.

Copy submitted to the Chief Engineer for Irrigation, in continuation of this office No. 1332 T.N. of the 4th instant.

TRICHINOPOLY,
4th December 1896.

(Signed) O. V. BODDY, Lt.-Col., R.E.,
Superintending Engineer, VI Circle.

No. 237 I.

Submitted to His Excellency the Governor for information. The breaches reported are not serious.

(Signed) W. HUGHES,
Chief Engineer for Irrigation.

10th December 1896.

ORDER—No. 1069 I., dated 18th December 1896.

Recorded.

(True Extract.)

Under Secretary to Government,
Irrigation Branch.

To the Chief Engineer for Irrigation.
" Superintending Engineer, VI Circle.

Exd. T. K. Narayana Aiyangar.

1

From Mr. R. V. Comarasamy Achari,
Supervisor, Tinnevely, to the Ex-
-cutive Engineer, Tinnevely Du, No.
690 of 21 November 1896: -

I beg to report that on ac-
-count of recent heavy rains some
small breaches have occurred in
the undermentioned Tanks & channels
in my section.

Tinnevely Tahsil.

1. Dinashulam Branch channel
near Tinnevely town $40' \times 14' \times 5'$
2. Tinnevely channel west of Kupi-
-pahurichi supply sluice 17 ft long
9 feet high
3. Pillayashulam Tank
4. Ponnakudiyam channel east of
Limseengulam $45' \times 5'$

Sankaranaimarkoil Tahsil.

1. Marathoni Periyashulam Supply
channel 84 feet long.
2. Marathoni Periyashulam Tank 75 ft.
long.
3. Marathoni Periyashulam Tank north
of surplus weir 30 ft long.
4. Achankulam Tank east of surplus

meir 18 feet long.

5. Achankulam supply Channel
12 feet long.

6. Periyar Periyabulamu Tank 32' x 12' x 10'

7. Perumbuthur Periyabulamu Channel
80' x 15' x 4 1/2'

8 — — — 72' x 15' x 4'

I have arranged to put the ring
bunds in front of the above breaches.
Estimates with other informations
will be submitted later on as soon
as water subsides.

No: 5050 dated 29th November 1896.

Copy forwarded to the Super-
intending Engineer, Trichir, for
information. It is a matter for
regret that these breaches should
have occurred at a time when
the Division is already starved for
funds.

Wm. A. Joyce
Executive Engineer

No:

No: 1333-Td

page 2

Copy submitted to the Chief
Engineer for Irrigation, in con-
-tinuation of this office No: 1332-Td
of the 4th Inst.
Please see
linked file

Trichinopoly
4th Dec 1896

4/-

J. V. Hooley

Lt Col. R. B.

Super Engineer, Trichir

Wm. A. Joyce

CHIEF ENGINEER
FOR IRRIGATION.
DEC. 96.
No. 106.TV

HR Breaches by floods in Tinnevely
+ Sankaranainar Coit Taluk
Public Works (1896) Department.

CURRENT No. ~~106.TV~~
11461

Order

Handwritten notes:
12/12/96
11/12/96

From

*See Supt. Engr
11 Circle.*

No. 1333-TN

Dated 4th December 1896.

Received 5-12-96

Enclosures 17.12.96

Spare copies

SUBJECT.

Floods -

submits report about
the breaches in Tinnevely
& Sankaranainar coit
Taluk -

*Submitted to H.E.
for information. The
breaches reported are
not serious.*

*10/12/96 W.H.
No. 1069 of 18.12.96.*

Recorded

To the Chief Engineer for Irrigation
Supt. Engr 11 Circle

Handwritten signatures and dates:
12/12/96
11/12/96

Handwritten initials:
D.E.I.

5-12-96

Handwritten:
11461/96

BACK PAPERS.

FURTHER PAPERS.