

(1) Number of pages 4
(2) Date of repair 26.2.71
(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

GOVERNMENT OF MADRAS

Revenue DEPARTMENT

G.O. No.	<i>2457</i>	Press
B.P. No.		Mis.
Dated	<i>23.10.1876</i>	196

Not to be folded or roughly handled

Read following:—

2-W.

No. 477.

Note by the Engineer for Irrigation.

The Superintending Engineer, K forwards with his letter marginally noted an estimate in connection with the Viswanadapully Pulivartivari tank, situated in the Bunder taluq, Masulipatam range.

2. The nature of the work for execution and the heads of account to which it is chargeable are as follows:

ORDINARY AGRICULTURAL.

	Rs.
Repairing the bund	420
Total	420

3. The following particulars are recorded:—

Ayacut area	Acres 445
Assessment	Rupees 1,820
Average revenue	787
Highest do	817
Expenditure during the previous	578

The area of the catchment basin is square miles; the maximum flood supply is calculated at — cubic feet per second for discharging which as surplus there is no outlet.

The estimate provides for repair bund.

4. The work provided for estimate has been undertaken on emergency and sanction is therefore recommended though the papers contain no information as to whether it is or is not practicable to prevent a recurrence of breaches. The tank is situated in the island of Divi and is surrounded by an inundation channel. It is not clear that some effective and inexpensive character could not be adopted for the discharge of the Kistum breaches are unusually high.

If the Bank canal estimate be sanctioned, the whole system of irrigation in the island will be at once superseded and it is not worth while to carry out at present any permanent works which may be superseded.

ORDINARY

21st September 1876

To the Secretary to Government,

A. M. SCOTE Major, R.E.,
Dy. Chief Engineer for Irrigation,
for Chief Engineer for Irrigation.

Specimen.

No. 478.

ORDER THIRDON,

IRRIGATION, No. 48.

Account.

VISWANADAPULI

Group or Project.	Fund.	Class.	Particulars of Work.	Amount.
	Ordinary Agricultural	Repairs.	Repairing the bund.	Rs. 420.
				To be carried out by the Public Works Department Officer in charge Manipalpetam Range.

2. This sanction has been registered 159 I of 1876-77.
(True)

[Signature] Colonel,
Under Secy. to Govt., P.W.D.

To the District Engineer, Kistna.
Collector of do.
Chief Engineer for Irrigation.
Examiner of Public Works.
Revenue Department.

Yd. B. G. Shankar.
Spurs Officer

ber 1876, No. 2,593.

The following estimate from the
stam range, forwarded by the
tending Engineer, Kistna, is sanc-

ARI TANK.

WORKS.

10.2.20.21.22.23.24.25.26.27.28.29.30.31.32.33.34.35.36.37.38.39.40.41.42.43.44.45.46.47.48.49.50.51.52.53.54.55.56.57.58.59.60.61.62.63.64.65.66.67.68.69.70.71.72.73.74.75.76.77.78.79.80.81.82.83.84.85.86.87.88.89.90.91.92.93.94.95.96.97.98.99.100.

28 October

28.10.57

Consent to the
Board of Revenue

28 October 1957

Dated

196

Not to be folded or roughly handled