M.R.O. 1—10,006—28-2-50

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE

Government of Madras

Pub. Works · DEPARTMENT

G.O. No.	3269	Press
~~B.P. No.~~ 322-323+.		~~Mis.~~
Dated	29-11-1949	~~195—~~.

Not to be folded or roughly handled

Proceedings of the Madras Government, Public Works Department,
19th November 1874.

No. 322. Read the following letter from Major J. BEATTY, R.E., District Engineer, Godavery, to Lieutenant-Colonel J. MULLINS, R.E., Chief Engineer for Irrigation, dated Dowlaishweram, 9th October 1874, No. 2,179:—

As directed in G. O., No. 1,847, of 10th July 1874, I have the honor to report that owing to the repeated changes of Range Officers in the Ellore Range during the last few years, and the Officer now in charge of the Range having only joined it a few weeks since, I have not been able to discover, and there is nothing on record to show, why the Anappa tank in Rayaveram was not repaired.

2. An estimate for repairing that tank was prepared and submitted to the Collector on the 31st December 1870, and was returned by him with his approval on the 9th January 1871, but the range records do not show why the repairs were not carried out. It is however observed that the Range Officer was changed three times in 1871, which may have led to that and possibly other sanctioned works being overlooked, a circumstance less likely to occur under a more settled state of things.

No. 323. ORDER THEREON, 19th November 1874, No. 3,269.

IRRIGATION, No. 37.

RECORDED. The explanation is sufficient, though necessarily not satisfactory.

(True Extract.)

Colonel, R.E.,
Secretary to Government.

To the District Engineer, Godavery.

Exd. S. T. Austin.
Spare Copies

№ 2179 District Engrs Office, Godavery,
Dowlaishwerum 9th October 1874

From,

Major J. Beatty R.E.
District Engineer Godavery.

To,

Lieutenant Colonel J. Mullins R.E.
Chief Engineer for Irrigation.

Sir,

As directed in G.O. № 1847 of 10th July 1874, I have the honor to report that owing to the repeated changes of Range Officers in the Ellore Range during the last few years, and the officer now in charge of the Range having only joined it a few weeks since, I have not been able to discover, and there is nothing on record to show, why the Anappa tank in Rayaveram was not repaired.

2. An estimate for repairing that tank was prepared and submitted to the Collector on the 31st December 1870 and was returned by him with his approval on the 9th January 1871, but the Range records do not show why the repairs were not carried out. It is however observed that the Range

Officer

officer was changed three times in 1871, which may have led to that and possibly other sanctioned works being overlooked, a circumstance less likely to occur under a more settled state of things.

I have the honor to be,
Sir,
Your most obedient Servant
R. Beatty - Major R.E.
District Engineer Godavery.

From W. 1874 Depart- No. 6862
From Lr No. 1914. Cop
The District Engineer
Godavery.

To,
The Chief Engineer
for Irrigation.

Dated 9th October 1874
Recd 15th
Reg 3 Nov/74 2179

Reporting on the neglect of repairs at the Anappa tank in Rayaveram

With an order

Recommn. The estimate is sufficient, though inquiry will establish whether

Engr
Lieut. 24/10/74

322 — 323.
Cir 6/11/74
Sent to Collr 3 Nov 74

D.E. Godavery. No. 2 Capitn Reg. 28/11/74.

6862

Govt. of 1874 Madras.

PUBLIC WORKS.

To The Dr. Engr.
Godavery

Dated

Rcd. Encl.

G. O. 19 Nov. 1874, No 3249

Nos. 322-323.

Remarks.

Ed. Dondapa Tank
Godavery Dr Letter
from the Dr Engr.
~~relating to repairs~~
~~regarding repairs to~~
~~the tank~~ reporting why
the tank was left un
repaired, recorded with