(1) பக்கங்களின் எண்ணிக்கை 54
(2) புதுக்கித் திருப்பிய நாள் 3-11.88
31 (3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம்

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

P.W.D துறை

அரசாணை எண்.
மு. கோப்புத் தாள் எண். 2934
அச்சகம்
பலவகை

நாள் : 27-11-1884. 198

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

27 கே.த

ஆவண : கா-1—18,000—15-6-87.

60

27th November 1884, No. 2934 W., Public Works.

2934
1

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Buildings and Roads.
Civil Works.

Read—the following letter from H. R. GRIMES, Esq., Inspector-General of Jails, to the Chief Secretary to Government, dated Madras, 11th November 1884, No. 336:—

1 Report.
1 Specification.
1 Abstract estimate, &c.
1 Plan of gate.

I have the honor to forward, for the sanction of Government, the accompanying estimate, amounting to Rs. 583, for putting down a cement concrete flooring over the existing cut stone flooring to the female wards of the District Jail at Madura and also altering the gates.

2. As the work cannot be carried out departmentally I request that Government will be pleased to permit the Public Works Department to execute the same.

3. Funds are available from the grant of Rs. 25,000 assigned to this department on account of petty works of construction.

18th October 1883, No. 2385, Financial Department.

No. 2603, Judicial.

Approved and transferred to the Public Works Department.

(By Order.)

(Signed) M. HAMMICK,
Acting Assistant Secretary.

21st November 1884.

Order—dated 27th November 1884, No. 2934 W., Public Works.

The estimate, amounting to Rs. 583, for improving the District Jail at Madura, is sanctioned for execution by the Public Works Department.

2. This sanction has been registered as Provincial No. 206 W. of 1884-85, and classified as Civil Buildings, Original Works.

(True Extract.)

Major, R.E.,
Under Secy. to Govt., P.W.D.

To the Superintending Engineer, VI Circle, with four enclosures.
" Examiner, Public Works Accounts.
" Judicial Department.

Exd. C. Howarth.
Spare Copies

BUILDINGS AND ROADS.
CIVIL WORKS.

Govt. of (1884) Madras.

PUBLIC WORKS.

Dated November, 27th.

Recd. *Encl.*

G.O., 27th Nov. 1884, No. 2934 W.

NOVEMBER.

District Jail at Madura

Estimate for improving the — sanctioned for execution by the Public Works Department.

2934/2

Madras 11th November 1884

From
H. K. Grimes Esq
Inspector General of Jails
To
The Hon'ble E. F. Webster
Chief Secretary to Government
Fort St. George

Sir

I have the honor to forward for the sanction of Government the accompanying Estimate amounting to Rupees 583 for putting down a cement concrete flooring over the existing cut stone flooring to the female wards of the District Jail at Madura and also altering the gates.

2. As the work cannot be carried out departmentally I request that Government will be pleased to permit the D.P.W to execute the same.

Funds are available from the grant of Rupees 25,000 assigned to this Department on account of Petty works of construction.

I have the honor to be
Sir
Your most obedient Servant
Henry R. Grimes.
Inspector General of Jails

Fcml. G.O. 28-10-85: 2385

B.R. 2779 W d/ 7-11-84
No 19838 d/ 20-10-84
" 683 E d/ 16-9-84
" 436 E d/ 6-8-84
" 394 E d/ 28-7-84

Judl (1884) Depart.

CURRENT No. 4186

From
The Inspector General
of Jails
To
The Chief Secy to Government
Fort St. George
Dated 11th November 1884.
Recd 13.-

N

No 2603 d/ 21st Nov/84-
Approved and trans-
ferred to the P. W. Dept.
By order.
[illegible]
Ag Asst Secy.
.11.84.

No 326

Recd 24/11/84

Encls 4 (1 plan)

Forwarding for sanction Estimate amounting to Rs 583 for flooring the female wards of the District Jail Madura.

[illegible]

See pencil note on first
page.

2972x: [illegible]

25-7-84

To W/
G.O. 1762 W. d/ 17 July
/84 settled this question.

3A/ [illegible]
25-7-84

Issue
orders on
3 ... [illegible]
26/7/84

Sanction
CJ.
25-11-84

Public Works Department, 1884-85.

2934W 9744

Current No. 9744

Letter No. 2603

Dated the 21st November 84.

From the Judicial Department

NOTE OF REMARKS. 2934/5

1. The accompanying estimate, with plan, provides for certain improvements of the District Jail at Madura. The estimate amounts to Rs. 583.

2. The stone flooring of the female compartment of the jail is to be covered with Portland cement 2 inches thick; and eave boards are to be provided for the ventilators. The gate pillars of two gates are to be renewed, and the iron work of the gates is to be improved. The Quarters of the Jailor are to be supplied with pipes to carry off rain

3. The Inspr. Genl. of Jails requests that the works may be carried out by the P.W. Department.

4. The estimate has been countersigned by the Inspr. Genl. of Jails.

25th Nov/84
BH

BP

No 771

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

2934 / ~~26~~ 6

UNDER date the 7 [illegible]

READ the following

From
The Supt. Engineer VI Circle } (H. Ex. dt 10th July 1884)
Do — do — do — (" No 223 M.D. dt 2nd Augt/84)
Do — do — III do — (" " 1365 " 11th Octr ")
Do — do VI do — (" 388 M.D. " 22nd ")

Recorded, with the remark that the Govt. expect Executive Engineers concerned to give proper attention to all the details of works designed and carried out by them. In the case of the female ward, Madura Jail, if such attention had been given by Messrs

Johnston and Grimes, the complaints as to indifferent workmanship made by the Jail authorities would have been avoided.

CW.
4.11.84

CW
5.11.84

7-11-84

S.E. VI Circle
S.E. III Circle
Desp. 7-11.84.

P. W. Department.

2934/7

Remarks by the Chief Engineer, on Inspection Notes of the Suptg. Engineer VI, circle for the month of July/84 on Madura Palace &c dd 4th July/84.

Forwarded to the Suptg. Engineer VI Circle for note and return.

(Signed) J. Shaw Stewart
28. 7. 84 Col R. E.
Chief Engineer P. W. D.

To

The Suptg. Engineer
VI Circle.

(with the Inspection Notes, in original to be returned)

Desp. 28/7/84
6

P: P.G.

GO 170 WA/19.1.84

No 3194 Ed

S. 7/7

No 224 S.E. 20: July 1884.

2934/8

From,

The Executive Engineer
Madura Division

To,

The Supd Engineer
6: Circle.

Enclo: 1.

Sir,

In forwarding the enclosed precis of the Female Jail case, I have the honor to inform you that since the Building has been handed over to the Jail authorities that the pointing between the stones has been disappeared, so the floor looks worse now than when I last inspected it. also the earth under stones seems to have sunk. The convicts have coir

In accordance with your No 165 Mt / 10.7.84.

mats to sleep on so I did not think that a little roughness of the floor would matter.

2. I have often seen gates with rollers under them which helps to carry the weight of the gate and therefore considered that it was permissible.

The other way to hang a gate is to make the pillar strong enough to hold up the gate without any roller, & certainly in this case the pillar was not strong enough.

I have &c.

(sd) J. Grimes

Executive Engineer

Madura Division

(True copy)

No. 223. MD

Enclo 21.

2968 of 84

Forwarded to the Chief Engineer P.W.D. with reference to his remarks on Notes of Inspection of 4' July dated 28' July.

The Superintending Engineer has no further remark to make on the matter.

2934/9

Trichinopoly

2d August 1884

Lt Col. R.E.

Supg. Engineer. 6 circle.

No. 6465

(6)

From,

The Supt. Engineer
6th Circle

To,

The Chief Engineer
P. W. D.

No. 223 M.D.

Dated 2d August 1884
Recd 4 —

Enclo: 1

G.O. No. 170 W d/ 19th Jany 84
No. 394 E. d/ 28th July '84
No. 436 E d/ 6th August 84

Madura Jail

Forwards copy of Executive Engineer's explanation in regard to bad work done in the ___

X

To D.W. Proposed to call the letter to bag – whether previous papers are

O/4

Please do
Cy
C.L.

O. 4.8.84

Caw.

29351/10

On examining the E bundle for August 1884 I find that C. No. 6465 is awaiting the return of the S.E.'s inspection note of the 4th July. This was returned to the Madras Office and recorded E. No. 494 d/ 16/8/84.

E.A.S.
13/9/84.

To W

Submitted with draft disposal. The S.E. omitted to send a direct reply to Memo: 436 E d/ 6 Aug. 84. The paper thus comes to be taken up for disposal in the usual course, on a review of the unanswered references.

A.S.

2/

No. 436 E d/ August 6 1884

P.W. Department

2934
11

Memo.

From the Suptg: Engr: VI. Circle No. 223. M. D d/ 2d. August /84

The Superintending Engineer VI. Circle is requested to be so good as to return ~~the~~ his Inspection notes ~~of the~~ dated 4th July, as ~~desired~~ requested in this office endorsement No. 394. E d/ 28th July /84.

6-8-84

E. W.

10

S. E. VI. Circle. Despd 6/8/84

C. S.

No. 1326 E. dy Augt 1st 18[illegible]

P. W. Department

No. 683 E. dy 16th Septr. 1884

Read Inspection Notes of the S. E. VI Circle for the 7th & 10th July 1884.

2934/12

Précis of correspondence on the subject of the Madura Jail.

The above documents are forwarded in original (to be returned) to the Supdg Engr III Circle, who is requested to call on Mr. J. C. Johnston for such explanation as he may wish to offer in respect to the bad work complained of of by the Jail authorities

JJS
16.9.84

EW

desp.d 16/9/84

S.E. III Circle with 2 Enclos.
(to be returned

E.S.
Ex Eal.

1884.

P. W. DEPARTMENT.

Current No. 8606 13

From The Supt.g Engineer III Circle

No. 1365
Dated 11th October 1884
Received 14th

SUBJECT.

Jail Works at Madura. Forwarding the Explanation of Mr. J.C. Johnston, Executive Engineer, regarding the ——

DISPOSAL.

No. Dated

Referred to the Supt.g Engineer VI Circle for any remarks he may wish to offer on Mr. Johnston's explanation

(Sd) J Shaw Stewart
Col RE
Chief Engineer P.W.Dept.

To The Supt.g Engr. VI Circle in original to be returned.

2934
14

wing is a precis of
ase.

spector General of
rded to the Superin-
ineer copy of letter
perintendent District
dura reporting on
Block completed and
e by this Department.

s endorsed by the
ing Engineer to the
Engineer for report
king that it is feared
as not been properly

tter of the Jail Su-
t to the Inspector
Jails, that officer
at, in the completion
ade the following
s:- The floors seem
being too rough, the
damp in places near
ich the executive Engineer

13

of by the Jail authorities

J.S.
16.9.84

E.W.

No. 170 W.D./19.1.84
" 394 Ed/28.7.84
" 436 Ed/16.8.84
" 683 Ed/16.9.84

The following is a precis of the Jail case.

---

1. No. 6315 / 19.12.83. The Inspector General of Jails[1] forwarded to the Superintending Engineer copy of letter from the Superintendent District Jail at Madura reporting on the female Block completed and handed over by this Department.

2. No. 468 W.D. / 22.12.83. This[2] was endorsed by the Superintending Engineer to the Executive Engineer for report and remarking that it is feared the work has not been properly done.

3 No. 397 / 10.12.83. In this[3] letter of the Jail Superintendent to the Inspector General of Jails, that officer remarks, that, in the completion Report, he made the following observations:- The floors seem unsuitable being too rough, the walls were damp in places near the roof which the executive Engineer

said could be set right at a cost of a few annas by putting on a tile, the steps leading up to the Hospital verandah were placed on one side instead of in the centre. Two of the pillars supporting the gates require repair, the weight of the gates having broken them, the breakage occurred previous to the building being taken over. The enclosing wall of the Jail should be raised in the vicinity of the gates to prevent the prisoners getting over the wall. To these remarks the Executive Engineer replied as follows:— "The work was fully completed when I took charge of the Division. The floors are granite stone dressed on sides but not smooth dressed on face, the Estimate rate was very low being only ·40 per cft. but from the specification I find that the stones should be two line dressed if the rate was too low the Estimate should have been revised and a Deviation Statement submitted for sanction. Stone dressed as provided for in the Specification would cost Rs 1-8-0 instead of 6 annas as allowed in the Estimate. The female wards and solitary cell were measured and paid for by Mr Johnston on 29: January 1883, and the female Hospital by Gopal Kristnier Assistant Engineer in March 1883. The face of the Stones is not smooth dressed but good enough for a Jail or Barracks and if required to be made smooth, the convicts could do it themselves by putting on a layer of clay and cowdung. As regards the walls being damp at top, I have explained this in my inspection note of 26.11.83; with respect to the steps it was considered advisable to have the steps in front of the door, as in front of the Hospital there

No 2859
25-12-83

is one window and one door & the plan showed the steps in the centre of the verandah between the window and door. In my Inspection Note of the 2nd November /83 I have fully explained the cause of the damage to the gate pillars and maintain that the damage was owing to the carelessness of the Jail people, who opened the gates too wide and threw them off the curb. The building was handed over to the Jail Superintendent on or about 21st August 1883, and the gate pillars were damaged on or about the 20th September 1883, or one month after, the Superintendents Statement is therefore not understood, where he says that the breakage occurred previous to the building being handed over to him. The Superintending Engineer[5] in reply to this letter stated that he would inspect the Jail floorings when he next visits Madura, as he fears they are far from satisfactory and regrets that the petty details of the gates & steps were not carried out in consultation with the Superintendent.

2934/16

/Sd/ I. Grimes.
Executive Engineer
20.7.84.

/True Copy/

Lieut. Col. R.E.
Supd. Engineer 6: Circle

5. No. 479 M.O / 8-1-84

SUPERINTENDING ENGINEER
27 OCT 84
6th CIRCLE

6th Eng
6455/84

1/744 W/84

Inspection Notes of the Superintending Engineer
6th circle for the month of July 1884.

Dated 4th July 1884.

2934/17

Madura Palace &c.

Arranging with the Consulting Architect with regard to what works should be put in hand and what the estimate.

Plastering and ornament is at present in progress in the inside of the 4 corners of the Court yard; these are to be completed as soon as possible; 4 iron ties for the Waggon Vault B have been received; the rest it is hoped, will come soon; these ties should be put up as soon as possible, and by the time this is done we shall probably get orders as regards the style of

orders have been passed on this matter. Vide G.O. 17.7.84, No. 1762 W

SUPERINTENDING ENGINEER'S OFFICE
27 OCT 84
6th CIRCLE

1/744 W/84

Inspection Notes of the Superintending Engineer 6th circle for the month of July 1884.

Dated 4th July 1884.

2934/17

Madura Palace &c.

Arranging with the Consulting Architect with regard to what work should be put in hand and what the estimate.

Plastering and ornament is at present in progress in the inside of the 4 corners of the Court yard; these are to be completed as soon as possible; 4 iron ties for the Waggon Vault B have been received; the rest it is hoped, will come soon; these ties should be put up as soon as possible, and by the time this is done we shall probably get orders as regards the style of

18

Orders have been passed on this matter. Vide G.O. 17-7-84, No. 1762 W ornamentation to be adopted. Scaffolding to be put up on the out side of the West end of the South side of Court Yard and 2 Bays to be done as now proposed as a pattern for approval the Executive Engineer is requested to press this on and also see that the Architect's proposals are attended to as little as possible of the old work to be removed.

Settled with Major Morant what was required for the estimate for the other buildings.

Dated 7 July 1884

Madura Jail.

A new female ward was completed last year; there was great delay in sending in the Completion

certificate and finally when sent to this office it was found that the Jail Department made a complaint with regard to the flooring and the hanging of the iron gates. The present Executive Engr Mr. Grimes was asked to report on these points and did so, this report gave me to understand that the complaint was unreasonable and therefore no action was taken.

I regret to find that the flooring is disgraceful, the iron gates are far heavier than they should be and badly designed; they are hung on good large stones built in the pillars but these owing to the weight of the gate have shifted.

The Exec: Engineer will of course be called on for explanation respecting both the bad work, and his ~~the~~ misleading report.

I have written to the Inspector

General of Jails to propose the following:

To put down a coat of Portland cement concrete not less than 1½ inches thick over the present rough stone flooring:

If the iron gates are necessary for new ones to be made up of a proper pattern.

As the Ridge ventilators have been put too high, that a new deep eave board should be put in to prevent rain from blowing in.

There is an old building that was used as a ward, but is not in use now; the roof is unsafe; if not required it should be dismantled; if required a new roof will be necessary; it should be super & purlins and the old rafter could be

used. Inspector General of Jails written to about this.

Some repairs &c have been done by this Department to the Jail lately; they appear fairly done but the Verandah roof of the Jailors house on one side is bad from a heavy [illegible], ~~tar~~ drainage gutters being placed on it: this should have been attended to and must be done at once, the Executive Engineer must see that, when a building is repaired, it is done thoroughly.

All this is far from satisfactory.

Dated 10 July 1884.

Madura Palace.

18

On reconsideration with the Consulting Architect, we agree that the iron ties – referred to in the Waggon vaults, are not required and therefore the Executive Engineer has been requested not to put them in the work for the present.

Should they be considered desirable hereafter, they can be added.

We have also agreed that the whole of the front verandah should be completed according to the original idea of Mr. Chisholm; this will complete in one style the whole of the West outer Verandah.

Lt Col R.E.
Supg. Engineer Circle.

Camp Madura
10: July 1884.

Vide G.O. dated 17-7-84
W. 1762 W.

25-7-84

Noted and returned

Lt Col R.E.
Superintending Engr
6 Circle

11/8/84.

2/744 M/84   1/440 M/84   6723

To W pr forward

Cd
14.7.84

SUPERINTENDING ENGINEER
30 JUL 84
6th CIRCLE

(7)

From,

The Supdg Engineer
6th Circle

To,

The Chief Engineer
P. W. D

Recorded

SUPERINTENDING ENGINEER
22 OCT 84
6th CIRCLE

Cd
14.8.84

16.8.84

Dated 10th July 1884.

13 August 1884

No. 394 Edf July 28th 1884

Inspection Notes for the 6th, 7th & 10th July 1884 –

C.E. 83/8.

With disposal

Recy: 15.7.84. O.16.8.84

No. 1250

Executive Engineer's Office,
Camp
dated 7th Octr/84

From
The Executive Engineer
Cuddapah Division

2934/21

Enc 3.

To
The Superintending Engineer
III Circle
Bellary.

1 Inspection notes of the S E VI circle of 10th July /84.

1 Precis of the Correspondence of Jail Case.

1 Chief Engr's No 683 E of 16th Sept/84 with SE's endorst No 1245 of 23-9-84.

3.

Sir,

With reference to your No 1245 dated 23rd September 1884 – forwarding certain documents relative to the Madura Jail Female Wards. I have the honor to offer my explanation as follows –

2. Flooring of Wards – When the flooring was first put down – I noticed the surface was rough and ordered a little more dressing to be done – which was carried out – The overseer explained that the rate was too low to allow of the stones being dressed quite smooth – I examined the rate in detail with regard to quarrying and cartage and found that the overseer's statement was correct. I did not submit a deviation statement and have the flooring dressed smooth, because I considered it quite good

20

enough for Jail Wards - What was omitted then can however be done now - for it is only a matter of a higher rate.

3. Iron gates - The iron gates were designed by me and the plans and estimates received the Countersignature of the Superintending Engineer Col. Beatty and Col. Tennant the Inspector General of Jails - I think. The pillars were not designed to bear the weight of the gates - as each gate was provided for in estimate with a semicircular curb and ~~wheel~~ roller - The weight was then all distributed vertically - Mr. Grimes makes a mistake in saying the work was fully completed when he took over charge - The bulk of it had been done - but I do not remember seeing more than a quadrant of one curb and to the best of my belief no gates had been fixed - The gates when open had to be fastened to the railings and this necessitated a semi-circular curb - and I submit that unless the gates had been thrown off the curb - there would have been no horizontal stress and consequent displacement of the stones in the

2934
22

K.

pillars - It is so long since I left Madura - that I cannot now state for certain what details of the estimate had not been completed when I gave over charge - but I am almost positive all the iron work had not been done - Having designed the gates myself and having provided a curb and ~~wheel~~ roller on purpose to relieve the pillar of horizontal stress - I cannot think I could have been so careless as to have passed curbs of insufficient length. For any gate to have been thrown off the curb - the latter must of necessity have been of insufficient length -

2934

I have the honor to be
Sir
Your most obedient Servant
John C. Johnston
Executive Engineer -

21

3/744 MD/84

Rep No. 290 C
159/84-5

SUPERINTENDING ENGINEER
22 OCT 84

From
The Executive Engineer
Cuddapah Division

To
The Superintending Engineer
III Circle
Bellary.

Dated 7th } Oct. 1884
Despatched
Received 9th } do

No. 1250. Enclosures. 3.

SUBJECT

Madura Jail Female Wards:— Giving certain explanation as to the bad work of the —.

HMV
11/10/84

No. 1365

SUPERINTENDING ENGINEER'S OFFICE,
Seondoor ~~MADRAS~~,
~~Chepauk~~, 11th October 1884.

From
Lt. Col. H. M. Vibart R.E.
~~The~~ SUPERINTENDING ENGINEER,
III ~~1st~~ CIRCLE,
Bellary

2984
23

To
The Chief Engineer
P. W. Department
Madras.

Enclosures. 3.
1 Letter from Mr J. C. Johnston.
1 Inspection notes.
1 Precis

SIR,

With reference to your Memorandum No. 683 E dated 16th September 1884, I have the honour to forward the accompanying explanation received from Executive Engineer, Mr J. C. Johnston, in respect to the Jail Works at Madura

I have the honour to be
Sir
Your most obedient servt.

22

Lt. Col. R.E.
Superintending Engineer
III Circle

Col No 744 MD

From

The Superintending Engineer,
~~1st~~ VI Circle,

27 OCT 84

To

The Chief Engineer
P.W. Department
Madras.

Dated 11th } October 1884
Recd.

Enclosures. 3.

No. 1365

Jail Works at Madura:—

Forwarding the explanation of Mr J. C. Johnston, Exec; Engineer, regarding the

Referred

To the W— for perusal.

Col

Ootacamund October 20. 1884
No 796 E

Referred to the Superintending Engineer VI Circle for any remarks he may wish to offer on Mr. Johnston's explanation.

Col RE
Chief Engineer
P W Dept.

20.10.84

To
The Supdg: Engineer VI Circle
in original to be returned. [illegible] 21/10
c. 16.10.84

No 388 M.D. Supd. Engineer's office, 6 Circle.
Trichinopoly. 22nd October 1884.

~~From~~

The Superintending Engineer
6 Circle.

To,

The Chief Engineer
P.W.D.

2934/24

Sir,

With reference to your Endorsement No 796 E dated 20 October, I have the honor to return the papers and to remark that I cannot agree with Mr Johnston as regards the Jail ward stone flooring being good enough for Jail wards, the Rate in the estimate was certainly not sufficient to do the work according to specification but this might have been increased & good and proper work done.

Enclo: 3.
Returned with 2 enclosures.

2. With regard to the Iron gates, the details were not good; Mr Johnston is quite right as regards his remarks that the gates were intended to be carried on

23

a curb and rollers, this was done but the gates failed and this in my opinion was (not as stated by Mr. Grimes owing to the carelessness of the Jail people) owing to defective design. I do not consider that Mr. Johnston was to blame to any extent for this as the design and details for a good iron gate ~~is~~ are difficult but I do ~~not~~ think that Mr. Grimes when he found a mistake had been made, should have endeavoured to have ? Correct corrected it and not to have only reported that the work was done before he took charge and was due to carelessness of the Jail people.

With regard to the Jail ward flooring I do consider as before reported that Mr. Grimes' report on it was far more favourable than it should have been.

I

I have the honor to be
Sir
Your most obedient servt
Lt Col RE
Supg. Engineer, Circle

2934/25

24

No 683 E d/16-9-84
" 436 E d/6-8-84
" 394 E d/28-7-84
" 796 E d/20-10-84

To E.W.

pr orders. Probably an order to the effect that Govt expect Ex: Engrs concerned to give proper attention to all the details of works designed & carried out by them, & that in this case such attention does not appear to have been given by him: Errors & blunders & complaints of indifferent workmanship then avoided, will suffice.

C.S.
3.11.84

Yes
3-11-84

a. 24.10.84

---

(3)

From,
The Supdg Engineer
6: Circle
To,
The Chief Engineer
P.W.D

No 388 M.T
Dated 22/10/84.

Jail works at Madura.

Returns with remarks the explanation of Mr Johnston in connection with certain works carried out—

796 E of 20-10-84
at ackg— 24-10-84

EW
For orders
C.S.
1.11.84

No 2934 W

Buildings & Roads
Civil Works

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

2934/W
28/11/84

UNDER date the 27th November 1884

READ the following

From the Inspector General of Jails - H. E. No: 336 d/11th November 1884.
Endorsement thereon by the Judicial Deptt. H. E. No: 336 d/21st Novr. 1884.

The estimate amounting to Rs. 583, for improving the District Jail at Madura, is sanctioned for execution by the Public Works Department.

2. This sanction has been registered as Provincial No: 206 W of 1884-85, and classified as Civil Buildings, Original Works.

C.S.
26-11-84

To The Supt. Engr. VI Circle with 4 enclos.
" Examiner P. W. Accts
" Judicial Department

Despd 3-12-84.

9744

Govt. of (1884) Madras.

PUBLIC WORKS.

26.

Press 29/11/84

Dated

Recd.

Encl. 1

G.O., 27 Nov. 1884, No. 2734

District Jail at Madras

Estimate ~~of Rs.~~

for improving the —

sanctioned for execution

by the P.W. Dept.

60
4

E 28/11
Id 28/11