(1) பக்கங்களின் எண்ணிக்கை 34

(2) புதுக்கித் திருப்பிய நாள் 11.2.90

(3) ஆதாரங்குறிப்பவர் சுருக்கெழுப்பம் [illegible]

தமிழ்நாடு ஆவணக் காப்பகம்.

(67)

தமிழ்நாடு அரசு

P.W.D. துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	2830	அச்சகம் பல்வகை

நாள் : 10-10-1889 19 .

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

17 Sheets

ஆவண. கா-1—18,000—15-6-87.

care will be taken that no Salary is disbursed before the despatch of the Salary Bill.

6 The Trichinopoly Divisions Requisition for payment was received in this office on the 8th October 1888 when a Debit Advice and an Acquittance Roll were prepared and sent to camp for Signature with information that a cheque may be drawn in the Executive Engineers favor. But the Executive Engineer signed and returned the Debit Advice. This was of course sent to the Trichinopoly Division on the assumption that the Executive Engineer has paid himself.
On asking the Executive Engineer to Sign the acquittance roll he said he would Sign it when he draws the cheque and that he would draw it only when he returns to Head quarters. He returned to Head quarters on the 18th and drew the cheque.

7 Since Signed and Submitted.

8 Signatures and initials are being taken regularly now.

9 Vouchers are sent with cheques to payees to their address. We have since been directed not

5. The attention of the Executive Engineer is drawn to code para 473 Rule 2

2680

7 & 8 } The vouchers should be signed by Executive Engineer without keeping them till the accounts are ready for submission to Examiner —

9

Supdg. Engineers remarks	Executive Engineers explanation
	and sent to the Examiner.
	10 Will be attended to
	11 Since attended to
	12&13 — Do —
12&13 The Register of works should be maintained under code para 1866 for all major Annual works and Repair works estimated to cost more than Rs 2000 each.	

EXECUTIVE ENGINEER
16 AUG
76

Executive Engineers explanation	Supdg. Engineers remarks
14 Will be done The overpayment of Rs 0-2-9 will be recovered.	14. Noted 2880 The measurement sheet attached to the Contractors Bill should always be a Copy to the measurement book.
15 Will be done.	2 15. The measurement sheet can be only allowed under the initials of the officer by whom it was submitted.

Supdg. Engineer's remarks	Executive Engineer's explanation
16/ The Register of cheques drawn but not paid away & consequently not brought to account should be maintained under para 3 of G.O. No. 732 W dated 3 March 1888.	16 The cheque was since cancelled.
	17 Completion Report for this work was sent on 13th March 1889.

Executive Engineer's explanation	Supdg. Engineer's remarks
18 Will be done in future.	(18) The Executive Engineer should have not accepted these measurement sheets without the signature or initial of the Sub Divl Officer. The measurement in the measurement books as required by Note I printed in M 19 should be cancelled and the measurement sheets being copies of measurement books should be similarly corrected.
19 The Subordinates concerned have been addressed on the subject.	19. The sub Divl Officers should be told to submit bills within first week from the date of measurement of works.

3

Supdg: Engineers remarks	Executive Engineers explanation
20. The attention of the Executive Engineer is invited to Code para 1350 regarding the limit of Executive Engineer power of accepting tender.	20 Will be attended to.
	21 All have since been recovered with the exception of Parassarama Mudaly and this will now be recovered.
22 The schedule of Rates have been revised in 1886-87 and lastly in 1889-90 which	22 Since completed and submitted to Superintending Engineer.

Executive Engineers explanation	Supdg: Engineers remarks
	Which will be submitted to Chief Engineer. In the Current Schedule for 1889-90 there are various descriptions of concrete work varying in cost from Rs 4 to 16
	The rate for gravel may vary in reference to the distance of carriage from Rs 1-6-0 to 1-8-0
	Turfing rate from annas four to annas 5½
23 Since completed.	23. The Register of Buildings Corrected upto 1888-89 include the two works - Pallavadai Police station House No 8 in the Register of Buildings of Vellore Taluq.
	Tirutani Sub Registrars Office No 27 in the Register of Buildings of Wallajah Taluq.
24 2 Levelling instruments were sent to P.W. Workshops for Repair since returned.	
Since rectified.	
25 The last Supply is not yet posted.	25 The Code should be corrected up to date
Will be attended to	

Supt'g. Engineer's remarks	Executive Engineer's explanation
	26 Since entered
	27 Corrected
28. The entries should be attested by the head of the office Concerned.	28 Will be entered.
	29 Will be done
	30 Since completed.
31. should be attested by the Head of the office Concerned.	31 Will be done.

Executive Engineer's explanation	Supt'g. Engineer's remarks
32. Since opened	2830
33. Will be attended to.	

Wm Burton
Colonel R.E
Superintending Engineer Circle

Executive Engineer
North Arcot Divn

Mayor R.E

Nat'l office
31st May 1898

EXECUTIVE REGISTRY
20 MAY 89
M.D.

18 AUG 9
706

2830

b

Supdg: Engineer's remarks	Executive Engineer's explanation
	Rego: No. 148. 1-6-89

Notes of Inspection by H. Rainier Esquire of the Office of the Executive Engineer North Arcot Division on the 11th. and 12th. February 1890.

Mr. J. J. Whiteley, Executive Engineer 4th. Grade took charge of this division on the 2nd. February 1890. M.R.Ry. Y. Yuvarungam Naidu is still the accountant.

This office was last examined by an account officer in September 1888.

2. The Sub-Divisional Officers (Captain West and Mr. Ashpital Assistant Engineers) have no drawing accounts.

3. The following imprests are held.

Name and rank of Imprest-holder	Amount of Imprest	By whom recouped
	Rs	
Captain W. C. S. West Assistant Engineer	20	Executive Engineer
V. R. Kuppusawmy Moodelliar Overseer	200	
A. Kuppusawmy Moodelliar Overseer	50	
P. Panchapakesa Aiyar Overseer	100	
Mr. J. Willis Overseer	100	
S. T. Raghava Aiyangar Overseer	160	
M. C. Singara Aiyangar Overseer	50	
Mr. Mahomed Kassim Sahib Assistant Engineer	130	
M. Moorogesa Moodelliar Head Clerk	7 15	

4. x x x x x x x

5. Salaries are as a rule disbursed some days before the despatch of the salary bill to the audit office which is an infringement of rule.

6. Captain Langley R.E. a former Executive Engineer of this division, paid himself on the 10th. October 1899 Rs.306-11-9 debitable in transfer to the Trichinopoly Division which debit had already been advised on the 8th. October 1899, ten days before the payment was made.

7. The following vouchers have not been signed or initialled by the Executive Engineer. Vouchers Nos. 6,8,10,12,13 14, 15,60,68,126,130,138,139,140,143,145,146,159,166.

8. The custom has been to take the Executive Engineer's initials on all vouchers of the month, at one time, namely when accounts are ready for submission to the Examiner.

The following vouchers for January 1900 were not produced.

Voucher No.	Contract	Certificate for	Reason
115	"	173-0-0	Sent to payee for signature
127	"	97-14-3	
128	"	36-0-0	
136	"	192-6-4	
137	"	225-15-10	
141	"	717-0-0	
142	"	500-0-0	
144	"	65-5-7	
147	"	50-4-0	
157	"	852-0-0	
163	"	105-2-9	
164	"	31-2-8	
165	"	218-7-3	

10. The register of works is not kept up for repairs and carriage of tools and plant although a work voucher in Form No. M.46 is submitted for the same.

11. The appropriation for major works is not generally entered in the register of works.

12. Constructing condemned cells, gallows and wards in the Vellore Central Jail Estimate Rs.4188-0-0.

The accounts of this work in the Register of works are not kept by sub-heads. The expenditure is recorded as for works costing below Rs.2500-0-0.

The Accountant stated that as no work voucher is due under clause 11 para 1000 the register account is not considered necessary. This is a misconception under para 1000 the accounts should be kept in detail in the register unless the normal cost system is adopted when quantities of work done under each sub head would be posted and estimated rates applied.

13. The last para also applies to the following works:-

Name of work	Estimate Rs.
(1) Easyanur large tank Repairing and improving the bund of	3,180
(2) Clearing sand from the bed of Kaweri paunk tank main channel	4,475
(3) Repairing the bund of Madimangalam tank	5,600
(4) Repairing the bund and reconstructing the sluice of Vengonam tank	4,840
(5) Raising the bund and clearing ~~supplementary~~ supply channel of Uderyathur tank	3,220
(6) Repairing bund and reconstructing Low Level Sluice Shola Veeram tank	3,360
(7) Repairing the bund of Ammineur Therkari tank	2,580
(8) Repairs to Bradum tank	2,860

14. Repairing cracks in the terrace roof of jail Superintendent's bungalow Central Jail Vellore Estimate Rs. 400-0-0.

This work done by contractor Subbarpya Moodelliar was measured on 30th. November 1888 by Overseer Mr. Willis and checked on 4th. December 1888 by Sub Divisional Officer Mr. Ashpital.

The measurements in the book being compared with those in the measurement sheet and bill, it was found that the measurement book shews 104 Square feet of Lead flashing though the measurement ~~book~~ sheet shews 201 Square feet. The difference 03/8 Square feet is stated in the measurement sheet to represent over lapping and joints (34 x 1/4 x 3/4 or 6 3/8) but this cannot be traced in the measurement book of which the measurement sheet should be an exact copy. The measurement sheet has undergone certain corrections in the Divisional Office due to incorrect calculations by the Overseer who prepared the bill. Thus under sundry plastering here and there was an item "1X7X1 1/4= 1 3/4" in the measurement sheet which was corrected to 1X7X1 1/4= 8 3/4 thus increasing the value of work done by Rs. 3-0.

This correction has not been communicated to the Overseer on comparing the measurement book with the measurement sheet it was found that the measurement is stated in the former as 1X7X1/4 only which comes to 1 3/4.

The overpayment of 2 annas 6 pies should now be recovered and future corrections if found necessary in measurement sheets should always be made in communication with the Officer in charge of work and who prepared the bill.

15. Similarly in the case of "closing breach of Vanur Tank" estimate Rs. 1000-0-0 the measurement sheet shews in one case "33X10X1 3/4= 347 1/2 Cubic feet" which has been altered in the Divisional Office to 33X10X1 3/4= 577 1/2 Cubic feet.

It is just possible that 1 3/4 is a clerical error for 3/4 A reference in this case was necessary and should have been made. The measurement book was not available for comparison. 2880

16. Temporary Survey Establishment for surveying tanks etc. Kaveripak tank Estimate Rs. 1000-0-0.

In the month of December 1888 there is a charge of Rs. 343-0-0 in the Register of Works. This is the amount of a cheque drawn on the 13th. December 1888 in favor of two Contractors Nagamuthu Pillay and Veeriah Chetty for work done. The cheque in question was despatched to their address through Sub-Overseer in charge of the work on the same date on which it was drawn but has lately been returned unaccepted by one of the Contractor Veeriah Chetty who states that the whole amount is due to him and him alone the other contractor having nothing to do with the work. The bill is in favor of both of ~~them~~ them. The cheque is now in the Executive Engineer's Office and it is stated will be cancelled.

In this case the cheque was ~~not~~ but should not have been entered in the cash book as paid away on the same date as it was sent to the payee through the Sub Overseer in charge of the work.

The Register ordered in C.O. No. 732 ~~77~~, dated 3rd. May 1888 is not maintained.

17. Constructing a weir at Vonbakkam Tank Estimate Rs. 630 There are arrears of Rs. 4-0-0 due to Maistry Munisawmy Mudoo outstanding since May 1888. As this is outstanding for more than six months and as it is said that there is no likelihood of its early adjustment it may be credited to Revenue by debit to 9 work.

18. Measurement sheets from the Vellore Sub Division are not generally signed or initialled by Sub Divisional Officer. The rules regarding cancelling of measurements are not observed these are perhaps as important as any rules in the Code and have the uncommon merit of being uniformly applicable and very easy of adoption every where in the Presidency.

19. The following instances of delay in pilfang for measured work came under notice.

Name of Contractor	Name of work	Date of Measurement	Date of bill
(1) Streenivasulu Naidu	Constructing sluice to Marasada Mudalari tank	2nd October 1888	20th October 1888
(2) Thepermal Moodelliar	Reconstructing a sluice Korakathan tank	27th September 1888	26th October 1888
(3) Lutchmana Moodelliar and Muthukalathy Moodly	Repairing bund of Tidiathur tank	9th October 1888	23rd October 1888
(4) Ethirajulu Naidu	Repairing Masonry works and improving bungalow of Kaveripauk tank	1st and 23rd October 1888	7th November 1888
(5) Bhashakaier	Repairing Slip No. 2 Kaveripauk tank	27th September 1888	25th October 1888
(6) Streenivasulu Naidu	Reconstructing sluice to Vengonam tank	1st October 1888	27th October 1888
(7) Thepermalu Moodeley	Repairing the damage done to Sheyant Amount	6th October 1888	27th October 1888
(8) Streenivasulu Naidu	Reconstructing sluice to Kaveripauk tank	15th September 1888	20th October 1888
(9) Siva Chidambaram Moodelliar	Earthwork to Thenumpett Channel	2nd October 1888	31st October 1888
(10) K. Subbier	——do——	——do——	——do——
(11) Ayasawmy Moodelliar	Closing breaches in Sarai Supplementary Channel	2nd May 1888	3rd December 1888
(12) Streenivasa Iyer and Varadacharry	Repairing bund of Ammanur Therkari tank	16th October 1888	10th December 1888
(13) Appasawmy Moodeley	Repairing the Rest house at Arkonam	5th November 1888	30th November 1888
(14) Kuppusawmy Naidu	Repairing the bund of Thellar Large tank	2nd and 3rd December 1888	15th December 1888

20. Contract agreements were found generally in order 287 respecting the following contracts (for sums in excess of the Executive Engineer's powers of acceptance) the Superintending Engineer's prior sanction was not obtained.

Name of Contractor	Name of work	Date of agreement	Date of Superintending Engineer's sanction
(1) Theperumala Moodaly	Constructing flush escape Cheyane Left Bank	16th August 1888	22nd August 1888
(2) K. S. Kuppusawmy Naidu and Streenivasalu Chetty	Cutting bed and banking Muckeri Channel	30th July 1888	3rd September 1888
(3) P. Streenivasalu Naidu	Repairing the bund of Maracada tank	14th May 1888	15th June 1888
(4) T. Namasivaya Moodly	Clearing sand from the bed of Karrepauk Main Channel	do	do
(5) Myratha Moodelliar	Repairing the bund of Cholavaram tank	12th April 1888	26th April 1888

21. In the Miscellaneous Advance Account there was on the date of Examination Rs. 13-0-0 representing the value of 20 blank stamped agreements of these only 21 were produced the other 5 being explained away thus:-

1 issued to Contractor Namasivaya Moodaley.

1 written up (the agreement of Parasarama Moodaley from whom recoveries has yet to be made) prepayment should be obtained in such cases.

3 spoiled and consequently sent to Collector for refund of their value.

10

22. The schedule of rates is dated 1884-85.

The rates in some of the recently sanctioned estimates were

were compared with those of the schedule and were not found to agree.

	As per schedule			As per sanctioned estimate		
	Rs	As	P	Rs	As	P
Concrete	10	8	0	9	0	0
Gravel	1	6	0	1	0	0
Turfing	0	5	6	0	4	6

The schedule is stated to be under revision.

23. The Registor of Buildings does not include the following buildings recently completed and handed over to the Departments concerned.

(1) Police station at Pallikondu.

(2) Sub Registrar's Office at Thiruvalam

24. The divisional consolidated return of tools and plant for the half year ending 30th. September 1888 was compared with the sub divisional returns and the following discrepancies were noticed.

	As per Consolidated return	As per Sub. Divisional return
Mamoties	819	816
Levelling Instrument Dumphy with Staff and	10	8

25. The Divisional Code is not posted up to date. The last standing order posted is 232 of 1887.

26. The grant of three months sick leave to Supervisor Vettivelu Pillay from 1st. December 1888 is not noted in his service book. 2880

27. In the service book of V. Arunachella Moodaley Superintendent Ponnai Anicut his pay is entered as Rs. 20-0-0 where as his actual pay is only Rs. 19-8-0.

28. The entries in the service book of Saroem Vasoor Munisawmy regarding name of appointment, pay etc. are not signed by the Head of the Office.

29. The following service books require reattestation:-

Name and rank	Date of last attestation.
R. Vadivelu Lascar	28th May 1883
P. Munisawmy Lascar	8th June 1883
T. Veneatachellam Lascar	28th May 1883
P. Chengalroyen Lascar	28th May 1883
A. Loganatha Mudt. Clerk	9th January 1884
V. L. Runga Rau Clerk	1st September 1883

30. Allabad Anicut Superintendent Kuppusawmy Naidu is on leave but no entry is made in his service book regarding it.

31. In the case of thirty four service books attestation ~~should~~ has been by Upper Subordinates or others not in charge of divisions. It is thought that the attestation should be by the Executive Engineer himself.

11

1/942
3-89

32. Service books have not been but should be opened for the following individuals:-

Name and rank	Date of appointment
Narayanasawmy Lascar	17th January 1889
Apogian Lascar	24th January 1889

33. The claims to Travelling Allowance of Lower Subordinate office and petty establishment for March and October 1888 inclusive were audited.

The memoranda of claims do not show the movements of the claimants and have not generally been signed by the Executive Engineer in token of his approval.

34. × × × × × ×

Chettipett
25th to Feby 1889

(Sd) E. Rainier
Inspecting Officer.

No. 506 J 17th April 1889

Forwarded to the Secretary to Government P. W. Department for information and orders of Government with the accompanying summary and remarks.

2. Special attention is invited to items 12,13,17 and 23 which deal with matters noticed also in the report of the last inspection of this division.

(C. No. 93.)

Division North Arcot Summary of Inspection Notes dated 25th February 1889.

280

Item No.	Para. of Inspection Notes.	Irregularity noticed.	Code or other order bearing on the subject.	Examiner's Remarks.
1	5	Irregular payment of salaries as a rule, before submission of bill to the Examiner's office for audit	473(2)	The Executive Engineer should explain this disregard of the code rule and should report whether it is now being observed
2	6	Irregular debit of 1882 item in Transfer to another Division 10 days before the payment was actually made	1882	The circumstances under which the amount was transfered before actual payment should be explained
3	7&8	Failure of Executive Engineer signing or initialling 19 vouchers	311	If the vouchers are in support of entries in the Executive Engineer's cash book or in the account of an imprest holder holding directly under him they should have been signed by the Executive Engineer
4	9	Failure to produce 19 vouchers at the inspection 9 of which were due to the return to payees for signature	1642 1907	The Executive Engineer should state whether the vouchers returned to payees for signature as well as the other vouchers not produced at the inspection have since been received back, and explain why the signature of payees were not obtained at the time of payment.

Item No.	Para. of Inspection Notes.	Irregularity noticed.	Code or other order bearing on the subject.	Examiner's Remarks.
5	10	Failure to post outlay on repair of Gold and Plant in the Register of works.		The necessity of posting such outlay in the register of works will be separately considered, and separately reported upon if necessary.
6	11	Failure to note appropriation for Major works in the Register of works.	1066 Rule IV	The Executive Engineer should report whether this is now being attended to.
7	12 & 13	Failure to post outlay by items of work in the Register of works in the case of mine & works estimated to cost over Rs 2500/-, because no work voucher is required.	1066 Rule V	The outlay on works estimated to cost more than Rs 2500/- should be posted in the "Register of works" in accordance with the rules in Code para 1066 (v). The submission or non-submission of a work voucher has nothing to do with the matter. The Executive Engineer should state whether the rule is now being observed.
8	14 & 15	Measurement sheet in a certain case not an exact copy of Measurement Book and corrections made in the measurement sheets in the Divisional office not		It should, I think, be an understood rule that corrections — at any rate those increasing the payment due — should not be made without first ascertaining from the subordinates concerned where the error really lies, otherwise

Item No.	Para. of Inspection Notes.	Irregularity noticed.	Code or other order bearing on the subject.	Examiner's Remarks.
		not communicated to the officer in charge of work in two cases.		serious overpayments may easily result. In the present cases the amounts involved are trifling but that is an accident. If the correction results in an underpayment it is better to make it, as if wrong it is certain to be pointed out. In other words, whenever there is any room for doubt the smallest of all the possible sums should be paid. The overpayment should of course be recovered.
9	16	Irregular entry of a cheque drawn but not paid away in the cash book and failure to maintain a Register of cheques drawn but not paid away.	1744 Audit & Acc	The Executive Engineer has since stated that the rules on this subject are now being observed.
10	17	Failure to adjust an item of unclaimed arrears of labour	1750 Existing Order No. 988.	13 As the amount has been due for more than six months and there is apparently no likelihood of its being claimed it should be credited to Provincial Revenues. Such claims lapse after six months.

Item No.	Para. of Inspection Notes.	Irregularity noticed.	Code or other order bearing on the subject.	Examiner's Remarks.
11	10	Failure of a Sub Divisional Officer to sign Measurement sheets submitted by him.		Though nowhere prescribed, it seems evident that measurement sheets should be signed or initialled by the Sub Divisional Officer who accepts responsibility for them. Orders are requested.
12	10	Failure to cancel measurement sheets	1708	The Executive Engineer should report whether this matter is now being attended to. The failure to cancel measurement sheets was also noticed in last report (please see paras 32 and 48 of report items 19 of summary)
13	19	Delay in billing for measured work in 14 cases	1924	The delays are in some cases very great and seem to require explanation.
14	20	Failure to obtain Superintending Engineer's prior sanction to acceptance of contracts in 5 cases in which the contracts were beyond Executive Engineer's powers of acceptance.	1350	The Executive Engineer should explain this disregard of the Code rule.

Para. of Inspection Notes.	Irregularity noticed.	Code or other order bearing on the subject.	Examiner's Remarks.
21	Failure to recover value of stamped agreement forms issued to two contractors		The value of the stamped forms should have been recovered from the contractor when the agreements were drawn up. It should be recovered now.
22	Schedule of rates 900 not up to date		Apparently it is desirable that the Superintending Engineer should look into the matter and consider whether the schedule of rates requires revision.
23	Failure to enter in the Register of buildings two buildings lately completed ~~completely~~ Completed	975	The Executive Engineer should complete the Register of buildings and report accordingly. The incomplete state of this Register was brought to notice in last report. Also (see para 62 item 33 of summary)
24	Discrepancies in the Cash and Plant returns	1702	The Executive Engineer should explain the discrepancies and have them rectified and report when this has been done.
25	Divisional office copy of A to D Code not kept up to date	840	The Executive Engineer should satisfy himself periodical inspection that the office copy of the Code is kept up to date and

Item No.	Para. of Inspection Notes.	Irregularity noticed.	Code or other order bearing on the subject.	Examiner's Remarks.
				and should make some one clerk responsible for posting it.
20	26 & 30	Failure to note leave granted to subordinates in their service books in two cases.	864	The service book should be completed and the Executive Engineer should report when this has been done.
21	27	Salary of an Assistant Superintendent incorrectly entered in his service book.	864	The service book should be corrected and the Executive Engineer should report when this has been done.
22	28	Certain entries in a service book not signed by the Executive Engineer	864	All entries in service books should be signed by the Executive Engineer, the head of the office in the case of a S. & D. Division.
23	29	Want of re-attestation to service books in 6 cases.	864 Note 1	The service books should be re-attested and the Executive Engineer should report when this has been done. Want of re-attestation in the case of service books was also noticed in last report (Please see paras 69 & 73 item 36 of summary)
24	31	Service books irregularly attested by subordinates and others in 34 cases	864	Service books should be attested by the Executive Engineer the head of the office in the case of a S. & D. Division and the Executive Engineer should report when this has been done.

Item No.	Para. of Inspection Notes.	Irregularity noticed.	Code or other order bearing on the subject.	Examiner's Remarks.
		and not by the Executive Engineer		
25	32	Failure to open out service books in two cases.	864 and Govt. Pensions Code Instruction 139	The service books should be opened out and the Executive Engineer should report when this has been done.
26	33	Memos of claims for Travelling allowances on behalf of members of the Lower Subordinate Office, and Petty Establishments do not show movements of individuals and are not generally signed by the Executive Engineer.	Code para 871 Govt. Travelling Allowance Instruction No 18.	This should be attended to, as without this information the claims cannot be audited by the inspecting officer. These memos should also be signed by the Executive Engineer in token of his approval of the claims.

Madras
April 1889

Major R.E.
Examiner of P.W. Accounts, Madras

15

Item No.	Para. of Inspection Notes.	Irregularity noticed.	Code or other order bearing on the subject.	Examiner's Remarks.

EXECUTIVE ENGINEER
20 MAY 89
P.W.D.
NORTH ARCOT DIVISION

18 AUG

SUPERINTENDING ENGINEER'S OFFICE.

No. 3206 V Circle, Madras, 2880.

Vellore (Camp), 9th August 1889.

From Colonel W.H. Burton R.E.

SUPERINTENDING ENGINEER, V CIRCLE,

To THE Chief Engineer

P.W.D. Department

Sir,

Enclosures. 2.

1 Inspection notes

1 Summary of Examiner

With reference to G.O. No. 1170 W dated 1st May 1889 I have the honor to forward herewith the Inspection Notes of the North Arcot Division with Summary of the Examiner No. 506 dated 17th April 1889 with explanation of the Executive Engineer and my remarks thereon.

2. With reference to Item No. 11 of Summary the Executive Engineer should have not acceptd the measurement sheets without the signature of the Sub Divl Officer and that measurement sheets may be cancelled being Copies of contents of measurement books required to be cancelled by note 1 printed in Form No. 19 and Code para 1756

3.

3. As to reference to item 16 of Summary the Schedules of rates have been twice revised in 1886-87 and lastly in 1889-90 the latter will be submitted to Chief Engineer. In the Current schedule for 1889-90 there are various descriptions of Concrete provided varying in Cost and in accordance with localities from Rs 9 to 16. The rate for gravel may vary in reference to the distance of Carriage; it is provided in the schedule from Re 1 to Re 1-8 Turfing. the rate provided is from annas 4 to annas 5½.

I have the honorable
Sir,
Your most obedient servant
W Burton
Colonel &
Superintending Engineer Circle

17

726
18 AUG
ENGINEER-IN-CHIEF'S
W. ACCOUNTS

No. 3686 C dy 15th Augt. 1889

To C

For perusal and favour of return, and for remarks if considered desirable.

3686 C/1578/89 Work 15.8.89
1170 W/2578/89
2176 W/1717/88 A. Cr.

No. 1425 dy 5th October 1889.

To W.

I beg to return herewith — with remarks, the explanations from the Supg. Engineer 5th. Circle, and the Executive Engineer North Arcot Division in regard to certain items in the last inspection report of the — North Arcot Division sent with your office note No. 3686 C. dated 15th. — August 1889.

2. The Executive Engineer's further report regarding items 22, 23, 24 will be awaited.

3. The other items call for no remarks.

C.

Enc. 2

1595
Retd 7504

From

THE SUPERINTENDING ENGINEER,

V CIRCLE,

To

THE Chief Engineer
Ptr department

Dated 9th
Recd. 12 } August 1889.

Recd 7/10/89

X2

Enclosures 2

No. 3206

Inspection Notes of the North Arcot Circle with Summary of the Examiner's No 506 dated 17th April 1889 ——

(17) Returned with Explanation of the Executive Engineer and Supg Engineers remarks thereon. No 2830 dy Dec 10, 1889

S.E. V. 10/11/89

8.10.89

8.10.89