Public Works (1897) Department.

G.O., No. 2110 W

Dated 3. August 97

[Despatch Abstract.]

Safety of the Treasury Rooms at Narasaraopet and Sattenapalle: Sanction accorded to the Subdivisional Officer's certificate in regard to the — Kistna Northern Division being admitted in lieu of that of the D.C. Officer.

D.C. 28.5

[P.W. 25. 5,000—30-11-96.]

Indexed.

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

~~Public~~ Works (1897) Department.

CURRENT No. 6542

W 2110 W 23.8.97

Dft 13

Order

R.S.H 26.7.97

Sanctioned.

17/7/97

From Major W.L.C. Baddeley R.E. Supt Engr 2nd Cir.

No. 977 K.W.

Dated 2 July 1897

Received 5.7.97

Registered

Enclosures

Spare copies

SUBJECT.

Irrg. Rooms of Nanasarapatt and Sattenapalli Talug Offices. Requests Sanction of Govt: to admit the certificate by the S.D.O. of the Inspecting Sr as the EE had no occasion to inspect the Buildings.

S.E. II circle / D 4/8
Rev. depr. /

W

O L S. 290 R 29/7

H.L. 17.7.97 R 26.7.97 ... your ... D 1.8.97 ... Talug ... Inspg ...

BACK PAPERS.

No.	Date.

FURTHER PAPERS.

No.	Date.

Letter from Captain W. M. Stle R.E., Exec: Engineer, Krishna Northern Dv., to the Supdg Engineer, 2nd Circle, dy 29th June 1897, No. 233 S.E.

As I have not had occasion to visit Narasarowpett or Sattenapalli during the last six months I instructed the Assistant Engineer (Mr. Kharegat) in charge of the Sub D. to inspect the Treasuries and give certificates for the safety of the Treasury rooms. I see that under Code Vol I, Ch: III - 67, the sanction of Government is required for this procedure. I request that such sanction may be obtained.

Sattenapalli is an out of the way place where I have no works and the Narasarowpett Treasury is built to present standard plan.

Copies of certificates of Mr. Kharegat are enclosed.

No. 977 KW
2.7.97

Forwarded to the Chief Engineer, P.W.D. for favour of sanction of Govt: being obtained.

D 1/7/97 — Supdg Engr