

G.O., No. 80

DATED 25th Oct. 1895

INDEXED

ST. STEPHEN'S CHURCH AT BERHAMPUR

Communicating to the Ven'ble the Archdeacon Proceedings, Public Works Department, returning to the Superintending Engineer, I Circle, for sanction and execution, the estimate amounting to Rs.1400 for repairs to -- .

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.
50	5		27-1-96				
C	200		1896				

CURRENT No. 239
1895.

Public Works Department.

mu.

this

Order No 80 d/25-10-95
Comm^d to the Venble

the Archdeacon.

No. 2532 u

Dated 15th October 1895

Despatched

Received 16 - 10 -

Recd 18 - 10 -

30/10
22.10.95

22/10/95

SUBJECT.

St. Stephen's Church at
Berhampore.

Returning to S.E.T.
Circle for sanction and
execution, estimate
for repairing the

To the Venble the Archdeacon,
Madras.
dtd 31/10/95

CHIEF SECRETARIAT,

~~Madras~~, Ootacamund

24th September 1895.

OFFICE NOTE.

No. — 2237

From

THE CHIEF SECRETARY,

To

The Secretary to Govt.

P. W. Deptt.

In connection with the repairs to the Berhampore Church, an estimate for which has to day been approved and transferred to you, the Hon: Mr. Grose enquires "What repairs were executed in 1892? were the cracks noticed then? Will you kindly supply the information for communication to the H. M.?"

1895 J. F. Price

Chief Secretary

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

Endowment in the Ecclesiastical Department NO:2238
d/24th September 1895, on letter from the Venerable the Archdeacon of Madras No 2250d/26th August 1895.

Office Note from the Chief Secretary No:2237d/24th
September 1895.

Order thereon:— 2532 W of 15 October 1895

The estimate amounting to Rs 1400 for repairs to St. Stephens' Church at Bernampore is returned to the Suptg: Engineer I Circle for sanction and execution from the Repair grant to the Gangam Division under Provincial Civil works, which will be augmented if necessary.

2. The Suptg: Engineer will report what repairs were carried out in 1892, under the sanction given in G.O. No:1299W d/23rd April 1892 and whether the cracks now to be remedied were noticed then.

(True Extract)

Under Secretary to Govt: P.W.D.

The Suptg: Engineer I Circle
with 4 enclosures.

THE Examiner P.W. Accounts.
" Ecclesiastical Department.

[G
25]
50-6-8-04.

Ecclesiastical
Name DEPARTMENT.

C. No. 188

Am. M. G. M.

FOR ORDERS.

The Church was built about
the year 1867 by the Public
Works Dept and the amount of the
estimate was Rs: 92 66: in 1892 it
was repaired at an outlay of
Rs: 1070. The estimate now sent
up is for Rs: 1400 of which the
Venerable the Archdeacon says
that he can find Rs: 300 -
There must apparently have
been bad work to begin with.
The Church now appears to be
unsafe.

Should any inquiry be made or
should the estimate be approved

12/9/95

There must have been bad work
in 1867, but there seems to be
no alternative but to erect in
the same place now. What repairs
were executed in 1892? Were
the cracks noticed then?

13/9

14/9

FOR ORDERS.

C. No. 188

Order No. 2238 of 24.9.95

Approved & transferred to the
Public Works Department.
(Sd) by C.S.

vide also office note to O. No.
of 24/9/95, No. 2337.

When given for copying _____
When copied _____ } 189
When examined _____
When signed _____

READ AGAIN G.O., No.
189

DATE:

CURRENT No.

ENCLOSURES TO O. No.

ORDER OF GOVERNMENT

A A A A A A A

LETTER OF GOVERNMENT.

STATEMENT WITH DITTO.

PAPERS NOT FILED UP, BEING MEANT FOR DESPATCH
IN ORIGINAL.

N.B. -

- A = Copy in full.
- B = Not to be copied
- P = Copy abstract only.
- Q = Copy heading only.