

Ecclesiastical (1898) Department.

ORDINARY MS.

G.O., No. 95

DATED 27-7-98

INDEXED.

[Despatch Abstract.]

Coming to the Ven^{ble}
the Arch deacon from the Rev^d on end C. of
the Sup^r Engr 4th circle to bring letter from
the Executive Engr, West Coast Diocese,
reporting that an estimate of Rs
45 for repairing the bellfry of the Church
at Cochin has been sanctioned by him

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

Eccelesiastical (1898) Department.

CURRENT No 23



From Mr P.W. Deptt.

Order No 95, dt 27/7/98

Commnd. to the Venble the Archdeacon

No. 1829W

Dated 19.7.98

Received

Registered

Enclosures

Spare copies

Thereto: the Archdeacon (a) Dt 20.7.98

23/7/98

SUBJECT. Church at Cochin
Communicating endorsement of the S.E. IV in submitting copy of letter from the Ex Commr West Coast Dist: reporting sanction to an estimate of Rs 45 for repairing the roof of the

BACK PAPERS.

FURTHER PAPERS.

No.	Date.
Encl 5028	23-2-98 (also)

No.	Date.

Current No 238

PUBLIC WORKS DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following

Letter from C. W. Wood Esq. Executive Engineer West Coast Division to the Superintendent Engineer 4th Circle dated 30th June 1898, No. 333 S.E.

With reference to your Endorsement, No. 115 dated 13th March last, I have the honour to state that an estimate of Rs 45 has been sanctioned by me for repairs to the belfry of the Church at Cochin and that no further repairs requiring skilled supervision are needed to the building.

Endorsement thereon by the Superintending Engineer 4th Circle, No. 359 dated 7th July 1898.

Copy submitted to the Chief Engineer P. W. Department for information with reference to G.O. No. 575 W dated 4th March 98.

Order thereon No. 1829 W of 19.7.98.

Communicated to the Ecclesiastical Department with reference to endorsement No. 502 Eccles., dated 23rd February 1898. (True Extract)

A

As per order.
Undersecretary to Govt.

To The Secy. to Govt.