M.R.O. 1—77,006—8-6-37.

(1) Number of pages

(2) Date of repair 12-8-00

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Finance DEPARTMENT.

G.O. No. 174 Press Mis.

2-6-37 236-237

Dated 29-1- 1875.

7/8

Not to be folded or roughly handled

Municipal.

No. 236. Read the following letter from R. W. BARLOW, Esq., President of the Municipal Commission, Conjeveram, to the Hon. D. F. CARMICHAEL, Acting Chief Secretary to Government, Fort St. George, dated Conjeveram, 18th January 1875, No. 5 :—

In reply to G.O., Financial Department, No. 1990, dated the 30th November last, I have the honor to forward an extract from the Proceedings of the Municipal Commissioners of the 12th ultimo, and to report that I have personally inspected the pond in question.

2. The necessary measures have been taken to prevent the fouling of the same by the ground round it being used as a latrine, and the Municipal Commissioners have issued a notice to the owner to repair the wall at once.

3. I should add that the falling of this wall appears to have been caused by the defective drainage of the railway compound. The artificial embankment for the station interferred with the natural drainage, and no provision was made to supply the want, and the water stands to a considerable depth on the side near the pond after heavy rain. I have addressed the Consulting Engineer for Railways on the subject.

EXTRACT from the Proceedings of the Municipal Commissioners for the Town of Conjeveram, held on the 12th day of December 1874.

* * * * * * *

10. Read G.O., No. 1990, dated 30th November 1874, in the Financial Department, and the President's docket, No. 98, thereon.

As regards the pond nuisance alluded to in paragraph 6 of the Government Order, the Commissioners resolve to issue a notice to the owner, under Section 117 of the Municipal Act, to cleanse it and drain off the stagnant water, and, under Section 119, to erect a proper enclosing wall round the tank.

It is believed that the wall originally built came down on account of the railway authority failing to provide proper escapes for the rain water within the railway premises.

Resolved that a report be submitted to this effect.

(Signed) V. DORASAWMY IYER,
Vice-President.

No. 237. ORDER THEREON, 29th January 1875, No. 174.

Transferred to the Public Works Department, with reference to G.O., dated 13th November 1874, No. 3210, Public Works Department.

(True Extract.)

Acting Chief Secretary.

To the Public Works Department.

Exd. J. H. Burns.

Govt. of India.
FINANCIAL.
To
THE PUBLIC WORKS DEPARTMENT.
Dated January, 29th.
Read.
Encl.
G.O., 29th January 1875, No. 174.
JANUARY.
Nos. 136-137.
Conjeeveram Municipality.—The President's report on the state of the pond near the railway station transferred to the Public Works Department, with reference to the Order in that Department, No. 3210, dated 16th November 1874.

Extract from the Proceedings of the Municipal Commissioners for the Town of Conjeveram held on the 12th day of December 1874.

× × × × × × ×

10. Read G. O. No. 1990 dated 30th November 1874 in the Financial Department and the President's docket No. 98 thereon.

As regards the pond nuisance alluded to in para 6 of the G. O, the Commissioners resolve to issue a notice to the owner under Section 117 of the Municipal Act to cleanse it and drain off the stagnant water and under Section 119 to erect a proper enclosing wall round the tank.

It is believed that the wall originally built came down on account of the Railway Authority failing to provide proper escapes for the rainy water within the Railway premises.

Resolved that a report be submitted to

to this effect.

(Signed) V. Doras aumy Iyer
Vice President

(True Extract)

W W Bowden
President

Sd. Ex.

Chingleput District Collector's office
Camp Conjeveram, 18 January 1875

No 5

From

R. M. Barlow Esquire,
President of the Conjeveram Municipality,

To

The Honorable D. F. Carmichael
Ag Chief Secretary to Government F.D

Sir

In reply to G. O. F. D, No 1990 dated the 30 November last, I have the honor to forward an extract from the Proceedings of the municipal Commissioners of the 12 Ultimo, and to report that I have personally inspected the pond in question.

2. The necessary measures have been taken to prevent the fouling of the same, by the ground round it, being used as a latrine, and the municipal Commissioners have issued a notice to the owner, to repair the wall at once.

I

Ch a letter from the President of the Conjeveram Municipality dated 18th January 1875 No 5

In Fwd No 90 of 75.

3. I should add that the falling of this wall, appears to have been caused by the defective drainage of the Railway Compound. The artificial embankment for the station, interfered with the natural drainage, and no provision was made to supply the wank, and the water stands to a considerable depth, on the side near the pond after heavy rain. I have addressed the Consulting Engineer, for Railways on the subject.

I have the honor to be
Sir
Your most Obedient Servant

W W Pearson
President

P.T.O.

Himaira (1875) Despn
(Municipal)

From

The President M.C.
No. 96 Conjeeram

To

The Ag. Chief Secretary
to Govt. Y.D.

Dated 18 January, 1875.
Recd 20.

Enclosure one.

No. 5

Reports on the state of the pond near the Conjeeram Railway Station.

Mis. 30th Nov. 1874, No. 119 to 120

From

Engineer 25-Dec/74

Communicating the Public Works Estimate

Dated 4 S.O. No. 3710 Rupees

Public Works Depte 11 Circle
5 Dec 1874

No. 236-

Govt. of India Madras.

Irrl

G. O., 29 Jany 1875 No. 174

Nos. 236-7

Conveyance from the Road's
Report on the State of the Road
near the Ry Station, transfd
to the Rd, with ref. to the
order in that Dept. No 3210
of 13 Nov. 74.