

MADRAS RECORD OFFICE.

Government of Madras.

Insial DEPARTMENT.

G.O. No. 867	Press <u>MIS.</u>
Dated 27-5-40-1867	

225-566

Not to be folded or roughly handled

*Proceedings of the Madras Government, Judicial Department,
27th May 1867.*

No. 275. Read the following :—

Progress Report of Central Jail at Rajah-
mundry for March 1867, submitted by
the Acting Superintending Engineer,
1st Division. } (Dated 14th May 1867.)

	Rs.	A.	P.
Towers and Workshops.....	55	8	9
Radial Blocks, Barracks, &c.....	3,811	4	1
Jailer's Quarters and Out-offices.....	695	4	1
Palisading.....	3,577	8	11
Walls.....	1,417	11	8
Hospital and Stores.....	3,891	9	9
Latrines.....	54	0	11
Purchase of Stock.....	574	13	8
Unadjusted advances.....	8,537	0	9
	17,314	8	10
DEDUCT—			
On account of expenditure of previous			
month's stock and adjustment of ad-			
vances.....	4,300	4	4
Net amount...	13,014	4	6

Referred to the Judicial Depart-
ment.

2. The net expenditure during
March 1867 was Rupees 13,044 on the
items noted in the margin, and the total
outlay during the year, up to the 30th
idem, was Rupees 38,343.

3. The original allotment was Ru-
pees 36,679, and the progress made would,
therefore, appear to have been satisfac-
tory.

(Signed) C. A. ORR, Colonel, R. E.,
Secretary to Government, P. W. D.

23rd May 1867.

No. 276.

ORDER THEREON, 27th May 1867, No. 867.
Communicated to the Inspector General of Jails.
(True Extract).

Chief Secretary.

To the Inspector General of Jails.

Exd. J. Tulloch.

Report of the Central Jail at Peshawar for the month of March 1887.
Work performed in this month upto this month

Item	Quantity	Rate	Amount	Quantity	Rate	Amount	Remarks
4. H. K. K. K.							
Rough stone in Chumam	Cyds 1478 ¹ / ₂	3	4431 50				
Plastering with lime & mud	Sqrs 220 ¹¹ / ₁₀₀	22	484 22				
Whitewashing in Chumam	Sqrs 261 ²⁴ / ₁₀₀	3	783 72				
Flooring with brick on edge	Sqrs 192	7 4	1392 00				
Excavating foundation & filling			154 00				
Deal wood wrought and put up	Cft 3540 ¹² / ₁₀₀	2 4	8196 00				
Wood Oil & Coals	Sqrs 292	1	292 00				
Cut stone over pillars heads	Each 152	1 4	190 00				
Contingencies	84	1 8	126 00				
			1957 12				
			217 00				
5. Partition wall between Centre pillars							
Rough stone in Chumam	Cyds 185 ² / ₄	3	555 00				
Contingencies			91 64				
Whitewashing	Sqrs 67 ¹⁰ / ₁₀₀	3	12 90				
			660 00				
6. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
7. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
8. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
9. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
10. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
11. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
12. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
13. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
14. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				
Contingencies			256 13 6				
Flat arch work	129		24 3				
Arched roof work	73 ¹ / ₂		184 14				
Making Embossures	36	1	36 00				
			2508 00				
15. Towers							
Rough stone in Chumam	Cyds 405	3	1215 00				
Plastering with brick on edge	Sqrs 5 ⁹ / ₁₀₀	7 4	40 10 6				
Whitewashing in Chumam	109	3	20 7				
Excavating foundation & filling			15 00				
Bricks in Chumam	Cyds 89 ⁹ / ₁₀₀	4	357 5				
Iron work	Sqrs 10 ¹² / ₁₀₀	22	233 9				
Deal wood wrought and put up	Cft 52 ⁶ / ₁₂	2 4	118 2				
Wood Oil & Coals			6 00				

Work done

Plough & harrow in Chumam	Cyts	34 ¹³ / ₂₇	2	100
Arch work in	Cyts	152	3	25 5
Terracing with brick on Edge	Cyts	20 ⁸² / ₁₀₀	18 10	250 41
Whitewashing in Chumam	Cyts	15 ²⁵ / ₁₀₀	7 4	102 5
Stone Columns	Each	12	12	9
Cornice work in Chumam	Cyts	12 ⁷ / ₂	4	150
Wooden Stair Case Comp. etc.				80
Excavating foundation & filling in				78
Country wood shutter doors with frames and iron fixtures		3	25	40
Country wood shutter windows shutters with frames and iron bars & Comp. etc.		8	15	120
Teak wood wrought and put up	Cyts	333 ⁵ / ₁₂	2 4	750 76
Cut stone over pillars heads	Each	12	1 8	18
Wood oil 3 Coats	Cyts	13	1	13
Red paint 3 Coats	Cyts	5 ¹ / ₂	1 12	9 10
				3009 15

Upper Story

Brick in Chumam	Cyts	154 ¹³ / ₂₇	4	518 108
Flat arch work	Cyts	116 ¹ / ₂	3	21 136
Cornice work in Chumam	Cyts	12 ⁷ / ₂	4	31 14
Terracing with brick on Edge	Cyts	21 ⁷² / ₁₀₀	22	477 135
Whitewashing in Chumam	Cyts	71	3	13 5
Stone Columns	Each	12	12	144
Cut stone over pillars heads	Each	12	1 4	15
Teak wood wrought and put up	Cyts	333 ⁵ / ₁₂	2 4	750 46
Country shutter doors with frames and iron fixtures 8" 8 x 6		3	25	78
		2	20	40
Carried forward				

Total - 31/7/13 2 same as last reported

Teakwood Joists (40) Brought forward				
Iron doors with wooden frames 8' - each	cft	250	2 4	562 8
Wood Oil 3 coats to the Joists		320	60	19200
Lead Colour 3 Coats to the wheller beams and Iron doors				25
Pad Locks	300	2 6		712 8
Contingencies	No	360	8	2880
				8135 12
				92335

47 2 2
 156 10 9
 37 8
 6163 15 9
 35824 3 4 Same as last reported
 Total 71315 5 2
 Actual Expenditure 119 2 9

Solitary Cells for women				
Rough Stone in Chumam	Cyds	1513 ²¹ / ₂₇	3	4541 54
Arch work in	cft	112 ¹ / ₂	3	77 51
Terracing with brick on Edge	Sqrs	76 ⁸⁰ / ₁₀₀	22	1689 91
Flooring with		54 ¹² / ₁₀₀	7 4	392 51
Excavating foundation & filling the basement				140
Teakwood wrought and put up	cft	7753 ⁴ / ₁₂	2 4	1746 10
Iron doors with wooden frames 4' - each		40	35	1400
Wood Oil 3 Coats to the Joists				60
Lead Colour 3 Coats				40
Contingencies				1016 310
Whitewashing				69
Cut Stone over pillars heads	368	3		47 8
	38	1 4		11220

Total 7439 11 10 Same as last reported

Sailors Quarters				
Rough Stone in Chumam	Cyds	465 ¹² / ₂₇	3	1396 53
Arch work	cft	409 ¹ / ₂	3	76 12 6
Terracing with brick on Edge	Sqrs	26 ¹⁵ / ₁₀₀	22	575 154
Flooring with		24 ⁴² / ₁₀₀	7 4	177 8
Pairs Panelled section doors 7' - complete		4	22	88
Doors		10	18	180
Excavating foundation & filling		16	11	176
Carries forward				22

30 17 65 ⁸⁸/₁₀₀
 9 5 013 12 2

Thought forward

I thought forward					
Teak wood wrought and put up	cft	334 $\frac{1}{2}$	2	4	753
Wood oil 3 Coals to the beams and Sails					20
Red paint 3 Coals to the doors and windows					35
Cornice work					41
Contingencies	Apr	156 $\frac{1}{2}$	4		359
Whitewashing					22
Cut stone over pillars heads		121	3		3
Planks and Nails		3	1	4	2
Out Office for Sailor					3930
Rough stone in Chumam					327
Flat Arch work in Chumam	Apr	107	3		21
Flooring with brick on Edge	cft	112 $\frac{1}{2}$	3		24
Terracing with brick on Edge	Apr	3 $\frac{35}{100}$	7	4	104
Country wood batten windows with frames and iron fixtures & complete 2-6 x 3.3		4 $\frac{75}{100}$	22		18
Painting Country wood batten doors		3	6		48
Excavating foundation &c					6
Teak wood wrought and put up	cft	29 $\frac{3}{12}$	2	4	65
Contingencies					62
For pangs and Chimney					400
Cornice work					3
Whitewashing		13	4		5
Roofing with reapers &c		30 $\frac{68}{100}$	3		11
Country wood Necessary Seat		9 $\frac{3}{100}$	12		16
					1120

3521 7 7 Same as last reported
Total 4135 3 9

. 83 58 158
 11 79 38 46
 9 87 102 88 *Converted to white in March*

7 4 3
81 6 15. x ^{including} 3-8-11 Shell Churnam both

29.
669 11 10 Same as last reported
Total 10 18 12 5

This Estimate
was cancelled

Carried forward

Concrete Work Brought forward
 Excavating foundations &c
 Contingencies
 Rough Stone in Chumam
 Painting in Chumam

651

Enclosure Wall
 Rough Stone in Chumam 3 205 12 1/2
 Brick in Chumam 4 3422 1/2
 Brick in arches 5 1753 1/2
 Concrete work over arches 1 12 1/2
 Whitewashing in Chumam 3 255 1/2
 Broken bottles in 3 255 1/2
 Wrought Iron Railings 2 1375
 Fixing and setting up 300
 Red painting to Iron Railings 200
 Excavating foundations and filling 280
 Contingencies 693
 Scaffolding and Sundries 1100
30064

Paints &c
 Broken bottles in Chumam
 Contingencies

Inner Partition Wall
 Rough Stone in Chumam 3 7589 1/2
 Whitewashing in 3 80 1/2
 Carried forward

120909 3 1

8

This Estimate was
 Cancelled

Total 717 15 7 Same as last reported

47 1 13 85 4 6 11892 5/27 2 5 4 27765 5 71 12-13-4 Rough Stone
 55 5 12 11 319 6 10 243 15/27 5 15 1446 7 3 64-3-10 Lime
 115 5 6 753 3 8 4428 14 3 Same as last reported
Actual 209 1 7
Actual Expenditure 310 15 3
Total 34393 15 7

Total 43 15 Same as last reported

156065. 9

15665 " 9

Brought forward

Excavating foundations and filling the basement
Broken bottle in Chumam
Contingencies

100

711
8541

Palisading
Wooden railings complete
Masonry work
Painting
Contingencies

Rft 1532 2 5 3830
560
150
540
5080

595 513 113483 141 1810
118 . 12 . 88 12 1 165 ^{23 1/2}/₃₇
414 9
Actual 1591 14 11
1575
Actual Expenditure 16 14 11

Total 4226 10 9 Same as last reported

4 4 11 7854 8 7
4 24 687 8 7
265 1 11
118 13 . Same as last reported
Total 8876 . 1

Well
Earth work

do 2237 1 4 190
do 620 1 6 58
do 2118 ¹¹/₁₅ 2 5 320
do 2400 7 1050
Pailing water and sinking well frame 422
Value of well frame 483
Cut Stone in Chumam
do 40-5 27 11 1167
do 40-5 22 6 11 901
do 40-5 18 4 724
do 16-2 17 8 281
do 24-3 17 8 421
do 36-4 1/2 16 14 610

Filling in out-side of Steering 6600 1 412
Contingencies 355
Clearing Jungle
Machine

1161
Actual 1161
Actual Expenditure " " "

1161 1161 Machine
7910 6 10 Same as last reported
Total 9071 6 10

Carried forward

178239 2 5

Workshop Brought forward
 Iron pipes

Cistern
 Rough Stone in Chumam
 Brick in do
 Plastering
 Contingencies

Parapet Wall outside top of workshop
 Brick in Chumam
 Plastering
 Whitewashing

Centrewall under Upper Shop
 Iron pipes

No 10 Radial block on G. Danock
 Iron pipes
 Black up Iron doors No 2
 Windows work No 10
 Wall Venetian shutters
 Tying Trusses
 Cut Stone flooring
 Roofing with reapers flat & pentates
 Repairing Ventetator
 Red washing

Carried forward

1923 2 5

Total 13 11 3 Same as last report

Total 148 7 3 Same as last report

Total 13 2 4 Same as last report

Total 130 14 1 Same as last report

11 ⁷⁵ / ₁₀₀	24	15	9	293	11	10	55 ²⁵ / ₁₀₀	8	8	10	172	3	3
56	50	12	9	284	4	12	8	194 ¹³ / ₁₀₀	16	7	325	4	7
						1	10	3			5	12	6
78		25		12					78		2	5	12

Actual Expenditure 3152 3 9
 Deduct 2 1
 Actual Expenditure 3128 3 9

Total 5044 14

Brought forward

(1) Parapet wall outside of Radial No. 1

(2) Mulk in Chumam

(3) Plastering

(4) Whitewashing in Chumam

(5) Temporary sheds for Vahingona

(6) Bamboo ladders

Sailors Quarters
Plastering walls
Plastering floor
Clearing foundation

Sues roof work R. Shop
 Plastering walls —
 Repairing windows with Iron bars —
 Making alterations to 3 wards —
 Flat arch work —
 Red washing —
 Cornice work —

Enclosure Wall
Painting in Chumam:

Publishing
 © Massey, 1901
 Publishing Foundation

[illegible]

. . 114 158 x ^{including} 11-10 Cornbers

 . . 3 23
30253 Corns as last reported
Total 42072

Total 6421 cameras last reported

Total = 8 - common subject / 6 / 8 / 10

82 — *Small* — "

13553 3

Brought forward

Ventilation windows	Rs	4	16	"	64
Glazed windows		1	16	"	16
Wood Oil for timber roof and for doors					45
Excavating foundation					40
Scaffolding and Contingencies					725 8 9
					12500

Out Houses of Hospital

Cook House of " " " "

Rough Stone in Chumam

Concrete work

Store house of Hospital

Rough Stone in Chumam

Concrete work

Out Offices for Sailor

Red washing

Plastering on Terrace

Solitary work shed

Excavating foundation

Contingencies

Temporary Latrine for A Bama R

Rough Stone in Mud

Roof work

Contingencies

Carried forward

155533.3

136 1 9

3739 8 6

1264

2475 8 6

161 113

5 43 Same as last reported

Total 4359 67

1 11 85 10 10 57 27

11 1 6 14 10 10

1 11 85 10 10 Concrete finished 76 in hand

11 1 6 14 10 32

Total 92 9 8

1 75 54 3 5 37

11 4 5 4 2 7 1/2

1 75 54 3 5 87 in

11 4 5 4 2 30 in

Total 59 7 7

1641

26 2 8 16 41

26 1 1 6 15

3 9

Desert 2 8

Actual Expenditure 1 1

88 4 1 12 88

5

26 28

26 1 1

Total 39

4 1 12

5

Total 6 12

16 12

10 13 1 16 12

6 4 5 6 4 6 9 38

2 13 7

10 13 1 Concrete finished 85 in hand

6 4 5 6 4 6 7

2 13 7

Total 72 3 1

Brought forward

Building Cistern for LaPrue
Rough Stone in Chumam
Mortar in Chumam

C Barrack
Floor work

G Barrack work shop
Concrete work

Cook house for G Barrack
Roof work
Contingencies

H Barrack
Roof work

Total

Whole Expenditure 13242 11 2

Deduct 4277 55

Actual Expenditure 8965 59

190177 2

14

9 55 : : : : :
2 8 5 : : : : :
Total 11 13 10

Concrete of which 16 inch

59 2 : : : : :
59 2

9 13 8 : : : : :
9 13 8 Concrete of which 27 inch

25 2 8 : : : : :
5 11 2 : : : : :
Total 30 13 10

112 59 : : : : :
112 59

Carried forward

190401 1 3

190401 / 3

Stock payments - Brought forward

1	Rough Stone	
2	Flowering Stone	Gr
3	Polosoolcouce Quarry Rough Stone	Gr
4	Firewood	Tons
5	River Sand	Gr
6	Shell Churnam Pots	Tons
7	Crowbars	Gr
8	Hatchets	"
9	Hammers	"
10	Shovels	"
11	Iron borings	"
12	Flat files	"
13	Pad Lock	"
14	Iron bars	"
15	New Liner Film	Gr
16	Asphalts	"
17	Manufacture of Bricks	"
18	Measuring Paras	"
19	Wheel barrows	"
20	Rafts	"
21	Hip Rafts	"
22	Dress Summers	"
23	Gun powder	Gr
24	Match	Gr

24 $\frac{3}{16}$	97	14	710	24 $\frac{3}{16}$	97	14	710
				2414	3	43	13
				217 $\frac{6}{18}$	101	138	11
763	26	179	108	763	26	179	108
1-4	2145	333	1-4	2145	333	1-4	333
				735	78	345	152
				12	1011	20	29
				16	15	15	
				27	8	13	8
				31	112	21	122
				2	115	1	611
				6	104	3	14
				67	15	127	125
33 $\frac{1}{2}$	13	29	33 $\frac{1}{2}$	13	29		
				4134	277	28	
				4190	7	164	92
55763	611	367	13955763	611	367	139	
				6	3	139	2327
				6	8	142	5352
				101-2	1	28	1284
				4-3	1	35	5
				213	137	181	
10	24	174	10	24	174		
50	3	126	50	3	126		
							2135134

Unadjusted

Total whole
9. each

Expenditure of last Month
 — 00 — from last Month
 — 00 — by sale of Materials

Advances	13340 5 5	8420 4 8
	3537 . .	178963 2 10
	<u>17077 3 5</u>	76 8 11
	17344.8 18	198836 11 11
Expenditure	<u>17354 8 18</u>	

J. Rubeey Captain B.C.
Acting Superintending Engineer - 1st Divⁿ

Lt. Engineers Office / Division
 Camp Douglas, Ill.
 Nov. 11, 1859

Laundry for the month of March 1857.

17

Work performed in this month Work performed
up to this month

Account	Quantity	Rate	Amount	Quantity	Rate	Amount	Stamps
---------	----------	------	--------	----------	------	--------	--------

29 May 1867 No 867.
 Communicated to the Inspector General
 of fairs.

W. J. F. Jones

275.296

To the Inspector General of fairs and 29/5

From 27 May

The Works Exposed

To the Secretary to Govt

D. P. W.

Recd 14 May 17

Recd 20 May 17

Recd 25 May 17

Progress Report of

General J. A. &

Department of

March 17.

with in 1867

Department.

Reported to the Inspector

March 1867 and Refused 13,044 on the items

Wine and Whisky 55-3-9

Retail 100 to 100 3511-4-1

Wine 100 to 100 695-4-1

Wine 100 to 100 3577-8-11

Wine 100 to 100 1407-11-8

Wine 100 to 100 3891-9-9

Wine 100 to 100 84-0-11

Wine 100 to 100 574-13-8

Wine 100 to 100 3537-0-0

Wine 100 to 100 17344-8-10

Wine 100 to 100 4,300-4-4

Wine 100 to 100 13044-4-6

noted in the margin
 and the total within
 during the year 1867
 to the 30 " when was
 Refused 38,343.

The original
 statement was Refused
 36,679 and the balance
 made would then be
 appear to have been
 satisfactory.

W. J. F. Jones

Secretary to Govt

23rd May 1867
 J. A. & Co. General Department.