(1) பக்கங்களின் எண்ணிக்கை 4

(2) புதுக்கித் திருப்பிய நாள் 4/07

(3) ஆதாரங் குறிப்பவர் சுருக்கொப்பம்

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

துறை

அரசாணை எண். 379 — அச்சகம்

மு. கோப்புத் தாள் எண். — பல்வகை

~~387~~ 91

70-71

நாள் : 19- 12- 1861 199 .

மடிக்கவோ கண்டபடி கையாளவோ கூடாது.

ஆவண. கா. I—18,006—6-9-90.

பாதுகாப்பு பிரிவு - 1.

செப்பனிடுபவர் பெயர் க. கணி.

செப்பனிடுவதற்காக எடுத்துக் கொள்ளப்பட்ட நாள். 7-06.

செப்பனிட்டு முடித்த நாள் 4/07

பரிசோதிக்கும் முதல் இ.நி.பா.எ. கையொப்பம்

சரிபார்க்கும் இ.நி.பா.எ. கையொப்பம்

தொழில்நுட்ப உதவியாளர் கையொப்பம்

0

Proceedings of the Madras Government, Marine Department,
19th November 1861.

No. 70. Read the following letter from Commander F. W. HOPKINS, I.N., Commanding Her Majesty's Steam Vessel "Dalhousie" I. N.; to T. PYCROFT, Esq., Chief Secretary to Government, Fort Saint George, dated Madras Roads, 18th November 1861, No. 257.

With reference to my letter of yesterday's date No. 250, I have the honor to report that on taking out the Crank pin of one of the Engines it is found to be in a bad state and requires to be cut and refitted, which can be done by the Government Engineer's Department on shore here, and I beg to request that what is necessary to be done to it be completed with as little delay as possible.

No. 71. ORDER THEREON, 19th November 1861, No. 379.

The Chief Engineer is requested to afford Commander Hopkins the necessary assistance.

(Signed) T. PYCROFT,
Chief Secretary.

Exd. F. Carltedge.

No 257

From

Commander F. W. Hopkins I. N.
Commdg. H. Mas. S. V. Dalhousie

To

The Secretary to Govt
Chief Secretary to Government
Madras

Madras Roads D/ 18th November 186

Sir

With reference to my letter
of yesterday's date No 250 I have the
honor to report that on taking out the Gu
in a bad state and requires to be cut
refitted which can be done by the Governm
Engineers Department on shore here and
beg to request that what is necessary
be done to it be completed with as
little delay as possible.

I have the honor to be
Sir
Your most obed. Servant

F. W. Hopkins.

Commander
Comm. H. Mas. S. V. Dalhousie

Marine 1861 Dept.

From

The Commander

of the "Dalhousie".

257.

Dy 18th
Rcd 18th 3 Novr 1861.

No 387

States that the Crank
of one of the Engines is found
to be in a bad state & that
it requires to be cut & refitted
which can be done by the Ship
Engineers Dept here on shore
Requests that the necessary
repairs be completed with

Dalhousie

Dalhousie 257

No 379 Dy 19 Novr 1861.

The Chief Engineer is
requested to afford
Commander Hopkins the necessary
assistance.

[illegible]

The Chief Engineer
" Commander the
"Dalhousie"

dispd 19