

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

TAMIL NADU ARCHIVES

GOVERNMENT OF TAMIL NADU

DEPARTMENT

G.O. No.	360	Press.
B.P. No.	H. A. K.	Mis.
Dated	19. 5. 1986	1986

Not to be folded or roughly handled.

124-4-96. 703W. 812-3-96
 84-4-96. 1451W. 815-6-95
 e 830-3-96 182W. 824-6-96
 e 824-3-96

No. 457
 Dec 8.5.96
 Dec 18.5.96

360 Mar 819.5.96
 Communicated to
 Presidency. Lab
 Office for information.

Copy submitted to the
 Chief Engineer P. N. De =
 Department for information.

19/5/96

Column
 7.5.96
 L. Col. R. E.
 Ref. Engineer & Circle

in S.P.O.
 C.S.
 19.5.96

7th May
 1896

DEPT

No 192 DQ 16th May 1896
 Forwarded to the
 Marine Department
 for information and a favor
 of retention.

16/5/96

28/5 2006

15.96 o.s. 98 for the order

Report of Executive Engineer Negapatam Division on his inspection
of the Negapatam Light House on the 24th April 1896.

Name	Class	Height of centre of lantern above H. W. L.	Distance at what light is visible	Object of light	When lighting was last tested	Remarks.
Pegapalam Light House	Cata Dioptric 4 th Order	79 Feet	14 miles as per descriptive roll kept at Light House in clear weather	To enable vessels to approach anchorage	24 th April 1896	Inspected by Mr. C. Nathassabhapati Pillai Executive Engineer Pegapalam Division on 24 th March 1906

N. B. One of the lower ribs of the lens is broken and not replaced. It is reported that the necessary index has already been made by the Post Officer.

26th April 1896.