

Marine (1899) Department.

G.O., No. 8 Marine

DATED 3rd Jan^{ry} 1899.

[Despatch Abstract.]

Locanda Bar

Letter from the 1st Port Office forwarded in 9.
An extract from a report of the local Port Office regarding
the (admission) of the —, recorded.

27

Indexed. 3/1/99

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

CURRENT No. 1569

The Presy Tort officers,
Madras

No: 8 Mar 23.1.99

Reverend

W. H. H.

17-12-80

No. $\frac{1822}{456} 4$

Dated 16th December 1898

Received

Registered

Enclosures

Spare copies

SUBJECT.

Forwarding for information
an extract of a report
regarding the condition of
the Lacanada Bar.

No.

Date.

No.

Date.

No. 1882

456

Presidency Port Office,

Madras, 16 December 1898.

Heading

From

Commander H. A. Street, R. I. M.,
Presidency Port Officer,

Madras,

To

THE SECRETARY TO GOVERNMENT,

MARINE DEPARTMENT,

CHEPAK.

Sir,

I annex for the information
of Government extract of a report
dated 7th December 1898 from the
Port officer, Locanada, regarding
the condition of the Locanada Bar.

I have the honour to be,

Sir,

Your obedt. servant,

H. A. Street

Commander, R. I. M.,

Pres. Port Officer

Extract

"Bar." - The Bar was sounded on the
19th and the least water found in

the fairway channel was 3 feet (reduced to datum) which shows a decrease of 6 inches of water since last month. There has been a considerable increase in the growth of sand outside the Groynes towards North, but in other directions the increase has been very small. The sand bank lying inside the channel along the North Groyne has not undergone any material change since last month. The foreshore to the North of the Groynes has slightly increased in an easterly direction, since last month, and the mouth of the drainage channel or creek which opened up this year has worked to the South during the month, and (as previously reported) has thrown out, a bar in front of the mouth which has increased in size.

the fairway channel was 3 feet (reduced to datum) which shows a decrease of 6 inches of water since last month. There has been a considerable increase in the growth of sand outside the Groynes towards North, but in other directions the increase has been very small. The sand bank lying inside the channel along the North Groyne has not undergone any material change since last month. The foreshore to the North of the Groynes has slightly increased in an easterly direction, since last month, and the mouth of the drainage channel or creek which opened up this year has worked to the South during the month, and (as previously reported) has thrown out, a bar in front of the mouth which has increased in size.

the fairway channel was 3 feet
(reduced to datum) which shows
increase of 6 inches of water since

Marine Department.

GENERAL
ACCOUNT.

Government (1898) of Madras.
PUBLIC WORKS.

Recd.

Regd.

1898.

Enclosures

Spare copies

G.O., No. 3111 W., 5th December 1898.

No. 4 Mar 31 77.

Communicated to the

Presidency Port Officer.

DECEMBER.

127 A.S.R.

To

The P.P.O.

Indent

Ordered that the — for a sand pump and bucket dredger required for the port of Cocanada, be forwarded to the Director-General of Stores, for early compliance.

2

No. 3111 W, 5TH DECEMBER 1898.

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

General.
Account.

READ—the following papers:—

From the General Superintendent, Public Works Stores, dated 10th September 1898, No. 145 C.E.

Endorsement from the Examiner, Public Works Accounts, dated 13th September 1898, No. 3163 B./B.

ABSTRACT.—Submitting indent for a sand pump and bucket dredger required for the port of Cocanada.

ORDER—No. 3111 W., dated 5th December 1898.

Ordered that the indent be forwarded to the Director-General of Stores for early compliance.

[Here enter No. 3112 W., dated 5th December 1898.]

(True Extract.)

(Signed) W. B. DEWINTON,
Secretary to Government.

To the Superintending Engineer, I Circle.

" Examiner, Public Works Accounts.
" Marine Department.