

1. Number of pages *6*
2. Date of repair. *26-7-3*
3. Initials of Reference: *G*

M.B.O. 1-22,400-22-11-20

MADRAS RECORD OFFICE.

Government of Madras.

Police DEPARTMENT.

G.O. No.	<i>57-57-81</i>	Press Mis.
<i>30-31</i> Dated	<i>26 2</i>	<i>18 57</i>

Not to be folded or roughly handled

Fort Saint George, Public Works Consultation of 21st July 1857.

No. 56. Read the following Extract from the Minutes of Consultation in the Judicial Department, dated 9th July 1857, No. 797.

Read the following letter from J. ROHDE, Esq., Inspector of Prisons; to E. MALTBY, Esq., Acting Chief Secretary to the Government of Fort Saint George, dated 30th June 1857, No. 238.

SIR,

I have the honor to forward copy of a letter from the Session Judge of Honawar, reporting that the walls of the new Jail are mud built, and have fallen down, and suggesting that they should be rebuilt in lime mortar; this is a building that I had no official intelligence about till I saw it in the end of 1855, my impression is that it was estimated for in lime mortar according to a standing order of the Department that no works should be executed in mud, and in my opinion some explanation is required. I am decidedly of opinion that the building should be in lime above ground and for 1 foot under ground.

The Government resolve to call upon the Chief Engineer to explain the manner in which the outer wall of the Jail was built, and to submit an estimate for its re-construction.

(True Extract and Copy.)

(Signed) E. MALTBY,
Acting Chief Secretary.

No. 57. ORDER THEREON, No. 1389; dated 21st July 1857.

Ordered to be communicated to the Chief Engineer.

(Signed) H. FORBES,
Acting Secretary to Government.

JUDICIAL DEPARTMENT.

No. 797.

Extract from the Minutes of Consultation under date the 9th July 1857.

Read the following letter from J. ROHDE, Esq., Inspector of Prisons; to E. MALTBY, Esq.,
Acting Chief Secretary to the Government of Fort Saint George, dated 30th June
1857, No. 238.


SIR,

I have the honor to forward copy of a letter from the Session Judge of Honawar, reporting that the walls of the new Jail are mud built, and have fallen down, and suggesting that they should be rebuilt in lime mortar; this is a building that I had no official intelligence about till I saw it in the end of 1855, my impression is that it was estimated for in lime mortar according to a standing order of the Department that no works should be executed in mud, and in my opinion some explanation is required. I am decidedly of opinion that the building should be in lime above ground and for 1 foot under ground.

(Signed) J. ROHDE,
Inspector of Prisons.

The Government resolve to call upon the Chief Engineer to explain the manner in which the outer wall of the Jail was built, and to submit an estimate for its re-construction.

(True Extract and Copy.)


Acting Chief Secretary.

To the Department of Public Works.
„ Inspector of Prisons.

Exd. F. Cartledge.

No 1389

Ordered to be com-
municated to the Chief
Engineers

BB

John A. George
21st July 1839 - }

Order No 1389 after
Cons 21st July

No 1437

Ordered from the Chief
of Fort in the West
Department.

Ordered 9th July 1839
No 153

From the Ch. Eng 21st July
Cons 288 in Cons

No 56157

Calling upon the Chief Engineer
to explain the manner in which
the outer wall of the fort at
Shrewsbury was built, and to
submit an estimate for its
reconstruction.

Order in Cons

No 1389. 21st July

Order to the Chief Eng. Cons 288