1. Number of pages. 10
2. Date of repair 14-7-37
3. Initials of Reference.
4
M.R.O. 1—82,406—32-11-30

MADRAS RECORD OFFICE.

Government of Madras.

Public & Police DEPARTMENT.

Con. 30.6.57

G.O. No. 1246 Press Mis.

31-32

Dated 25—6—18 57

Not to be folded or roughly handled

1-4

Fort Saint George, Public Works Consultation of 30th June 1857.

No. 31. Read the following report from Colonel C. E. FABER, Chief Engineer; to H. FORBES, Esq., Acting Secretary to Government, dated 2nd June 1857, No. 863.

Report H. on an Estimate prepared by the Acting Executive Engineer in charge of Vizagapatam, for constructing a wall on the inner side of the stone drain which bounds the compound on the north side of the church at Vizagapatam.

Amount of Estimate, Rupees (460) four hundred and sixty, comprising the following items:

$88\frac{8}{9}$ Cubic yards Rough stone in Chunam @ R. 1 As. 2 ₱ cubic yard...	100
$124\frac{4}{9}$ Cubic yards brick in Chunam @ 2 Rupees	249
51-20 square Plastering and white-washing @ R. 1 As. 8...	77
Excavating foundation...	9
Sundries including fractions...	25
Total Rupees...	460

1. The wall is to be 320 feet long, and 7 feet high, raised on a foundation sunk 3 feet.

2. The Estimate has been prepared in accordance with the order of Government conveyed in Extract Minutes of Consultation No. 271, dated 6th February 1857, which was communicated to the Acting Executive Engineer with Extract from Proceedings No. 10175, of the 10th Idem.

3. The submission of the estimate, which has now been received with the Collector's countersignature, was delayed by the Acting Executive Engineer, pending the result of a correspondence which he understood was being carried on between that Gentleman, and the Reverend Mr. Griffiths.

4. The rates allowed for the work are moderate and sufficient, and the Chief Engineer recommends the estimate for entry in the Budget of 1858-59.

No. 32. ORDER THEREON, No. 1246; dated 25th June 1857.

With this report, the Chief Engineer forwards in pursuance of Extract Minutes of Consultation of the 6th February last, No. 271, an estimate for constructing a wall on the inner side of the stone drain which bounds the compound on the north side of the Church at Vizagapatam, but no provision has been made in it for removing the Stables and Pound as required in the subsequent order of 22nd May 1857, No. 978, which appears to have been lost sight of in the Central Office when sending up the above estimate. The Chief Engineer will be requested to obtain and forward a revised estimate supplying the omission now pointed out.

(Signed) H. FORBES,
Acting Secretary to Government.

Vizagapatam
Ecclesiastical
Burial Ground

No 863 Engineer

Report on an Estimate prepared by the Acting Executive Engineer in charge of Vizagapatam for constructing a Wall on the inner side of the stone drain which bounds the compound on the north side of the Church at Vizagapatam.

Amount of Estimate Rupees (460) four hundred and sixty. Comprising the following items.

55 9/16	Cft. Gts Rough Stone m/s Chunam @ Rs 1-2 per Cft	100----
214 3/9	Cft. Gts brick m/s Chunam	218-2/4----
5	20- Square Plastering and White washing @ 1-8	77----
	Excavating foundation	9----
	Sundries including fractions	25----
	Total Rupees	460----

1.- The Wall is to be 320 feet long, and 7 feet high raised on a foundation sunk 3 feet.

2.- The Estimate has been prepared in accordance with the Order of Government conveyed in Extract Minutes of Consultation No 271, dated 6th February 1837, which was communicated to the Acting Executive Engineer with Extract from Proceedings No 10175, of

the

the 10 ideml.-

3.. The submission of the Estimate, which has now been received with the Collectors countersignature was delayed by the Actg Executive Engineer pending the result of a correspondence which he understood was being carried on between that Gentleman and the Reverend Mr Griffiths..

4.. The rates allowed for the works are moderate and sufficient, and the Chief Engineer recommends the Estimate for entry in the Budget of 1858/59..

Central Office of Rds
Fort St George
2nd June 1857.

Lieut Colonel
Chief Engineer

Sd
Dy Sup. Engr N.C.

To the Secretary to Government
P.W. Department

List of Enclosures
No 1 Letter from the Actg Exe Engr dated 9 May 1857 No 376
No 1 Abstract Estimate

299

Cons: 6th February 57 No 1864 117.
" 26th May " " 25726.

Public Works 1857 Deptt
Dto Cons 30th June
No 1147

H

From
The Chief Engineer
To
The Secretary to Government
P.W. Department

Dated 22nd
Recd 4th June 1857.

2 Enclos. Returned

Sec No. 1246. 25th June

No 863

Respecting an Estimate of Rupees (460) four hundred and sixty, for constructing a Wall on the inner side of the Stone drain which bounds the compound on the north side of the Church at Negapatam: with reference to Extract Minutes of Consultation No 271 dated 6th February 1857. & recommends the same for entry in the Budget of 1858/59.-

No 94.

Clg Lines 223.

P. C. P.
H
No 1246

Extract from the Minutes of Consultation
Under date the 25th June 1857.

Read the following
Report from the Chief
Engineer

(Recorded 2nd June 1857 No 863H)

With this Report
the Chief Engineer forwards
in pursuance of Extract
Minutes of Consultation
of the 6th February last No
271 an Estimate for con-
structing a Wall along the
inner side of the Stone drain
which bounds the compound

on

on the North side of the
Church at Vizagapatam,
but no provision has been
made in it for removing
the Stables and Pound as
required in the subsequent
order of 22nd May 1854 No 995,
which appears to have been
last sight of in the Central
Office when sending up the
above estimate. The Chief
Engineer will be requested
to obtain and forward a
revised Estimate supplying
the omission now pointed
out.

J R

9 Copies to the Chief Engr
with 2 Encls
Dispd 26

Dft to Com. 28th May/57 Ft. 258 26.

Public Works. 857 Dept.
Dft to Com. 30th June.

No 1246.

Extract Mins of Com.
Dft 25th June/57.
From the Chief Engr 21st & 27th Oct 1856
- Com 11 May.

Requesting the Chief Engineer to obtain and forward a revised estimate for constructing a wall on the inner side of the stone drain which bounds the compound on the north side of the Church at Negapatam, making provision for removing the stables and Pound which was lost sight of in the former estimate.

No 31 of 92.

C/19 June 1223