MADRAS RECORD OFFICE.

Government of Madras

DEPARTMENT.

G.O. No. Proc. No.

Dated 18

Not to be folded or roughly handled.

Fort Saint George, Public Works Consultation of 7th September 1858.

No. 22. Read the following Extract from the Minutes of Consultation in the Public Department, dated 23rd August 1858, No. 1051.

Authorize the immediate execution of certain repairs to the Monegar Choultry at an estimated outlay of Rupees 3,350, and direct that the requisite orders be issued in this Department for the purpose. } (Vide Pub.Cons. 24th Augt. 1858, Nos. 30-31.)

No 23. ORDER THEREON, No. 1791; dated 2nd September 1858.

Ordered to be communicated to the Officiating Chief Engineer with a request that he will issue orders for the immediate execution of the work to the Monegar Choultry contemplated in the estimate of Rupees 3,350 forwarded with his letter of the 4th August last No. 2495.

(Signed) T. PYCROFT,
Chief Secretary.

PUBLIC DEPARTMENT.

No. 1051.

Extract from the Minutes of Consultation, under date the 23rd August 1858.

Read the following Extract from the Minutes of Consultation in the Public Works Department.

Refer for consideration a letter from the Officiating Chief Engineer with an Estimate amounting to Rupees 3,350 for the thorough repair of the buildings of the Monegar Choultry. (Here enter 16th August 1858, No. 1636.)

Order.—A thorough repair of the buildings of the Monegar Choultry will, it is estimated, involve an outlay of Rupees 3,350, of which upwards of two-thirds will be absorbed in altering the roofs of the Hospital, the leaky condition of which is represented to be such as would endanger the lives of the patients during the monsoon.

2. Under these circumstances and as a case of emergency, the Government authorize the immediate execution of the work. The requisite orders for this purpose will accordingly be issued from the Department of Public Works.

(True Extract.)

Chief Secretary.

To the Department of Public Works, with an Estimate.
" Accountant General.
" Civil Auditor.

Exd. F. Cartledge.

Buildings / (New Work)

Abstract of Estimate No of 185 /5

District Madras.

Work Making through repairs to the whole of the Buildings of the Manegar Choultry together with the Native Infirmary & Idiot Hospital attached to the Gaole & also Improving the roofs of Several Buildings.

Quantities	Description of Work	Rates			Amount	Amount of each part
C. Yds		Rs	As	P	Rupees	Rupees
	No. 1					
	Superintendents Quarter					
	Lower Story					
4800	Sup^{ft}. Whitewashing in Chunam with one Coat ——— Sup^{ft}.	"	1	10	5	
	Yellow washing & Blue washing ———	"	"	"	1	
950	Sup^{ft}. Repairing the floors with 2 coats Cement Chunam ——— Sup^{ft}.	1	13	9	17	
88	Do. Do. floors with 2nd Sort bricks in Chunam where required ——— Sup^{ft}.	5	2	"	5	
550	Sup^{ft}. Pointing in Chunam to the Common floors ——— Do.	"	5	7	2	
250	Do. Shifting tiles & Repairing the Chunam borders ——— Do.		8	"	1	
560	Do. Removing the palmerah Rafters Reepers flat & pantiles & Chunam borders of the Shed Roof of the Verandah & replacing the same with 20 new palmerah rafters 50 reepers nails 6 C^{o} flat tiles 3 C^{o} pantiles 1 new Chunam borders the present Roof being entirely decayed ——— Sup^{ft}.	6	12	"	38	
	Carried Over					69

Quantities	Description of Work	Rates			Amount	Amount of each part
C Yds.		Rs	as	Ps	Rupees	Rupees
	Brought Over				69	"
800	Sqft. Laying tar 2 Coats to the Gutters and Reefing of the Roof	"	14	-	7	
1/4	Cft. Teakwood wrought and put up	1	13	-	1	
	Fixing 2 Brackets in the wall in Masonry and Plastering the Same	"	"	"	1	
	2 Pairs Rattan window Shutters and frames with iron folding hinges and nails &c complete C.	3	"	"	6	
	1 Panes of Glass each 8 by 6 in Putty to above &c	"	"	"	1	
	Repairing the doors windows bolts and locks and oiling the same	"	"	"	1	
616	Sqft. Key green paint 2 Coats to the doors and windows &c	1	12	"	11	
	Difference of price in 3 Cft. of Teakwood required to this work between 4 and 3 Cubt. ft 9½ Rs Charged in the Estimate and the rates of the Market	"	"	"	1	
	Carried Over				98	"

Quantities	Description of Work	Rates			Amount	Amount of each part
		Rs	as	Ps	Rupees	Rupees
	Brought Over				98	"
	Scraping the walls doors and windows and removing the old rubbish and Sundry Charges and Scaffolding &c	"	"	"	5	
						103
	No 2					
	Upper Story					
2900	Sqft. Whitewashing in Chunam with 1 Coat	"	1	10	3	
80	C. Bluewashing in &c with 2 Coats	"	3	2	1	
1000	C. Yellow washing in &c with 1 Coat	"	2	3	1	
775	C. Repairing the floors with 2 coats Cement Chunam	1	13	9	14	
246	C. Repairing floors with 2 Coats blue and white Coloured Chunam in	2	8	"	6	
1275	C. Shifting tiles and repairing the Chunam borders	"	8	"	6	
180	C. Removing the old roof and replacing the same with 1/6 new flattiles 1/5 pantiles and new Chunam borders	3	2	"	15	
	2 Pairs Glazed window Shutters with brass hinges and screw nails &c Complete C	6	12	"	14	
	Repairing the doors windows bolts and locks and oiling the same	"	"	"	1	
	Repairing the roof with 10 new palmyrah rafters 25 reepers and nails &c	"	"	"	9	
	Carried Over				70	103

Quantities	Description of Works	Rate Rupees	as	p	Amount Rupees	Amount of each part Rupees
	Brought Over				70	163
700	Sup^{t} ft Paying the 2 Coats to the above roof $\frac{}{}$	"	14	"	6	
675	Do Green painting 2 Coats to the doors & windows &c $\frac{}{}$	1	12	"	12	
	Difference of price in 2½ Cub^{t} ft of Teakwood required to this work between 2½ and 3 Cub^{t} ft per 3½ Rupees Charged in the data and the rates of the Nearest	"	"	"	1	
	Scraping the walls doors and windows and removing the old rubbish and Sundry charges & Scaffolding &c	"	"	"	4	
						93
	— No 3 —					
	— Cook Rooms and Godowns &c —					
1450	Sup^{t} ft Whitewashing in Chunam with 2 Coats $\frac{}{}$	"	2	6	2	
425	Do Blue washing in Do with 1 Coat $\frac{}{}$	"	2	4	1	
292	Repairing the floors with 1 Coat Cement Chunam $\frac{}{}$	1	5	6	3	
1040	Rubbing Tiles and Repairing the Chunam borders $\frac{}{}$	"	8	"	5	
	Yellow washing in Chunam with 1 Coat $\frac{}{}$	"	2	3	1	
236	Cub^{t} ft Brick work in clay $\frac{}{}$	"	1	4	19	
300	Sup^{t} ft Plastering with 2 Coats Yellow Chunam $\frac{}{}$	2	"	"	6	
	Carried Over				37	196

Quantities	Description of Works	Rate Rupees	as	p	Amount Rupees	Amount of each part Rupees
	Brought Over				37	196
	Excavating the foundation Cutting the wall and fixing a new door frame and Lintel in Masonry and plastering the same	"	"	"	1	
	Coolly hire for removing part of the old Roof for giving better Ventilation and repairing the same in Chunam	"	"	"	2	
1½	Cub^{t} ft Teakwood Lintel wrought and fixed up $\frac{}{}$	1	13	"	3	
1	Pair Batten door with frame hooks hinges and bolts &c complete	"	"	"	13	
186	Sup^{t} ft Red painting 2 Coats to the doors and windows &c $\frac{}{}$	1	7	9	3	
	Difference of price in 7¾ Cub^{t} ft of Teakwood required to this work between 4 and 3 Cub^{t} ft per 3½ Rs Charged in the data and the rates of the Nearest	"	"	"	2	
	Scraping the walls doors and windows and removing the old rubbish and also Sundry charges and Scaffolding &c	"	"	"	4	
						65
	— No 4 —					
	— Office —					
2150	Sup^{t} ft Whitewashing in Chunam with 1 Coat $\frac{}{}$	"	1	10	2	
305	Do Repairing the Plaster with 2 Coats Chunam to the Columns &c $\frac{}{}$	1	14	9	6	
50	Do Repairing the floors with 2 Coats Yellow Coloured Chunam in Sup^{t} ft where required $\frac{}{}$	2	"	"	1	
						9
	Carried Over					261

Quantities	Description of Work	Rate Rs	as	p	Amount Rupees	Amount of each part Rupees
	Brought Over				9	261
564	Sup^{d} sf^{t} Pointing in Chunam to the Common floors ——— J^{d}	"	3	7	2	
1	6 Iron fastening hooks each 1½ feet long ——— Each	"	1	9	1	
24	Iron bars each to the windows ——— ^{do}	1	2	"	27	
	Cooly hire for making the holes in the top and bottom frames of the windows for receiving the iron bars				1	
	Repairing the doors windows bolts and locks and oiling the same ———				1	
673	Sup^{d} sf^{t} Key green paint 2 Coats to the doors and windows &c ——— J d^{o}	1	12	"	12	
138	^{do} Redo paint 2 Coats to the doors and windows &c ——— J d^{o}	1	7	9	2	
	Scraping the walls doors and windows and removing the old rubbish and also Sundry Charges & Scaffolding &c				3	
	— No 5 —					58
	— Sheds —					
210	Sup^{d} sf^{t} Yellow washing in Chunam 1 Coat ——— J d^{o}	"			1	
520	^{do} Repairing the plaster with 2 Coats Yellow Chunam wer required — J d^{o}	2	"	"	10	
210	^{do} 2 Coats blue Chunam wher required ^{do}	2	"	3	4	
	Scraping the walls and removing the old rubbish and Sundry Charges and Scaffolding &c ———	"	"	"	1	
	— No 6 —					16
	— Paupers wards —					
4.900	Sup^{d} sf^{t} Blue washing in Chunam with 1 Coat ——— J d^{o}	"	2	4	6	
	Carried Over				6	335

Quantities	Description of Work	Rate Rs	as	p	Amount Rupees	Amount of each part Rupees
	Brought Over				6	335
11,000	Sup^{d} sf^{t} Yellowwashing in Chunam with 2 Coats ——— J d^{o}	"	3	1	21	
1650	^{do} Repairing the plaster with 2 Coats blue chunam where required J d^{o}	2	"	3	33	
850	^{do} Repairing 2 Coats yellow Chunam where required ——— J d^{o}	2	"	"	17	
1900	^{do} Whitewashing in Chunam with 1 Coat ——— J d^{o}	"	1	10	2	
	Repairing the doors and windows bolts and locks and oiling the Same ———	"	"	"	3	
1800	Sup^{d} sf^{t} Red paint 2 Coats to the doors and windows &c ——— J d^{o}	1	7	9	27	
	Sundry Charges and Scaffolding &c ———	"	"	"	6	115
	— No 7 —					
	— Privy to the Males —					
1900	Sup^{d} sf^{t} Blue washing in Chunam 1 Coat J d^{o}	"	2	4	3	
1260	^{do} Repairing the plaster with 2 Coats blue Chunam ——— J d^{o}	2	"	3	26	
50	^{do} Repairing floors with bricks in Chunam where required J d^{o}	5	2	"	2	
320	^{do} Repairing the floors with Cowks Cement Chunam ——— J d^{o}	1	13	9	6	
270	^{do} Pointing in Chunam to the Common floors ——— J d^{o}	"	5	7	1	
	Sundry Charges and Scaffolding &c ———	"	"	"	2	40
	— No 8 —					
	— Privy to the Females —					
1025	Sup^{d} sf^{t} Blue washing in Chunam 1 Coat J d^{o}	"	2	4	1	
1200	^{do} Repairing the plaster with 2 Coats blue Chunam ——— J d^{o}	2	"	3	24	
	Carried Over				25	490

Quantities	Description of Work	Rate Rs	as	ps	Amount Rupees	Amount of each part Rupees
	Brought Over				21	490
1040	Sup^{s} feet Repairing the floors with 2 Coats Cement Chunam @	1	13	9	3	
20	C^{ft} Brick work in Chunam for raising the Compounds wall @	"	1	9	2	
30	Sup^{s} Fixing the Iron Bolts in Chunam over the Compound wall @	"	1	1	2	
	Sundry Charges and Scaffolding &c	"	"	"	1	60
	— N^{o} 9 — Cookroom to the Pauper wards					
840	Sup^{s} feet Shifting tiles and repairing the Chunam borders @	"	8	"	1	
725	D^{o} Blue washing in Chunam with 2 Coats @	"	3	2	1	
75	D^{o} Red paint 2 Coats to the doors &c	1	7	9	1	
	Sundry Charges and Scaffolding &c				1	4
	— N^{o} 10 —					
	Store Godowns and Guard Room					
840	Sup^{s} feet Shifting tiles and repairing the Chunam borders @	"	8	"	1	
1000	D^{o} Whitewashing in Chunam 1 Coat @	"	1	10	1	
140	D^{o} Blue washing in D^{o} 1 Coat @					
260	D^{o} Yellow washing in D^{o} 1 Coat @	"	"	"	2	
200	D^{o} Repairing the plaster with 2 Coats Blue Chunam where required @	2	"	3	1	
192	D^{o} Repairing the floors with 2 Coats Cement Chunam @	1	13	9	3	
192	D^{o} Flooring with jelly in Chunam 6 ins thick and well rubbed in @	1	5	"	8	
12	C^{ft} Brick work in Chunam to the Dwarf wall @	"	1	7½	1	
	Carried Over				23	554

Quantities	Description of Work	Rate Rs	as	ps	Amount Rupees	Amount of each part Rupees
	Brought Over				23	554
	1 Teakwood waste board with Cleats and nails	"	"	"	1	
341	Sup^{s} feet Red paint 2 Coats to the doors and windows &c @	1	7	9	5	
	Sundry Charges and Scaffolding &c				3	32
	— N^{o} 11 —					
	Cookroom to the Paupers wards					
3400	Sup^{s} feet Blue washing in Chunam with 2 Coats @	"	3	2	1	
100	D^{o} Repairing the plaster with 2 Coats Blue Chunam were required @	"	"	"	2	
381	D^{o} D^{o} floors with 2 Coats Cement Chunam @	1	13	9	1	
130	D^{o} D^{o} floors with 6 ins thick bricks in D^{o} @	5	2	"	6	
675	D^{o} Pointing in Chunam to the Granite floors @	"	9	4	4	
53	D^{o} Red paint 2 Coats to the doors &c @	1	7	9	1	
	Sundry Charges and Scaffolding &c	"	"	"	2	29
	— N^{o} 12 —					
	Womens ward					
2475	Sup^{s} feet Yellow washing in Chunam 1 Coat @	"	2	3	3	
180	D^{o} Blue washing in D^{o} 1 Coat @	"	"	"	1	
561	D^{o} Whitewashing in D^{o} 1 Coat @					
150	D^{o} Repairing the plaster with 2 Coats Blue Chunam @	2	"	3	3	
330	D^{o} D^{o} floors with 2 Coats Cement Chunam @	1	13	9	6	
	D^{o} D^{o} with 2 Coats Chunam @	1	4	9	1	
50	D^{o} D^{o} with 2 Coats Chunam @	"	5	4	2	
500	D^{o} Pointing in Chunam @					
	Carried Over				16	618

Quantities	Description of Works	Rate Rs	as	P	Amount Rupees	Amount of each part Rupees
	Brought Over				16	618
	1 Pair Batten doors with frame Complete in lieu of old ones	"	"	"	12	
	Red plain 2 Coats &c	"	"	"	1	
	Differences of prices in 5⅓ Cubic ft of Earth rounds required to this work between 4 and 3 Cubic ft 3½ Rupees Charged in the data & the rate of the Market	"	"	"	2	
	Sundry Charges & Scaffolding &c				2	33
	— No 13 —					
	— Apothecarys quarter —					
189	Sup.ft fair Whitewashing in Chunam 1 Coat — Sup.ft	"	"	"	2	
730	do Blue washing in do 1 Coat Sup.ft					
2800	do Yellow washing in Chunam 1 Coat Sup.ft	"	2	3	3	
120	do Repairing the pilasters with 2 Coats blue Chunam	"	"	"	2	
936	do Shifting tiles and repairing the Chunam borders Sup.ft	"	8	"	11	
100	do Repairing the doors with 8 inch Sup.ft bricks in Chunam	"	"	"	5	
500	do Painting in Chunam Sup.ft	"	5	/	2	
100	Running feet Repairing the cracks with tar putty and Cloth &c	"	"	"	2	
150	do do do without Cloth	"	"	"	1	
	1 Pair Ruling doors with hinges Complete in lieu of old ones	"	"	"	1	
	Repairing the doors & windows &c	"	"	"	2	
850	Sup.ft feet Hay green paint 2 Coats to the Doors & windows &c Sup.ft	1	12	"	15	
	Carried Over				15	651

Quantities	Description of Works	Rate Rs	as	P	Amount Rupees	Amount of each part Rupees
	Brought Over				45	651
	Sundry Charges & Scaffolding &c	"	"	"	3	48
	— No 14 —					
	— Cook Rooms and godowns &c —					
700	Sup.ft feet Shifting tiles and repairing the Chunam borders Sup.ft	"	8	"	3	
925	do Whitewashing in Chunam 1 Coat Sup.ft	"	1	10	1	
900	do Blue washing in do 1 Coat Sup.ft	"	2	4	1	
100	do Red plain 2 Coats to the doors and windows &c Sup.ft	1	1	9	2	
	Sundry Charges and Scaffolding &c	"	"	"	1	8
	— No 15 —					
	— Infirmary —					
1500	Sup.ft feet Shifting tiles and repairing the Chunam borders Sup.ft	"	8	"	7	
2250	do Whitewashing in Chunam 1 Coat Sup.ft	"	1	10	3	
100	do Repairing the floors with 8 inch bricks in Chunam Sup.ft	"	"	"	5	
250	do Painting in Chunam Sup.ft	"	5	4	1	
95	do Lining the canvas with nails and leather, tape &c over the weather boards Sup.ft	6	8	"	6	
200	do Lead Colour 2 Coats to the weather boards Sup.ft	2	"	9	4	
	Repairing the doors and windows &c	"	"	"	1	
462	Sup.ft feet Red paint 2 Coats to the doors and windows &c Sup.ft	1	1	9	1	
	Sundry Charges and Scaffolding &c	"	"	"	2	36
	— No 16 —					
	— Sick Hospitals —					
8,000	Sup.ft feet Whitewashing in Chunam 1 Coat Sup.ft	"	1	10	9	
	Carried Over				9	743

Quantities	Description of Works	Rate			Amount	Amount of each part
		Rs	as	ps	Rupees	Rupees
	Brought Over				9	743
5500	Sup.fac.t Blue washing in Chunam					
	1 Coat ——— Sup.fac.t	"	2	4	8	
100	Do Repairing the plaster with 2					
	Coats Chunam ———	"	"	"	2	
600	Do Do Do 2 Coats blue Chunam Sup.fac.t	"	3		12	
550	Do Do Doors with 8 ins Sq.re Cracks					
	in Chunam ——— Sup.fac.t	5	2	"	28	
1800	Do Painting in Chunam ——— Sup.fac.t	"	5	4	6	
	Repairing the doors & windows &c	"	"	"	2	
2400	Sup.fac.t Red paint 2 Coats to the					
	doors and windows &c ——— Sup.fac.t	1	7	9	36	
	Sundry Charges and Scaffolding &c	"	"	"	5	108
	— No 14 —					
	— Privies —					
1500	Sup.fac.t Shifting tiles and repairing					
	the Chunam borders ——— Sup.fac.t	"	8	"	8	
4150	Do Whitewashing in Chunam 1 Coat Sup.fac.t	"	1	10	5	
2325	Do Blue washing in Do 1 Coat Sup.fac.t	"	2	4	3	
100	Do Repairing the plaster with 1					
	Coat Chunam ———	"	"	"	1	
70	Do Do with 2 Coats blue Sup.fac.t	2	"	3	1	
100	Do Doors with 2 Coats Cement Chunam ———	"	"	"	2	
800	Sup.fac.t Painting in Chunam Sup.fac.t	"	5	4	3	
	Sundry Charges and Scaffolding &c				1	24
	— No 18 —					
	— Conservancy Godowns —					
1236	Sup.fac.t Whitewashing in Chunam 1 Coat Sup.fac.t	"	1	10	1	
375	Do Blue washing in Do 1 Coat Sup.fac.t	"	2	4	1	
175	Do Repairing the plaster with 2 Coats					
	blue Chunam ——— Sup.fac.t	2	"	3	4	
	Repairing 2 pairs batten doors &c ———	"	"	"	3	
	Carried Over ———				9	875

Quantities	Description of Works	Rate			Amount	Amount of each part
		Rs	as	ps	Rupees	Rupees
	Brought Over				9	875
250	Sup.fac.t Red paint 2 Coats to the doors					
	and windows &c ——— Sup.fac.t	1	7	9	3	
278	Do Repairing Gaggers with 2 Coats					
	Cement Chunam ——— Sup.fac.t	1	13	9	5	
	Sundry Charges and Scaffolding &c				1	18
	— No 19 —					
	— Select Hospitals for Females —					
6400	Sup.fac.t Whitewashing in Chunam 1 Coat Sup.fac.t	"	1	10	7	
570	Do Painting in Chunam ——— Sup.fac.t	"	5	4	2	
1089	Do Red paint 2 Coats to the doors					
	and windows &c ——— Sup.fac.t	1	7	9	16	
	Sundry Charges and Scaffolding &c ———	"	"	"	2	27
	— No 20 —					
	— Privy —					
670	Sup.fac.t Shifting tiles and repairing					
	the Chunam borders ——— Sup.fac.t	"	8	"	3	
2850	Do Whitewashing in Chunam 1 Coat Sup.fac.t	"	1	10	3	
2025	Do Blue washing in Do 1 Coat Sup.fac.t	"	2	4	3	
220	Do Red paint 2 Coats to the doors					
	and windows &c ——— Sup.fac.t	1	7	9	3	
	Sundry Charges and Scaffolding &c	"	"	"	1	13
	— No 21 —					
	— Compound wall —					
5000	Sup.fac.t Whitewashing in Chunam 1 Coat Sup.fac.t	"	1	10	5	
	Sundry Charges and Scaffolding &c	"	"	"	1	6
	— No 22 —					
	— Select Hospitals for Females —					
730	Sup.fac.t Whitewashing in Chunam 1 Coat Sup.fac.t	"	1	10	1	
	2 lb Iron fastening hooks each 1 1/4 feet long @	"	1	9	2	
	Sundry Charges &c ———				1	4
	Carried Over ———					943

Quantities	Description of Work	Rate		Amount	Amount of each part
		Rs	As	Rupees	Rupees
	Brought Over			"	943
	— № 23 —				
	— Well and Cistern —				
56	Cft. Brick work in clay for rebuilding upper portion of the well where the bricks are corroded @	"	1	4	5
56	do Brick in Chunnam for rebuilding parapet wall @	"	1	9	6
412	Sup. feet Plastering with 2 Coats Cement Chunam @	1	13	9	8
26	do Flooring with Jelly in Chunam 3 ins. thick and rubbed over the bede of the Cistern @	2	13	6	1
	Cleaning and removing the accumulation of the well	"	"	"	1
	Sundry Charges and Scaffolding &c.	"	"	"	1 — 22
	— № 24 —				
	— Stable —				
725	Sup. feet Shifting tiles and repairing the Chunam borders @	"	8	"	4
1100	do Whitewashing in Chunam 1 Coat @	"	1	10	1
100	do Repairing the plaster with 1 Coat Chunam	"	"	"	1
	Repairing the roof with 10 palmirah rafters 50 reepers and nails &c.	"	"	"	12
	Sundry Charges and Scaffolding &c.	"	"	"	1 — 19
	— № 25 —				
	— Dispensary —				
2175	Sup. feet Whitewashing in Chunam 1 Coat @	"	1	10	3
1000	do Pointing in Chunam @	"	5	7	3
1430	do Shifting tiles and repairing the Chunam borders @	"	8	"	7
	Carried Over			12	984

Quantities	Description of Work	Rate		Amount	Amount of each part
		Rs	As	Rupees	Rupees
	Brought Over			12	984
10	Fastening hooks each 1½ flat charge	"	1	9	1
2	Panes of Glass each 8 by 6 ins. Putty to do	"	"	"	1
375	Sup. feet Rub plaster 2 Coats to the doors and windows &c. @	1	1	9	6
	Sundry Charges and Scaffolding &c.	"	"	"	1 — 21
	Contingencies				5
	Total Cost for the Repairs Rupees				1010
	Improving the roofs of Several Buildings by raising the walls for giving better Slope.				
	— № 26 —				
	— Office —				
163	Cft. Brick work in Chunam for raising the main walls @	"	1	9	18
292	Sup. feet Removing the old roof and replacing the same with &c. new plattites &c. puntites and new Chunam borders to the Main building @	3	8	"	12 — 1
1173	do Removing the old flat and puntites and Chunam borders of the roof of the Verandah and replacing the same with 50 palmirah reepers and nails &c. @	4	2	"	48
	Plastering with 2 Coats Chunam @	1	13	9	4
220	do Plastering with 2 Coats Chunam @				
	Coolly hire for raising the palmirah rafters on the Verandah to the ridge and in height above the present level	"	"	"	11 — 93 —
	Carried Over				

Quantities	Description of Works	Rate		Amount	Amount of each part
		Rs	as	Rupees	Rupees
	Brought Over			93	"
	Carpenters Coolly hire for making and fitting up jack rafters and couples out of old palmirahs and Lining old reepers with new nails to the main roof where renewed and also supplying with 7 new palmirah rafters and 20 reepers and nails &c	"	"	12	
	Paying tar 2 Coats to the roof			18	
	Sundry Charges and Scaffolding &c	"	"	6	129
	— No 27 —				
	— Paupers ward —				
1313	Cft Brick work in Chunam for raising the old walls and pillerings	"	1 9½	147	
7830	Sqft for Removing the palmirah couples reepers flat & pantiles & Chunam borders of the main roof and replacing the same with ½ flatttiles & ½ Pantiles & new Chunam borders ——— Sqft	3	8 "	274	
5380	Do Removing the palmirah rafters reepers flat and pantiles and Chunam borders of the roof of the Verandah and replacing the same with new palmirah rafters nails ¼ flatttiles ½ pantiles and new Chunam borders Sqft	8	10 3	265	
2500	Do Plastering with 2 coats Chunam ——— Sqft	1	13 9	46	
	Carried Over			932	129

Quantities	Description of Works	Rate		Amount	Amount of each part
		Rs	as	Rupees	Rupees
	Brought Over			932	129
	Carpenters coolly hire for making and fitting up 40 Palmirah couples Jack rafters out of old palmirahs and Lining old reepers with new nails the whole of the main roof and Verandah where renewed and also supplying two palmirah new reepers and nails &c	"	"	142	
	Paying tar 2 coats to the roof	"	"	158	
	Sundry Charges & Scaffolding &c	"	"	58	1290
	— No 28 —				
	— Paupers Cookroom —				
204	Cft Brick work in Chunam for raising the walls ——— Cft	"	1 9½	23	
1248	Sqft for Removing the old roof & replacing the same with ½ flatttiles ½ pantiles and new Chunam borders ——— Sqft	3	8 "	43	
1224	Sqft for Removing the old tiles of the roof and replacing the same with ½ flatttiles ½ pantiles and new Chunam borders ——— Sqft	3	8 "	43	
275	Do Plastering with 2 coats Chunam ——— Sqft	1	13 9	5	
	Coolly hire for raising the palmirah rafters in the Verandah at the ridge 2 in height above the present level	"	"	11	
	Carried Over			125	1419

Quantities	Description of Work	Rate	Amount	Amount of each sheet
		As A/s	Rupees	Rupees
	Brought Over		125	1419
	Lining the old rafters with new nails to the roof and supplying 10 new palmerah rafters to rafters and nails &c	" " "	18	
	Sundry charges in Scaffolding &c	" " "	7	150
	— No 29 —			
	— Wanneys wards —			
424	Cft Brick work in Chunam for raising the old walls — @ 4 Cft	"	1 9½	48
1154	Sup.d feet Removing the roof & replacing the same with ½" flattiles ⅛ pantiles and new Chunam borders to Main roof — @ 4	3 8 "	40	
1625	Do Removing the roof of the Verandah and replacing the same with ½ flattiles ⅛ pantiles and new Chunam borders — @ 3	3 5 "	57	
100	Do Plastering with 2 Coats Chunam @ 4	1 13 9	13	
	Paying tar 2 Coats to the roof	" " "	8	
	Coolly hire for raising the palmerah rafters in the Verandah at the ridge 2 ft in height above the present Level	" " "	10	
	Carpenters coolly hire for making and fitting up Jack rafters and couples out of old palmerah and lining old rafters with			
	Carried Over		176	1569

Quantities	Description of Work	Rate	Amount	Amount of each sheet
		As A/s	Rupees	Rupees
	Brought Overs		176	1569
	with new nails to the Main roof & where renewed and also supplying 15 palmirah rafters to rafters and nails &c	" " "	30	
	Sundry charges & Scaffolding &c	" " "	11	217
	— No 30 —			
	— Sick Hospital —			
1286	Cft Brick work in Chunam for raising the walls — @ 4 Cft	"	1 9½	114
5196	Sup.d feet Removing the old roof and replacing the same with ½ flattiles ⅛ pantiles and new Chunam borders to the Main building @ 3	3 8 "	192	
2555	Do Removing the old flat and pantiles and Chunam borders of the roof and replacing the same with ½ flattiles ⅛ pantiles and new Chunam borders to the Verandah — @ 3	3 8 "	84	
1970	Do Plastering with 2 coat Chunam — @ 4	1 13 9	35	
	Coolly hire for raising the palmirah rafters in the Verandah at the ridge 2 ms in height above the present Level	" " "	14	
	Carried Overs		469	1786

Quantities	Description of Work	Rate	Amount	Amount of each part
		Rs a p	Rupees	Rupees
	Brought Over		469	1786
	Carpenters Corly hire for marking and fitting up Sack rafters and Coupletes out of old palmiralis and fixing old reepers with new nails to the Main Roof where renewed and also supplying with new palmirah rafters reepers and nails &c	" " "	63	
	Sundry charges & scaffolding &c		23	554
	Total Cost for Improving the roofs of several buildings by raising the walls for giving better slope as per items from No 26 to 30 of the above Estimate	" " "	"	2340
	Total Cost for thorough repairs of the buildings and out Offices &c as per items from No 1 to 25 of the above Estimate	" " "	"	1010
	Total Company's Rupees			3350

Central Office of P.W.D.
Fort Saint George
4 August 1858.

Majr
Offg Chief Engineer P.W.D.

Enclosure

Dated Letter

From

The Offg Chief Engineer

D.P.H.

To

The Secretary to Government

D.P.H.

— P.W. 1745/58

Dated 4 August/58

Rec'd

P.W. 1932/58

No 2495

Abstract Estimate for —

Making thorough repairs to the whole of the Buildings of the Triangular Choultry together with the Native Infirmary and Adult Hospital attached to the same and also for Improving the Roads of General Communication in the District of Madras.

Amounting to Company's Rupees 3330 —

P.W.D.

Fee Rs 97 —

Cons: 17th Augt/58 No 1001
—a— 1st June —a— —" 32
—a— 4th Augt/57 —a— 88

No 22 & 23.

Pr Works 1858 Despatch
Dy to Cour: 7th Sept.
No 1932

Exc: Imis: Cons: in
the Public Departt

Dated 23d
Recvd 24th } Augt/58.
No 1057

Enclo: 1

Authorize the immediate execution of certain repairs to the Honegar Country at an Estimated outlay of Rs 3850 and direct that the requisite orders be issued in this Department for the purpose.

Written order -
No 1791. 2d Sept 1858

No 1791

Ordered to be Communicated to that officiating Chief Engineer with a request that he will issue orders for the immediate execution of the work to the Honegar Country contemplated in the Estimate of Rupees 3,350 forwarded with his letter of the 4th August last No 2495.

Fort St George
2d Sept 1858

10 Copies to the Offg Chief Engr Dinapore
with F. D. P. C. No 1057.