

(1) Number of pages 6(2) Date of repair 17-5-38(3) Initials of the Referencer G**MADRAS RECORD OFFICE.****Government of Madras.****DEPARTMENT.**G.O. No. 1103Press
Mis.152 53
Dated 9-6- 18 59

18 59

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
from 1st to 10th June 1859.*

No. 152. Read the following.

No. 1145.

List of Bills submitted for the sanction of Government which exceed their Estimates by more than 5 per cent.

Audit No.	Date of Bills.	Description of Works.	Amount of Estimate.	Amount of Bill.			Excess.			Per centage of Excess.	The year to which the expenditure appertains.	Remarks.
				Rs.	A.	P.	Rs.	A.	P.			
234	1859 May 5	Repairing the bund and Calingulah of Canala Nagamah Tank, sanctioned by the Chief Engineer on the 18th November 1858.....	327	349	6	0	22	6	0	6 1/2	1858-59	The excess is owing to having carried the foundation of the wing wall a yard deeper than was allowed in the estimate which was found necessary.
289	Do. 10	Repairing the bund of Nundiah small Tank 2d part bill. ... Add the amount of the 1st part bill passed by the Chief Engineer 13th August 1858.....		1,601	8	9						The excess is owing to a large portion of the stone facing of this Tank having bulged out in consequence of the heavy rain in October last. The Tank bund was in such a dangerous state that it was repaired at once, the additional work being charged to this Estimate.
				542	0	11						
			1,880	2,143	9	8	263	9	8	14	1858-59	
Total.....			2,207	1,950	14	9						

Central Office of P. W.,
Fort Saint George,
1st June 1859. }

(Signed) J. H. BELL, Lieut-Colonel,
Chief Engineer.

No. 153. ORDER THEREON, 9th June 1859, No. 1403.

The Bills are sanctioned.

(Signed) J. D. BOURDILLON,
Secretary to Government.

N^o 1145

List of Bills submitted for the sanction of Government which exceed their Estimates by more than 5% of cost

Audit Date	Description of Work	Amount at Estimate	Amount of Bill	Excess	Percentage of Excess	The year to which the expenditure appertains	Remarks
1859							
234 May 5	Repairing the band and Calingulak of Canala Nagamah Tank &c. ordered by the Chief Engineer on the 18 th November 1858.	327	319 6	22 6	6 3/4	1858, 59	The excess is owing to having carried the foundation of the wing wall a yard deeper than was allowed in the estimate which was found necessary.
289	5: 10 Repairing the band of Sundiah Small tank. 2 part bill add the amount of the 1 st part Bill passed by the Chief Engineer 13 th August 1858.	1601 89	1880	263 9 8	16 46	1858, 59	The excess is owing to a large portion of the stone facing of this tank having tumbled out in consequence of the heavy rain in October last. The tank was much injured & such a dangerous state that it was repaired at once, the additional work being charged to this Estimate.
Enc. 2 Bill:							

Total Excess 2207 .. 1950 149

Central Office of P.W.
Fort St. George
1st June 1859

J. H. Bell
Chief Engineer

Done

1859
1834

Chief Engineer
The Secretary to Govt
C. R. R.

1859
1834

1859

1859
1834

1859
1834

1859
1834

1859
1834

The Office are
mentioned.

1859

1859
1834

1859
1834