M.R.O. 1—77,006—8-6-37.

(1) Number of pages 6

(2) Date of repair 5/11/38

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

Ex 21/1935

G.O. No. 2436 Press / Mis.

123 24

Dated 13—10— 1859

Not to be folded or roughly handled

19

Proceedings of the Madras Government, Public Works Department, from 5th to 21st October 1859.

No. 123. Read the following.

No. 5832.

List of Bills of the District Engineer of Nellore, submitted for the sanction of Government which exceed their estimates respectively by more than 5 per cent.

Audit No.	Date of Bill	Description of Work.	Amount of Estimate.	Amount of Bill.			Amount of Excess.			Per centage of Excess.	To what year the expenditure appertaining.	Remarks.
	1859		Rs.	Rs.	A.	P.	Rs.	A.	P.			
1149	April 7	Repairing the Pynumpoorum small tank in Survapully talook, sanctioned by the Collector of Nellore on the 19th May 1858.....	760	847	6	4	87	6	4	11½	1858-59	The excess on these items was caused by more work than was provided for in the estimate having been done and from the explanation afforded, it appears that as the expenditure during the months in which the repairs to these tanks were being executed, was very great, a difficulty was experienced in controlling the outlay on every work. The executive officer of the range was Captain Ritherdon and the Overseer in charge of the work was Mr. Plunkett, but the latter through an oversight omitted to warn the Goomastah against exceeding the estimate. Captain Mullins, however, reports, that when he inspected these works he found that the money expended thereon had been carefully and effectually laid out. This statement proves the insufficiency of the original estimates of Rupees 760 and 630 respectively.
1150	do 7	Repairing the Nallatoor small tank in Survapully talook, sanctioned by the Collector of Nellore on the 19th May 1858.....	630	713	5	10	83	5	10	13$\frac{21}{64}$	do.	
1269	June 30	Repairing Lagoontapaud tank in Nellore talook, sanctioned by the Collector of Nellore on the 5th August 1858.....	890	994	15	3	104	15	3	11$\frac{21}{64}$	do.	An excess in this item was caused by the insufficiency of the rate. 8 pice allowed for earth-work in the estimate, and which was raised on an inspection of the work by the District Engineer to 10 pice.
		Total Rupees.....	2,280	2,555	11	5	275	11	5			

Central Office of P. W., Fort Saint George, 7th October 1859.

(Signed) J. H. BELL, Lieut.-Colonel,
Chief Engineer.

No. 124. ORDER THEREON, 13th October 1859, No 2436.

The bills are sanctioned.

(Signed) T. PYCROFT,
Chief Secretary.

N°5832

List of Bills of the District Engineer of Nellore submitted for the sanction of Government which exceed their Estimates respectively by more than 5 per Cent.—

Audit N°	Date of Bill	Description of Work	Amount of Estimate	Amount of Bill	Amount of Excess	Per Centage of Excess	To what year the Expenditure is to be charged	Remarks
	1859.							The excesses on these items are caused by more work than was provided for in the Estimate on the ordeal it appears that as the Expenditure during the months in which the Repairs to these Tanks were being executed, was very great a difficulty was experienced in controlling the outlay on every work. The Executive Officer of the Range was Captain Rotherdon & the Overseer in charge of the work was Mr. Plumbell, but the latter this an over sight omitted to warn the Gomastah against exceeding the Estimate Cash for Mallins however reports, that when he inspected these works he found that the money expended thereon had been disposed of contrary to and out this State proved the insufficiency of the original Estimate of Rs. 760 & 630 respectively. An Excess in this Item was caused by the insufficiency of the rate 8 price allowed for Earth work in the Estimate, and which was raised on an inspection of the work by the D.E. to 10 price.
1149	April 7	Repairing the Pyaumpoo-rum small Tank in Surva-gully Taluck, sanctioned by the Collector of Nellore on the 19th May 1858	760 " "	847 6 1	87 6 1	11½	1858/59	
1150	Do 7	Repairing the Nallatoor small Tank in Do sanctioned by Do Do	630 " "	713 5 10	83 5 10	13 15/64	Do	
1269	June 30	Repairing Lugoondapund Tank in Nellore Taluck sanctioned by Do Do on the 5th August 1858	890 " "	994 15 3	104 15 3	11 51/64	1858/59	
	June 3	Bills	Total Rupees	2280 " "	2555 11 5	275 11 5		

Central Office of P.W.
Fort St. George
7 October 1859.

Lieut.-Colonel
Chief Engineer

To
The Secretary to Government
Pub. Works Depart.

P. Ellray

No 1234 1859 Depart.
Rec.d from Genl 21st October.
No 7623.

From
The Chief Engineer
To
The Secy. to Govt.
P.W.D.

Dated Fort St. George
Sec.t 8th October 1859

No 5832

2 Encls.

List of Bills of the Dist.t Engineer of Nellore submitted for the sanction of Government which exceed their Estimates respectively by more than 5 per Cent.

No 7436. 13th October 1859.
With an Order
L.

No 1234 1859.

No 2436.

The Bills are returned

JJ

Fort St. George
13th Oct.r 1859.

10 Copies
Chief Engr. with Bills Dist.t
1 Acct. Genl

10th October