M.R.O. 1—77,006—8-6-37.

(1) Number of pages 10

(2) Date of repair 12-4-38

(3) Initials of the Reference

4

# MADRAS RECORD OFFICE.

---

## Government of Madras.

Public Works DEPARTMENT.

Ca. 15/3/59

G.O. No. 555 Press
52-55 Mis.

Dated 12 — 3 — 1859.

***Not to be folded or roughly handled***

No. 54. Read the following

*List of Works executed on emergency submitted for the sanction of Government.*

| Date of Bill. | Audit No. | From whom received. | Description of Works. | Amount. Rs. | A. | P. | Remarks. |
|---|---|---|---|---|---|---|---|
| 1859. | | | | | | | |
| Jany. 18. | 170 | Acting Civil Architect. | White and Blue washing the interior Wards and Cells, and repairing the Superintendent's Quarters at the Penitentiary..... | 133 | 7 | 1 | This work was executed under instructions from the Barrack Master. |
| „ „ | 171 | do. | Covering with gratings, the mouths of the Wells in the General Hospital..... | 126 | 7 | 10 | do. from the Town Major. |
| „ „ | 172 | do. | Examining the foundation, beams, and joists of the Sudder Uddalut Court Building at Royapettah..... | 113 | 8 | 0 | do. do. Chief Engineer. |
| „ „ | 173 | do. | Setting up a new Meridional Instrument at the Observatory..... | 605 | 12 | 7 | do. do. do. |
| „ „ | 174 | do. | Repairing the foot bridge adjoining Wallajah bridge.... | 25 | 5 | 1 | do. do. do. the present is the 2nd part, or final bill for the work. |
| „ „ | 175 | do. | Removing the Gallery at St. George's Cathedral and flooring with square Granite stones..... ..... | 251 | 0 | 7 | do. E. M. C., No. 1,024, dated 31st May 1858. |
| „ „ | 176 | do. | Filling up breaches and strengthening the Vasurpaudy Tank Bank in different places, and turfing and forming Bund behind Calingulah..... ..... | 84 | 0 | 0 | do. Civil Architect. |
| | | | Total Rupees..... | 1,339 | 9 | 2 | |

Central Office of P. W.,
Fort Saint George,
5th February 1859.

(Signed) C. E. FABER, Colonel,
*Chief Engineer.*

*Fort Saint George, Public Works Consultation of 15th March 1859.*

1 B.

*Fort Saint George, Public Works Consultation of 15th March 1859.*

No. 55. ORDER THEREON, No. 555; dated 12th March 1859.

Of the Seven Bills submitted with the above letter for works executed on emergency in the Presidency Division, the Right Honorable the Governor in Council sanctions the undermentioned Six amounting to Rupees (733-12-7) seven hundred and thirty-three, annas twelve and pice seven.

| Audit No. | Description of Works. | Amount. | | |
|---|---|---|---|---|
| | | Rs. | A. | P. |
| 170 | White and Blue washing the interior Wards and Cells, and repairing the Superintendent's Quarters at the Penitentiary | 133 | 7 | 1 |
| 171 | Covering with gratings, the mouths of the wells in the General Hospital | 126 | 7 | 10 |
| 172 | Examining the foundation, beams, and joists of the Sudder Uddalut Court Building at Royapettah | 113 | 8 | 0 |
| 174 | Repairing the foot bridge adjoining Wallajah bridge | 25 | 5 | 1 |
| 175 | Removing the Gallery at Saint George's Cathedral and flooring with square Granite stones | 251 | 0 | 7 |
| 176 | Filling up breaches and strengthening the Vasurpaudy Tank Bank in different places and turfing and forming Bund behind Calingulah | 84 | 0 | 0 |
| | Total Rupees ..... | 733 | 12 | 7 |

2. Bill No. 173 is for setting the new meridional instrument in the Observatory; before sanctioning this the Government would wish to know under what rule the work which appears to be a new one was anctioned by the Chief Engineer.

(Signed) J. D. BOURDILLON,
*Secretary to Government.*

No. 7663.

# List of Works executed on emergency, submitted for the sanction of Government.

| Audit No. | Date Bill | Audit No. | From whom received | Description of works | Amount | | | Remarks |
|---|---|---|---|---|---|---|---|---|
| | 1859 January 18. | 170 | Acting Civil Architect | White and Bluewashing the interior wards and Cells, and repairing the Superintendents Quarters at the Penitentiary | 133 | 7 | 1 | This work was executed under instructions from the Barrack Master |
| 170 | " " | 171 | Do. | Covering with gratings the mouths of the wells in the General Hospital | 126 | 7 | 10 | Do. from the Town Major |
| 171 | | | | | | | | |
| 172 | | | | | | | | |
| 174 | | | | | | | | |
| 175 | " " | 172 | Do. | Examining the foundation, beams, and joists of the Sudder Uddalut Court Building at Royapettah | 113 | 8 | " | Do. Do. Chief Engineer |
| 176 | | | | | | | | |
| | | X | | | | | | |
| | " " | 173 | Do. | Setting up a new Meridional Instrument at the Observatory | 605 | 12 | 7 | Do. Do. Do. |
| | " " | 174 | Do. | Repairing the foot bridge adjoining Wallajah Bridge | 25 | 5 | 1 | Do. Do. Do. the present is the 2d part, or final, bill for the work |
| | | V | | | | | | |
| | | 175 | Do. | Removing the Gallery at St. George's Cathedral and flooring with Square Granite stones | 251 | " | 7 | Do. E. M. C. No. 1024. dated 31st May 1858 |
| | | 176 | Do. | Filling up breaches and strengthening the Vasumpandy Tank Bank in different places and turfing and forming bund behind Calingulah | 84 | " | " | Do. Civil Architect |
| | | | | Total Rupees. | 1339 | 9 | 2 | |

4 7 Bills 12

2 5½ 19½ 133-12-7

Central Office of P. W.
Fort Saint George
5th February 1859

To The Secretary to Government P. W. D.

Compd Civil

W. Taber Colonel
Chief Engineer

P W Departt

No. 555.

Extract from the Minutes of Consultation

Under date the 12th March 1859

Read the following

Letter from the Chief

Engineer.

(Govt enter 5th February 1859

No. 7663)

Of the seven Bills

submitted with the above

letter for works executed

on emergency in the ex

Presidency Division, the

Right Honorable the

Governor in Council sanc-

tions the undermentioned

Six amounting to Rupees

/1733-12-7/ Seven hundred

and thirty three, annas

twelve

From
The Chief Engineer
To
The Secretary to Govt
Pub. Dept.

Dated Calcutta 2 February 1859.

Rec'd 8th Do

No. 555 - Pub. Dept.

Enclosures 7 Bills

Subject

Bill of Works executed on Emergency submitted for the sanction of Government amounting to Rs 1339-9-2

Ans.

Pub. Cons. 1st June/58 No 181

No. 11 - 1858, dated Fort William the 2nd March

Rs 1339-9-2

Rs 1733-12-7

Amount allowed Rs 394-3-5

Amount disallowed Rs 1339-9-2

Amount allowed Rs 1733-12-7

twelve and piece seven.

| Audit No. | Description of works | Amount Rs | a | p |
|---|---|---|---|---|
| 170 | White and Bluewashing the interior wards and cells, and repairing the Superintendent's Quarters at the Penitentiary | 133 | 7 | 1 |
| 171 | Covering with gratings, the mouths of the wells in the General Hospital | 126 | 7 | 10 |
| 172 | Examining the foundation, beams, & joists of the Sudder Uddalut Court Building at Royapettah | 113 | 8 | . |
| 174 | Repairing the foot bridge adjoining Wallajah bridge | 25 | 5 | 1 |
| 175 | Removing the Gallery at Saint Georges Cathedral and flooring with square Granite Stones | 251 | . | 7 |
| 176 | Telling up breaches and strengthening the Vasurpauy Tank Bund in different places and turfing and forming bund behind in Calingulah | 84 | . | . |
| | Total Rs | 733 | 12 | 7 |

2. Bill No 173 is for setting the new meridional instrument in the observatory before sanctioning this the Government would wish to know under what

what rule the work which appears to be a new one was sanctioned by the Chief Engineer

To Copies to the Chief Engr with 7 Bills Encls 14

1 — Accts Genl

Public Works 1859 Dept.
Dy. to Cons: 15th March

No. 555

Extract Mins: of Cons:
D/ 12th March /59.

From the Chief Engr. D/ 30th March /59
Rec'd 62 in Cons: 4th Apl

Of 7 Bills for certain works executed on emergency in the Presidency submitted, sanctioning 6 for Rs 733-12-7 and requesting certain information regarding the remaining one.

No 574 55.