M.R.O. 1—77,006—8-6-37.

(1) Number of pages 10

(2) Date of repair 12-4-38

(3) Initials of the Reference

4

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

Ca. 15/3/59

G.O. No. 555 Press
52-55 Mis.

Dated 12 — 3 — 1859.

Not to be folded or roughly handled

No. 54. Read the following

List of Works executed on emergency submitted for the sanction of Government.

Date of Bill.	Audit No.	From whom received.	Description of Works.	Amount. Rs.	A.	P.	Remarks.
1859.							
Jany. 18.	170	Acting Civil Architect.	White and Blue washing the interior Wards and Cells, and repairing the Superintendent's Quarters at the Penitentiary.....	133	7	1	This work was executed under instructions from the Barrack Master.
„ „	171	do.	Covering with gratings, the mouths of the Wells in the General Hospital.....	126	7	10	do. from the Town Major.
„ „	172	do.	Examining the foundation, beams, and joists of the Sudder Uddalut Court Building at Royapettah.....	113	8	0	do. do. Chief Engineer.
„ „	173	do.	Setting up a new Meridional Instrument at the Observatory.....	605	12	7	do. do. do.
„ „	174	do.	Repairing the foot bridge adjoining Wallajah bridge....	25	5	1	do. do. do. the present is the 2nd part, or final bill for the work.
„ „	175	do.	Removing the Gallery at St. George's Cathedral and flooring with square Granite stones.....	251	0	7	do. E. M. C., No. 1,024, dated 31st May 1858.
„ „	176	do.	Filling up breaches and strengthening the Vasurpaudy Tank Bank in different places, and turfing and forming Bund behind Calingulah.....	84	0	0	do. Civil Architect.
			Total Rupees.....	1,339	9	2	

Central Office of P. W.,
Fort Saint George,
5th February 1859.

(Signed) C. E. FABER, Colonel,
Chief Engineer.

Fort Saint George, Public Works Consultation of 15th March 1859.

1 B.

Fort Saint George, Public Works Consultation of 15th March 1859.

No. 55. ORDER THEREON, No. 555; dated 12th March 1859.

Of the Seven Bills submitted with the above letter for works executed on emergency in the Presidency Division, the Right Honorable the Governor in Council sanctions the undermentioned Six amounting to Rupees (733-12-7) seven hundred and thirty-three, annas twelve and pice seven.

Audit No.	Description of Works.	Amount.		
		Rs.	A.	P.
170	White and Blue washing the interior Wards and Cells, and repairing the Superintendent's Quarters at the Penitentiary	133	7	1
171	Covering with gratings, the mouths of the wells in the General Hospital	126	7	10
172	Examining the foundation, beams, and joists of the Sudder Uddalut Court Building at Royapettah	113	8	0
174	Repairing the foot bridge adjoining Wallajah bridge	25	5	1
175	Removing the Gallery at Saint George's Cathedral and flooring with square Granite stones	251	0	7
176	Filling up breaches and strengthening the Vasurpaudy Tank Bank in different places and turfing and forming Bund behind Calingulah	84	0	0
	Total Rupees	733	12	7

2. Bill No. 173 is for setting the new meridional instrument in the Observatory; before sanctioning this the Government would wish to know under what rule the work which appears to be a new one was anctioned by the Chief Engineer.

(Signed) J. D. BOURDILLON,
Secretary to Government.

No. 7663.

List of Works executed on emergency, submitted for the sanction of Government.

Audit No.	Date Bill	Audit No.	From whom received	Description of works	Amount			Remarks
	1859 January 18.	170	Acting Civil Architect	White and Bluewashing the interior wards and Cells, and repairing the Superintendents Quarters at the Penitentiary	133	7	1	This work was executed under instructions from the Barrack Master
170	" "	171	Do.	Covering with gratings the mouths of the wells in the General Hospital	126	7	10	Do. from the Town Major
171								
172								
174								
175	" "	172	Do.	Examining the foundation, beams, and joists of the Sudder Uddalut Court Building at Royapettah	113	8	"	Do. Do. Chief Engineer
176								
		X						
	" "	173	Do.	Setting up a new Meridional Instrument at the Observatory	605	12	7	Do. Do. Do.
	" "	174	Do.	Repairing the foot bridge adjoining Wallajah Bridge	25	5	1	Do. Do. Do. the present is the 2d part, or final, bill for the work
		V						
		175	Do.	Removing the Gallery at St. George's Cathedral and flooring with Square Granite stones	251	"	7	Do. E. M. C. No. 1024. dated 31st May 1858
		176	Do.	Filling up breaches and strengthening the Vasumpandy Tank Bank in different places and turfing and forming bund behind Calingulah	84	"	"	Do. Civil Architect
				Total Rupees.	1339	9	2	

4 7 Bills 12

2 5½ 19½ 133-12-7

Central Office of P. W.
Fort Saint George
5th February 1859

To The Secretary to Government P. W. D.

Compd Civil

W. Taber Colonel
Chief Engineer

P W Departt

No. 555.

Extract from the Minutes of Consultation

Under date the 12th March 1859

Read the following

Letter from the Chief

Engineer.

(Recd inter 5th February 1859

No. 7663)

Of the seven Bills

submitted with the above

letter for works executed

on emergency in the ex

Presidency Division, the

Right Honorable the

Governor in Council sanc-

tions the undermentioned

Six amounting to Rupees

/1733-12-7/ Seven hundred

and thirty three, annas

twelve

From
The Chief Engineer
To
The Secretary to Govt
Pub. Dept.

Dated 8th February 1859.

Rec'd 8th Febry 1859.

No. 555 - Pub. Dept.

Enclosures 7 Bills

Subject

Field-of-Work

executed on Emergency

submitted for the Sanction

of Government amount-

ing to Rs 1339-9-2

Pub. Cons. 1st June 1859 No 181

No. 11 - 1859, dated Fort St. George the 2nd March

From
The Chief Engineer
To
The Secretary to Govt
Pub. Dept.

Dated 8th February 1859.

Rec'd 8th February 1859.

No. 555 - Pub. Dept.

Enclosures 7 Bills

Subject

Field-of-Work

executed on Emergency

submitted for the Sanction

of Government amount-

ing to Rs 1339-9-2

12 (Number 10 illegible)

twelve and piece seven.

Audit No.	Description of works	Amount Rs	a	p
170	White and Bluewashing the interior wards and cells, and repairing the Superintendent's Quarters at the Penitentiary	133	7	1
171	Covering with gratings, the mouths of the wells in the General Hospital	126	7	10
172	Examining the foundation, beams, & joists of the Sudder Uddalut Court Building at Royapettah	113	8	.
174	Repairing the foot bridge adjoining Wallajah bridge	25	5	1
175	Removing the Gallery at Saint Georges Cathedral and flooring with square Granite Stones	251	.	7
176	Telling up breaches and strengthening the Vasurpauy Tank Bund in different places and turfing and forming bund behind in Calingulah	84	.	.
	Total Rs	733	12	7

2. Bill No 173 is for setting the new meridional instrument in the observatory before sanctioning this the Government would wish to know under what

what rule the work which appears to be a new one was sanctioned by the Chief Engineer

To Copies to the Chief Engr with 7 Bills Encls 14

1 — Accts Genl

Public Works 1859 Dept.
Dy. to Cons: 15th March

No. 555

Extract Mins: of Cons:
D/ 12th March /59.

From the Chief Engr. D/ 30th March /59
Rec'd 62 in Cons: 4th Apl

Of 7 Bills for certain works executed on emergency in the Presidency submitted, sanctioning 6 for Rs 733-12-7 and requesting certain information regarding the remaining one.

No 574 55.