

(1) Number of pages 4(2) Date of repair 8-12-38(3) Initials of the Referencer A**MADRAS RECORD OFFICE.****Government of Madras.***Public Works* **DEPARTMENT.***Cons. 20.2.1860*

G.O. No.	356	Press Mis.
Dated	16-2.	1860 .

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
for the month of February 1860.*

No. 52. Read the following.
No. 10228.

List of a Bill received from the District Engineer of Kurnool, submitted for the sanction of Government which exceeds its estimate by more than 5 per cent.

Audit No.	Date of bill.	Description of work.	Amount of estimate.			Amount of bill.			Excess.			Per centage of excess.	To what year the expenditure appertains.	Remarks.
1839	1859. Oct. 12	Repairing Táti-káya tanksluice at Pániem	90	7	0	101	5	8	10	14	8	12	1859-60	This excess was occasioned by the wing walls, which were newly built being destroyed in June last by the tank filling unexpectedly.

Central office of P. W.,
Sépákkam,
13th February 1860. }

(Signed) J. H. BELL, Colonel,
Chief Engineer.

No. 53.

ORDER THEREON, 16th February 1860, No. 356.

The Bill is sanctioned.

(Signed) T. PYCROFT,
Chief Secretary.

10928

List of a Bill received from the District Engineer of Hurwood, submitted for the sanction of Government which exceeds its Estimate by more than 5 per cent.

Audit Date of Bill	Description of work	Amount of Estimate	Amount of Excess	Per centage of Excess	In what year the expenditure is to be made	Remarks
1839 Oct 12	Repairing Stationary Sink Sluice at Cannies	90 7	10 14 8	12	1839/40	This excess was occasioned by the wing walls, which were newly built being destroyed in June last by the tank falling unexpectedly.

1839
Oct 12

Central Office of P.W.
Department
13 February 1860.

To The Secretary to Government
Public Works Department

J. H. L. W. Colonel
Chief Engineer.

94-356

The Bill is
herewith



Thos. W. Jones
6a Octy / 60

10 Copies Christ and his world - April - 1897
1 " Christ and his world - 17

With me and
No. 358. 16. St. 67