M.R.O. 1—77,005—8-6-57.

(1) Number of pages 1

(2) Date of repair 3.11.38

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.
Ex 29/2/60

G.O. No. 404 Press
Mis.

98.50

Dated 24—2—1860.

Not to be folded or roughly handled

7

No. 49. Read the following.

No. 10102.

List of Bill received from the District Engineer of North Arcot, and submitted for the sanction of Government which exceeds its estimate by more than 5 per cent.

Audit No.	Date of bill.	Description of work.	Amount of estimate.	Amount of bill.			Excess.			Per centage of excess.	To what years expenditure appertains.	Remarks.
	1859.		Rs.	Rs.	A.	P.	Rs.	A.	P.			
1786	Dec. 31.	Final bill for repairing Kadapéri tank estimate sanctioned by the Chief Engineer on the 22nd November 1856	.....	266	12	3						This excess is owing to a sum of Rupees 254-14-2 having been paid for the clearing of a large quantity of prickly pear from the tank bund, for which no provision was made in the estimate prepared by Mr. Assistant Overseer Lee. The contractors for the work claimed Rs. 290-11-9, but a fair valuation having been made, the District Engineer states that they are only entitled to the sum first mentioned.
		Add the amount of part bills already passed by the Chief Engineer.	1,030	1,018	1	7	254	13	10	24¾	1859-60.	
				1,284	13	10						

Central office of P. W., Sépákkam, 9th February 1860.

(Signed) J. H. BELL, Colonel,
Chief Engineer.

No. 50. ORDER THEREON, 24th February 1860, No. 404.

1. The Bill is sanctioned.

2. Adverting to the explanation in the column of remarks, the Government trust that the views expressed in their order of the 9th July 1859 No. 1672 respecting the liability of ráyats to remove prickly pear from tank bunds will be duly acted upon in future similar cases. The work now in question, it is observed, was completed on the 15th July 1859.

(Signed) T. PYCROFT,
Chief Secretary.

List of Bills received from the District Engineer of North Arcot and Submitted for the Sanction of Government, which exceeds its Estimate by more than 5 per Cent. — No 10102

Audit No.	Date of Bill	Description of work	Amount of Estimate	Amount of Bill	Excess	Percentage of Excess	Year expenditure ascertained	Remarks.
1786.	1859 Dec. 31st	Final Bill for repairing Cadapary Tank. Estimate sanctioned by the Chief Engineer on the 22d. November 58.	"	"	266 12 3			This excess is owing to a sum of Rupees 254-14-2 having been paid for the Clearing of a large quantity of prickly pear from the Tank bund, for which no provision was made in the Estimate prepared by Mr. Assistant Bransom Lee. The Contractors for the work claimed Rupees 290-11-9 but a fair valuation having been made, the District Engineer states that they are only entitled to the sum first mentioned.
		Add the Amounts of Part Bills already passed by the Chief Engineer	1050 " "	1318-1 1/2 254-13 10	254-13 10	24 3/4	1859/60.	

Central Office P.W.
Department
9th February 1860.

L.A. Scott
Dy. Chief Engineer Central Circle

To The Secretary to Government
Department of Public Works

H.D. Colonel
Chief Engineer

P.W. 1860 Department
Pro: of Govt 29 February.

No. 366.

From

The Chief Engineer

To

The Secretary to Govt.

Dept. of Public Works

Dated 9th February 1860.

Rec'd 9th February 1860.

No. 1012

Enclosure. One Bill

A Bill received from the District Engineer of North River & submitted for sanction, for which exceed the Estimate by more than 5 per Cent.—

Letter Order

No 404 - 24 Feb.

No. 404.

1 The Bill is sanctioned.

2 Adverting to the explanation in the Column of remarks the Government trust that the principles expressed in their order of the 9 July 1859 No 1672 respecting the liability of parties to remove pricky pear fences to roads will be duly acted upon in future similar cases. The work now in question it is observed, were completed on the 15th July 1859.

Fort St George
24th Feby 1860

10 Copies to the Chief Engr with Bill Rec'd 25
1 " " Accountant General

Pay 450

Rs 15 Feby & 20