M.R.O. 1—77,005—6-6-31.

(1) Number of pages 4

(2) Date of repair 31-10-36

(3) Initials of the Referencer

4

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

Con 29/2/60

G.O. No. 427 Press Mis.

9798

Dated 28—2—1860.

Not to be folded or roughly handled

No. 97. Read the following.

No. 10244.

List of bills received from the District Engineer of Godavery, for a work executed on emergency, submitted for the sanction of Government.

Audit No.	Date of bills.	Description of works.	Amount of bill.			The year to which the expenditure appertains.	Remarks.
	1859.		Rs.	A.	P.		
1814	May 1st.	Repairing temporary buildings of Sappers and Miners at Dowlaiweram...	804	13	3	1857-58.	Ordered by the Officer Commanding Northern Division on the 20th May 1857.
1815	Nov. 15th.	Do. do. at. do.....	18	5	10	1858-59.	
		Total.....	823	3	1		

Central Office of P. W., Sépâkkam, 13th February 1860.

(Signed) J. H. BELL, Colonel,
Chief Engineer.

No. 98. Order thereon, 28th February 1860, No. 427.

Sanctioned.

(Signed) T. PYCROFT,
Chief Secretary.

List of Bills received from the Deputy Executive Engineer of Godavery for a work executed on emergency submitted for the sanction of Government.—

Audit No	Date of Bills	Description of work	Amount of Bill	The year to which the expenditure pertains	Remarks
	1859				
1814	May 1st	Repairing temporary Buildings of Sappers and Miners at Dowlaisweram	764 13 3	1857/58	Ordered by the Officer Commanding Northern Division on the 20th May 1857.
1815	Nov. 15	Do Do at Do	18 5 10	1858/59	
	Enc. 2 Bills	Total	883 3 1		

For Depy Ch. Engr. N. Circle
A. St. Croll

Central Office of Public Works
Sepaktaum 13th February 1860

To The Secretary to Govt
of M. Depts.

J. H. Dall Colonel
Chief Engineer

No 427.

Dated 10th February 1860

Received 15th February 1860

Registered

Letter from the Deputy Engineer of Gardanery for a work executed on emergency submitted for the sanction of Government amounting to Rupees 883-3-1.

Read

Sanctioned.

28th May 1861

Brevet Lt Genl

Chief Engineer

Bill

Chief Engineer

Bill

Chief Engineer