M.R.O. 1—77,000—8-6-37.

(1) Number of pages 4

(2) Date of repair 5.74 5. 42.

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 8 Press ~~Mis.~~
14-15

Dated 15-1- 1862.

Not to be folded or roughly handled

Proceedings of the Madras Government, Public Works Department,
15*th Jannary* 1862.

No. 14. Read the following Proceedings of the Madras Government in the Ecclesiastical Department, dated 4th January 1862, No. 1.)

Sanctioning a revised Estimate for suspending a Bell at Saint Paul's Church at Waltair in Vizagapatam. } (Vide Ecclesiastical Proceedings, 4th Jaunuary 1862, Nos. 1-2.

No. 15. ORDER THEREON, 15th January 1862, No. 8.

Communicated to the Deputy Chief Engineer Northern Circle, for information and guidance.

(Signed) W. H. HORSLEY, Lieut.-Colonel,
Chief Engr. and Secy. to Govt. D.P.W.

ECCLESIASTICAL DEPARTMENT.

PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following letter from Lieutenant-Colonel W. H. HORSLEY, Chief Engineer, D. P. W.; to J. D. SIM, Esq., Secretary to Government, P. W. D. Fort Saint George, dated Chepauk, 12th December 1861, No. 8,267.

Ecclesiastical.

Enclosures 5.
1 Letter from Commissary of Diocese, No. 465, dated 14th August 1861, with 2 Enclosures.
1 Do. District Engineer, Vizagapatam, No. 871, dated 7th November 1861.
1 Estimate.

I have the honor to bring the following circumstances to the notice of Government.

2. On the 14th August 1861, the Commissary of the Diocese forwarded an Estimate amounting to Rupees 70 for suspending a Bell at Saint Paul's Church at Waltair in the District of Vizagapatam, but the plan having been found defective, a revised one amounting to Rupees 100 was prepared in this Office and sanctioned by me agreeably to the Order of Government No. 889, dated 3rd May 1861.

3. The District Engineer now solicits permission to construct the walls of the Belfry of cutstone instead of brick, as a very inferior description of the latter material is procurable in the Vizagapatam District, and to increase the thickness of the Belfry wall to two feet instead of one foot nine inches, as allowed in the sanctioned Estimate.

4. As the alterations proposed have my approval, I beg to recommend that the revised Estimate amounting to Rupees 130, (less Rupees 100 already sanctioned) which has been examined in this Office and found correct, may receive the sanction of Government.

Transferred to the Ecclesiastical Department.

(Signed) C. G. MASTER,
Deputy Secy. to Govt.

16*th December* 1861.

ORDER THEREON, 4th January 1862, No. 1.

The Government sanction the work provided for in the revised Estimate now submitted, amounting to Rupees (130) one hundred and thirty, less Rupees (100) one hundred already passed on this account by the Chief Engineer.

(True Extract.)

Chief Secretary.

To the Chief Engineer.
(with five enclosures.)
„ Department Public Works.
„ Accountant General.
„ Venerable the Archdeacon.

Exd. T. O'Connor.

P. W.- 1862 Despat
Pro: of Govt. for January
No. 2

Proceedings of the
Madras Govt. in
the Ecclesiastical
Despat.

Dated 4th }
Received 5th } January
1862.
No. 1

Letter & Order.

Sanctioning a re-
vised Estimate for
suspending a Bell at
Saint Paul's Church at
Waltair in Vizagapatam

No. 8
Communicated to the Dy. Chief
Engineer Northern Circle
for information and
guidance
No. 8. 15th January

No. 14 & 15

6 Copies

To
The Dy. Chief Engineer N.C.
with Pro: Govt. No. 8 dated 15th