M.R.O. 1—77,000—8-6-37.

(1) Number of pages 6

(2) Date of repair 15-5-42

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 108 Press
Mis.

Lo—11.

Dated 1—2— 1942.

Not to be folded or roughly handled

Proceedings of the Madras Government, Public Works Department, 1st February 1862.

No. 10. Read the following letter from Colonel W. I. BIRDWOOD, Deputy Chief Engineer, Southern Circle, to Lieutenant-Colonel W. H. HORSLEY, Chief Engineer and Secretary to Government, Department Public Works, dated Chepauk, 23rd January 1862, No. 9,705:—

SIR,

1. In submitting the accompanying Proceedings* of the Board of Revenue, communicating a letter† from the Collector of South Arcot, bringing to notice the falling off in the Salt sales during the month of November 1861, owing to the "bad state of the approaches to the several Depôts," occasioned by the heavy fall of rain in that District, I have the honor to state, for the information of Government, that the District Engineer has been requested to forward an Estimate for repairing them, together with a sketch map showing the direction of the different lines. These documents will be submitted to Government on receipt.

* No. 266, dated 11th January 1862.

† No. 164, dated 23rd December 1861.

2. I beg to add that Captain Foord has also been directed to commence, on emergency, any temporary repairs that he may consider absolutely necessary to the roads in question, and which I trust will meet with the approval of Government.

No. 11. ORDER THEREON, 1st February 1862, No. 108.

1. The Government will await the receipt of the estimate referred to in paragraph 1.

2. The Deputy Chief Engineer's proceedings, as reported in paragraph 2, are approved; but that Officer should have mentioned whether the cost of the emergent repairs will be met from the ordinary repair allotment of the District. The Board of Revenue will ascertain from the Collector if the Deputy Collector in charge of the Pans had reported to him the bad state of the roads; and if so, what steps had been taken by him to have them repaired.

(Signed) W. H. HORSLEY, Lieut.-Colonel,
Chief Engr. and Secy. to Govt., D.P.W.

2/2

Central Office of Pks.
Chesapeake, 3
23d January 1862.
No. 9705

From
Colonel W. S. Birdwood
Dy. Ch. Engr. Dr. C.

To
Lt. Col. Sir W. Yorke
Ch. Engr. & Secy. to Gen. Bd.
York & St. George.

Sir,

I do submitting the ac-
6,911. 1/62. companying Proceedings of the
Board of Revenue, communi-
6,923. 1/61. cating a letter from the Collector
of South Arcot, bringing to
notice the falling off in the
Salt Sales during the month
of November 1861, owing to the
"bad state of the approaches
to the several Depôts," occasioned
by the heavy fall of rain
in that District, I have the
honor to state, for the information
of Government, that the a-

District

4/4

District Engineer has been requested to forward an estimate for repairing them, together with a Sketch map shewing the direction of the different lines. These documents will be submitted to Government on receipt.

2. I beg to add that Captain Ford has also been directed to commence, on any emergency temporary repairs that he may consider absolutely necessary, to the roads in question, & which I trust will meet with the approval of Government.—

Central Office
Chittagong
23rd Jan 1862.

I have the honor to be,
Sir,
Your most obedt Servt

A.W. Rawlins. Major

To
Lt Col. H. H. Horsley
Ch. Engr & Secy to Govt
Fort William

for Offg Ch. Engr & C.

5/2

From the Dy. Chief Engr
S. C. D/ 21 Feby /62
C. P. 519 in Ltr

No. 10811.

25 Jany 1829

Public Works 1862 Dept.
Secy's Office February
Gov. Jr. 108
Col. H. J. Biddwood
Dy. Chf. Engr. &c.
To
Lieut. Col. H. Haverty
Ch. Engr. & Secy. to Govt.
P.W.D.

Date 23 Jany 1862.
Rec. 24. 5 Encl.
No. 108-1862 No. 9705

Submits for information Rep. from the Bd. of Rev. commanding a letter from the Collector of South Arcot, reporting the cause of falling off in the Salt Sales for 1861, and states what steps have been taken to repair the Salt wells. With an Order.

* The Board of Revenue will accordingly forward to the Collector in charge of the Pon Land Customs a list of the roads, which it has been decided by Govt. to have them repaired.

Fort St. George 1st February 1862.

X. 87.
63 Copies
To
The Deputy Chief Engr. 1st Circle
6. — Revenue Department.

No. 108
The Deputy Chief Engr. 1st Circle
receipt of the
to in para 1.

The Deputy Chief Engineers
Proceedings as reported in paragraph 2 are approved, but that Officer should have mentioned whether the cost of the emergent repairs will be met from the ordinary repair allotment of the District. *