M.R.O. 1—77,006—8-6-37.

(1) Number of pages 12

(2) Date of repair 16-5-62

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 936 Press / Mis.
94-95

Dated 3-5- 1862.

Not to be folded or roughly handled

Proceedings of the Madras Government, Public Works Department, 3rd May 1862.

No. 94. Read the following Endorsement of the Officer in charge of the Audit and Account Departments, dated Chepauk, 9th April 1862, No. 12,486.

Read the following letter from Major J. F. STODDARD, Acting District Engineer, Godavery, to Lieutenant-Colonel J. OUCHTERLONY, Acting Deputy Chief Engineer, Northern Circle, dated Dowlaishwaram, 12th February 1862, No. 1,236 :—

SIR,

I have the honor to forward two Bills amounting to Rupees 1,439-9-0 and Rupees 956-7-2 respectively, on account of the expenditure incurred in the months of October and November last, in fitting up, cleaning and painting certain Steamers and Paddle boats; also repairing, cleaning, and otherwise preparing three houses selected for the reception of His Lordship the Viceroy of India and Suite at Dowlaishwaram, and to request that you will be so good as to submit the same to the Government of Madras for the purpose of being forwarded for payment to the Government of India.

Bill for fitting and painting Steamers for use of His Lordship the Governor General of India, in the month of October and November 1861.

Description of charges.	Rate.	Amount.	Total.
	RS. A. P.	RS. A. P.	RS. A. P.
FITTING AND PAINTING STEAMERS.			
Steamer "Frank and Ada."			
Labour.			
3 Smiths	... each	0 4 5	0 13 3
15½ Do.	... „	0 5 4	5 2 8
3 Hammer men	... „	0 3 10	0 11 6
9½ Do.	... „	0 2 9	1 10 1
20 Vice men	... „	0 4 5	5 8 4
44 Do.	... „	0 6 3	17 3 0
3 Bellows Boys	... „	0 3 10	0 11 6
9½ Do.	... „	0 1 5	0 13 6
3 Vice Boys	... „	0 4 3	0 12 9
24 Do.	... „	0 2 4	3 8 0
9 Lascars	... „	0 4 0	2 4 6
33½ Do.	... „	0 3 4	6 15 8
11 Moochies	... „	0 5 0	3 7 0
6½ Carpenters	... „	0 5 8	2 4 10
Materials.			
14 lbs. Round iron ½"	... „	0 1 3	1 1 6
16½ lbs. Sheet iron	... „	0 1 6	1 8 9
6¾ lbs. Cast steel	... „	0 10 0	4 3 6
2 lbs. Lamp oil	... „	0 1 11	0 3 10
¼ lb. Nails	... „	0 2 3	0 0 7
1 Tin sheet	... „	0 1 7	0 1 7
⅛ lb. Tin	... „	0 12 10	0 1 7
⅛ lb. Salmoniac	... „	0 8 0	0 1 0
⅙ lb. Do.	... „	0 10 8	0 0 8
⅛ lb. Zinc...	... „	0 4 0	0 0 6
1 lb. Soap	... „	0 3 0	0 3 0
31 lbs. Red lead	... „	0 3 10	7 6 10
56 lbs. White paint	... „	0 3 0	10 8 0
56 lbs. Yellow paint	... „	0 2 4	8 2 8
29 lbs. Linseed oil	... „	0 3 10	6 15 2
6½ lbs. Turpentine	... „	0 12 0	4 14 0
25 lbs. Black varnish	... „	0 6 0	9 6 0
½ lb. Borax	... „	0 8 0	0 0 3
3 lbs. Cotton rope	... „	0 5 0	0 15 0

Bill for fitting and painting Steamers, &c. (Continued.)

Description of charges.	Rate.			Amount.			Total.		
	RS.	A.	P.	RS.	A.	P.	RS.	A.	P.
13 lbs. Coal Tar ... ... each	0	2	0	1	10	0			
1 lb. Waste Hemp ... ... ,,	0	0	4	0	0	4			
½ lb. Thread ... ... ,,	0	8	0	0	4	0			
⅛ lb. Wax ... ... ,,	0	10	0	0	1	3			
¼ lb. Brass sheet ... ... ,,	0	12	8	0	3	2			
25 lbs. Copper Tacks 100	0	6	0	0	1	6			
2 Files ... ... each	1	10	8	3	5	4			
2 Do. ... ... ,,	1	0	2	2	0	4			
22 Screws ... ... ,,	0	0	2	0	3	8			
18 Do. ... ... ,,	0	0	3	0	4	6			
1 Sand Paper ... ... ,,	0	0	4	0	0	4			
1 Pot ... ... ,,	0	0	4	0	0	4			
2 Rags ... ... ,,	0	0	1	0	0	2			
66½ Yds. Dungaries ... ... ,,	0	5	0	20	12	6			
1 Foot coarse cloth ... ... ,,	0	1	2	0	1	2			
15½ Parrahs Wood Charcoal ... ... ,,	0	3	8	3	8	10			
4 Parrahs Palmyra Charcoal ... ... ,,	0	3	0	0	12	0			
Painting by contract	0	0	0	7	0	0			
Workshop general superintendence and sundries at 10 per cent. on Rupees 148-1-11	0	0	0	14	12	11			
				162	14	10			
Stores supplied.									
212 lbs. coils of Coir rope ... ... each	0	0	8	8	13	4			
32½ lbs. Cotton rope ... ... ,,	0	5	0	10	2	6			
56 lbs. Cocoanut oil ... ... ,,	0	2	8	9	5	4			
20 lbs. Castor oil ... ... ,,	0	2	8	3	5	4			
4 lbs. Grease ... ... ,,	0	3	4	0	13	4			
8 lbs. Do. ... ... ,,	0	3	3	1	10	0			
6 lbs. Waste Hemp ... ... ,,	0	0	4	0	2	0			
26 lbs. Hemp ... ... ,,	0	0	10	1	5	8			
4 lbs. Lamp oil ... ... ,,	0	1	11	0	7	8			
2 Yds. Dungary ... ... ,,	0	3	3	0	6	6			
Workshop general superintendence and sundries at 10 per cent. on Rupees 36-7-8	0	0	0	3	10	4			
				40	2	0			
							203	0	10
Steamer "Arthur Cotton."									
Labour.									
13 Vice men ... ... each	0	6	3	5	1	3			
10½ Do. Boys ... . ,,	0	2	4	1	8	6			
15 Carpenters ... ... ,,	0	5	8	5	5	0			
4½ Apprentices... ... ... ,,	0	2	2	0	9	9			
15 Lascars ... ... ,,	0	3	4	3	2	0			
3 Moulders ... ... ,,	0	4	0	0	12	0			
6 Bellows Boys ... ... ,,	0	1	5	0	8	6			
3 Moochies ... ... ,,	0	5	0	0	15	0			
Materials.									
62 lbs. Old Copper ... ... ,,	0	10	3	39	11	6			
8 lbs. Tin ... . ,,	0	12	10	6	6	8			
½ lbs. Zinc ... ... ,,	0	4	2	0	2	1			
2 lbs. Red ochre ... ... ,,	0	2	4	0	4	8			
2 lbs. Boiled Linseed Oil... ... ... ,,	0	3	10	0	7	8			
½ lb. Turpentine ... ... ,,	0	12	0	0	6	0			
4 lbs. Wrought nails ... ... ,,	0	4	0	1	0	0			
3 lbs. Country nails ... ... ,,	0	2	1	0	6	3			

Bill for fitting and painting Steamers, &c. (Continued.)

Description of charges.	Rate.			Amount.			Total.		
	RS.	A.	P.	RS.	A.	P.	RS.	A.	P.
6 lbs. White paint ... ... each	0	3	0	1	2	0			
6 Crucibles ... ... ,,	0	1	6	0	9	0			
400 Tacks, iron 100	0	1	6	0	6	0			
72 Screws ... ... each	0	0	3	1	2	0			
6 Parrahs Wood Charcoal ... ... ,,	0	3	8	1	6	0			
Workshop general superintendence and sundries at 10 per cent. on Rupees 71-3-10	0	0	0	7	2	0			
							78	5	10
Steamer "Little Nell."									
Labour.									
19¾ Smiths ... . each	0	5	4	6	9	4			
14½ Hammer men ... ... ,,	0	2	9	2	7	11			
24¼ Bellows Boys ... ... ,,	0	1	5	2	2	4			
26 Carpenters ... ... ,,	0	5	8	9	3	4			
7 Apprentices... ... ... ,,	0	2	2	0	15	2			
13 Vice men ... . ,,	0	6	3	5	1	3			
7 Do. Boys ... ... ,,	0	2	4	1	0	4			
67 Lascars ... ... ,,	0	3	4	13	15	4			
20 Sail makers... ... ... ,,	0	3	4	4	2	8			
17 Moochies ... ... ,,	0	5	0	5	5	0			
131 Tailors ... ... ,,	0	4	0	32	12	0			
Materials.									
140½ lbs. Round Iron ... ... each	0	1	3	10	15	7			
33 lbs. Do. ... ... ,,	0	1	6	3	1	6			
3½ lbs. Pig Lead ... ... ,,	0	3	0	0	10	6			
21 lbs. Coal Tar ... ... ,,	0	2	0	2	10	0			
4 lbs. Red Lead ... ... ,,	0	2	3	0	9	0			
28½ lbs. White paint ... ... ,,	0	3	0	5	5	6			
12 lbs. Yellow paint ... ... ,,	0	5	4	4	0	0			
1 lb. Red Lead ... ... ,,	0	3	4	0	3	4			
10 lbs. Do. ... ... ,,	0	3	10	2	6	4			
32 lbs. Do. ... ... ,,	0	4	0	8	0	0			
¼ lb. Prussian Blue ... ... ,,	0	2	0	0	8	0			
3 lbs. Turpentine ... ... ,,	0	12	0	2	4	0			
1 lb. Do. ... ... ,,	0	12	8	0	12	8			
28 lbs. Boiled Linseed Oil ... ... ,,	0	3	10	6	11	4			
¾ lb. Soap ... ... ,,	0	3	0	0	2	3			
½ lb. Do. ... ... ,,	0	2	8	0	1	4			
8 lbs. Waste Hemp ... . ,,	0	0	4	0	2	8			
¼ lb. Tin ... ... ,,	0	12	8	0	3	2			
⅛ lb. Salmoniac ... ... ,,	0	8	0	0	1	0			
⅛ lb. Iron wire ... . ,,	0	8	0	0	1	0			
1⅛ lb. Lamp oil ... ... ,,	0	1	11	0	2	11			
1 lb. Twisted thread ... ... ,,	0	8	0	0	8	0			
⅛ lb. Wax ... ... ,,	0	10	0	0	1	0			
¼ lb. Do. ... ... ,,	0	2	1	0	2	6			
2 lbs. Country Nails ... ... ,,	0	8	0	0	4	2			
1½ lbs. Cotton Thread ... ... ,,	0	2	4	0	12	0			
2¾ lbs. Cut Nails ... ... ,,	0	2	0	0	6	5			
¼ lb. Country Twine ... ... ,,	0	0	5	0	0	6			
6 lbs. Coir rope ... . ,,	1	0	2	3	0	6			
3 Files .. .. ,,	1	12	8	3	9	4			
2 Rubber valves ... ... ,,	0	10	0	2	8	0			
4 Paint Brushes ... ... ,,	0	2	0	0	4	0			
2 Glass panes ... ... ,,	0	0	6	0	2	0			
4 Red thread bundles ... ... ,,	0	1	6	0	7	6			
5 Tin Sheets ... ... ,,	0	2	8	0	1	4			
50 Iron tacks 100	0	1	3	0	1	0			
80 Do. ... ... ,,									

Bill for fitting and painting Steamers, &c. (Continued.)

Description of charges.	Rate.	Amount.	Total.
	Rs. A. P.	Rs. A. P.	Rs. A. P.
12 Yds. Curtain cloth ... ... per Yd.	0 3 0	2 4 0	
2½ Yds. Red cloth ... ... „	0 7 6	1 2 9	
2½ Feet coarse cloth ... ... each	0 2 0	0 5 0	
23 Yds. Green Tape ... ... 20 Yds.	1 0 0	1 2 4	
2 Feet Europe Canvas ... ... „	0 8 0	0 5 4	
68 Yds. Dungaries ... ... „	0 5 0	21 4 0	
25 Yds. Do. ... ... „	0 3 3	5 1 3	
31 Parrahs Wood charcoal... ... ... each	0 3 8	7 1 8	
7 Do. Palmyra charcoal ... ... „	0 3 0	1 5 0	
22′ 1″ Cubic feet Pegue wood ... ...C. ft.	2 4 0	49 11 0	
142½ Sqr. feet Sawyer's hire ... 100 feet	1 5 4	1 14 5	
46 Screws ... ... each	0 0 3	0 11 6	
11 lbs. Cotton rope ... ... „	0 5 0	3 7 0	
3 Pairs Brass hinges ... ... „	0 5 0	0 15 0	
Workshop general superintendence and sundries at 10 per cent. on Rupees 241-11-9	0 0 0	24 2 9	
		265 14 6	
Stores supplied.			
24 lbs. Cocoanut oil ... ... each	0 2 8	4 0 0	
8 lbs. Grease... ... ... „	0 3 3	1 10 0	
4 lbs. Hemp... ... ... „	0 0 8	0 2 8	
6 lbs. Do. ... ... „	0 0 10	0 5 0	
½ lb. Boiled Linseed oil ... ... „	0 3 10	0 1 11	
2 Yards Coarse cloth... ... ... „	0 2 0	0 4 0	
12 lbs. Lamp oil... ... ... „	0 1 11	1 7 0	
1⅛ lbs. Cotton Thread... ... ... „	0 8 0	0 9 0	
1 Small pot... ... ... „	0 0 4	0 0 4	
Workshop general superintendence and sundries at 10 per cent. on Rupees 8-7-11...	0 0 0	0 13 7	
		9 5 6	275 4 0
Steamer "Pioneer."			
Labour.			
16 Vice men... ... ... each	0 6 3	6 4 0	
17 Do. boys... ... . „	0 2 4	2 7 8	
4½ Smiths... ... ... „	0 3 4	12 4 8	
2½ Hammer men... ... ... „	0 5 4	1 8 0	
5½ Bellow boys... ... ... „	0 2 9	0 6 11	
6 Carpenters ... ... „	0 1 5	0 7 9	
3 Apprentices ... ... „	0 5 8	2 2 0	
12 Moochies... ... . „	0 2 2	0 6 6	
71 Lascars for bringing Steamer from Bezwada. „	0 5 0	3 12 0	
1 Do. do. ... „	0 4 6	19 15 6	
1,200 Running feet caulking hire... ... 100 ft.	0 3 2	0 3 2	
131 Tailors.. ... ... each	0 12 0	9 0 0	
	0 4 0	32 12 0	
Materials.			
55 lbs. White paint ... ... each	0 3 0	10 5 0	
1 lb. Do. ... ... „	0 2 8	0 2 8	
22 lbs. Red lead ... ... „	0 4 0	5 8 0	
68 lbs. Do. ... ... „	0 3 10	16 4 8	
1½ lbs. Prussian blue ... . „	2 0 0	3 0 0	

Bill for fitting and painting Steamers, &c. (Continued.)

Description of charges.	Rate.	Amount.	Total.
	Rs. A. P.	Rs. A. P.	Rs. A. P.
6 lbs. Turpentine... ... ... each	0 12 0	4 8 0	
28 lbs. Yellow paint... ... ... „	0 5 4	9 5 4	
14 lbs. Black varnish ... ... „	0 6 0	5 4 0	
2 lbs. Paint brushes ... ... „	0 10 0	1 4 0	
45½ lbs. Boiled Linseed Oil... ... ... „	0 3 10	10 14 5	
12 lbs. Lamp Oil ... . „	0 1 11	1 7 0	
8 lbs. Cocoanut Oil... .. .. „	0 2 8	1 5 4	
10 Covedy Ropes. ... ... „	0 1 0	0 10 0	
2 lbs. Coir rope... ... ... „	0 0 8	0 1 4	
1/16 lbs. Rosin ... ... „	0 1 2	0 0 1	
2 lbs. Twisted Thread... ... ... „	0 8 0	1 0 0	
4 lbs. Grease... ... ... „	0 3 3	0 13 0	
1⅞ lbs. Soap... ... ... „	0 3 0	0 5 7	
26½ lbs. Cotton Rope.. ... ... „	0 5 0	8 4 6	
⅛ lb. Chalk line... ... ... „	0 8 0	0 1 0	
1¼ lbs. Cut Nails. ... ... „	0 2 4	0 2 11	
¾ lb. Tin... ... ... „	0 12 10	0 9 7	
½ lb. Do. ... ... „	0 12 0	0 6 0	
11 lbs Coal Tar... ... ... „	0 2 0	1 6 0	
¼ lb. Iron Wire ... . „	0 8 0	0 2 0	
¾ lb. Borax ... ... „	0 8 0	0 6 0	
6 3/16 lbs. Sheet Copper... ... ... „	0 13 0	5 0 5	
37½ lbs. Pitch... ... ... md.	2 1 3	3 1 11	
6½ lbs. Cotton... ... ... each	0 2 6	1 0 3	
1¾ lb. Zinc... ... ... „	0 4 2	0 7 3	
1 File... ... ... „	1 0 2	1 0 2	
⅛ lb. Salmoniac. ... ... „	0 10 0	0 1 3	
⅛ lb. do. ... ... „	0 8 0	0 1 0	
36 Yds. Dungaries... ... ... 12 yds	3 12 0	11 4 0	
1 Do. do. .. .. „	0 3 3	0 3 3	
5 Do. Coarse cloth ... ... „	0 2 0	0 0 0	
2 Feet Do. ... . feet	0 0 10	0 1 8	
1 Feet Do. ... ... „	0 1 3	0 1 3	
2 Brooms... ... ... each	0 0 2	0 0 4	
1 Small pot... ... ... „	0 0 4	0 0 4	
1 Large pot ... ... „	0 1 0	0 1 0	
6½ Parrah Wood charcoal... ... ... „	0 3 8	1 7 10	
1 Crucible... ... ... „	0 1 6	0 1 6	
4 lbs. Waste Hemp ... ... „	0 0 4	0 1 4	
34 Screws... ... ... „	0 0 3	0 8 6	
1 Yard blue cloth ... . yd	0 4 7	0 4 7	
3 Do. red cloth... ... ... „	0 7 6	1 6 6	
17¼ Do. green chintz... ... ... „	0 5 4	5 12 0	
¾ Do. long cloth ... ... each	0 4 0	0 3 0	
1/16 lb. Wax..... .... „	0 10 8	0 0 8	
4 lbs. Chalk ... . „	0 0 8	0 2 8	
1 Empty paint bucket ... ... „	0 6 0	0 6 0	
Workshop general superintendence and sundries at 10 per cent. on Rupees 208-11-3...	0 0 0	20 13 11	
		229 9 2	
Stores supplied.			
20 lbs. Cocoanut oil... ... ... each	0 2 8	3 5 4	
8 lbs. Lamp oil... ... ... „	0 1 11	0 15 4	
6 lbs. Grease.. ... ... „	0 3 3	1 3 6	
8 lbs. Hemp... ... ... „	0 0 10	0 6 8	
1 lb. Cotton Thread ... ... „	0 8 0	0 8 0	
1 Pot... ... ... „	0 1 0	0 1 0	

Bill for fitting and painting Steamers, &c. (Continued.)

Description of charges.	Rate.			Amount.			Total.		
	RS.	A.	P.	RS.	A.	P.	RS.	A.	P.
1 Yard Dungary ... . each	0	3	3	0	3	3			
Workshop general superintendence and sundries at 10 per cent. on Rupees 6-11-1...	0	0	0	0	10	8			
				7	5	9			
							236	14	11
Steamer "Prince."									
Stores supplied.									
27½ lbs. Cotton rope... .. .. each	0	5	0	8	9	6			
122½ lbs. Coir rope... ... ... „	0	0	8	5	1	8			
43¼ lbs. Hemp rope... ... ... „	0	1	6½	4	2	8			
52 lbs. Cocoanut oil... ... ... „	0	2	8	8	10	8			
12 lbs. Grease... ... ... „	0	3	3	2	7	0			
10 lbs. Red Lead... ... ... „	0	3	10	2	6	4			
20 lbs. Hemp... ... ... „	0	0	10	1	0	8			
2 Yds. Dungaries... ... ... „	0	3	3	0	6	6			
¾ Soap... ... ... „	0	3	0	0	2	3			
10 lbs Lamp oil. ... ... „	0	1	11	1	3	2			
2 Yards Dungaries... ... ... „	0	5	0	0	10	0			
1 lb. Cotton thread... ... ... „	0	8	0	0	8	0			
1 Padlock... ... ... „	0	10	0	0	10	0			
2 lbs. Boiled Linseed Oil.. ... ... „	0	3	10	0	7	8			
Workshop general superintendence and sundries at 10 per cent. on Rupees 36-6-1...	0	0	0	3	10	2			
							40	0	3
Wages of extra crew employed on Steamer "Prince."									
1 Tindal for 10 days ... ... month	10	0	0	3	5	4			
2 Steers men for 10 days per month each...	8	0	0	5	5	4			
5 Fire men for 15 do. do. do.	7	0	0	17	8	0			
3 Do. for 10 do. do. do.	7	0	0	7	0	0			
2 Lascars for 10 do. do. do.	6	0	0	4	0	0			
1 Do. for 15 do. per month...	6	0	0	3	0	0			
1 Do. for 8 do. do.	6	0	0	1	9	7			
				41	12	3			
Wages of extra Crew employed on Steamer "Pioneer."									
1 Engine driver. ... . each	12	0	0	12	0	0			
3 Lascars... ... ... „	6	0	0	18	0	0			
1 Steer man ... . „	8	0	0	8	0	0			
3 Fire men for 13 days per month ... ... „	7	0	0	9	1	6			
3 Lascars for 13 days do. ... ... „	6	0	0	7	12	9			
1 Do. for 12 do. do. ... ... „	6	0	0	2	6	4			
1 Do. for 1 day... ... ... „	0	0	0	0	3	0			
				57	7	7			
Wages of extra Crew employed on Steamer "Hope."									
4 Stokers for 10 days per month each	7	0	0	9	5	4			
3 Lascars for 10 do. do. do.	6	0	0	6	0	0			
1 Do for 9½ do. do. do.	6	0	0	1	14	4			
				17	3	8			
Wages of extra Crew employed on Steamer "Little Nell."									
1 Syrang for 16 days per month each	15	0	0	8	0	0			

Bill for fitting and painting Steamers, &c. (Continued.)

Description of charges.	Rate.			Amount.			Total.		
	RS.	A.	P.	RS.	A.	P.	RS.	A.	P.
1 Engine Maistry for 16 days per month	12	0	0	6	6	5			
1 Steer man for 16 do. do. do.	8	0	0	4	4	3			
2 Firemen for 16 do. do. do.	7	0	0	7	7	6			
1 Lascar for 16 do. do. do.	6	0	0	3	3	2			
				29	5	4			
							145	12	10
Fitting up and painting 3 Paddle Boats for the use of His Lordship's party.									
Labor.									
187½ Carpenters ... ... each	0	5	8	66	6	6			
5 Smiths... ... ... „	0	5	4	1	10	8			
5 Hammer men... ... ... „	0	2	9	0	13	9			
18 Bellows boys... ... ... „	0	1	5	1	9	6			
72 Lascars... ... ... „	0	3	4	15	0	0			
2 Vice men... ... ... „	0	6	3	0	12	6			
39¾ Moochies... ... ... „	0	5	0	12	6	9			
2 Coolies... ... ... „	0	1	6	0	3	0			
1 Cooly... ... ... „	0	2	6	0	2	6			
1 Do.	0	1	3	0	1	3			
Caulking by contract...	0	0	0	22	3	5			
Materials.									
1 lb. Cut nails ... ... „	0	2	4	0	2	4			
15 lbs. Chalk... ... ... yd.	0	0	8	0	10	0			
11½ Yards coarse cloth... ... ... „	0	0	2	0	12	4			
2 Do. do. ... ... each	0	2	0	0	4	0			
156 Screws... ... ... „	0	0	3	2	7	0			
8 Wood screws... ... ... md.	0	0	6	0	4	0			
327½ lbs. Pitch... ... ... each	0	1	3	27	3	7			
46 lbs. Lamp oil... ... ... yd.	0	1	11	5	8	2			
168¾ Yards dungary cloth ... ... each	0	5	0	52	11	4			
12 lbs. Coal tar... ... ... „	0	2	0	1	8	0			
43 lbs. Red ochre. ... ... each	0	2	4	6	4	4			
1 Paint brush... .. .. lb.	0	10	0	0	10	0			
50 lbs. Boiled Linseed oil ... ... „	0	3	10	11	15	8			
58½ lbs. Wrought nails... ... ... each	0	4	0	14	10	0			
6 Rags... ... ... „	0	0	½	0	0	3			
15 Rags... ... ... „	0	0	¾	0	0	11			
⅝ lb. Wax... ... ... „	0	10	8	0	4	0			
119 lbs. White paint ... ... „	0	3	0	22	5	0			
28 lbs. Do. ... ... „	0	2	8	4	10	8			
4 lbs. Turpentine... ... ... „	0	12	0	3	0	0			
1 lb. Do. ... ... „	0	12	8	0	12	8			
22⅛ lbs. Cotton... ... ... „	0	2	6	3	7	4			
3⅛ lbs. Do. ... ... „	0	2	8	0	8	4			
3 lbs. Do. ... ... „	0	3	0	0	9	0			
7 Pots... ... ... „	0	1	0	0	7	0			
1 Do. ... ... „	0	1	3	0	1	3			
6 lbs. Black varnish 100	0	6	0	2	4	0			
3,860 Iron tacks... ... . Prhs.	0	1	3	3	0	3			
5 Partahs wood charcoal... ... ... each	0	3	8	1	2	4			
2 Teak tundoos... ... ... „	5	8	0	11	0	0			
1 Do. ... ... „	5	0	0	5	0	0			
1 Do. ... ... „	4	8	0	4	8	0			
1 Do. ... ... „	4	0	0	4	0	0			
6½ lbs. Sheet iron... ... ... „	0	1	6	0	9	9			
2⅛ lbs. Round iron... ... ... „	0	1	6	0	3	2			
6 lbs. Do. ... ... „	0	1	3	0	8	1			
½ lb. Soap... ... ... „	0	3	0	0	1	6			
133 lbs. Coir rope... ... ... „	0	3	7	4	12	7			

Bill for fitting and painting Steamers, &c. (Continued.)

Description of charges.	Rate.			Amount.			Total.		
	RS.	A.	P.	RS.	A.	P.	RS.	A.	P.
8 1/16 lbs. Cotton rope ... ... each	0	8	0	4	1	6			
1/4 lb. Do. ... ... „	0	4	0	0	1	0			
20 lbs. Red lead... ... ... „	0	3	10	4	12	8			
1/4 lb. Hide... ... ... each	2	0	0	0	8	0			
1 lb. Prussian blue ... ... lb.	2	0	0	2	0	0			
1 lb. Do. ... ... „	1	12	0	0	14	0			
Hire for Sawyers for 395 square feet per... ... 100	1	5	4	5	4	3			
Workshop general superintendence and sundries on Rupees 338-3-1 at 10 per cent...	0	0	0	33	13	1			
							372	0	9
Sundries.									
1 Union Jack for His Excellency the Governor General's Steamer...	0	0	0	15	0	0			
Sundry flags for different steamers to attend His Lordship.									
32 Yards red cloth ... ... each	0	7	6	15	0	0			
6 Yards long cloth... ... ... „	0	4	0	1	8	0			
3 Yards coarse cloth ... ... „	0	2	6	0	7	6			
12 Balls thread... ... ... „	0	0	4	0	4	0			
3/8 lb. Cotton rope... ... ... lb.	0	5	0	0	1	10			
7 1/4 lbs. Do. ... ... „	0	5	6	2	7	11			
13 Tailors... ... ... each	0	4	0	3	4	0			
Workshop superintendence and sundries... ..	0	0	0	2	0	11			
							40	2	9
Value of 16 tons firewood used for bringing Steamer "Pioneer" from Bezwada to Dowlaishweram at 3 Rupees per ton...							48	0	0
Rupees...							1,439	9	0

Godavery District Engineer's Office,
Dowlaishwaram, 12th Feby. 1862.

(Signed) J. F. STODDARD, Major,
District Engineer Godavery District.

Bill for repairing and fitting up and clearing three Bungalows for His Lordship's use.

Items.	Rate.			Amount.			Total.		
	RS.	A.	P.	RS.	A.	P.	RS.	A.	P.
Repairing white-washing and fitting up two large and one small Bungalow for the use of His Lordship and Suite.									
Labor.									
1 Maistry for 1 month...	15	0	0	15	0	0			
21 Carpenters ... ... each	0	5	8	7	7	0			
49 3/4 Do. ... ... „	0	4	0	12	7	0			
6 Apprentices ... ... „	0	2	2	0	13	0			
7 Moochies .. .. „	0	5	0	2	3	0			
1 Lascar ... ... „	0	3	4	0	3	4			
118 Tailors ... ... „	0	4	0	29	8	0			
67 Bricklayers ... ... „	0	4	0	16	12	0			
14 1/4 Bearers ... ... „	0	5	0	4	7	3			
44 Coolies ... ... „	0	2	0	5	8	0			
53 Do. ... ... „	0	1	0	3	5	0			
							97	9	3
Materials.									
26 Teak wood posts .. .. each	3	0	0	78	0	0			
1 Do. ... . „	4	0	0	4	0	0			
2,000 Bamboos ... ... per 100	2	0	0	41	3	3			
1,500 Palmyra leaves ... ... „	0	4	0	3	12	0			
1/2 Garce ground chunam ... ... each	16	0	0	8	0	0			
10,000 Pantiles... ... ... per 1,000	1	8	0	15	0	0			
14 Vossunes ... ... each	0	8	0	7	0	0			
6 Jack rafters ... ... „	0	4	0	1	8	0			

Bill for repairing and fitting, &c. (Continued.)

Items.	Rate.			Amount.			Total.		
	RS.	A.	P.	RS.	A.	P.	RS.	A.	P.
4 Teak logs ... ... each	1	8	0	6	0	0			
4 Hip Rafters ... ... „	1	0	0	4	0	0			
10 Rafter pieces ... ... „	0	4	0	2	8	0			
46 1/2 Yards Brown Holland for Punka frills ... „	0	8	0	23	4	0			
4 Pieces colored cloth for Pandal ceiling, &c.... „	4	10	6	18	10	0			
23 Yards Red curtain silk for half door ... „	2	8	0	57	8	0			
26 Pieces of white cloth for ceiling of rooms ... „	1	15	4	50	14	8			
1,102 1/2 Cubits dyed cloth for carpeting of rooms ... „	0	1	9	120	9	0			
65 3/4 Yards Bombay cloth for Punka curtains ... „	0	6	9	27	11	9			
23 Yards Curtain muslin ... ... „	0	4	0	5	12	0			
70 1/2 Yards Long cloth ... ... Dozen	0	3	6	15	6	9			
72 Glass pans ... ... each	2	13	0	16	14	0			
62 Pots Shell Chunam ... ... „	0	9	0	34	14	0			
36 Yards Tape ... ... „	0	1	0	2	4	0			
18 Yards Red tape ... ... „	0	4	0	4	8	0			
2 Bundles broad tape ... .. 12 Sqr. Yds.	1	0	0	2	0	0			
98 Sqr. Yds. Bamboo mat ... ... each	1	0	0	8	2	8			
6 lbs. Varnish ... ... „	0	7	6	2	13	0			
14 lbs. Iron hooks ... ... „	0	1	3 1/2	1	2	1			
50 lbs. Coir rope ... ... „	0	0	5	1	4	10			
41 Baskets ... ... „	0	0	9	1	14	9			
15 1/4 lbs. Cotton rope for Punkas ... 100 Sqr. feet	0	5	3	5	0	1			
158 Sqr. feet Sawyer's hire ... ... each	1	5	4	2	1	10			
6 3/4 Maunds nails 100	3	0	0	19	2	0			
1,900 Copper nails 100	0	3	0	3	9	0			
800 Iron nails	0	3	0	1	8	0			
Rings for iron hooks ... ... each	0	0	0	2	14	8			
8 lbs. Green paint ... ... „	0	4	0	2	0	0			
7 Bottles Wood oil ... ... „	0	6	6	2	13	6			
Workshop general superintendence and sundries ... „	0	0	0	4	13	6			
Sundry materials such as pots, brooms, paint, ball thread, brushes, &c., &c.,...	0	0	0	22	15	11			
							633	7	3
Sundries.									
Hire of two Transit Boats for three days engaged for conveying His Lordship's Baggage from Cocanada to Dowlaishwaram at 20 Rupees each per day ...	0	0	0	120	0	0			
Hire of Boat for bringing globes, &c. from Yanam ...	0	0	0	10	0	0			
Batta to Peons and Boat Lascars	0	0	0	11	11	0			
6 Coolies for taking Paddle Boats to Cocanada at 1 1/4 Rupees. ... ... each	0	0	0	7	8	0			
Taking firewood and coal to different Locks, &c., for the use of Steamers.									
6 Coolies ... ... each	0	2	0	0	12	0			
19 Do. .. .. „	0	1	9	2	1	3			
8 Do. ... ... „	0	1	0	0	8	0			
Hire for 1 Dhoney ... ... each per month	0	0	0	2	15	6			
4 Boat Lascars for 15 1/2 days... ... do.	6	0	0	12	6	4			
17 Do. for 15 1/2 days... ... do.	4	0	0	35	2	1			
2 Do. for 16 days... ... do.	2	0	0	2	2	0			
Wages of Boat Lascars employed on different Boats for taking furnitures, &c.									
3 Lascars for 7 days ... ... each per month	6	0	0	4	3	2			
17 Do. for 7 days ... ... do.	4	0	0	15	13	10			
1 Do. for 3 days ... ... do.	2	0	0	0	3	2			
							225	6	4
						Total...	956	7	2

Godavery District Engineer's Office, Dowlaishwaram, 12th February 1862.

(Signed) J. F. STODDARD, Major,
Acting District Engineer, Godavery District.

1 Letter No. 1,236, dated 12th February 1862.
2 Bills.
1 Bill for Rupees 1,439-9-0
1 Do. for „ 956-7-2
Total.. „ 2,396-0-2

Submitted to Government with the recommendation that the Bills received with the foregoing letter, amounting in the aggregate to Rupees 2,396-0-2 may be sanctioned as a contingent charge.

(Signed) F. H. RUNDALL, Lieut.-Colonel,
In charge of the Audit and Account Departments.

No. 95. ORDER THEREON, 3rd May 1862, No. 936.

The Government sanction the Bills submitted with the foregoing Endorsement amounting together to Rupees 2,396-0-2, the same to be charged against the sum allowed for contingencies in the Public Works Budget of the current year.

(Signed W. H. HORSLEY, Lieut.-Colonel,
Secretary to Government.

ii

Central Office of P.W.
Chepauk
9th April 1862

No. 12486

Submitted to Government with the recommendation that the Bills received with the foregoing letter, Amounting in the aggregate to Rupees 2396...2 may be sanctioned as a Contingent Charge...

Recd No. 1236 12th February 1862

1 Bill for Rupees 1439-9-...
1 Do. — „ — 956-7-2
2396...2

F. H. Rundall Lieut. Colo.
In ch. of the Audit & Account Departt.

To Lieut. Colonel W. H. Horsley
Secretary to Government P.W.D.

X/1117

Public Works 1862 Depart.
Pro: of Sov.r for May.
From
No 1862.
Lieut. Colo. F.H. Rundall
In Ch. of the Audit.
and Account Deptt.

To
Lieut. Colo. H.H. Horsley
Secretary to Govt. G.I.P.D.

Dated 2nd April 1862
Recd. 11th " "
3 Encls. Estimate No 12486

Submits for sanction
2 Bills received from the
District Engineer Odassery
for fitting and painting
Steamers and also repairing
3 Bungalows for the use
of His Lordship the
Governor General of India.

Attended
No 936 - 3rd May.

No. 94 - 95.

Commd

No 936

The Government
sanction the Bills submitted with
the foregoing endorsement amounting
together to Rupees 2396 - - 2,
the same to be charged against the sum
allowed for contingencies in the P.W. Budget
of the Current year.

Chesney
3rd May 1862

4 Copies
To
The Offg Ch. of the Audit & Acct Deptt
with 3 Encls. Dist Do.
13. " Ch. Engr. Nagpore
3. " Civil Paymaster