

(1) Number of pages 14

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No.	3799	Press
		Mis.
Dated	23-12-18	62.

Not to be folded or roughly handled

16

*Proceedings of the Madras Government, Public Works Department,
23rd December 1863.*

No. 567. Read the following Proceedings of the Madras Government in the Ecclesiastical Department.—

Sanctioning the repair of certain Burial Grounds at the } (Here enter 15th December 1863, No. 295.)
Presidency at an outlay of Rupees 1,416.

No 568. ORDER THEREON, 23rd December 1863, No. 3,799.

1. Communicated to the Superintending Engineer, 4th Division, for information and guidance.

2. The cost of the works will be defrayed in the manner pointed out in paragraph 3 of the Superintending Engineer's letter No. 3,748, dated 2nd December 1863.

(True Extract.)

(Signed) CHARLES A. ORR Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 4th Division.

„ Accountant General.

„ Controller and Auditor of Public Works Accounts.

Exd. S. T. Augustin.

BUILDINGS

ABSTRACT of Estimate No.

of 186 -6

(Repairs) 34

DISTRICT *Presidency*

WORK - *Repairing the Compound walls of the Govt Comptrols in the South Range of the Presidency.*

Quantities.	Description of Work.	Rate.		Amount.	Amount of each part.
		Rs.	A. P.	Rupees	Rupees.
	<i>N^o 1.</i>				
	<i>St. Mary's Burying ground Entrance room</i>				
220	<i>Sq^s of White washing with 2 Coats of Sq^s</i>	2	7	5	
2100	<i>Sq^s of Blue D^o D^o Sq^s</i>	3	6		
270	<i>D^o of White washing to ceiling</i>				
	<i>— Sq^s Square —</i>	2	9		
325	<i>D^o of Repairing the plaster with 2 coats of chunnam of Sq^s</i>	2	15	7	
500	<i>D^o D^o Blue in chunnam</i>				
	<i>— Sq^s —</i>	2	33	11	
500	<i>D^o Pointing to 8 & 10 Square bricks of Square</i>		88	3	
100	<i>D^o Repairing with new 8 Square bricks for the floor of Sq^s</i>			7	
50	<i>D^o Laying 2" Jelly & Plastering with 2 coats cement chunnam of Sq^s</i>	4	310	2	
200	<i>D^o Repairing the cracks of the terrace with tar pitch & cloth of Sq^s</i>	2	36	4	
	<i>Carried over</i>			39	

at Blue chunnam to the new walls — 2 33 3 4 10.

portion of compound wall & collecting old bricks. — 38.

113 loads chunnam for 2 monuments — 14.

scaffolding &c — 15 72 302.

Carried Over 302.

No.	Description of Work.	Rate.		Amount.	Amount of each part.
		Rs.	A. P.	Rupees	Rupees.
	Brought over			39	
	Repairing the cracks of the wall with 3 anchawood binders & Plastering &c.			8	
	coolly hire for repairing doors & windows with bolts, nails & piece of planks &c.			5	
1/2	Sq. of Wood oil 2 coats & Sq.	12	9	3	
4	Sq. of Lead colour 2 coats & Sq.	2	9	14	
	Red paint 2 coats for 6 water spouts			1	
	coolly hire for rooting out trees & filling with brick in chunam & Plastering &c.			4	
	1 Europe Padlock of 3"		8	1	
	Compound wall				
2	Sq. Repairing the plaster with 2 coats chunam. Sq. Sq.	2	1	5	42
0	Sq. of Repairing the plaster with 2 coats blue chunam. Sq. Square	2	3	3	70
	Carried over			187	

Quantity	Description of work.	Rate			Amount	Amount each part
		Rs.	A.	P.	Rupees.	Rupees.
	Brought over				187	
	coolly hire for repairing the gate-shutters with new piece of wood &c. with 2 coats red paint				5	
	1 Europe Padlock of 3"		8		1	
	Gravelling foot paths				106	
	Sandries				4	306
	No. 2					
	St. Georges Cathedral					
1065	Sq. of Repairing the plastering with 2 coats chunam to the compound wall					
	Sq. Sq.	2	1	5	223	
	Repairing the Plaster of the rustic work to the gate pier				10	
	Sandries				7	260
	No. 3					
	St. Thome Burial Ground					
3275	Sq. of Repairing the plaster of the compound wall with 2 coats in chunam where found necessary					
	Sq. Square	2	1	5	68	
	Plastering with 2 coats in chunam to a cemetery with arnamental work complete				8	
	Repairing the gate shutters with teakwood pieces & iron articles &c. Complete				7	
	Carried over				83	546

the Blue chunam to the new walls 2 3 3. 3 4 10.
 portion of compound wall & collecting old bricks. " " 3 8 "
 113 coats chunam for 2 monuments " " 14 "
 scaffolding &c. 15 7 2 302 "
 Carried Over. 802 "

Enclosure.
 In a
 From
 The Sup^t Engineer
 4th Division
 To
 The Secretary to Govt
 D. P. P.

Dated
 Received, P.W. 5040

No.
 Abstract Estimate for
 repairing the Compound
 walls of Government be-
 matoes in the South range
 of the Presidency.
 Amounting to Rs. 302.
 Escl^d P. 776.
 No. 370

Abstract Estimate No. 107 of 1863/64.
 Presidency District
 Work For repairing the walls &c of St. Matthias Burial ground and Dyfraters
 Burial ground at Purasavakam.

Quantity	Description of works	Rate	Amount	Amount of each part
No. 1				
775 ft	Blue washing in chunam with 2 boats to walls	3 6	19 31	
7550	White washing in chunam with 2 boats	2 7	12 3	
1075	Repairing the plaster with 2 boats chunam where required	2 1 5	22 73	
5500	Repairing the plaster with 2 boats blue chunam where required	2 3 3	121 29	
300	Laying broken bottle in chunam over the coping where required	1 2 1/4	22 43	
1175	Shifting tiles and repairing chunam border	10	7 56	
1500 ft	Repairing the cracks of the wall with brick jilly and chunam where required	6	4 11	
5000	Repairing the floor with new 8" Sq ^d bricks where required	7 4	3 10	
400	Painting 8" Sq ^d bricks floor	9 6	2 6	
156 3/4	Brick in chunam	2 5	23 10 10	
	Repairing the cracks with 4" Sucha wood binder each 2 x 4 x 3	1 4	5	
1000	Teak wood wrought and put up	2 15	3 2 6	
	Cooly hire for repairing doors and windows with new Teak wood 8" x 2		2	
1	Thick iron hinges at 4 1/2 with nails		3	
6	Iron fastening hooks at 3/4 foot	1 3	7 6	
1	Iron round bolts at 1 1/4 foot	5	6 3	
1	2" cross at 1 foot	5	5	
1	Europe single Padlocks at 3"		14	
565	Lead paint 2 boats to Gate shutters, doors and windows &c	20 9	11 9 1	
150	Plastering with 2 boats Blue chunam to the new walls	2 3 3	3 4 10	
	Cooly hire for removing a portion of compound wall & collecting old bricks		3 8	
	Repairing the Plaster with 3 boats chunam for 2 monuments		14	
	Sundry charges and scaffolding &c		15 7 2	302
			Carried Over. 302	

No. 2

Dissenters Burial Ground

Brought Over 302

7,600 ft. Repairing the plaster with 2 coats chunam where required	215	158	11	8
12,900. Whitewashing in chunam with 2 coats	"	27	20	13 3
300 ft. Repairing the cracks of the wall with jelly & chunam	"	6	9	6 "
143 3/4 ft. Flooring with new 8 Sq. bricks with a levelling course of old bricks	7	11	10	15 11
Repairing the cracks of the wall with 1/2 inch Ashwood binders each 2 x 4 x 3	14	"	5	" "
497 13/16 ft. Brick in chunam	"	25	75	3 1
800 ft. Plastering with 2 coats chunam for new wall	2	2	16	1 4
112 1/2 ft. Plastering with 2 coats cement chunam mixed with lampoil to well	2	3	6	2 7 11
516 ft. Red paint 2 coats to the doors and windows	1	7	9	7 10 7
Coaly hire for removing the walls and excavating foundation	"	"	"	13 "
Sundry charges and Scaffolding 1/4	19	10	3	338

Total Repairs 640

Pr. Asst. Engr. Office
Northern Range
Madras
9th October 1863

Am. P. M. S. L. L. R. C.
Assistant Engineer Presidency
Northern Range

**ECCLESIASTICAL DEPARTMENT.
PROCEEDINGS OF THE MADRAS GOVERNMENT.**

Read the following letter from Lieu enant Colonel A. J. M. BOILEAU, R. E., Superintending Engineer, 4th Division; to Colonel CHARLES A. ORR, R. E., Secretary to Government, Public Works Department, dated Madras, 2nd December 1863. No. 3748.

With reference to paragraph 1 of the Proceedings of Government in the Ecclesiastical Department, No. 212, dated 15th October 1863,

I have the honor to forward the accompanying estimates for repairing the Corporal walls of the following Burial grounds at the Presidency, viz:—

1st. St. Mary's	Rupees 306
2nd. St. George's Cathedral	240
3rd. St. Thomé	90
4th. St. Patrick's	140
5th. St. Matthias'	302
6th. Dissenters'	338

2. So far as I am able to ascertain all these Cemeteries, except Nos. 4 and 6, are Government property, and if I am correct, it will be for them to decide at whose expense they are to be kept in order.

3. Excluding these two the total cost of repairing the remaining Burial grounds amounts to Rupees 938, which I recommend should be met from the funds marginally noted.

If, however, Government are pleased to take upon themselves the repairs of the Roman Catholic and Dissenters' Burial grounds (and I presume the Government Soldiers of those denominations find their last resting place therein) then the amount to be sanctioned is Rupees 1416 and the funds may be provided as shown in the margin above, only taking 1016 Rupees in lieu of Rupees 538 out of Military Staff.

Referred to the Ecclesiastical Department.

CHEPAUK,
7th December 1863.

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government, P. W. D.

ORDER THEREON, 15th December 1863, No. 295.

The Government sanction the repair of the Burial grounds, Nos. 1 to 6, at the estimated outlay of Rupees (1416) one thousand four hundred and sixteen.

(True Extract.)

Chief Secretary.

To the Department Public Works,
(with enclosures.)
Accountant General.

Exd. T. McMoorty.

*Estimate of the probable
expense for repairing the walls
of St. Matthias' Burial
ground and Dissenters' Burial
ground at Chepauk.*

*Amounting to Rs. 640—
5339/63*

*5044/63
1003/70*

Dated 9th October 1863

*The Lieut. Colonel
4th Division*

*The Asst. Engineer
R. E.*

*Proceeding
from*

Don. 1863 Raphael
No. 2 of 2nd 5339

John Madsen & Son
No. 222 Broadway

13th
 1863
 1/63

11/11/11

the spring of current
year and grows at
the Providence man-
sion of Dec. 1916.

8799-28 Room 605

17
M. H. 17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841
842
843
844
845
846
847
848
849
850

12

3799

Communicated to the Department
ending August 4. The Division for
Information and Guidance will re-
ceive them but off the cost of the matter

never be depressed in the manner

forwarded out in June 3rd of the year
1863. The
Lectures on Semantics and Arguments for No 3/48
23 Dec 1863

Edited & published 2nd edition 1863.

To Mr. DeLong Aug 12. H. Geo. S. Webb

u — u *Accountant General*

Collection of 1877.

28

Dr. J. H. Moore.

Ms. A. 9.2. 557. 558

Each 1/6 30
100.370