

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No.	<i>42</i>	Press <u>Mis.</u>
Dated	<i>17/12/54</i>	18 <i>54</i>

Not to be folded or roughly handled

13

*Proceedings of the Madras Government, Public Works Department,
12th January 1864.*

No. 230. Read the following Proceedings of the Madras Government in the Military Department:—

Approving of the Estimate of Rupees 1,605 for repairing the } Here enter 6th January 1864, No. 41.)
Arsenal at Vizagapatam.

No. 231. ORDER THEREON, 12th January 1864, No. 112.

1. Communicated to the Superintending Engineer, 1st Division.
2. The cost of the repairs, viz., Rupees 1,605, will be met from the sum of Rupees 25,000 authorized by the Government of India to be transferred from the head of "Reserve" to that of "Repairs."—

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 1st Division.

„ Accountant General.

„ Controller and Auditor of Public Works Accounts.

Estimate of the probable expense for repairing the Arsenal
in the Fort of Evrigapalam. 36

Measure: Supb
= ment Contents
Number Length Breadth Height Squares Feet Cubic Contents

2 96-22-9 " 43 68 " 43 68

Particulars of Work Rate Amount Total

Conductors Room

Repairing the roof with new
Rafters, Ropers, Rafters &
Ropers tarred & poisoned with
Arseenic

for
Sgt 3497 1

2 96- " 16 30 72
2 22-9 " 16 7 28
2 96- " 16 30 72
2 22-9 " 16 7 28
76 "

Halls

Blue & Whitewashing inside &
outside

" 29 " 13 1 "

1 15- " 8-9 " 7-6

Replacing new breast summers

1 12- " 8-9 " 6- "

12-6

for
Sgt 23 10 "

Old stone & Cascaris Godown

2 83-22- " 36 52
36 52

Godown

Repairing the roof with new
Rafters, Ropers, Rafters & Ropers
tarred & poisoned with Arseenic

for
Sgt 292 27

2 83- " 16 26 56
2 22- " 16 7 4
2 83- " 16 26 56
2 22- " 16 7 4
67 20

Halls

Blue & Whitewashing inside
& outside

" 29 " 11 8 10

Verandah

4 11- " 6-5 " 9-2

9-2

9-2

for
Sgt 16 " 8

2 88-17-0 " 29 92
29 92

Roof

Repairing the Roof with new
Rafters, Ropers, Rafters &
Ropers tarred & poisoned with
Arseenic

for
Sgt 239 59

Carried over - 953 11

where the system was first introduced 700
 295 gm 5-108
 Carried over - 1976/7

~~Total Rupees 15744~~

C. P. Mobery Captain
As Executive Engineer
Digbar Range

34811/4 Nov

MILITARY DEPARTMENT.
PROCEEDINGS OF THE MADRAS GOVERNMENT.

Read the following papers:—

Memorandum from the Quarter Master General, Fort Saint George, 23rd December 1863,
No. 10,060; to the Secretary to Government, Military Department.
Forwarded to Government for early sanction.

From the Officer Commanding Northern Division, Head Quarters, Camp Vizianagram, 9th
December 1863, No. 387; to the Quarter Master General, Fort Saint George.

I have the honor to enclose, for the information of His Excellency the Commander-in-Chief,
an Estimate amounting to Rupees 1,605, for repairing the Arsenal at Vizagapatam.

The repairs are emergently required, and I beg that with His Excellency's approval, the
sanction of Government may be obtained for their immediate execution.

ORDER, No. 41, 6th January 1864.
Approved, and communicated to the Public Works Department.
(True Extract.)

W. H. M. S. S.
Deputy Secretary to Government.

To the Quarter Master General.
" Public Works Department, with an Estimate.

W. H. M. S. S.

