

(1) Number of pages

8

(2) Date of repair

19-10-62

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 3120

Press

Mis.

Dated

31-10-1962

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
31st October 1864.*

No. 583. Read the following Proceedings of the Madras Government in the Revenue Department :—

Requesting the preparation of the necessary estimates for certain additions and improvements recommended by the Board of Revenue to the Custom House at Keelakarra, Madura District. } (Here enter 22nd October 1864, No. 1,049)

No. 584. ORDER THEREON, 31st October 1864, No. 3,120.

1. Communicated to the Superintending Engineer, 8th Division, with a request that he will report the cause of the "leaky state of the Custom House," and whether the repairs, sanctioned in Proceedings, No. 2,336, dated 29th September 1862, were properly executed. If not, he will state who is responsible for the defective character of the work performed.

2. Captain Moberly will also report whether any repairs were carried out subsequent to those sanctioned in the orders quoted above.

3. The estimates for the works referred to in paragraph 2 of the Board's Proceedings should be submitted with as little delay as practicable.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 8th Division.
„ Revenue Department.

Exd. T. O'Connor.

28

*Proceedings of the Madras Government, Revenue Department,
22nd October 1864.*

No. 272. Read the following Proceedings of the Board of Revenue, dated 30th September 1864, No. 6,439.

Read the following letter from V. H. LEVINGE, Esq., Collector of Madura, to W. HUDLESTON, Esq., Secretary to the Board of Revenue, dated 12th August 1864, No. 213 :—

* Original Petition returned.

† Separate Revenue, No. 2 Customs.

1. With reference to the Proceedings* of the Madras Government, Revenue Department, dated the 1st June, and the Order thereon, No. 937,† I have the honor to report that I visited Keelakarai, inspected the Custom House, landing place, and gave an interview to such of the chief merchants as chose to appear.

2. I find that the space in the Custom House is contracted by a room in it being occupied as a Police station, but it is the most convenient arrangement that the Police be located in the Custom House, as they guard the Treasury in which the Custom collections are secured, and they at the same time afford a security to the goods stored in the Custom House; in lieu of the room occupied by the Police, another to be used as a godown or store should be built on to the east end of the Custom House, which can be easily done, and for which there is space.

3. Though the roof of the Custom House was lately repaired at a cost of some 400 Rupees, it leaks excessively as I was informed by the Sea Custom Superintendent, the Police and others attached to the Customs. The present is a terraced roof. I believe the best plan would be to remove the terrace, and to have a tiled roof substituted; it is for the Department Public Works to propose the most economical sound roof.

4. With reference to the alleged want of room in the Custom House, in my opinion the Custom House would be large enough if another room, as suggested in paragraph 2 above, be added.

5. I find the merchants for their own convenience and profit leave their goods lying in the Custom House under all sorts of pretences for an immoderate time, thus saving themselves godown rent, and the interest of their Custom dues, till they find a good opportunity to clear their goods. I request the Board will fix the number of days within which goods should be cleared out, after which godown rent will be charged and the rates at which it should be charged. On my visit I found the Custom House rather blocked up with goods of all sorts.

6. The landing place is sufficiently wide, but there are some rocks a little out from the shore opposite the Custom House on which the sea breaks; these are dangerous to boats, and should be blasted and removed; there is a Detachment of Sappers at Pamben employed on the blasting operations in that passage; for some months in the year they are unable to work at Pamben, during such period of suspension of work there, the opening of the north-east monsoon, they might be employed in blasting these rocks at Keelakarai, at which time the sea at that place is quite calm and sheltered; the Superintending Engineer could have the necessary estimates for the above improvements prepared if the suggestion is approved of.

7. Some of the merchants complained of the position of the Sea Custom House, and wished to have it removed to a more central place; others are contented with its position.

8. The Sea Custom House is situated at the eastern extremity of the town, which stretches along the coast for about three-quarters of a mile, and the coast is much indented.

9. One merchant offered the use of one of his buildings for a Custom House, but the position is bad, it is too far back from the sea, and the view of the landing place opposite it is intercepted by trees, hedges, and sheds, for the removal of which and purchase of the ground, heavy compensation would be claimed.

10. Formerly the merchants were in the habit of landing and shipping their goods at such points of the coast as suited their convenience; now that they are only permitted to land and ship goods at the appointed landing place, those of the west end of the town complain of the expense of having to carry their goods to the appointed place, but such extra expense must, I opine, be inevitably borne by some at all sea-ports; all cannot be close to the landing place.

*Proceedings of the Madras Government, Revenue Department,
22nd October 1864.*

ENCLOSURE No. 1.

ABSTRACT.—Original Petition of the merchants residing at Keelakarrai in Madura District

1. Ordered that the above letter and its enclosure be submitted for the information of Government with reference to their Proceedings, dated 1st June 1864, Revenue Department, No. 937.
2. The Board approve of the suggestions for adding another room to the Custom House at Keelakarrai, and for substituting a tiled roof for the present terraced roof; and they request that the Superintending Engineer of the Division may be called on to furnish plans and estimates for the work.
3. As regards godown rent the Collector is referred to the Board's Proceedings, dated 23rd April 1864, No. 2,467, which shows the rules now in force at the Madras Sea Custom House, and he can submit his proposal for Keelakarrai.

No. 273.

ORDER THEREON, 22nd October 1864, No. 1,949.

Separate Revenue, No. 14
Customs.

Orders will be issued from the Public Works Department for the preparation of the necessary estimates, and notice will be taken of the extremely leaky state of the roof of the Custom House lately repaired.

(True Extract.)

L. P. S.
Secretary to Government.

To the Public Works Department.
„ the Board of Revenue.
„ the Marine Department, with copy of No. 937.

2120 - 5
X
Communicated to the
Superintendent S. D. with a request
that he will report the cause of
the leaky state of the Custom
House, and whether the repairs
sanctioned in No. 2336,
of 29th Sept/62, were properly
executed. If not, he will
state who is responsible for
the defective character of the
work performed.

2. Captain Mobley will
also report whether any repairs were
carried out subsequent to those
sanctioned in the orders quoted above. The

3 The estimates for the
works referred to in para 2

of the Board Prov: should
be submitted with as
little delay as prac-
ticable

Chapman
21st Oct/64

No 588. 584

To The Supy of 8th Div
Rev: Secy to Govt

1082 Recd 1st November

1564 Dept
Pro: of Govt for October
No 4624

Pro: of Govt in the
Revenue Department

D/ 22 } Oct/64
Recd 26.

No 1917-

Requesting the pre-
paration of the necessary esti-
mates for certain additions &
improvements recommended
by the Board of Revenue, to
the Custom House at Keela-
karrai, Madras Dist.
Nos 3120-3125, Oct/64

Withamondor