

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 3273	Press ~~Mis~~
296-297	
Dated 15 - 11 - 1864.	

Not to be folded or roughly handled

12

*Proceedings of the Madras Government, Public Works Department,
15th November 1861.*

No. 296. Read the following Endorsement of the Superintending Engineer, 4th Division, dated Madras, 4th November 1861, No. 3,923:—

Read the following letter from Captain T. BECKLEY, R. E., Acting Executive Engineer, Presidency, to Colonel A. J. M. BOILEAU, R. E., Superintending Engineer, 4th Division, dated Madras, 3rd November 1861, No. 480.

Sir,

I have the honor to report that the awning of the western side of the Banquetting Hall at Government House was burned on the evening before last, through a spark having been blown on to it from the fire which was on the roof for melting the pitch, &c., for repairing it; a very high wind was blowing at the time, and the accident occurred in spite of every precaution to prevent sparks from being blown about. The quantity destroyed is 2,297 square feet.

1. Submitted to Government for information.
 2. Further repairs have been stopped till after the Ball of the 9th instant.
- (Signed) A. J. M. BOILEAU, Colonel, R. E.,
Superintending Engineer, 4th Division.

No. 297.

ORDER THEREON, 15th November 1861, No. 3,273.

Ordered to be recorded.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

Edl S. T. Augustie.

A: 1180

Presidency Executive Engineer
Madras. D. November 1864.

Sir,

The Asst. Executive Engineer,
Presidency

To The Superintending Engineer

Sir, I have the honor to report that the
awning of the shooting side of the Ban-
quetting Hall at Government House was
burned in the evening before last through
sparks having been blown on it from
the fire which was on the roof for mending
the patch we for repairing it, a very high
wind was blowing at the time & the accident
occurred in spite of every precaution to pre-
vent sparks from being blown about. The
quantity destroyed is 297 sq ft.

I have the honor to be,

Sir,

Yours most Obedt Servt

J. Killeby Captain

No 3923. Asst. Executive Eng. Presy

Submitted to Govt for information.

Further repairs have been stopped till after the Ball.

of the 9th Instant.

Supd. Office 4th Dec 1864

J. B. Colwell Col. R. L.

Supd. Engr. 4th Dec

no 3273

Recorded

Chapman }
15th & 10th 1864 }

22 Sept 1923, Pacific

Q-1043410
Stamm.

Wm. H. Burdett

Dr. Geo. S. Rogers

[illegible]

22-1.50

Report the residents
that caused the
opening of the western
side of the Conquistador
Hall at Forest Avenue.

[Handwritten signature]

A. L.

178

757 1864
To the Hon. Secy of the Interior
Washington D.C. 792

The Sup Engineer
L. D. W.

To The Secretary of the
I. B. R.

Dated 4th }
Recd 5th } November
1864
No. 3923

2123273-1550-1864
Submitting letter from
the Executive Comtee
Southern Range Pres
reporting the accident
that occurred to the owner
of the western side of the
Bannockburn Hall
at Govt House.

296. 297

Records
11-13
W
AP