M.R.O. 1—77,006—8-6-37.

(1) Number of pages____________

(2) Date of repair____________

(3) Initials of the Referencer____________

MADRAS RECORD OFFICE.

Government of Madras.

~~Public Works~~ **DEPARTMENT.**
Financial Railway

P.W.D. G.O. 5791-92
29-11-64

G.O. No. ~~[illegible]~~ 6-7-8

Press / Mis.

Dated 22 10 1864.

Not to be folded or roughly handled

Detailed Estimate No. 14. of 1864/65.

District South Canara.

Work: Alteration to the Prison-rooms in the Taluq Kachery at Mangalore.

Particulars of Work.	Measurement			No.	Contents
	Length	Width or Height	Breadth or Thickness		
Eastern side Prison room.					
Two Gable walls to be raised over the existing walls.	12.	8½	1½.		153.
Deduct the space for a ventilator —					12.
Laterite in chunam — C feet.					141.
Plastering with 2 coats of chunam — Sq ft.					212½.
Iron barred railings with wooden frames from the top of the existing southern wall to the ridge	12.	8½	.	1.	.
Iron barred ventilator in the proposed western Gable wall —	4.	2.	.	1.	"
West rooms					
Walls to be raised over the existing inner wall —	23.	8½	1½.		293¼.
Gables over the existing inner & partition walls.	12.	4¼	1½.	3.	229½.
					522¾.
Deduct the spaces for Ventilators. —					36.
Laterite in chunam — C ft.					486¾.
Iron barred ventilators in the new inner walls complete without shutters —	4.	2.	.	3	
Plastering with 2 coats of chunam Sq ft.					673.

Mangalore,
7th June 1864.

M.D. Mills
Taluq Overseer

F. A. Fernandez
Supervisor D.P.W.

Abstract Estimate No. 14 of 1864/65.

District South Canara.

Work. Alteration to the Prison-rooms in the Talug Kachery at Mangalore.

Quantity	Description of work	Rate.	Amt.	Total
627¾	C. feet of laterite in chunam per 100 C. ft.	15.0.0.	94.2.7.	
885½	Square feet of plastering with 2 coats of chunam — per sq.	3.8.1.	30.15.10.	
1.	Iron barred railing with wooden frames over the existing wall to the ridge for the eastern rooms complete each		60.0.0.	
4.	Iron barred ventilators with wooden frames	10.0.0.	40.0.0.	
	Sundries & Superintendence		14.13.7.	240.0.0.
	Deduct the value of existing ceiling on the western rooms			40.0.0.
	Net Estimate Amount requiring Sanction			200.0.0.

Mangalore,
7th June 1864.

M. D'Mello
Talug [illegible]

E. [illegible]
Supervisor D.P.W.

[illegible]
Rupees 200 [illegible]

Sanctioned 29th June 1864.

J. Thorp
Ag. Collr.

[illegible] Lieut. Col. R.E.
Supt. Engineer 1st Divn

D.P.W.

Enclosure in a letter from ~~Land & Miscellaneous~~ the Supt Engr 7 Dn No 167 Dd. of November 1864.

~~Allotment 506~~

~~Approp. 640~~

~~Excess 9 8~~

Police

Rev 2969/64

~~PW 4997/64~~

PW 5062/64

Abstract Estimate No of 64

District South Canara

Work Alteration to the Prison Rooms in the Talug Kachery at Mangalore

Estimate Rupees 200-0-0

No 114 of 1864-65
Rs 200
6th July 1864 Sub Sent

591-92 PWD
29-11-64