

(1) Number of pages 6
(2) Date of repair 24-7-43
(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No.	1332	Press
		Mis.
177-178		
Dated	9-5-	1864.

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
9th May 1864.*

No. 177.

Read the following:—

No. 3,134.
List of Bill received from the Superintending Engineer, 4th Division, submitted for the sanction of Government, which exceeds its Estimate by more than 5 per cent.

Audit No.	Date of Bill.	Description of Work.	Amount of Estimate.	Amount of Bill.	Excess.	Percentage of excess.	To what year the expenditure appertaining.	Date when received.	Remarks.
1,082	1863. March 26th	Repairing and whitewashing, &c., the Commandant's quarters at Rannett, in North Arcot District.	RS. 260	RS. A. P. 300 13 7 47 9 4	RS. A. P. 47 9 4	18 nearly	1862-63.	Received 4th June 1863. Returned 21st July 1863. Received back 22nd April 1864.	This work was sanctioned by the Deputy Chief Engineer, Central Circle, on the 19th September 1862, and the cause of excess is attributed by the District Engineer to the mismanagement of late Sub-Overseer Ruthnavaloo Moodli who was recommended to be reduced and subsequently dismissed by order of the late Deputy Chief Engineer of the Circle. As the difference, viz., Rupees 47-9-4, is above 5 per cent. of the sanctioned Estimate, this Bill is submitted for the sanction of Government.
		1st Part Bill already passed.	...	6 11 9					
		Total...	...	307 9 4					

CHEPAUK,

27th April 1864.

(Signed) C. V. WILKIESON, Lieut.-Colonel, R. E.,
Controller and Auditor of P. W. Accounts

*Proceedings of the Madras Government, Public Works Department,
9th May 1864.*

No. 178.

ORDER THEREON, 9th May 1864, No. 1,332.

The Bill is sanctioned.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 4th Division.

„ Accountant General.

Controller and Auditor of Public Works Accounts, with a Bill and a Certificate.

Exd. S. T. Augustin.

List of Bill received from the Superintending Engineer & Division submitted for the sanction of Government which exceeds the estimate by more than 5 p cent.

AD No.	Date of Bill.	Description of work.	Amount of Estimate	Amount of Bill	Excess	Per cent of Excess	To what year or portion of appertain- ing.	Date when received	Remarks.
1082	1863. 26 March	Repairing & whitewashing the Commandant's Quarters at Rancepet in N. Coast District.	260	300 13 7	47 9 4	18 44	1862/63	Returned 25 July 1863	This work was sanctioned by the Deputy Chief Engineer C.C. on the 17 Sept 1862 the cause of excess is attributed by the District Engineer to the mismanagement of late Sub Engineer Rattan Laloo Moodely who was recommended to be reduced and sub-sequently dismissed, by order of the late S ^r Chief Eng ^r of Madras. As the difference of Rs 47 9 4 is above 5 p cent of the sanctioned estimate, this bill is submitted for the sanction of Government.
		* Part Bill already passed.		6 11 9					
				307 9 4					

Office of the Controller &
Auditor of P^{ro} Accounts
Chennai. 27th April 1864

Encls. 1 Bill

[Signature]
Controller & Auditor of P^{ro} Accounts.

To
Colonel C. A. Orr Esq
Secretary to Government, Mad
Chennai.

1884
Geo. J. ...
June 1886

McC. ...
...

Robert ...

...

...

...

...

...

...

...

No 1392

The Bill is ...

...

...

...

...

No 87

...