

(1) Number of pages 10(2) Date of repair 16-11-42

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.**Government of Madras.***Public Works* **DEPARTMENT.**

G.O. No. 1152	Press
526-527	~~Mis.~~
Dated 28-6-	1865

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
28th April 1865.*

No. 526. Read the following letter from Captain J. G. RYVES, R. E., Superintending Engineer, 1st Division, to Colonel C. A. ORR, R. E., Secretary to Government, Public Works Department, dated Waltair, 3rd April 1865, No. 1,421 :—

SIR,

1. In the accounts of the Vizagapatam District there is an unadjusted balance of Rupees 224-2-7 from the expenditure incurred in 1861-62; this amount being one-fifth share of Rupees 1,120-13-2, spent in repairing the Duggada anicut, should have been recovered from the Doratla proprietress, who always bears a portion (one-fifth share) of the repairs executed to the anicut in question; but the Collector, after some correspondence with the party concerned, states that "she declines paying her share, on the grounds that the repairs (which she says were unnecessary) were executed to the anicut without her consent being previously obtained; and she further says that in case, however, she cannot be exempted from paying the required share, the fifth portion due to her of the charges she had incurred in 1862-63 in repairing the Búragapolem Cuttu, which irrigates a village belonging to the Government, might be taken as a set off to the present demand."

2. The work stated to have been executed by the proprietress in 1862-63, was inspected by Mr. Bevan, the Sub-Engineer lately in charge of the Golgondah Range, and reported to have been very badly done.

3. The Collector, however, suggests that credit be given to her for the repairs she says she has done to the amount of Rupees 113-5-4, and that the balance, viz., Rupees 111-13-3, be recovered by legal process.

4. As the work done by the proprietress so far back as 1862 cannot be now valued by this Department, and as the unadjusted balance of Rupees 224-2-7 has been outstanding for upwards of three years, I do myself the honor of requesting permission to write off to "profit and loss" the whole sum Rupees 224-2-7, and of applying for an order of Government authorizing me (if they deem it worth while) to institute a suit against the proprietress for the recovery of the Rupees 111-13-3, which remains due by her after giving credit for the whole amount which she claims as having spent on the other irrigation work.

No. 527. ORDER THEREON, 29th April 1865, No. 1,152.

ACCOUNT, No. 86.

1. The Superintending Engineer, 1st Division, is authorized to write off the sum of Rupees 224-2-7 referred to in this letter.

2. The Government are not disposed to press their claim against the Doratla proprietress.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 1st Division.

" Accountant General.

" Controller of Public Works Accounts.

Ed S. T. Augusta.

Salem District.

5th Division A.S.W.

New York

Prosser Range.

Abstract Estimate.

Trigatore Taliga.

Work. Constructing a Rest House for Troops proposed to be built at Jollarpett.

Quantity	Description of work.	Per. Rate.	Amount	Total.
203 $\frac{1}{2}$	Cubic yards of brick work in clay	At 2.12.	558.12.9	
24.	" " of " in chunam	4.00	96.00	
927	" " of flat arch work in chunam	5.8.	53.76.0	
1.	" " of circular	5.14.6	5.14.6	
57	Squares of plastering with 2 coats of chunam	3.00	171.00	
14.	" " of flooring with 8" square bricks			
	and 1 coat of tar	9.00	126.00	
22.	" " of roofing with palm-leaf complex			
	pers, flat and pan-tiles	28.00	616.00	
165.7.6	Cubic feet of jungle wood wrought and put up	At 2.00	331.4.0	
5.	Pairs of Panelled doors with frames, locks, hinges &c complete 8x5 $\frac{1}{2}$	65.21.0		
3.	" " " " 5 $\frac{1}{2}$ x3	12.6.0	37.2.0	
10.	" " of Panelled windows with frames, locks, hinges &c complete 5x5 $\frac{1}{2}$	12.5.0	125.00	
	Nails for Trusses		1.00	
12.	Running feet of Rod iron for Globes wrought and put up	At 4.00	48.00	
126.	Cubic yards of excavating foundation and filling the basement	At 1.14.	14.2.0	2237.9.1
	Sundries at 5 per cent		112.6.11	
	Total Arises			2350.

Cook Room.

15	Cubic yards of brick in chunam	At 4.00	5.5.4	
28 $\frac{1}{2}$	" " of " in mud	2.12.0	72.6.0	
13.	" " of flat arch work in chunam	5.8.0	1.13.4	
35.	Running feet of cornice work in chunam	At 3.00	6.9.0	
	Carried Over		92.1.8	2352.00

Quantities.

Description of work.	Per.	Rate.	Amount.	Total.
Brought Over			92.18.	2352.
1. Square of flooring with brick jelly in chumam & one coat of chumam	Sq.	2.8.	2.8.	
8. — of plastering with 1 coat of R.		1.8.	12.	
2. — of roofing with Palmirah rafters Bamboos and fantiles		21.	42.	
1.3. Cubic feet of jungle wood wrought & put up		2.	8.	
1. Pair of jungle wood batten door with frames & complete 3x3		11.4.	11.4.	
8 Cubic yards excavating the foundation	Cy.	1.4.	11.2.	
Sundries at 5 per cent			1.58.	
Total Rupees				170.

Privy.

46 3/4 Cubic yards of brick in mud	Cy.	2.12.	137.90.
43. Running feet of cornice work in chumam		3.	8.1.
17 1/4 square of flooring with brick jelly in chumam and plastering with 1 coat of R.	Sq.	2.8.	4.6.
14 1/4 R. of plastering with 2 coats of chumam		3.	42.12.
2 1/10 R. of roofing with palmirah rafters bamboos & fantiles		21.	48.8.2.
7.9. Cubic feet of jungle wood wrought & put up	Cy.	2.	15.8.
Excavating the foundation			4.
Sundries at 5 per cent			12.16.11.
Total Rupees			260.
Compensation for Sand			150.

Store Room.

24 1/2 Cubic yards of brick work in mud	Cy.	2.12.	67.6.
19. — of flat arch work in chumam		5.8.	4.19.
16.5. Cornice work in chumam	R.	3.	3.1.6.
1 1/2 square of flooring with brick jelly in chumam & plastering 1 coat of chumam	Sq.	2.8.	3.
7. — of plastering with 1 coat of chumam		1.8.	10.67.
Carried Over			89.15.11.2930.

Quantities.

Description of work.	Per.	Rate.	Amount.	Total.
Brought Over			89.15.11.	2930.
2. Square of roofing with palmirah rafters Bamboos and fantiles	Sq.	21.	42.	
1.8. Cubic feet of jungle wood wrought & put up	Cy.	2.	3.5.4.	
1. Pair of jungle wood batten door with frames & complete 3x3		11.4.	11.4.	
2. Pairs of — windows — 3x4		18.	18.	
Excavating foundation			3.	
Sundries			5.3.10.	
Total Rupees				170.
Total Amount of Estimate Rupees				3100.

Superinty. Engr. Office 5th R.
 Value Amount 1865
 18th March

Superinty. Engineer 5th R.
 5th Col. R.

Campbell

29/12/97

Abstract submitted for
consideration on 11/12/97
for copies prepared &
be built up & completed.

No. 2. No. 1001. 07/10/97

29/12/97

29/12/97
No. 1152



I do not think that there would be a well course
to adopt for it actually settles the question as to the
liability of the owner of the estate to contribute towards
the repair of the Amiral. I think that the Dr. Dept has
shown a very ungrateful policy in arranging for
what ought to be done but to have been allowed to hang on for years
without the best expert plan would be to me for the
value of the work.

The Superintendent
Engineers 1st Division is au-
thorized to write off the sum
of Rs. 224-2-7 referred
to in this letter.

The Government
are not disposed to press
their claim against the
Proprietors.

To The Supy Engr 1st Div
" Accountant Genl
" Controller PWD Accounts
x 82 Dec 1st May 1 Accountant

For St George
29/12/97

W. N. (1)

155

To 1865 Date
Pro. of Govt. for April
from No 1258
The Superior Engineer
1st Division

To
The Secretary & Government
D. P. P.
Madras

Dated 31 } April 1865
Despatch }
Recd 11 }

No 1421

Brought notice that a sum of
Rs 224-2-7 is outstanding in the
accounts of the Vizagapatam
district as an unadjusted
balance of 1861-62 and requests
permission to write off to
Profit and Loss for the year
same being given -

No 526. 527

No 1152-29th April 1865

With an Order

c. 12th April 1865 Or. 195