

- (1) பக்கங்களின் எண்ணிக்கை 8
 (2) புதுக்கித் திருப்பிய நாள் 2.5.1889
 (3) ஆதாரங்குறிப்பவர் கருக்கொப்பம் 15/3

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

(2)

PWP துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	1360	அச்சகம் பலவகை
நாள் :	20-5-1889	108

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

43/1000

20/5

Paragraph 3 of Government of India Circular Resolution No. 185, Dated 14 January 1947

Description or Class of Store	Number or Quantity	Actual Cost in India		Estimated Cost if obtained from Foreign		Remarks	
		Average price or rate	Incidental Charges or Contingents	Total Cost	Average price or rate		Incidental charges freight ex- change &c
Steel joists (Rotted beams) No	2	200-00	6-00	206-00	For 21 st 12 th 4 th 6 th	160-00	Request for emergency to purchase for 2. No. 10 because of the same dimensions found unsound at the Collector's Residence transportation must be furnished

W. Bullam
9 April 1889.

46 123 Submitted to the Chief Engineer for
Sanction of Government

23
Submitted to the Chief Engineer for
Sanction of Government

V. S. Cheliff


H. T. Jackson, Colonel R.E. Executive Engineer.

11-4-77 Superintending Engineer, M.C. Ck.

No. 1940C of 16 April 1887

To

S. & V. circle.



Please fill up
the columns in this
statement that
have been left
blank.

WCS
15.4.87

D. W.

Dated } April 1887
Rec'd }

No 123

Stores manufactured
in Europe but purchased
in India.

Submitting a statement
for

To

1360

P. W. DEPARTMENT

Circular No. 3469

From The Supply Engineer

V Circle

No. 123

Dated 11 April 1889

Received 13 - 1889

Submitting for consideration
a statement of stores
manufactured in Europe
and purchased in India
in Bombay Division

RECEIVED

No. 1940 C Dated 16 April 1889

To

S. C. Venkata

Please fill in
the Column in the
statement that has
been left blank.

W. H. Burton

Enclosures.

1360

SUPERINTENDING ENGINEER'S OFFICE,

V Circle, Madras,

Chepák, 9 May 1889.

No. 899

From

Colonel W. H. Burton R.E.

SUPERINTENDING ENGINEER, V CIRCLE,

To

The Chief Engineer

P. W. Department

SIR,

In returning your endorse-
ment No 1940 C dated 16 April
1889, I have the honor to state
that the General Superintendent
P. W. Stores has filled in - the
Column "Estimated Cost if
obtained through the India
office" in the Statement. But
as no dimensions of the joists
are given the price of a 21x12x6
Rolled Iron joists recently
received from England has
been entered - and a Rolled
Steel girder is in all probability

3

25

25 percent dearer - if of equal
weight.

I have the honor to be
Sir
your most obedt servant

W H Burton Colpe.
Superintending Engineer
5th Circle

1360

memor to 1960 C of 16-4-89

HW/ 3469 24280

H.C. 15 May

The local purchase of woodstubs
rolled beams is questioned,
but the remark that they
are to replace teak beams
of the same dimensions
is not understood.

A copy of letter no 897 of
9th May 1889 from the S.E. V Circle
will be furnished to the S.E. III Circle

11.5.89
Cued 12.5.89

100 means length?
A teak beam 2' long
would surely be more than
12' deep or 5" thick

S.E. III & V Circles

Ry. Mr. A. Desai

22/5/89

Asst. Secy. H. 14/5 89

(11)
From
The Superintending Engineer
5th Circle

To
The Chief Engineer
P. W. Department

Dated 9th May 1889.
Recd.

Encls 1

No. 897

Statement of Stone Mason-
-factured in Europe but
purchased in India

Returns the - having
duly filled in, the values
column.

(11)

With orders