

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.**Government of Madras.***Public Works* **DEPARTMENT.**

G.O. No. 2037

Press
~~Mis.~~

422-423

Dated 17-7-1865.

Not to be folded or roughly handled

7

*Proceedings of the Madras Government, Public Works Department,
17th July 1865.*

No. 422. Read the following Proceedings of the Madras Government in the
Estimate Ecclesiastical Department:—

Calling for a plan for renewing the rob-
bing room attached to the Burial Ground } (Here enter 11th July 1865, No. 183.)
at Bellary.

No. 423. ORDER THEREON, 17th July 1865, No. 2,037.

CIVIL WORKS, No. 55.

Communicated to the Superintending Engineer
of the 3rd Division, who will be requested to submit
the estimate called for in paragraph 1.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 3rd Division.
„ Ecclesiastical Department.

Exd. S. T. Augustin.

Civil Works

242037

Communicate to the
Superintending Engineer of the 3^d Division,
who will be requested to sub-
mit the estimate called for

in Paris.

Wm. A. George
17th July 1865

*The Superintendent says he
has no objection to our
collecting birds & specimens*

[Handwritten signature]

Dec^r 18th 1891

27

2

*Proceedings of the Madras Government, Ecclesiastical Department,
11th July 1865.*

No. 12. Read the following letter from Captain A. S. MOBERLY, R. E., Superintending Engineer, 3rd Division, to the Honorable A. J. ARBUTHNOT, Chief Secretary to Government, Fort Saint George; dated Camp Darojee, 30th June 1865, No. 526.
With reference to paragraph 2 of G. O., No. 124, Ecclesiastical Department, dated 28th May 1863, I have the honor to submit a Report on the Burial grounds in the 3rd Division, for the year 1864-65.

2. At Cuddapah, the Burial grounds in the Cantonment and Civil Lines are in tolerable order; slight repairs are required for which estimates are being prepared, but the amount sanctioned in the Budget is insufficient.

3. The Burial ground at Bellary is in a bad state of repair, the roof of the dressing house requires to be renewed, and the wall on the west side should be extended, as it is almost full. Those at Ghooty and Ramandroog are in good order, and require white-washing; but there are no funds at my disposal for carrying on the work, as no amount whatever has been entered in the Budget for 1865-66 for repairs to Burial grounds in the Bellary District.

4. Slight repairs are required to the Burial grounds at Kurnool; estimates for the same will shortly be submitted. The one at Cumbum is in very good order; but Rupees 50 only is allotted to the Cumbum Range for the repair of this class of buildings in the Budget, and nothing in the Kurnool Range.

No. 13. ORDER THEREON, 11th July 1865, No. 183.

An estimate will be called for in the Department Public Works for renewing the roof of the robing room attached to the Burial ground at Bellary. On its submission, it will be determined, in that Department, from what source the charge is to be met.

2. As it appears that this ground is almost wholly occupied by graves, the Collector will report whether the land necessary for its extension on the western side is public or private property,—if the latter, at what cost it is procurable.

(True Extract).

A. J. Arbuthnot
Ag. Chief Secretary

To the Department Public Works.
" Collector of Bellary.

Exd. J. H. Burns.

15 spare copies

5
7. 1868 Depa
Pro. of Govt for July

No. 2587

Pro. of Govt in the
Ecclesiastical Dept

Of 14 July
Rev. Mr. J.

No. 188.

Calling for an
~~estimate~~
~~plan~~ for renewing
the robing room
attached to the Buid
ground at Bellary.

No. 422.423

Order
No. 3037-175 July 1865
With an Order