

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Publ. & Work DEPARTMENT.

G.O. No. 2421	Press
482 483	~~Mis.~~
Dated 21-8	1865.

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
21st August 1865.*

The plan of the Jail is as follows:—

- I.—Outer wall of twelve sides or divisions.
- II.—Inner wall of do. do.
- III.—Radial cell and workshop, eleven blocks.
- IV.—Centre Warder house.
- V.—Outside, Jailer's quarter.

Work as follows has been executed to 31st July 1865:—

- I.—Outer-wall, eight sides, completed to full height of 16 feet.
- II.—Inner wall, four sides, completed, four sides foundation built.
- III.—Radial cells and workshop, eleven blocks.
 - 1. Workshop, } Foundation excavated.
 - 2. Radial cells, }
 - 3. Workshop : masonry all done, nine trusses for roof ready.
 - 4. Radial cell : foundation excavated, and portion of foundation built.
 - 5. Workshop completed.
 - 6. Radial cell completed.
 - 7. Workshop completed all but flooring.
 - 8. Radial cells : masonry built to springing, all doors and windows up, roofing in progress.
 - 9. Workshop completed.
 - 10. Radial cells : masonry built to springing 8 feet, all doors and windows up.
 - 11. Workshop : masonry completed.
- IV.—Centre Warder, lower story completed.
- V.—Outside, Jailer's quarter, completed.

COIMBATORE,
7th August 1865.

(Signed) J. GEORGE,
Assistant Engineer.

Remark in reply to Memorandum from the Superintending Engineer.

N. B.—Item "Jungle-wood."—Excess of expenditure is due mainly to the very large wastage in cutting up Vengay wood (nearly 30 per cent.). I have an enormous amount of waste Vengay now on hand, but should certain proposed alterations to the Jail be carried out, much of this waste wood will be used up for venetians, louvre boards, planking over doors and windows, &c. &c., and the refuse will then be sold, and the proceeds brought to account in the usual way.

Item "Teak-wood wrought and put up."—A good deal of Teak has been used for purlins and summers, but is not yet paid for ; a charge against this item will be shown either in August or September accounts.

(Signed) J. GEORGE,
Assistant Engineer.

11th August 1865.

(Signed) G. W. WALKER, Lieut.-Colonel, R. E.,
Superintending Engineer, 7th Division.

No. 483.

ORDER THEREON, 21st August 1865, No. 2,421.

CIVIL WORKS, No. 67.

Communicated to the Judicial Department.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Judicial Department.

Exd. S. T. Augustin.

Rough Stone in Chunnam	Cy. 1158 1/2	2	8	-292712
Brickwork Ditto	" 12919 5/8	1	.	5167912
Terracing	Sqr. 1495 3/4	"	.	127888
Whitewashing	" 14769	-	22	6451210
Flooring Brick on edge	" 751	8	31	618914
Excavating foundation	"	.	.	16118
Teak wood wrought and put up	Cft	.	.	.
Jungle wood Ditto	" 8535 3/4	1	12	119561
Wood oil	Sqr. 163	1	25	51028
Cub Stone over Pillars	No. 269	1	.	269
Ditto for Centre Pillars	" 81	1	8	126
Slab Brickwork	Cft 1868 5/8	.	3	350510
Plastering	Sqr	"	.	.
Stone Columns	No. 21	11	12	354
Wooden stair Case Complete	Rs	.	.	120
Cornicework	Cft 2947	"	6	1258910
Country wood battens Doors	Pairs 60	.	.	108156
Complete.				
Ditto Windows Ditto	" 35	.	.	5188
Roofing with Country wood	Sqr. 131 1/4	8	34	107756
Painting	" 110 1/4	.	.	298.6
Wooden Trusses Complete	No. 35	30	.	1140
Arched Roof	Cft 65812 1/2	.	3	12339136
Centring for Ditto	Rs	.	.	3100
Putting Selly two Courses of				
flat Lime and plastering over	Sqr. 286 1/2	9	.	25785
the Arched Roof.				

112295106

21585 1/2	3	8	86477118	548 1/2	"	444211	10113 3/4	"	63928 1/2
4897 1/2	6	.	2950541	108 1/2	"	2672222	2502415	"	10
521 5/8	.	2	162093	22 1/2	"	215378	12622	"	23548
5482 1/2	.	6	205515	.	"	205515	205515	"	10
729 1/2	12	2	875147	.	"	875147	875147	"	10
.	.	.	1847	.	"	1847	1847	"	10
946 2/3	1	.	37862	.	"	37862	37862	"	10
764 1/2	2	.	152151	.	"	152151	152151	"	10
175 1/2	1	1	59412	.	"	59412	59412	"	10
307	1	12	5374	.	"	5374	5374	"	10
768 3/4	2	4	646711	.	"	646711	646711	"	10
83 1/2	3	8	2932	.	"	2932	2932	"	10
076	.	.	.	.	"	.	.	"	10
.	.	.	120	.	"	120	120	"	10
291 5/8	8	11	714	.	"	714	714	"	10
173	.	.	1199	.	"	1199	1199	"	10
.	.	.	.	.	"	.	.	"	10
35	.	.	654	.	"	654	654	"	10
132 1/2	78	.	210712	65 1/10	"	1014	56	65 1/10	2015 1/2
38 1/2	1	12	1894	.	"	1894	1894	"	10
38	80	.	3116	.	"	3116	3116	"	10
77000	.	1	621554	.	"	1091138	.	"	637189
.	.	.	3100	.	"	3100	.	"	1203114
291 1/2	15	.	592158	.	"	32297	.	"	345411
20568	.	.	20568255	.	"	1630114	.	"	13549396

[illegible]

३६५३६८ ..

Deduct for Council Labour.

0 - 7981 - " " " " 2/1/82 - " " " " 12/2/11

113021

The plan of the sail is, as follows.

II. Inner wall of "Ditch" "do" "do" "do"

III Radial-bellows Work Shop " " 1974-75

III Centre warder house.

Outside Journals Quarter

Work as follows has been recorded 651 1/2

I Outer wall 8 inches, completed to full height.

II. Annual wall journals completed 4, 40, 40, 40

III Radial bells and Work Shop " blocks

1. Workshop

1. Natural bills of lading are not required.

Workshop masonry all done 9 frames for roof

14. Atlantic Bell foundation, recovers portion

5 Work Shop could be

" " " Radial bill "com." "

7. At rock shop completed 1/4 of 1/2

8 Radial brls Masonry built at out flooring

doors + windows up roof made

9. Work Shop completes

2225022

23256955 " " " 1690357 " " " 148190153

[illegible]

1142

		Lit. am	1907	
--	--	---------	------	--

23288107 64288 10144.8

15833	15834	15835	15836	15837	15838	15839	15840	15841	15842	15843	15844	15845	15846	15847	15848	15849	15850	15851	15852	15853	15854	15855	15856	15857	15858	15859	15860	15861	15862	15863	15864	15865	15866	15867	15868	15869	15870	15871	15872	15873	15874	15875	15876	15877	15878	15879	15880	15881	15882	15883	15884	15885	15886	15887	15888	15889	15890	15891	15892	15893	15894	15895	15896	15897	15898	15899	15900	15901	15902	15903	15904	15905	15906	15907	15908	15909	15910	15911	15912	15913	15914	15915	15916	15917	15918	15919	15920	15921	15922	15923	15924	15925	15926	15927	15928	15929	15930	15931	15932	15933	15934	15935	15936	15937	15938	15939	15940	15941	15942	15943	15944	15945	15946	15947	15948	15949	15950	15951	15952	15953	15954	15955	15956	15957	15958	15959	15960	15961	15962	15963	15964	15965	15966	15967	15968	15969	15970	15971	15972	15973	15974	15975	15976	15977	15978	15979	15980	15981	15982	15983	15984	15985	15986	15987	15988	15989	15990	15991	15992	15993	15994	15995	15996	15997	15998	15999	16000
-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------

" 25711A " " " " 1/5 L. 0 1/2 3

Recoveries up to 31st July 1865 2981 152

Net Expense Ditto-Ditto 15535 1/2 " 9

10 Radral bells. masonry built to springing 8 feet all doors
and windows up.

10 Work Shop. masonry, completed

III Centre warder Lower story complete

▽ Outside Jarlers Quarter - completed

John G. Jones

Assistant Engineer

Countess }

7 August 1865 }
Remark in reply to memos. from the Sup^r Genl

13- Item "Inglenood" - Excess of Expenditure is due mainly to the very large wastage in cutting up beechy wood (nearly 30%) - I have an enormous amount of waste beechy now on hand, but should contain proposed alterations. The fuel be carried out, much of this waste wood will be used up - for benches - house boards - planing & other doors & windows etc etc - and the refuse will then be sold and the proceeds brought to account in the actual work.

Item "Teakwood brought in by us" - a
good deal of teak has been used for privies & gun
muzzles, but is not yet paid for - a charge against the
item will be shown either in August or Sept^r acct^s

John George

Adm^r Henry's

11 August 65

Matthew L. J.
Sup 8 Dec

Civil No 10

1872

Communicated to the

Judicial Department

Franklin D. Jones
21st August 1865

[Signature]

To the Judicial Department

21st August 1865

Progress Report of Mr John George Assistant Engineer in charge of Contract Sail at Coimbatore for the month of July 1865

[illegible]

1

1

the 1990s, the number of people in the world who are undernourished has declined from 1.1 billion to 800 million. The number of people who are malnourished has declined from 1.5 billion to 1 billion. The number of people who are obese has increased from 100 million to 300 million. The number of people who are overweight has increased from 100 million to 300 million. The number of people who are undernourished has declined from 1.1 billion to 800 million. The number of people who are malnourished has declined from 1.5 billion to 1 billion. The number of people who are obese has increased from 100 million to 300 million. The number of people who are overweight has increased from 100 million to 300 million.

10

10