

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public works DEPARTMENT.

G.O. No. 3566	Press Mis.
596-595	
Dated 26. 11. 1865.	

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
24th November 1865.*

Read the following:—

No. 2,100.

No. 594.
List of Bills received from the Superintending Engineer, 6th Division, for works executed in Tanjore District, submitted to Government agreeably to Chapter IV., paragraph 13, of the New Code.

Audit No.	Date of Bills.	Description of Work.	Amount.		To what year expenditure appertaining.	Date when received.
			RS.	A. P.		
516	28th October 1865.	Repairing the right embankment of Salt Pans of the Nasunniyar river.	200	0 0	1864-65	5th November 1865.
517	Do.	Do. the left bank of do. ...	122	0 0	Do.	

REMARKS.—These works are stated to have been "slovenly performed" and the banks very weak. Earth has been thrown upon them without levelling and ramming.

The Superintending Engineer states that "the unsatisfactory nature of the work has been reported to the Salt Deputy Collector personally."

(Signed) J. F. FISCHER, Captain, R. E.,
Controller of Public Works Accounts.

No. 595. ORDER THEREON, 24th November 1865, No. 3,566.

ACCOUNT, No. 64.

The Bills are sanctioned; but the attention of the Collector of Tanjore will be called to the unsatisfactory manner in

which the works are reported to have been carried out.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Controller of Public Works Accounts, with two Enclosures.

Accountant General.

Collector of Tanjore.

Superintending Engineer of the 6th Division.

Exd. S. T. Augustin.

List of Bills received from the Superintending Engineer 6th Div for work executed in Varanasi District, submitted to Government, according to Chapter IV, para 13 of the New Code.

Audit Date of Bills	Description of work.	Amount	Date when received	Remarks
576	20 th Dec 1865. Repairing the right embankment of salt pans of the Madanmugar River	200	864-65	These works are stated to have been "thoroughly performed" and the banks very much better than when thrown upon them without levelling & draining. The superintending Engineer states that the masonry facing nature of the work has been reported to the salt & op. collector formally.
577	do do the left bank of - do - do	122	do - do	

Enclosures 2. bills with certificate of completion.

Office of the Controller P.W. Works
Madras 10th Nov 1865.

Yr Secretary to Government P.W. Works
Controller P.W. Accounts

Mr 1865 Sept
Geo. W. Houston
of Houston
Tex 4618

203566

The Collector with
of the Collector with
of the Collector with
of the Collector with

The bills are

Sept 18-46
Sept 20
Oct 2/00

of the Collector with
of the Collector with

sanctioned, but the attention
of the Collector of Stamp
will be called to the
unsatisfactory manner
in which the records
are reported to have
been carried out.

Sept 18-46
Sept 20
Oct 2/00

25

from the Collector with
of the Collector with
of the Collector with
of the Collector with

Sept 18-46
Sept 20
Oct 2/00
of the Collector of Stamp
of the Collector of Stamp
of the Collector of Stamp
of the Collector of Stamp

1865. 398