

(1) Number of pages 8(2) Date of repair 9-8-1966

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 1497

140-141

Press

~~Mis.~~

Dated

7-6-

18 66.

Not to be folded or roughly handled

17

*Proceedings of the Madras Government, Public Works Department,
7th June 1866.*

No. 140 Read the following letter from the Superintending Engineer, 3rd Division, to the Secretary to Government, Public Works Department, dated Bellary, 22nd May 1866, No. 13 :—

1. With reference to G. O. No. 114, of 10th January 1866, I have the honor to submit a statement showing the measurements in the original estimate for stone revetment to the Hindoopoor Sooruppah Cuntah, the work performed by S Ramachendra Moodelliar, and that requiring to be constructed in consequence of omissions or bad work.

Rupees 200.

2. The amount of security money given by S. Ramachendra Moodelliar is lodged in the Government Savings Bank ; but I regret to say that I am unable to find any Security Bond ; the delay in replying has been caused by my having to search and make inquiries for this document.

No. 182 of 15th December 1865.

3. As already reported, this man's case has been laid before the Joint Magistrate for investigation. Mr. Reid, the late Acting Joint Magistrate, informed me, in the middle of March last, that he expected to bring the case to a close before the Easter holidays ; but he went away to England without completing it, and now it has had to be tried over again by the present Acting Joint Magistrate, up to this date I have not heard what has been the result.

No. 140.

ORDER THEREON, 7th June 1866, No. 1,797.

CIVIL WORKS, No. 26.

The Superintending Engineer of the 3rd Division will be requested to state distinctly whether a Security Bond was executed by Ramachendra Moodelly, and, if so where it was deposited, and who is responsible for the loss of the document. In the event of a bond not having been taken, Major Moberly will report the name of the Officer responsible for the neglect.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government,

To the Superintending Engineer, 3rd Division.

Erd. S. T. Augustin.

11

100

24

15

16

14 of submit in the per bar, 6 in only as un delay owing to this is to be set 'Easter' 'old'

Statement showing the original Estimates as they are the stone 'Reinforced' work performed and requiring to be performed at the same for 'Concave' Contact.

Original Estimate

Work performed by S. C. Williams & Co. for the purpose of the same.

Remarks.

Description of work		Length	Breadth	Thickness	Height or Depth	Cubic Contents	Length	Breadth	Thickness	Height or Depth	Cubic Contents	Remarks		
Rebuilding Rear Wall Stone	Old stone	8	1	1/2		12	8	3/4		6	8	1	36 Old stone	
Stone with side	New stone	8	1	2		16	8	3/4		12	8	1	16 New stone	
Smalling inner facing	New stone	36	1	1/2		18	10	1/2		1/4	1/4	3		
							12	1/2		1/2				
							8	1/2		1	4			
Outer facing	Old stone	30	1/2	2		60	17	1/2		1	1			
	New stone	13	1/2	1		6 1/2	12	1/2		2	60			
Outer facing	Old stone	13	1	1		13	12	1/2		1	8			
	New stone	13	1	1		13	12	1/2		1	8			
Smalling inner facing	New stone	32	1	1/2		16	30	1/2		1/2	7 1/2	30	1	1/4 1/2 New stone
Outer facing	New stone	9	1/2	1		4 1/2	8	1/2		1	4			
						21	5 6	1/2		1	28	64	1/2	1/2 1/2 Old stone
						3	7	1/2		1/2	1 3/4	64	1/2	1/2 1/2 New stone
Smalling inner facing	New stone	22	1	1/2		11	20	1/2		1/2	5 1/2	22	1	1/4 1/2 Old stone
														1/4 1/2 New stone
Outer facing	New stone	11 1/2	1/2	3/4		4 1/2	12	1/2		1/4	11 1/2	40	1/2	1/4 1/2 Old stone
							44	1/2		1/2	11	40	1/2	1/4 1/2 New stone
							6	1/2		1/4	3 1/2	40	1/2	1/4 1/2 New stone
							14 1/2	1/2		2 5/8	20 5/8			
Outer facing	Old stone	16	1	5 1/2		88	18	1/2		2 5/8	20 5/8			
	New stone	14	1	1/2		28	20	3/4		1 1/2	22 1/2			
Outer facing	New stone						12	1/2		1 1/2	9			
							10	1/2		1 1/2	9			
	Old stone						10	1/2		1 1/2	9			
Smalling inner facing	Old stone	13	1	1/2		6 1/2	36	1/2		5 1/2	11 1/2	36	1	1/2 1/2 Old stone
										</				

From the Superintendent
 Charge to 60 Cuz.
 To the Superintendent
 Engineer 3rd Division
 Dated 20th March 1866
 Showing the original
 Estimate as regards the
 Stone Revetment, work per-
 formed and requiring to be
 performed at the Hindoos
 for Surappah Cantt.
 P.W.D. 2182/83

No. 13. Superintending Engineer's Office
 Bellary 22nd May 1866.
 To, The Superintending Engineer
 3rd Division
 The Secretary to Government
 P.W.D.

Sir, With reference to G.O. No. 114 of
 10th January, 1866, I have the honor to submit
 a statement shewing the measurements in the
 original Estimate for Stone Revetment to the
 Hindoos for Surappah Cantt., the work per-
 formed by S. Ramachandra Moodliar,
 and that requiring to be constructed in
 consequence of omissions or bad work.

The amount of Security money
 given by S. Ramachandra Moodliar
 is lodged in the Government Savings
 Bank; but I regret to say that I am un-
 able to find any Security bond: the delay
 in replying has been caused by my having
 to search and make inquiries for this docu-
 ment.

As already reported this man's
 case has been laid before the joint Magistrate
 for investigation. Mr. Reid the late Acting
 joint Magistrate informed me, in the
 middle of March last, that he expected
 to bring the case to a close before the Easter

Holidays

Holidays; but he went away to England
without completing it and now it has had to
be tried over again by the present Acting Joint
Magistrate: up to this date I have not heard
what has been the result.

Yours &c

A. M. S. Major R.E.
Superintending Engineer 3rd Div.

2304 May 1866 0110

2304

10th Aug 1866 0114

14th 1797: 7th June 1866
In hand: a. M. S. M. S. M. S.
to measure made in the year
1866: for the purpose
of the M. S. M. S. M. S.
the which is given by
M. S. M. S. M. S.

10th 13.
Dated 22nd May 1866
Received 23rd May 1866
Dated 22nd May 1866
Received 23rd May 1866

Civil Works

Public Works Department

1797 121797

PROCEEDINGS of the MADRAS GOVERNMENT
under date the 7th June 1866
Read the following

from the Superintending Engineer
of the 3rd Div's com (Here enter No. 13 dated 20th May 1866.)

The Superintending Engineer
of the 3rd Div will be requested
to state distinctly whether a
Security Band was executed
by Chamaendra Kumbharly,
and if so where it was deposited
and who is responsible for
the loss of the document.
In the event of a Band
not having been taken,
Major Kumbharly will report
the name of the officer re-
sponsible for the neglect.

W. S.

Major Kumbharly had
stated something
about "the man's case".
We require a report
whether the case referred
to is one in which
Major Kumbharly
substantially has
performed

A criminal charge agst.
Kamiah & a Row 2 of lo
woned deservd him - to
servant - copy of the
charge so made.

We have seen that hasty
severity is the characteristic
of being a tyrannical pros-
per his subordinates
in office.

very

P. W. 1866 Department.

Pro: of Cash for 1st time

No 1194

PROCEEDINGS OF GOVERNMENT

Dated

The Acting Secy has
requested to furnish certain information
relative to the security of and,
you executed by S. P. Mochendro
Moddelly late a Village Provost
in the Bellary Dist.

No. 140-145

E. D. Palmer, 1866 - Dec. 1 to 9 June