M.R.O. 1—77,000—8-6-37.

(1) Number of pages_____

(2) Date of repair_____

(3) Initials of the Referencer_____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 2978 Press / Mis.

473-475

Dated 19-7- 1866.

Not to be folded or roughly handled

No. 473.

Read the following papers:—

Proceedings of the Board of Revenue, dated 30th August 1866, No. 6,185.

Read the following paper from the Collector of Cuddapah, to the Secretary to the Board of Revenue, dated 17th August 1866.

List of the more important Irrigation Works, which are most urgently in need of repair in the District of Cuddapah, specifying the estimated amount of repairs required, the date of last repair, and the irrigable Ayacut under each work, as directed in the Board's Circular, dated 11th June 1866, No. 3,972.

Táluq and Village.		Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present cultivation as per account for Fusly 1275.	Present revenue as per account for Fusly 1275.	Rough estimate of repairs needed.	Date of last repair.	Remarks, explaining what repairs are required.
1		2	3	4	5	6	7	8	9	10	11
Cuddapah.	Camalapuram	Pedda Chervu ...	Acres. 607	RS. 4,215	RS. 3,601	Rs. 3,907	Acres. 570	RS. 4,008	RS. 5,900	The exact dates are not known, but the repairs are reported to have been executed six or seven years ago.	An estimate, amounting to Rs. 5,900, for the repairs of the tank bund, which is much worn out, has been framed by the Department of Public Works.
	Chadipiralla.	Pullampati Calva.	169	1,058	378	400	64	443	250	.....	For repairing the sluice, which is out of order.
	Kutukur ...	Pedda Chervu ...	449	4,325	4,173	4,107	392	4,311	700	.....	For the repairs of the bund.
	Pata Cuddapah	Do. ...	1,066	14,373	13,818	14,069	865	11,337	1,000	.....	Do. do.
	Putlampally.	Pata Chervu ...	156	1,330	1,285	1,227	156	1,330	1,000	.....	Do. do.
		Total ...	2,447	25,301	23,255	23,710	2,047	21,429	8,850		
Vollpaud.	Navabpett...	Pedda Chervu ...	100	926	373	739	79	811	7,122	Not known...	For repairing the bund and sluice.
	Chinnagottigal	Jantrapupett do.	109	652	76	455	20	220	300	14th May 1852	For the repairs of the sluice, which is out of order.
	Tarigondah.	Ramanayani do.	190	1,463	1,267	1,122	100	828	1,300	27th Dec. 1856	For the repairs of the bund and sluice.
	Manchuru ...	Cotta do. ...	192	560	111	120	48	194	430	Not known...	Do. do. do.
		Total ...	591	3,601	1,827	2,427	247	2,053	9,152		

List of the more important Irrigation Works, &c.—(*Continued.*)

Táluq and Village.		Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present cultivation as per account for Fusly 1275.	Present revenue as per account for Fusly 1275.	Rough estimate of repairs needed.	Date of last repair.	Remarks, explaining what repairs are required.
1		2	3	4	5	6	7	8	9	10	11
			Acres.	RS.	RS.	RS.	Acres.	RS.	RS.		
Kadiri.	Patnam ...	Ranganayani Chervu.	572	3,736	2,199	2,053	313	2,523	500	In Feb. 1865.	For repairing the banks of the supplying channel of the tank.
	Vankamaddi.	Pedda Chervu ...	399	2,041	1,367	818	278	1,366	1,000	,, Aug. 1865.	For repairing the bund and sluice.
	Dhannayani Chervu.	Do. ...	175	742	593	655	150	713	1,200	,, May 1866.	For repairing the sluice and calingulah.
		Total ...	1,146	6,520	4,159	3,526	741	4,602	2,700		
Pullampet.	Poli ...	Chervu ...	1,135	7,558	5,463	5,550	937	5,294	3,000	,, 1862 ...	For raising the dam constructed to convey the supply to the tank and strengthening the bund, &c.
	Rangampally.	Do. ...	175	843	357	482	163	498	1,000	,, 1861 ...	For repairing the supplying channel and the bund.
	Nagiripad ...	Do. ...	739	4,820	4,210	4,316	625	2,528	1,000	,, 1862 ...	For repairing the bund and supplying channel.
	Settikunta...	Pedda Chervu ...	452	2,870	1,280	1,117	239	1,871	500	,, 1861 ...	For re-constructing a sluice, &c.
		Total ...	2,501	16,091	11,310	11,465	1,964	10,191	5,500		
Jammalmadugu.	Venakiah Kalva.	Chitravati river channel.	366	2,926	1,957	1,188	2,219	1,523	500	,, 1860 ...	For re-excavating the river channel, which has been almost filled up with sand.
	Chintakunta.	Govindammah Chervu.	286	3,971	905	1,065	4,345	2,450	200	Not known.	For repairing the sluice.
	Gudem Chervu.	Penna river channel.	168	1,652	1,075	676	1,594	1,164	1,200	In 1858 ...	For clearing the channel, which has been totally filled.
		Total ...	820	8,549	3,937	2,929	8,158	5,137	1,900		
Poddatur.	Duvur ...	Tank	415	7,270	6,015	6,311	406	7,149	800	In 1856 ...	For repairing the bund and calingulah.
	Pallavolu ...	Do.	383	707	446	517	373	698	2,230	,, 1865 ...	For re-excavating a new supplying channel, the old one having been entirely filled up by sand.
	Wupparapally	Rachervu ...	157	581	217	233	154	564	300	,, 1862 ...	For enlarging the bund.
	Civapuram...	Ragadi Chervu...	162	858	665	649	138	815	450	,, 1859 ...	For raising the bund and repairing the sluice.
	Ganzikunta.	Anantaraz do. ...	173	964	845	839	149	836	1,000	,, 1863 ...	For repairing the sluice.
	Chintakunta.	Chinna Chervu and Pedda Chervu.	384	6,689	4,656	5,315	370	6,479	5,000	,, 1864 ...	For enlarging the bund and repairing the sluice.
	Nandialampett.	Settiwaripally Chervu.	105	1,585	887	1,042	89	1,403	200	Not known.	For repairing the sluice.
		Yellampally do....	113	1,377	684	808	86	973	100	In 1856 ...	For repairing the bund.
		Tiruvapally do....	133	1,808	1,023	1,342	91	1,243	800	,, 1861 ...	For clearing the bed of the tank, which has almost been filled with mud, and enlarging the bank.
		Total ...	2,025	21,839	15,438	17,056	1,856	20,160	10,680		
		Grand Total ...	9,902	84,477	61,620	62,710	15,382	65,571	46,982		

Ordered that the foregoing List be submitted to Government, with reference to Government Order, dated 17th May 1865, No. 1,586, Public Works Department, and in continuation of Board's Proceedings, 17th August 1866, No. 5,813.

(A true Copy and Extract.)

(Signed) W. HUDLESTON, *Secretary.*

Transferred to the Public Works Department.

(Signed) J. GROSE,
Under Secretary to Government.

FORT SAINT GEORGE,
5th September 1866.

No. 474. Proceedings of the Board of Revenue, dated 31st August 1866.

Read the following letter from the Collector of North Arcot, to the Secretary to the Board of Revenue, dated Chittoor, 11th August 1866, No. 224.

Agreeably to the instructions of the Board contained in Mr. Dalyell's letter of the 11th June last, No. 3,972, I have the honor to forward a statement in the form therein prescribed, giving a selected list of the more important works of irrigation, which are most urgently in need of repair in this District, and explaining what repairs are required, and the date of last repair, with the irrigable ayacut under each work.

STATEMENT giving the names of the more important Works of Irrigation which are urgently in need of repair in the District of North Arcot, and showing also the Revenue derived from them, the Irrigable Ayacut under each work, and the date of last repair.

Táluqs.	Names of Irrigation Works.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average Tax actually paid from 1840 to 1850.	Average Tax actually paid from 1850 to 1860.	Present cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.	Remarks.
1	2	3	4	5	6	7	8	9	10	11
		Acres.	RS. A. P.	RS. A. P.	RS. A. P.	Acres.	RS. A. P.	RS. A. P.		
Chittoor Táluq.	Komati Guruvayagaripalli, eight months' Kona Gutta tank.	69	379 10 3	335 0 0	345 0 0	59	346 10 10	300 0 0	...	Tank breached; bund sunk in; sluice out of repair.
	Balejapalli, four months' tank ...	49	335 5 5	419 0 0	213 0 0	49	330 12 11	200 0 0	1838	Bund very much cut up and sunk in; sluice dilapidated.
	Chinnampalli, four months' Perumal's tank.	55	465 1 10	592 0 0	335 0 0	55	460 3 1	200 0 0	1858	Do. do.
	Karakampalli four months' Musti tank.	33	283 3 11	238 0 0	211 0 0	18	156 6 9	150 0 0	...	Do. do.
	Makulattur resumed Dulabundum river channel.	37	309 0 10	217 0 0	293 0 0	32	267 8 6	300 0 0	...	Channel choked up and breached in several places.
	Total ...	243	1,772 6 3	1,801 0 0	1,587 0 0	213	1,561 10 1	1,150 0 0		
Chendragherry Táluq.	Four months' large tank of Tripatti.	156	995 3 6	934 10 1	1,154 0 6	126	1,103 3 7	3,000 0 0	About 14 years ago.	The bund sunk in, stone revetment displaced, bed of the tank much silted up.
	Do. Venkataroyani tank of Kotarla.	50	416 13 3	249 6 1	289 14 0	28	249 6 1	800 0 0	Do. 15 do. ...	Do. do.
	Sattari tank of do.	36	310 14 2	165 3 3	164 6 3	16	165 3 3	500 0 0	Do. ...	Channel choked with sand; a rock to be removed.
	Three months' Lingalamma tank. Two months' Pata tank and ruined spring channel of Timmenayadipoliem.	93	256 0 8	Not known, as the village having been included in the Jari poliem. In 1859 Pymaish was done and the assessment was fixed.	129 7 2	80	227 2 5	1,000 0 0	About 15 years back.	Tank breached. Channel choked up.
	Total ...	315	1,978 15 7	1,349 3 5	1,737 11 11	250	1,744 15 4	5,300 0 0		
Gudiattam Táluq.	Peddakasam spring channel of Perumbadi.	78	468 12 4	386 12 10	380 12 7	35	236 8 0	200 0 0	...	The channel much choked up.
	River channel of Melur	89	736 10 7	716 4 1	614 3 6	79	674 15 10	500 0 0	...	Do. do.
	Do. of Kelur	83	776 4 1	833 8 8	673 6 10	76	716 13 10	500 0 0	...	Do. do.
	Kalanjur channel	379	1,915 6 2	985 12 4	1,036 2 5	182	1,062 5 11	1,300 0 0	...	Do. do.
	Spring channel of Arimbakam ...	53	373 12 7	215 8 4	303 1 10	51	360 12 2	1,000 0 0	...	Do. do.
	Do. of Serkad	68	316 13 3	68 14 9	96 7 8	23	101 6 9	800 0 0	...	Do. do.
	Do. of Vovalpattada of Chengundrum.	26	169 0 11	310 4 0	242 1 5	25	165 1 2	800 0 0	1845	Do. do.
	Do. of Tatimampalli	20	111 9 1	...	117 6 6	16	105 7 9	400 0 0	...	Do. do.
	Total ...	796	4,898 5 0	3,517 1 0	3,194 10 9	487	3,423 7 5	5,500 0 0		
Vellore Táluq.	Pudur Andi tank...	86	601 7 4	1,637 0 0	1,845 0 0	60	414 5 0	500 0 0	Not known ...	Bund of the tank much cut up; sluice out of repair.
	Ariyur tank	284	2,125 2 11			184	1,346 11 11	500 0 0	Do. ...	Do. do.
	Yelavambadi tank	117	706 15 6	1,647 0 0	1,992 0 0	96	586 9 8	300 0 0	Do. ...	Do. do.
	Allapuram tank	66	405 11 11	1,541 0 0	1,397 0 0	59	355 7 1	400 0 0	Do. ...	Bund in a dilapidated state.
	Yeddayanjadu tank	40	259 15 2	1,051 0 0	1,209 0 0	40	259 15 2	200 0 0	Do. ...	Do. do.
	Tuttipat tank	91	638 3 6	852 0 0	811 0 0	88	607 5 0	100 0 0	1864-65	Do. do.
	Kottamangalam river channel ...	103	917 15 9	449 0 0	884 0 0	102	908 9 8	350 0 0	Not known ...	Channel choked up.
	Sembedu tank	110	747 14 5	1,430 0 0	1,396 0 0	86	595 12 5	400 0 0	Do. ...	Tank bund is in a ruined state.
	Kaniyambadi tank	122	913 8 3	941 0 0	953 0 0	112	840 0 0	1,000 0 0	Do. ...	Do. do.
	Total ...	1,019	7,316 14 9	9,958 0 0	11,163 0 0	827	5,914 11 11	3,750 0 0		
Poloor Táluq.	Six months' large tank of Mambat.	303	1,228 7 6	794 2 3	777 12 0	113	445 6 6	1,200 0 0	In Fusly 1240...	Bund Sluice, and Condam quite out of repair.
	Attimur three months' large tank.	88	376 3 3	226 10 11	222 11 3	43	168 5 11	500 0 0	In 1854 ...	Do. do.
	Terumali four months' large Hissa tank.	196	987 13 11	627 5 1	637 0 1	155	793 2 4	800 0 0	In Fusly 1269...	Do. do.

Moor 11th Augt 1866.

Collector.

Ordered

Statement giving the names of the more important Works of Irrigation which are urgently in need of repair in the District of North Arcot, &c.—(*Continued.*)

Táluqs.	Names of Irrigation Works.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average Tax actually paid from 1840 to 1850.	Average Tax actually paid from 1850 to 1860.	Present cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.	Remarks.
1	2	3	4	5	6	7	8	9	10	11
Poloor Táluq. (*Concluded.*)		Acres.	RS. A. P.	RS. A. P.	RS. A. P.	Acres.	RS. A. P.	RS. A. P.		
	Mandocolattur, six months' tank...	635	3,245 7 11	3,121 10 8	3,210 4 8	303	1,648 15 3	800 0 0	In 1866.	Tank breached in many places.
	Mattapattu, six months' tank ...	313	1,632 12 1	1,049 10 9	828 1 9	123	578 15 3	1,000 0 0	In 1860.	Sluice and supply channel in ruin.
	Verallur, four months' tank ...	81	433 12 10	274 7 10	215 12 11	36	199 6 5	850 0 0	.....	The bund, calingulah, and channel in dilapidated state.
	Gengaveram, four months' large tank.	171	821 0 0	253 0 7	229 1 0	59	280 4 5	600 0 0	In 1861.	The bund and sluice in need of repair.
	Pallur do.	139	717 9 3	544 10 4	671 8 5	118	623 12 2	1,200 0 0	No repairs for the last 20 years.	The tank bund in ruin.
	Mahadevimangalam, five months' tank.	243	1,713 12 9	1,542 4 7	1,435 4 0	206	1,481 6 3	1,500 0 0	20th Oct. 1855.	Do.
	Karepattu, six months' tank ...	417	1,946 2 2	1,391 2 8	1,392 13 3	244	1,128 13 5	1,500 0 0	1854.	Do.
	Total ...	2,616	12,923 1 8	9,825 1 8	8,620 0 4	1,398	7,248 7 11	9,950 0 0		
Wandawash Táluq.	*Hissa tank sluice of Mummani, Kadalvadi and Aunnambut.*	208	891 4 10	525 0 0	578 0 0	148	656 1 4	150 0 0	About 10 years ago.	The sluice out of repair.
	Setteri sluice of Mummani ...	6	35 6 6	47 0 0	36 0 0	6	35 6 6	35 0 0	.....	Do.
	Two supplying channels of Vengunam.	113	793 0 0	957 0 0	802 0 0	108	753 1 10	500 0 0	.....	The channel very much choked up; the bund cut up.
	Bund of the Hissa tank of Voyapakam, Veyedepattu, Naduppattu, and Kossappatta.	320	1,766 14 11	968 0 0	1,078 0 0	265	1,495 14 4	900 0 0	About 8 years ago.	The tank breached in several places; the bund in a weak state.
	Bund and sluice of the Agaram tank.	74	421 6 1	295 0 0	307 0 0	48	300 13 4	300 0 0	.....	The bund very much cut up; the sluice out of repair.
	Sluice of the Vengada tank ...	118	638 5 10	400 0 0	446 0 0	97	565 0 0	200 0 0	1864.	The sluice dilapidated.
	Bund and sluice of the Sittamur tank.	55	239 0 0	244 0 0	254 0 0	49	217 1 9	230 0 0	.....	The bund is cut up in several places; sluice requires repair.
	Total ...	894	4,785 6 2	3,436 0 0	3,501 0 0	721	4,023 7 1	2,315 0 0		
Arcot Táluq.	Sattur large tank	480	2,852 6 5	3,539 0 0	3,232 0 0	349	2,148 9 0	700 0 0	.....	These being in a dilapidated state, earth and stone works are urgently required.
	Do. Sitteri tank	50	369 12 2	.....	.....	43	260 0 1	100 0 0	.....	
	Kaganam large tank	189	1,312 7 1	1,483 0 0	1,356 0 0	164	1,147 14 11	500 0 0	About 10 years back.	
	Do. Setteri tank	31	207 12 0	.....	.....	20	134 14 11	300 0 0	Do.	
	Brammadesem large tank ...	191	1,277 5 5	5,063 0 0	.....	134	942 3 0	500 0 0	Do.	
	Varagur large tank	180	1,212 4 11	2,860 0 0	6,180 0 0	106	715 4 10	500 0 0	Do.	
	Attiyanam Setteri	74	445 3 6	638 0 0	2,021 0 0	49	304 5 10	700 0 0	Do.	
	Mandyalam tank	192	1,336 0 10	1,599 0 0	731 0 0	130	843 11 3	300 0 0	Do.	
	Perumantangal tank	36	246 7 8	351 0 0	2,662 0 0	31	218 5 0	100 0 0	Do.	
	Kurambady large tank	51	303 1 6	624 0 0	337 0 0	47	290 5 1	200 0 0	Do.	
	Total ...	1,474	9,492 13 6	16,497 0 0	16,825 0 0	1,073	7,005 9 11	3,900 0 0		
Wallajah Táluq.	Munjivakam Anicut Kondam ...	113	535 7 5	124 6 0	240 7 0	47	255 9 8	1,000 0 0	About 20 or 30 years ago.	These works being in great disrepair, their early restoration is highly desirable.
	Bund of the Kelvenumbakum tank..	160	879 13 11	1,085 8 1	997 12 3	144	811 12 7	600 0 0	In 1846.	
	Yeralacheri sluice Kondam ...	35	1,336 0 0	153 7 7	134 13 7	14	57 7 6	900 0 0	About 20 or 30 years ago.	
	Bund of the Yecheruttur large tank.	202	957 14 5	871 2 1	884 0 6	172	863 7 1	800 0 0	In 1848.	
	Ruined supplying channel of Mangalam.	232	1,089 12 1	640 8 8	888 12 7	200	1,112 14 3	1,000 0 0	In 1857.	

Collector.

Statement giving the names of the more important Works of Irrigation which are urgently in need of repair in the District of North Arcot, &c.—*(Concluded.)*

Táluqs.	Names of Irrigation Works.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average Tax actually paid from 1840 to 1850.	Average Tax actually paid from 1850 to 1860.	Present cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.	Remarks.
1	2	3	4	5	6	7	8	9	10	11
Wallajah Táluq.—*(Concluded.)*	Attupakam large tank	Acres. 114	RS. A. P. 749 14 3	RS. A. P. 479 7 9	RS. A. P. 615 9 9	Acres. 102	RS. A. P. 665 2 10	RS. A. P. 600 0 0	About 30 years ago.	These works being in great disrepair, their early restoration is highly desirable.
	Chittoor large tank	376	1,982 7 9	583 8 10	753 10 4	173	1,288 14 4	1,000 0 0	Do. 40 do.	
	Manjambadi ruined spring channel	42	281 8 6	280 6 3	286 1 0	41	278 15 11	800 0 0	Do. 20 or 25 do.	
	Ganapatipuram spring channel ...	84	494 12 5	367 9 3	416 7 5	71	412 8 3	400 0 0	Do. 15 do.	
	Bund and sluice of the Terumalpuram tank.	355	1,762 9 0	1,046 9 5	1,331 11 0	230	1,326 13 3	1,000 0 0	Do. 15 do.	
	Total...	1,731	10,070 3 9	5,635 9 11	6,569 5 5	1,195	7,073 9 8	8,100 0 0		

CHITTOOR,
11th August 1866.

(Signed) J. D. ROBINSON,
Collector.

Collector:
Ordered
Chittoor 11th Aug 1866.

Proceedings of the Madras Government, Public Works Department,
19th September 1866.

Ordered that the foregoing letter be submitted to Government, with reference to Government Order dated 17th May 1866, No. 1,587, Public Works Department, and in continuation of Board's Proceedings of 17th August 1866, No. 5,813.

Transferred to the Public Works Department.

FORT SAINT GEORGE,
5th September 1866.

(Signed) J. GROSE,
Under Secretary to Government.

No. 475. ORDER THEREON, 19th September 1866, No. 2,998.

CIVIL WORKS, No. 86.

1. With these papers the Board of Revenue submit, in pursuance of G. O. No. 1,587, dated 17th May 1866, Returns of Agricultural Works which are most urgently in need of repair in the Districts of Cuddapah and North Arcot. The amount shown to be required for the purpose is roughly estimated at Rupees 46,982 for the former and Rupees 39,965 for the latter District.

2. It has been already intimated to the Board in separate Proceedings, that the Government are quite unable to make any special assignments for repairs. The Budget for the current official year contains a provision of Rupees 32,500 and Rupees 60,240 respectively for agricultural repairs in the Cuddapah and North Arcot Districts, and, as similar grants are annually assigned, the Government are in hopes that much may be done, in the course of a few years, to place the irrigation works of those Districts in an efficient state.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineers, 3rd and 4th Divisions.
,, Board of Revenue, with one Enclosure.
,, Revenue Department.

Exd. S. T. Augustin.

Revenue Department.

No. 4

Proceedings of the Board of Revenue.
dated 31st August 1866.

Read the following

No. 224.

From,
J. D. Robinson Esqre
Collector of North Arcot.

To,
W. Hudleston Esqre
Secretary to the Board of Revenue
Madras

Sir,

Agreeably to the instructions of the Board contained in Mr. Dalyell's letter of the 11th June last, No. 3972, I have the honor to forward a Statement in the form therein prescribed giving a selected list of the more important works of irrigation, which are most urgently in need of repair in this Distt, and explaining what repairs are required and the date of last repair with the irrigable ayacut under each work.

I have &c.

(Signed) J. D. Robinson.
Collector.

North Arcot....
Coll'r's Kacheri,
Chittoor 11th Aug. 1866.

Ordered

Ordered that the foregoing Letter be submitted to Government with reference to Government Order dated 17÷ May 1866, №. 1587, Public Works Department and in continua= =tion of Board's Proceedings of 17÷ August 1866, №. 5813.—

(A true Copy & Eoctract.)

Secretary.

To,
The Secretary to Government
Revenue Department.
with Enclosure.

C. P. C. Bermaultrouze

No. 6,185.

PROCEEDINGS OF THE BOARD OF REVENUE, dated 30th August 1866.

Read the following paper from H. G. SMITH, Esq., Collector of Cuddapah, to the Secretary to the Board of Revenue, dated 17th August 1866:—

List of the more important Irrigation Works, which are most urgently in need of repair in the District of Cuddapah, specifying the estimated amount of repairs required, the date of last repair, and the irrigable Ayacut under each work, as directed in the Board's Circular, dated 11th June 1866, No. 3,972.

Taluk and village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present cultivation as per account for Fusly 1275.	Present revenue as per account for Fusly 1275.	Rough estimate of repairs needed.	Date of last repair.	Remarks, explaining what repairs are required.
1	2	3	4	5	6	7	8	9	10	11
		Acres.	Rs.	Rs.	Rs.	Acres.	Rs.	Rs.		
Cuddapah.	Camalapuram ..... Pedda Chervu.....	607	4,215	3,601	3,907	570	4,008	5,900	The exact dates are not known, but the repairs are reported to have been executed six or seven years ago.	An estimate amounting to Rs. 5,900, for the repairs of the tank bund, which is much worn out, has been framed by the Department of Public Works.
	Chadipiralla ... . Pullampati Calva	169	1,058	378	400	64	443	250		For repairing the sluice, which is out of order.
	Kutukur..... ..... Pedda Chervu.....	449	4,325	4,173	4,107	392	4,311	700		For the repairs of the bund.
	Pata Cuddapah ..... Pedda Chervu.....	1,066	14,373	13,818	14,069	865	11,337	1,000		Do. do.
	Putlampally... ... . Pata Chervu.....	156	1,330	1,285	1,227	156	1,330	1,000		Do. do.
	Total.....	2,447	25,301	23,255	23,710	2,047	21,429	8,850		
Voilpaud.	Navabpett... ... . Pedda Chervu...	100	926	373	730	79	811	7,122	Not known	For repairing the bund and sluice.
	Chinnagottigal..... Jantrapupett Chervu ...	109	652	76	455	20	220	300	14th May 1852...	For the repairs of the sluice, which is out of order.
	Tarigondah..... ..... Ramanayani do.....	190	1,463	1,267	1,122	100	828	1,300	27th Dec. 1856...	For the repairs of the bund and sluice.
	Manchuru... .... Cotta Chervu...	192	560	111	120	48	194	430	Not known	Do. do. do.
	Total.....	591	3,601	1,827	2,427	247	2,053	9,152		

List of the more important Irrigation Works, &c.—(Continued.)

Taluk and Village.		Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present cultivation as per account for Fusly 1275.	Present revenue as per account for Fusly 1275.	Rough estimate of repairs needed.	Date of last repair.	Remarks, explaining what repairs are required.
1		2	3	4	5	6	7	8	9	10	11
			Acres.	RS.	RS.	RS.	Acres.	RS.	RS		
Kadiri.	Patnam.....	Ranganayani Chervu ...	572	3,736	2,199	2,053	313	2,523	500	In Feb. 1865 ...	For repairing the banks of the supplying channel of the tank.
	Vankamaddi...	Pedda Chervu.....	399	2,041	1,367	818	278	1,366	1,000	,, August 1865..	For repairing the bund and sluice.
	Dhannayani Chervu ...	Do.....	175	743	593	655	150	713	1,200	,, May 1866 ...	For repairing the sluice and calingulah.
		Total.....	1,146	6,520	4,159	3,526	741	4,602	2,700		
Pullampet.	Poli.....	Chervu.....	1,135	7,558	5,463	5,550	937	5,294	3,000	,, 1862.....	For raising the dam constructed to convey the supply to the tank and strengthening the bund, &c.
	Rangampally...	Do.....	175	843	357	482	163	498	1,000	,, 1861.....	For repairing the supplying channel and the bund.
	Nagiripad	Do.....	739	4,820	4,210	4,316	625	2,528	1,000	,, 1862.....	For repairing the bund and supplying channel.
	Settikunta.....	Pedda Chervu.....	452	2,870	1,280	1,117	239	1,871	500	,, 1861.....	For re-constructing a sluice, &c.
		Total.....	2,501	16,091	11,310	11,465	1,964	10,191	5,500		
Jammalmadugu.	Venakiah Kalva..... ...	Chitravati river channel.	866	2,926	1,957	1,188	2,219	1,523	500	In 1860.....	For re-excavating the river channel, which has been almost filled up with sand.
	Chintakunta.....	Govindammah Chervu .	286	3,971	905	1,065	4,345	2,456	200	Not known	For repairing the sluice.
	Gudem Chervu...	Penna river channel ...	168	1,652	1,075	676	1,594	1,164	1,200	In 1858.....	For clearing the channel, which has been totally filled.
		Total.....	820	8,549	3,937	2,929	8,158	5,137	1,900		
Poddatur.	Duvur.....	Tank.....	415	7,270	6,015	6,311	406	7,149	800	In 1856.....	For repairing the bund and calingula.
	Pallavolu.....	Do.....	383	707	446	517	373	698	2,230	,, 1865.....	For re-excavating a new supplying channel, the old one having been entirely filled up by sand.
	Wupparapally.....	Rachervu.....	157	581	217	233	154	564	300	,, 1862.....	For enlarging the bund.
	Sivapuram...	Ragadi Chervu..., ...	162	858	665	649	138	815	450	,, 1859.....	For raising the bund and repairing the sluice.
	Ganzikunta.....	Anantaraz do...	173	964	845	839	149	836	1,000	,, 1863.....	For repairing the sluice.
	Chintakunta	Chinna Chervu and Pedda Chervu.	384	6,689	4,656	5,315	370	6,479	5,000	,, 1864.....	For enlarging the bund and repairing the sluice.
	Nandialampett	Settiwaripally Chervu..,	105	1,585	887	1,042	89	1,403	200	Not known	For repairing the sluice.
		Yellampally do.....	113	1,377	684	808	86	973	100	In 1856.....	For repairing the bund.
		Tiruvapally do.....	133	1,808	1,023	1,342	91	1,243	800	,, 1861.....	For clearing the bed of the tank, which has almost been filled with mud, and enlarging the bank.
		Total.....	2,025	21,839	15,438	17,056	1,856	20,160	10,880		
		Grand Total.....	9,902	84,477	61,620	62,710	15,382	65,571	46,982		

Ordered that the foregoing List be submitted to Government, with reference to Government Order, dated 17th May 1865, No. 1,586, Public Works Department, and in continuation of Board's Proceedings, 17th August 1866, No. 5,813.

(A true Copy and Extract.)

Secretary.

To the Secretary to Government, Revenue Department.

Copy to the Collector of Cuddapah.

Exd. J. Wright.

Public Works Department.

No. 2998

PROCEEDINGS of the MADRAS GOVERNMENT

Under date the 19th Sept. 1866

Read the following

Proceedings of the Board of Revenue (R. No. 6185 dated 30th Augt. 1866)

do do do

(Here enter No. — dated 31st Augt. 1866)

With Mess. fr. the Board of Revenue submitting, in continuance of G. O. No. 1587 dated 17th May 1866, Returns of Agricultural Works which are most urgently in need of repair in the Districts of Cuddapah and North Arcot. The amount shown to be required for the purpose is roughly estimated at Rs 40,982 for the former and Rs 39,965 for the latter District.

It has been already intimated to the Board in separate Proceedings, that the Govt are quite unable to make any special assignments for repairs. The Budget for the current

Dated 30th August 1866.

Submitting list of important irrigation works urgently in need of repair in Cuddapah district.

No. 6,185.

From the Board of Revenue to the Secretary to Government, Revenue Department.

Read Sept. 1866 R. No. 2998-19 Sept. 66

official year Contains a provision of Rs 32,500 & Rs 60,240 respectively for Agricultural repairs in the Cuddapah and North Arcot Districts, and as similar grants are annually assigned, the Govt are in hopes that much may be done, in the course of a few years, to place the irrigation works of those Districts in an efficient state.

B. W. 1866. Department.

No. of Govt. Letter dated

No. 998

PROCEEDINGS OF GOVERNMENT. Public

Dated

To

The Secretary to Govt
Bd of Revenue with the enclosed
Rev Dept

Dept 20 Sept 66

No 473 @ 475

Rec'd 10th Sept 1866 R. 11th

O N 1866 Docket

Pet. of Gault for Sepl.

No 2998

Pet. of the Alabama Court

Dy 19th Septr 66.

Passing orders on Proceedings of the Board of Revenue submitting returns of Smuggling Goods in the Ports Mobile and Pensacola Districts which are in need of repair.

No 4730 @ 475

10th Sept. 1866 Ord. Item