

(1) Number of pages _____

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public works DEPARTMENT.

G.O. No. 693	Press
640-641	~~Mis~~
Dated 28 — 2 — 1866 .	

Not to be folded or roughly handled

*Proceedings of the Madras Government, Public Works Department,
28th February 1866.*

No. 640. Read the following letter from the Superintending Engineer, 4th Division, to the Secretary to Government, Public Works Department, dated Madras, 17th February 1866, No. 4,199 :—

1. I have the honor to submit, for the sanction of Government an estimate, amounting to Rupees 1,280, for clearing out the Yadoothoomotu spring channel of Avelalah in the Chendragherry Range, North Arcot District.

1 Abstract Estimate.
1 Ayacut Statement.

2. There is an average revenue of only Rupees 140 under this channel, but the proposed repairs are urgently required to prevent even this amount from falling off, there being no water in the channel for the crops dependent on it.

3. The work has been commenced at the request of the Collector of North Arcot, who has also countersigned the estimate in token of approval.

4. An increase to the revenue of Rupees 152 is expected. I beg to recommend the estimate for sanction from the Agricultural Repair Funds of the North Arcot District.

No. 641. ORDER THEREON, 28th February 1866, No. 693.

CIVIL WORKS, No. 86.

1. As the work which is provided for in the estimate submitted with this letter is calculated to cost a sum altogether incommensurate with the benefits to be derived from it, the Government must withhold their sanction, and must desire that it be discontinued on the receipt of these orders.

2. The Superintending Engineer will be reminded of the rule which prohibits the undertaking of repairs to irrigation works when the outlay is likely to exceed the highest revenue during the past five years.

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,

Secretary to Government.

To the Superintending Engineer, 4th Division, with two Enclosures.
,, Controller of Public Works Accounts.

Exd. S. T. Augustin.

estimate

No 4109

Superintending Engineer's Office 4th Div.
Madras, February 1866.

From

Colonel F. J. M. Edinure R.E.
Superintending Engineer 4th Division

To
Colonel C. A. Carr R.E.
Secretary to Government P.W.D.

Sir,

I have the honor to submit for the sanction of Government an estimate amounting to Rupees 1250 for clearing out the Gadlothimotai Spring Channel of c. P. P. P. in the Chendragherry range, North Arcot District

2. There is an average revenue of only Rupees 140 under this Channel but the proposed repairs are urgently required to prevent even this amount from falling off, there being no water in the Channel for the crops dependant on it.

3. The work has been commenced at the request of the Collector of North Arcot, who has also counter signed the estimate in token of approval.

4. An increase to the revenue of Rupees 152 is expected. They to recommend the estimate

estimate for sanction from the Agricultural
repair funds of the North West District.

It was the hon. to be

Yours Most Obedient Servant

A. H. H. H.

Subj. Eng. 4th Division

To
Colonel C. A. Orr P. S.
Secretary to Government (N. D.)

一、
 二、
 三、
 四、
 五、
 六、
 七、
 八、
 九、
 十、

No 693

Under date Nov. 28th February 1866

Read the following

From the Supy Engineer of the
4th Division.

Submitting for sanction an
Estimate Rs 1280 for clearing out
the Yadoot Moosaster Spring Channel
of Aulalab in the Cherdagherry
range North Arcot District.

Here enter 17: February 1866

No 41995

As the work which is provided for in the estimate submitted with this letter ~~appears to be~~ excessive, and is calculated to cost a sum altogether incommensurate with the benefits to be derived from it, the Govt. must withhold their sanction, and must desire that it be discontinued on the receipt of these orders -

2. The Supp. Leg. will be reminded of the rule which prohibits the undertaking of repairs to irrigation works when the outlay is likely

P. 77. 1865 Department
of Agriculture
Washington D.C.
A. B. C.

Curate

Is this all right?
According to rule? We
are confident an outlet
more than has been realized under
this channel.
with
to D
for

The estimate submitted

Deirdre

211

1876

19.

1879

2. Shuttlecock - 1 pair for
in Shuttlecock 1 pair 25c
for cleaning out 1 pair
Monometa 1 pair 1 shawl
of Quakata in the 1 pair
Waggon Range 1 pair
1 pair 1 pair 1 pair

with their letter accompanying
is No 1280 a "Certificate"
for immediate release from
their bonds for the current
year's contribution for
reform; whereas "Episcopal
Council" and the Board of
Church Discipline.

1884

25.3.20

3/20/01

27 October

Oct 693-28th July 1866.
With an Order.

2107 Academy 1866 (D. 267)

+ answered
 replied -
 Nov 15
 1891

to exceed the highest runs
during the past 5 years

11.10.20
24

to S. E. 4 D. H. 2 bus. 1/2
to further the [deep] 2nd bank

19

Deep 28th Feb.

P W 1866 Department
Pro: of Govt. for February

No 693.

Pro: of the Madras Govt.

D/ 28th February/66)

Yacoothoomotee Spring
Channel of Avelak in the
Chendragherry Range, North
Arcot District - Sanction
declined to the estimate of
Rupees 1200 for clearing out the
- and the discontinuance of
the work ordered.

P 640. 641.