M.R.O. 1—77,006—8-6-31.

(1) Number of pages 10

(2) Date of repair

(3) Initials of the Referencer

MADRAS RECORD OFFICE.

Government of Madras.

Public works **DEPARTMENT.**

G.O. No. 138. Press ~~Mis.~~

281-282.

Dated 15 - 1 - 1867.

Not to be folded or roughly handled

13.3.47

1/

Proceedings of the Madras Government, Public Works Department,
15th January 1867.

No. 281. Read the following Endorsement of the Superintending Engineer, 4th Division, dated Madras, 4th January 1867, No. 3,866:—

Read the following letter from the Sub-Engineer in charge 3rd Range, Madras District, to the Superintending Engineer, 4th Division, dated Poonamallee, 24th December 1866, No. 286.

1. In continuation of my No. 262 of 8th December, instant, I beg to report that the works hereinunder named have suffered damage during the late rains, and for their security as well as to prevent the revenue from suffering, I have ordered emergent repairs to be undertaken and executed with all dispatch. The estimates in connection therewith will shortly be submitted. The work ordered consists merely of closing of breaches, and strengthening the very weak portions, so as to stand out the season. Many tanks discharged over their banks, which has caused damage to the masonry works in some cases.

Names of Works.

Alagasamoodrum tank.
Tiroovanacovil, two tanks.
Keerapakkam, two do.
Woshalur Hissa tank.
Sogandy, two do.
Mosevakkam tank.
Woshalur do.
Tiroomanee, two tanks.
Saneekynee, two do.
* Manapakkam river channel and Palar left bank, breach.
Woshalur river channel and Palar left bank, breaches.
Maunimanglum tank.
* Panayur tank.
* Veettampakkam Hissa tank.
Vuttumpakkam, two tanks.
Perinjeevakkum tank.
Thodur do.
* Govindavady, two tanks.
Atoo Poottoor tank.
* Malapadoo do.
Parandur do.
Vampakkam, two tanks.
Chinna Sengadoo tank.
Sayloor, two tanks.
Perree Roshampakkam tank.
Amerambodoo tank
Motoopalayem, two tanks.
* Natarsampet Hissa tank.
* Soriwanjur, two tanks.
Oomealachary, two do.
Vadul tank.
Pooel Coopum tank.
* Vadamangalum, two tanks.
Kuram tank.
Poodooputtoo tank.
Tiroovedepullum tank.

All those marked with an asterisk (*) have had their masonry works somewhat damaged.

2. The above comprises the damage as acertained up to the present time. Further reports will be made as information is received.

Submitted to Government for information.

(Signed) A. J. M. BOILEAU, Colonel, R. A.,
Superintending Engineer, 4th Division.

No. 282. ORDER THEREON, 15th January 1867, No. 138.

CIVIL WORKS No. 61. Ordered to be recorded.

(True Extract.)

(Signed) J. H. M. SHAW STEWART, Major, R. E.,
Under Secretary to Government.

To the Superintending Engineer, 4th Division.
„ Controller of Public Works Accounts.

Exd. S. T. Augustin.

No. 284

3 Range Office. Madras Dist.
Perianallee. 24 Dec. 1866

From. Field Engineer in ch. 3 Range
Madras District

To. The Superintending Engineer
Ist Division

Sir.

In continuation of my No. 262 of 8 Dec. Inst. I beg to report that the works hereinunder named, have suffered damage during the late heavy rains, and for their security as well as to prevent the Revenue Establishment, I have ordered Emergent repairs to be undertaken and executed with all dispatch. The Estimates when received hereinto, will thereby be submitted. The work ordered consists merely of closing of breaches, and strengthening the very weak portions; so as to stand out the heavy banks discharged over their banks, which has caused damage to the masonry works in some cases.

Names of works	
Alagasamoodrum Tank	Sogandy. 2 Tanks
Tiroovanaeiel. 2 Tanks	Moseratchum Tank
Veerapatchum. 2 Tanks	Wathalur Tank
Woshalur Vrisa Tank	Tiroonanee 2 Tanks

Saneckypree 2 Tanks
+Manapakkam River channel, and Palar left bank. Breach.
Woshalur River channel & Palar left bank. Breaches.
Manminanglam Tank.
+Panayur Tank.
+Vettampakkam Weir & Tank.
Vettampakkam 2 Tanks.
Perumpakkam Tank.
Thodur Tank.
+Gorrudavady 2 Tanks.
Aboo Pookor Tank.
+Malapadoo Tank.
Parandur Tank.

Vampakkam 2 Tanks
Chunia Sengadoo Tank.
Saglevon 2 Tanks.
Perree Roothampakkam Tank.
Amerambadoo Tank.
Motoopalayam. 2 Tanks.
+Natarsampet Weir & Tank.
+Seriviyur 2 Tanks.
Oomealachary 2 Tanks.
Nabel Tank.
Poorl Coopum Tank.
+Vadamanglam 2 Tanks.
Thuraur Tank.
Poodoopuckkom Tank.

Trivedepullem Tank.

All those marked + (asterisk) have had their masonry works somewhat damaged.


2. The above comprises the damage as ascertained up to the present time. Further reports will be made as information is received.

I have the honor to be
Sir
Your most obedient Servant
[signature]
Subdl. Engr. in Ch. 2d Range

From
The Sub Engineer D.P.W.
No 3 Range Madras Dist.
To
The Dely. Engineer 4th Div.

Dated 24th Decr 66
Received
No 3
No. 286

In forwarding these certificates damages are caused to several Tanks by the late heavy rains which were ordered to be executed in Emergency for securing the safety of those Tanks at this season for which Estimates will be submitted shortly.



No. 3866.

Submitted to Government for information. —

A. Burlton Colonel R.E.
Supg. Engineer 6th Div.

Supg. Engrs Office 6th Div.
Madras 4th January 1867.

P.W. 1865 Despatch
Pro: of Govt 2nd January
No 1 Enclosure 1 to 31.
From
The Supt Engineer
4th Division

To
The Secretary
to Government 1865
dated 4th January
Rec'd 5th January 1866.

En: one No 3866.

Submitting a letter from the Sub Engineer No 3 Range reporting certain damages caused to several Tanks by the late heavy Rains.

No 138. 15th Jany 1867

No 281. 282

Wm Blackburn