

(1) Number of pages.....

(2) Date of repair.....

(3) Initials of the Referencer.....

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. *6830*

Press
Mis.

412-413

Dated *18-6-*

1867.

Not to be folded or roughly handled

14

*Proceedings of the Madras Government, Public Works Department,
18th June 1867.*

No. 412. Read the following letter from the Superintending Engineer, 3rd Division, to the Secretary to Government, Public Works Department, dated Camp, Hurpenhully, 4th June 1867, No. 599:—

1. With reference to G. O. No. 1,262 of 23rd April 1866, I have the honour to inform you that Mr. Blacker, the Sub-Engineer in charge of the Pullunpett Range, inspected the Munnoor Kitchama tank in the 131st mile, and reported that, in his opinion, sufficient provision had not been made by the Railway authorities for the free flow and escape of the water from a nullah which supplies the Munnoor and Munnoor Kitchama tanks.

2. I sent a copy of this report, together with a sketch plan, to the Consulting Engineer for Railways, requesting that the latter might be returned when no longer required, and stated that it appeared to me that the breaches in the channel and the inundation had been principally caused by an insufficient amount of waterway in the Railway works. These had all been constructed before the present system was ordered, of referring the Railway sections to the Public Works Department for opinion, as to the sufficiency or not of the waterway provided.

3. I received no reply to my letter; but in December last I met Colonel Anderson and Mr. Roberts, the Resident Engineer in charge of that portion of the line, and after careful examination of the country in the neighbourhood, we came to the opinion that the waterway provided by the Railway was insufficient, and that some steps should be taken by them to quicken the discharge, as it would be difficult to increase the waterway.

4. The Munnoor Kitchama tank has two rough stone calingulahs; but, to prevent any damage to the Railway from the breaching of this tank, I beg now to submit, for the sanction of Government, from the sum allotted for "Repairs Agricultural," an estimate amounting to Rupees 3,064 for putting the bank into good order, and for constructing two good calingulahs.

No. 413. ORDER THEREON, 18th June 1867, No. 1,830.

IRRIGATION, No. 18.

1. His Excellency the Governor in Council sanctions the estimate of Rupees 3,064 for repairing and constructing two calingulahs to the Munnoor Kitchama tank in the Cuddapah District.

* Rupees 2,117.

† Rupees 947.

2. The outlay* on repairs will be charged to the District *Repair* allotment, the cost† of the calingulahs being defrayed from the grant for Minor New Works under "Agricultural."

(True Extract.)

(Signed) CHARLES A. ORR, Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 3rd Division, with one Specification.

„ Accountant General.

„ Controller of Public Works Accounts.

Exd. S. T. Augustin.

N. 599.

Superintending Engineer Office B. D.
Telug. Meerpoorally
District Bellary
Camp Meerpoorally
4th Decr 1867

From

The Superintending Engineer
B. Division

To

The Secretary to Government
Public Works Department

Sir,

With reference to G. O. N. 1262 of 23rd June 1866, I have the honor to inform you that Mr. Blacker, the Sub Engineer in charge of the Pullampett Range, inspected the Munoor Pichanna tank in the 131st mile, and reported that, in his opinion sufficient provision had not been made by the Railway authorities for the free flow and escape of the water from a Muttah, which supplies the Munoor and Munoor Pichanna tanks.

2. — I sent a copy of this report together with a sketched Plan to the Consulting Engineer for Railways, requesting that the latter might be returned when no longer required, and sketched that it appeared to me that the breaches in the channels and the inundations had been principally caused by an insufficient amount of Waterway in the Railway works. There had all been submitted before the present system was ordered, of referring the Railway sections to the Public Works Department for opinion as to the sufficiency or not of the Waterway provided.

3. — I received no reply to my letter, but in December last I met Colonel Anderson and Mr. Roberts, the Resident Engineer in charge of that portion

portion of the line, and after careful examination of the Country in the neighbourhood we came to the opinion that the Waterway provided by the Railway was insufficient, and that some steps should be taken by them to quicken the discharge, as it would be difficult to increase the Waterway.

The Kumbhar Pichhanna Tank has two rough stone Calingulabs; but, to prevent any damage to the Railway from the breaching of this Tank, they now to submit for the sanction of Government from the sum allotted for "Repair Agricultural," an Estimate amounting to Rs. 2000 for putting the Tank into good order and for constructing two good Calingulabs.

I have the honor &c.

A. D. S. S. S.

Major R. S.

Superintendent Engineer 3rd Division

Mr. J. P. S. S. S.
Mr. of Govt. for some
A. 2200.

From
The Superintendent Engineer
3rd Division

To the Secretary to Govt.
P. W. Dept.

Dated 4th June 1867.

Recd. 4/2-1867.

No. 599

Enclosure 4

Forward Plans Estimate
and Specification for
Constructing Calingulabs
to Kumbhar Pichhanna Tank in the
Pulhumpet Range (Cuddalore District) amounting
to Rs. 2000-0-0.

No. 412

June 1867 P. 17^m

ex. 1830 - 18th June 1867.

Collector

Superintendent

Migration

Metrical Estimate
District Kudalaphu
Taluk Pullampatti
Village Munnar

Work Improving the Kitchanar Reservoir Tank at Munnar
Kudalaphu

Quantity	Description of work	Rate	Amount	Total
1038 3/4	Cubic Yards Earthwork to the bank including 1/2 ft. of	2	1297 15 6	
1208	" New Stone roughly dressed for revet-			
	ment to the bank	8	604	
915 3/4	" Old Stone	2	114 7 6	
	Surplus at 5 per cent		100 9	
				2117
	New Kalingalali No 1 North West end of Tank			
257 7/8	Cu yds. Earthwork	2 8	43 10 3	
69 1/2	" Stone in Channam	4 8	312 2 8	
180 5/7	" New Stone	10	112 13 6	
60 7/8	Square yds. Paving	2	7 7 5	
5	Cu yds. Woodwork	1	25	
	Surplus at 5 per cent		24 6 2	
				520
	New Kalingalali No 2 South West end of Tank			
350 7/8	Cu yds. Earthwork	2 8	58 6 10	
50 5/7	" Stone in Channam	4 8	225 14	
153 1/5	" New Stone	10	95 16 6	
52 1/2	Square yds. Paving	2	6 8 5	
5	Cu yds. Woodwork	1	20	
	Surplus at 5 per cent		20 3 3	
				427
	Total of Estimate No.			3064

Pullampatti Range Office
Ottumalai 22 April 1879

[Signature]
Collector

Sd/- W. A. Blacker
Sub Engineer in Charge

[Signature] Major D. C.
Superintendent Engineer

The Honble Secretary
 to the Government
 Madras
 18th June 1869.

18th June 1869.

The Honble Secretary to the Government
 Madras
 18th June 1869.

Public Works Department.

N^o. 1830.

PROCEEDINGS of the MADRAS GOVERNMENT.

Under date the 18th June 1869.

Read the following

To the Superintending Engineer
 of the S. D.

(Here enter No. 99 dated 18th June)


His Excellency the Governor in Council sanction the Estimate of Rs. 3061+ for repairing and constructing two Talingulaks to the Mannoor Kitchanor Tank in the Coimbatore District.

2. The outlay on repairs will be charged to the District Repair Allotment, the cost of the Talingulaks being defrayed from the grant for Minor New Works under "Agricultural".

Rs. 2117

Rs. 947.

To the S. D. Eng. 3rd or with one specific
 Acctt. Genl.
 Considered
 & passed
 Decr. 19/6/69



P. W. 1867. Department.

Proc. of Govt. for June
No. 1830

PROCEEDINGS OF GOVERNMENT.

Dated 18

16 June 1867

*Sanctioning the
Estimate of Rs. 3,064 for re-
pairing and constructing two
Calingulads to Munmor
Kitchama Tank in the
Kudalapad District.*

No. 412-413